

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

31/08/2018 15:46

JOB-NO: 85008584

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 3

ADDRESS: 50 UBI AVENUE 3
#01-12
SINGAPORE 4088660
NIL**VEHICLE DETAILS**

LICENSE NO: SLH2972Y

TRANS: AUTO

CHASSIS: MR053REH104559201

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY336316

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,800.00	0.00	1,800.00		Y	1000
2 TO SPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
3 TO SPRAY REAR REINFORCEMENT	1.00	250.00	0.00	250.00		Y	100
4 TO SPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	200
5 TO SPRAY REAR SPARE TYRE PANEL	1.00	250.00	0.00	250.00		Y	X
6 TO SPRAY REAR FENDER LHS	1.00	250.00	0.00	250.00		Y	200
7 TO SPRAY REAR FENDER RHS	1.00	250.00	0.00	250.00		Y	X
8 TO SPRAY REAR BOOTLID	1.00	250.00	0.00	250.00		Y	200
9 TO SPRAY REAR WHEEL HOUSE PANEL LHS	1.00	250.00	0.00	250.00		Y	X
10 RUST PROOFING	1.00	120.00	0.00	120.00		Y	60
11 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	120.00	0.00	120.00		Y	30
12 REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS,REAR SPARE TYRE BOARD,CUSHION,AND ETC	1.00	180.00	0.00	180.00		Y	150
13 REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	1.00	130.00	0.00	130.00		Y	30
14 REMOVE & REFIT FUEL TANK	1.00	140.00	0.00	140.00		Y	X
15 REMOVE REAR WINDSCREEN	1.00	120.00	0.00	120.00		Y	✓
16 MOUNT WORK BENCH	1.00	350.00	0.00	350.00		Y	200? photo
17 ALIGNMENT REAR CHASSIS	1.00	260.00	0.00	260.00		Y	200? photo
18 R & R BOOTLID COMPONENTS	1.00	140.00	0.00	140.00		Y	60
19 REMOVE & REFIT EXHAUST PIPE & MUFFLER	1.00	120.00	0.00	120.00		Y	X
20 REMOVE REAR SEAT & REMOVE REAR SPEAKER PANEL TRIM	1.00	130.00	0.00	130.00		Y	760 photo
21 R & R ROOF LINING	1.00	120.00	0.00	120.00		Y	X
TOTAL:		5,730.00	0.00	5,730.00			
MATERIALS							
1 REAR BUMPER	1.00	487.00	121.75	365.25	L	Y	de✓
2 REAR BUMPER SIDE RETAINER LHS LONG	1.00	105.00	26.25	78.75	L	Y	de✓
3 REAR BUMPER SIDE RETAINER RHS LONG	1.00	105.00	26.25	78.75	L	Y	X
4 REAR BUMPER SIDE RETAINER LHS SHORT	1.00	80.00	20.00	60.00	L	Y	de✓
5 REAR BUMPER SIDE RETAINER RHS SHORT	1.00	80.00	20.00	60.00	L	Y	X
6 REAR BUMPER BEAM ARM LHS	1.00	102.00	25.50	76.50	L	Y	?

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
7 REAR BUMPER BEAM ARM RHS	1.00	102.00	25.50	76.50	L	Y	X
8 REAR BUMPER REINFORCEMENT	1.00	380.00	95.00	285.00	L	Y	bt
9 REAR BUMPER REFLECTOR LHS	1.00	62.00	15.50	46.50	L	Y	cut
10 REAR BUMPER REFLECTOR RHS	1.00	62.00	15.50	46.50	L	Y	X
11 BOOTLID	1.00	880.00	220.00	660.00	L	Y	bt
12 BOOTLID "TOYOTA" EMBLEM	1.00	67.00	16.75	50.25	L	Y	new
13 BOOTLID "COROLLA" BADGE	1.00	67.00	16.75	50.25	L	Y	new
14 BOOTLID "ALTIS" BADGE	1.00	67.00	16.75	50.25	L	Y	new
15 BOOTLID HINGE LHS	1.00	115.00	28.75	86.25	L	Y	RY
16 BOOTLID HINGE RHS	1.00	115.00	28.75	86.25	L	Y	RY
17 BOOTLID LOCK	1.00	348.00	87.00	261.00	L	Y	?
18 BOOTLID INNER BOARD	1.00	475.00	118.75	356.25	L	Y	X
19 BOOTLID OUTER CHROME GARNISH	1.00	212.00	53.00	159.00	L	Y	X
20 BOOTLID LICENSE PLATE LAMP LHS	1.00	65.00	16.25	48.75	L	Y	X
21 BOOTLID LICENSE PLATE LAMP RHS	1.00	65.00	16.25	48.75	L	Y	X
22 TAIL LAMP OUTER LHS	1.00	378.00	94.50	283.50	L	Y	cut
23 TAIL LAMP OUTER RHS	1.00	378.00	94.50	283.50	L	Y	X
24 TAIL LAMP INNER LHS	1.00	294.00	73.50	220.50	L	Y	cut
25 TAIL LAMP INNER RHS	1.00	294.00	73.50	220.50	L	Y	X
26 REAR END PANEL	1.00	705.00	176.25	528.75	L	Y	bt
27 REAR END PANEL TOP GARNISH	1.00	343.00	85.75	257.25	L	Y	X
28 REAR SPARE TYRE PANEL	1.00	785.00	196.25	588.75	L	Y	X
29 REAR SPARE TYRE PANEL FLOOR BOARD	1.00	412.00	103.00	309.00	L	Y	X
30 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	cut
31 REAR FENDER RHS	1.00	1,085.00	271.25	813.75	L	Y	X
32 REAR FENDER LHS	1.00	1,085.00	271.25	813.75	L	Y	bt
33 REAR FENDER INNER SHIELD LHS	1.00	68.00	17.00	51.00	L	Y	de
34 REAR FENDER INNER SHIELD RHS	1.00	68.00	17.00	51.00	L	Y	X
35 REAR FENDER INNER PANEL TRIM LHS	1.00	389.00	97.25	291.75	L	Y	X
36 REAR FENDER INNER PANEL TRIM RHS	1.00	389.00	97.25	291.75	L	Y	X
37 REAR FENDER WHEEL HOUSE PANEL LHS	1.00	427.00	106.75	320.25	L	Y	X
38 REAR EXHAUST PIPE	1.00	571.00	142.75	428.25	L	Y	X
39 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	new
40 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200mm
41 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	X
42 BOOTLID INNER BOARD CLIP	1.00	35.00	0.00	35.00	S	Y	X
43 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	X
44 REAR FENDER INNER SHIELD CLIP LHS	1.00	35.00	0.00	35.00	S	Y	new
45 REAR FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	S	Y	X
46 REAR FENDER INNER PANEL TRIM LHS CLIP	1.00	35.00	0.00	35.00	S	Y	X
47 REAR FENDER INNER PANEL TRIM RHS CLIP	1.00	35.00	0.00	35.00	S	Y	X
48 REAR WINDSCREEN SEALANT	1.00	30.00	0.00	30.00	S	Y	new
49 REAR END PANEL SEALANT	1.00	30.00	0.00	30.00	S	Y	new
50 REAR SPARE TYRE PANEL SEALANT	1.00	40.00	0.00	40.00	S	Y	X
TOTAL:		12,562.00	974.25	9,587.75			
TOTAL PARTS & LABOUR :		18,292.00	2,974.25	15,317.75			

EXCESS/LOADING:\$S\$ 0.00

No. Of Day: 7

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$S\$

DATE OF SURVEY: 3/19/18

SURVEYED BY: Tanjhi

CONTACT NO: 97495744

FAX NO:

surelmantham

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00