

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587

Reg No : 200600989K GST No : 200600989k

MSIG Insurance (Singapore) Pte Ltd (SGX Centre)

Estimate Repair

Motorcar Claim Department

Attn Jocelyn - 65942539

Date : 3/9/2018

Re OD Claim

Car No SJF8638H

Page 1/2

Policy No A71340021 QMT

Item	Descriptions	Cost Prcie
1	Bonnet Cover	\$ 300.00
2	Bonnet Hinge RH & LH @\$20 X 2	\$ 40.00
3	Bonnet Lock	\$ 70.00
4	Bonnet Lock Cable	\$ 33.00
5	RH Fender	\$ 60.00
6	LH Fender	\$ 60.00
7	LH Fender Inner Shield	\$ 45.00
8	Side Skirt - RH & LH	\$ -
9	Front Bumper	\$ 285.00
10	Front Bumper Retainer RH & LH @\$15 X 2	\$ 30.00
11	RH Headlamp	\$ 270.00
12	LH Headlamp	\$ 270.00
13	Headlamp Lower Bracket RH & LH @\$18 X 2	\$ 36.00
14	Support Panel Assy	\$ 150.00
15	Brace Panel	\$ 20.00
16	Front Bumper Reinforcement	\$ 185.00
17	Airbag Impact Sensor Cover	\$ 15.00
18	Aircon Condenser	\$ 280.00
19	Radiator Assy	\$ 320.00
20	Radiator Air Guide RH & LH @\$40 X 2	\$ 80.00
21	Auto Transmissiohn Cooler	\$ 200.00
22	Fan Motor Assy	\$ 320.00
23	Air Duct	\$ 180.00
24	Aircon Discharge Pipe	\$ 110.00
25	Aircon Suction Pipe	\$ 135.00
26	Aircon Pressure Pipe	\$ 170.00

REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:

Total For Parts \$ 3,664.00

Add 15% Margin \$ 549.60

Grand Total \$ 4,213.60



To Be Continued



Not Notified

LI Rep 8?

Resurvey After Paint Ex 8500h

6 days

62564315

S/N Item (s)

1	Towing Service	\$ <i>501</i>	60.00
2	Front Number Plater With Frame	\$ <i>mir</i>	35.00 ✓
3	Front Bumper Clips - 1 Set	\$ <i>12</i>	35.00 ✓
4	Mazda Coolant	\$ <i>22</i>	22.00 ✓
5	Auto Transmission Oil	\$ <i>12</i>	78.00
			<i>35.00</i>
Total For S/N		\$	<u>170.00</u>

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel , Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ <i>6001</i>	950.00
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ <i>200</i>	1,100.00
3	Remove & Refix Aircon Parts To Facilitate Repair, Vacuum And Refill R134a Gas	\$	100.00 ✓
4	Check Wiring, Lighting Syetem For Proper Function	\$	50.00 <i>201</i>
Total For Labour		\$	<u>2,200.00</u>

Ready Auto Care Pte Ltd

Sulynn - 96606551

Total For Parts & Labour \$ 6,583.60

