

SHA 2459Y

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,600.00 1400/-
	Spray Painting Charge			\$ 1,800.00 1000/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 150.00 60/-
	Towing Charge			\$ 50.00 44
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 44
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Transfer of Door		\$ 120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	Four Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 44
	Remove/Refix Dashboard			\$ 450.00 44
	Remove/Refix Front Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 50/-
	TOTAL LABOUR			\$ 6,660.00
	ESTIMATE TOTAL			\$ 33,786.84
	05/09/2018 @ 0900am Not Actual 2/Sum 13 days. Ryan LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			