

Trans-cab Auto Services Pte Ltd**AAD1809-004**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 721L

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 721L

VF1ABL15AUC283314

RENAULT

LATITUDE

1.9.2018

AXA**SUPPLEMENTARY ESTIMATE**

PART		LIST	
1	DOOR PANEL REAR RH	\$	2,844.66 X
1	FENDER PANEL REAR RH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR RH	\$	543.47
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL CENTER RH	\$	990.25
1	HEADLAMP RH	\$	1,184.43
		\$	11,024.70
10%		\$	1,102.47
		\$	9,922.23

Special Nett

1	REAR DOOR STICKER '6555 3333'	\$	80.00
1	DOOR CHECK BOLT	\$	22.69
1	DOOR GUIDE SCREW	\$	10.85
1	DOOR HINGE BOLT	\$	10.85
1	DOOR HINGE NUT RH	\$	14.60
1	DOOR CHECK BOLT	\$	22.69
1	DOOR CHECK NUT	\$	3.75
1	DOOR LOCK SCREW L70Y	\$	6.12
1	DOOR CATCH SCREW L70Y	\$	10.06

TOTAL \$ 181.63**TOTAL PARTS \$ 10,103.86**