

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

 Reg. No. : SH F 339Y Ref. No. TAX 8 / 18 / 2116

 Make / Model : TOYOTA PRIUS4 Reg. Date : 10/10/2017

 Name of Driver : ANG BENG KEE

 Date/Time of Accident : 31/08/2018 09:30

 Surveyer is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)


 Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

 Accident Repair Job Card No. : 24097779

Special Instruction to ARC, if any :

The damages on the Taxi are as indicated in the following diagram :



Signed : _____ Date : _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : _____ Mileage : _____

 Date Prepared : 01/09/2018 Repair Completed date/time: _____

Summary of Repair Estimates

| | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------|--------------------|-------------------------------------|
| Total Labour Charges : | \$ <u>507</u> | \$ _____ |
| Total Spray Painting Charges : | \$ <u>558</u> | \$ _____ |
| Total Material Charges : | \$ <u>1308.89</u> | \$ _____ |
| Other Charges : | \$ <u>360</u> | \$ _____ |
| TOTAL : | \$ <u>2733.89</u> | \$ _____ () |
| No. of Repair Days : | [<u>4</u>] days | [<u>2</u>] days |

 Signature : _____
 Prepared by: MING
01/09/2018 12:00

Adjusted by: _____

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

QN No. _____ Invoice No. _____ Invoice Date _____

Signed : _____ Date : _____

Part 1 - Labour Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------|--------------------|-------------------------------------|
| TO REPAIR REAR PORTION | 507 | 350 200 |
| | | |
| | | |
| | | |
| | | |
| | | |
| Total Labour | \$ 507 | \$ |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO REPSRAY REAR BUMPER | 378 | 200 |
| TO RESPRAY BUMPER BEAM | 180 | X 00 |
| | | |
| | | |
| | | |
| | | |
| Total Spray Painting & Panel Beating | \$ 558 | \$ |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION | 80 | 20 |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120 | 20 |
| TO REPLACE SUNDRY PARTS | 100 | X 00 |
| TO WASH AND VACUUM | 60 | X 00 |
| | | |
| | | |
| | | |
| | | |
| Total Other Costs | \$ 360 | \$ |

Part 4 - Spare Parts / Material Usage

Reservation No : _

Page (3)

| To be completed by Service Advisor, ARC | | | | | | | Surveyor Adj |
|---|------------------------------|-----|-----------------|--------------|------------------|------------------------|--|
| Part Number | Parts Description | Qty | List Price (\$) | Discount (%) | Final Price (\$) | Repair (R) Replace (/) | Not given (x) Repair (R) Replace (/) |
| 5215947913 | COVER, RR BUMPER ASSY | 1 | 423.9 | 25 | 317.92 | / | x R |
| 5246247030 | PAD, RR BUMPER, RH & LH , 1 | 2 | 3.8 | 25 | 5.7 | / | x m |
| 5246247020 | PAD, RR BUMPER, RH & LH , 2 | 2 | 3.8 | 25 | 5.7 | / | y m |
| 5246247010 | PAD, RR BUMPER, RH & LH , 3 | 2 | 3.8 | 25 | 5.7 | / | x n |
| 5219147030 | SEAL, RR BUMPER ARM, RH & LH | 2 | 11 | 25 | 16.5 | / | x m |
| 5202347030 | REAR BUMPER REINFORCEMENT | 1 | 318.8 | 25 | 239.1 | / | x m |
| | SENSOR REVERSE | 1 | 180 | 0 | 180 | / | x SVL |
| | PIXEL STICKER | 2 | 60 | 0 | 120 | / | / m |
| 5245347010 | GUARD, RR BUMPER, LOWER | 1 | 558.3 | 25 | 418.72 | / | / CEA |
| 5216947020 | COVER, GUARD RR BUMPER LOWER | 1 | 14.8 | 25 | 11.1 | / | x SVL |
| 5246147010 | PAD, RR BUMPER, CTR | 3 | 2.2 | 25 | 4.95 | / | / m |
| TOTAL MATERIALS | | | | | \$ 1308.89 | | |

NA2 LKK
 4/9/18 1615
 PIP
 2 DAYS
 BEFORE PAINT PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: