

ASS. SEC. BY:

REF: CS/CTI/18016274/ R/S d3 ⁿ² Special Instruction:

Surveyor: meimen ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTI Date/Time: 6/9/18 @ 10:05am

Estimated Cost: _____ Bill to: _____

OD / TP RES / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 5765S Insured: SJY 2498J

at Workshop m/s: Chern's Customcraft Tel: _____

of BIK 1010, Bkt Merah Lane 3 #01-105

Policy No: DMPCSN3003201803 Claim No: SNM18D04244C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/08/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: 11/9/18 @ 10am-12pm

Date/Time: 11:26am @ 6/9/18 Person Contacted: Sharon Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLP 5765S - X</u>
	<u>SJY 2498J - X</u>

Surveyor: Rasul

REF:

2347C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / PI / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 57655

at Workshop m/s: CHARN'S CUSTOM CRAFT

of BLK 1010, BUCKET MARK 3 #01-105

Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) 10am - 12pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLP 57655 Yr Regn: 2010 / Sun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MITSUBISHI LANCER 1.5 c.c. 1499

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 093598 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMY SRCY 2AAM00010

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50ZR17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 28/08/18 D.O.I. 11/09/18

Survey held at CHARN'S CUSTOM CRAFT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/12/18	Confirmed P/P \$ 2,493.10 @ 7 days w.th Rasul. (\$ 933.80 Red - 27%)

RECEIVED 10 DEC 2018

[Signature]
10/12/2018

Date/Time, File Pass to? 10/12/18 : Preli. Report

1) Typist : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ 2,493.10 P/P)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2018		06 Sep 2018 10:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]			
Insured:							
Main Claimant: MOK WEIXIANG							
Vehicle Reg. No.: SLP5765S				Date of Loss: 28/08/2018 00:00 - :59			
Claim Type: TP / SNM18D04244C02				Policy/Cover Note No.: DMPCSN3003201803			
Vehicle Reg. No. (Insured): SJY2498J				Policy No. (Claimant):			
				Excess: S\$0.00			
Repairer: Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105, 159724 Bukit Merah - Tel: 62717054							
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]							
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2018]							
Adj Asg. Remarks: EST \$3666.78, ASSIGN KENNETH KONG AS SJE.							

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 10 December 2018 3:51 PM
To: 'Charn's Customcraft'
Cc: SUR; Rasul (LKKAuto)
Subject: RE: Finalization - SLP 5765 S - Mit Lancer

Sensitivity: Confidential

Hi Sharon,

Confirmed final fig of \$2,493.10 (part by part) @ 4 days of repairs before GST.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charn's Customcraft [mailto:charns@singnet.com.sg]
Sent: Wednesday, 5 December 2018 5:43 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: sur@lkkauto.com
Subject: Finalization - SLP 5765 S - Mit Lancer
Importance: High
Sensitivity: Confidential

Hi Rasul

Kindly find attached for finalization.

Parts: \$1178.10
S/N: \$235.00
Lab: \$1080.00

Total: \$2493.10 (before GST/Excess)

Please confirm

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L
Company Reg No: 25151300M

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2368C

Vehicle Details

Vehicle No.: SLP5765S
Vehicle to be Exported: Yes
Intended De-registration Date: 18 Sep 2018
Vehicle Make: MITSUBISHI
Vehicle Model: LANCER 1.5EX MIVEC A/T ELEGANCE 2WD 4DR
Primary Colour: Black
Manufacturing Year: 2009
Engine No.: 4A910127947
Chassis No.: JMYSRCY2AAU000710
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$17,035.00
Original Registration Date: 29 Jun 2010
First Registration Date: 29 Jun 2010
Transfer Count: 1
Actual ARF Paid: \$17,035.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Jun 2020
PARF Rebate Amount: \$9,369.00

Intended COE Rebate Details

COE Expiry Date: 28 Jun 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$31,510.00
COE Rebate Amount: \$5,601.00
Total Rebate Amount: \$14,970.00

The information contained herein is correct as at 31 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2018 09:59
Date Of Accident	28/08/2018 17:40
Exact Location Of Accident	TELOK BLANGAH ROAD OPP VIVO CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP5765S
Insured/Policyholder	
Name Of Registered Owner	MOK WEIXIANG
NRIC No	S8502368C
Email Address	MOKWEIXIANG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-83639778
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00007793
Cover Note Number	

Driver

Name of Driver	MOK WEIXIANG
NRIC No	S8502368C
Date Of Birth	30/01/1985
Occupation	INDOOR
Date Of Driving Pass	17/03/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83639778
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	MOKWEIXIANG@YAHOO.COM.SG

Address	BLK 424C YISHUN AVE 11 #12-300
Postcode	763424
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JOYCE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SUBMIT TO FWD DIRECTLY
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJY2498J
Vehicle Make/Model/Colour	TOYOTA ESTIMA - WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIANNE YEO SZE RAO
NRIC/Passport Number	870415-01-5212
Contact Number	81015558
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Sketch Plan Pg. 1



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8502368C



Name
MOK WEIXIANG

英 伟 祥

Race
CHINESE
Date of birth
30-01-1985
Country/Place of birth
SINGAPORE

Sex
M

S8502368C

S4P5765

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg	17 Mar 2006

NP 429A



5492347



NRIC No. S8502368C



Date of Issue
03-07-2015

Address
APT BLK 424C YISHUN AVENUE 11
#12-300
SINGAPORE 763424

Accident Sketch Plan Pg. 1

SKETCH PLAN

VEHICLE NO: SLP5765S
ACCIDENT DATE: 28/8/18

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
(e) the information so collected under (d) above may be shared / disclosed
(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
(ii) for complying with requirements under any regulations, laws or court orders

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policyholder's Signature: [Signature]
Date & Time: 29/08/18

Driver's Signature: [Signature]
Date & Time:


CHARN'S CUSTOMCRAFT
Reporting Centre Personnel's Signature: [Signature]
Name:
NRIC/FIN No.:

CHARN'S CUSTOMCRAFT
1010 #01-105
Singapore 154004
Tel: 6272 5554 / 6272 5553
Email: info@charns.com.sg

Accident Sketch Plan Pg. 1

SLP 57655
28/8/18

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I come to a stop during a Red traffic light.
 Suddenly a car bang onto my back of my car

OWN DAMAGE () 3RD PARTY CLAIM REPORTING ONLY () OWN WORKSHOP ()

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 29/08/18

Driver's Signature

(if driver is not the policyholder)

Date & Time:

CHARN'S CUSTOMCRAFT
Block 1010 #01-105
Bukit Merah Lane 3
CHARN'S CUSTOMCRAFT
Singapore 105740

Reporting Centre Phone No: 62736676

Name:

NRIC/FIN No:

Email: charns@singnet.com.sg



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

NTUC/CHINA TAIPING(SJY2498J)
DOA: 28/08/2018@1740

CHINA TAIPING INSURANCE PTE LTD
ATTN: THE MOTOR CLAIMS DEPT

31/8/2018

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SLP 5765 S - MITSUBISHI LANCER 1.5EX MIVEC A/T ELEGANCE 2WD 4DR
CHASSIS NO: JMYSRCY2A8U005583 (01/2008)

1 pc	Rear emblem 'LANCER'	net /	\$ 52.00	(NETT)
1 pc	Rear emblem 'EX'	net /	\$ 45.00	(NETT)
1 pc	Rear boot 'C&C' emblem	net /	\$ 45.00	(NETT)
1 pc	Rear boot logo	net /	\$ 49.00	(NETT)
1 pc	Rear boot rubber	X AN	\$ 176.00	(NETT)
1 pc	Rear bumper	DE -	\$ 815.00	(NETT)
1 pc	Rear bumper tow cover	MS -	\$ 27.00	(NETT)
1 pc	Rear bumper reflector RH	? CRF /	\$ 27.00	(NETT)
1 pc	Rear bumper reinforcement	? PA -	\$ 210.00	(NETT)
4 pcs	Rear bumper clips @ \$5	net /	\$ 20.00	(NETT)
1 pc	Rear bumper retainer RH	net /	\$ 19.00	(NETT)
1 pc	Rear end panel	repair	\$ 506.00	(NETT)
			<u>\$ 1,991.00</u>	
			\$ 199.10	
	LESS 10%		<u>\$ 1,791.90</u>	

1 pc	Rear no.plate (S/NETT)	\$ 35.00	BT -
1 set	Reverse sensor (S/NETT)	\$ 200.00	net /

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear fender LH, rear bumper, tyre compartment and affected areas.

\$ ~~600.00~~ 400 480

Putty and respray rear inner panel, rear end panel, rear boot, rear fender LH, rear bumper, rear tyre compartment and affected area.

\$ ~~800.00~~ 600

ADD 7% GST

\$ 3,426.90
\$ 239.88
\$ 3,666.78

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

LKK Auto Consultants hereby notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RASUL
HP 90010068
4 days
11/09/18 @ 11/10
Resurvey after repair 54

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016274/R1SD3N2
Date: 12/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3003201803
Claimant Vehicle No :	SLP5765S	Insured Vehicle No :	SJY2498J
Date of Loss:	28/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04244C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5765S	Engine No:	4A910127947
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSRCY2AAU000710
Reg. Date:	29/06/2010 (Man. Year: 2009)	Odometer:	93598 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50ZR17	Rear Tyre Size:	215/50ZR17
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,026.90	1,413.10	613.80	30.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,080.00	320.00	22.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,426.90	2,493.10	933.80	27.25
+ GST 7.00/7.00% (S\$)	239.88	174.52	65.36	27.25
Nett Amount (S\$)	3,666.78	2,667.62	999.16	27.25

INSPECTION

Date of Assignment:	06/09/2018	
Date Inspected:	11/09/2018 Inspected At:	Charm's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105 Singapore 159724

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Dec 2018)
 Parts: 143 MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLP5765S)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR EMBLEM LANCER	Necessary	52.00 FN	*52.00 FN	
2	1		*REAR EMBLEM EX	Necessary	45.00 FN	*45.00 FN	
3	1		*REAR BOOT C&C EMBLEM	Necessary	45.00 FN	*45.00 FN	
4	1		*REAR BOOT LOGO	Necessary	49.00 FN	*49.00 FN	
5	1		*REAR BOOT RUBBER	Not Necessary	176.00 FN	*- FN	
6	1		*REAR BUMPER	Deformed	815.00 FN	*815.00 FN	
7	1		*REAR BUMPER TOW COVER	Missing	27.00 FN	*27.00 FN	
8	1		*REAR BUMPER REFLECTOR RH	Cracked	27.00 FN	*27.00 FN	
9	1		*REAR BUMPER REINFORCEMENT	Bent	210.00 FN	*210.00 FN	
10	4		*REAR BUMPER CLIPS	Necessary	20.00 FN	*20.00 FN	
11	1		*REAR BUMPER RETAINER RH	Necessary	19.00 FN	*19.00 FN	
12	1		*REAR END PANEL	Repair	506.00 FN	*- FN	
13	1		*REAR NO PLATE	Bent	35.00 FS	*35.00 FS	
14	1		*SET REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS	
					Sub Total (\$\$)	2,226.00	1,544.00
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	199.10	130.90
					Total Parts (\$\$)	2,026.90	1,413.10

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE NECESSARY PARTS;JACKING,PANEL BEATING,REPAIR AND STRAIGHTEN REAR INNER PANEL,REAR END PANEL,REAR BOOT,REAR FENDER LH,REAR BUMPER,TYRE COMPARTMENT AND AFFECTED AREAS	New	600.00	480.00
2	PUTTY AND RESPRAY REAR INNER PANEL,REAR END PANEL,REAR BOOT,REAR FENDER LH,REAR BUMPER,REAR TYRE COMPARTMENT AND AFFECTED AREA	New	800.00	600.00
Gross Labour Cost (\$\$)			1,400.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >