

ASS. REC. BY:

REF:

CS/GAI18016298/Tlqdzbr

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAI

Date/Time:

6/9/18 @ 2pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 5932X

Insured:

at Workshop m/s

Leong Seng Motor

Tel:

62737469

of

Blk 1006, Bkt Merah Lane 2 # 01-08

Policy No:

Claim No:

CLMOMVM000000 368

Sum Insured:

Excess:

TBA

Make of Veh:

(Client's Record)

D.O.A.

26/08/2018

CA / (REV) /

REP. / REV 24 HRS

Date/Time:

2:30pm

Person Contacted:

Mr. Teo

H.O.D. Endorsement:

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	FBK 5932X - NBA/GAI18016252/Y	DOA: 26/08/2018
07/9/18 @ 1:30pm	revert to Rachel Tan by email.	
11/9/18 @	Mr Teo will absorb the towing fee and repair on US	
11/9/18 @ 3:31pm	authorise repair by Rachael Tan excess \$750	
11/9/18 @ 3:40pm	inform Teo authorise repair excess \$750 repair US	
13/10/18 @ 9:27am	confirmed with Mr Teo US \$5750, 5 days by email.	
	CPRA \$7313.70, 31%.	

Tanpin

REP:

GAI

DATE: 15 OCT 2018

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Claims No \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess: to be advise.  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 417K.  
 IDAC Accident Report: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBK 5932X Yr Regt: 215 Nov  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda CB400  
 Colour: white  
 Sp. Reading: \_\_\_\_\_ A/C: Insured / Std / NI / NA  
 T/Radio: Insured / Std / NI / NA  
 Eng/No: JH 2NC 47975K 000332  
 C/No: \_\_\_\_\_  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: N/D / S/Rim / STD A/Rim or  
 Tyre Size: F: 120 / 70 R17  
 R: 160 / 60 R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /  
 TOYO / YOKO or  
 Front: 5 mm Rear: 5 mm  
 R/Bal. mm L/Bal. mm  
 D.O.A. D.O.I. 6/9/18 @ 1700  
 Survey held at Leong Seng Motor  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

15/10 Tanpin

Date/Time, File Return to?

1

Report Format:

Lump Sum / L.P. / O/S

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)  
☐ Interpret (\$)  
☐ Tech Insp (\$)  
☐ Mapland (\$)

Survey Fee  
 Transportation

250

-20

230



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18016298/T1qd3

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Date : 06-09-2018



Code : GAI

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	FBK 5932X
Policy No.	Coverage (\$)	0.00
Claim No. CLMOMVM000000368	Excess (\$)	0.00
Assign From RACHEL TAN	Assign Date	06/09/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	26/08/2018	Inspection Date	06/09/2018
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## Nivitha (LKK Auto)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Thursday, 6 September 2018 2:00 PM  
**To:** leongsen@singnet.com.sg  
**Cc:** LKK Assignments  
**Subject:** FW: CLMOMVM000000368] FBK5932X O/D claim - request for survey  
**Attachments:** FBK5932X\_26082018.PDF; IMG\_20180906\_0002.pdf

Dear Mr Teo

Noted on your OD survey request, we will arrange for LKK to conduct OD survey.

Dear LKK

Please assist. Attached estimates and GIA report at NAC.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

---

**From:** leongseng <leongsen@singnet.com.sg>  
**Sent:** Thursday, September 06, 2018 11:20 AM  
**To:** General Claims <GeneralClaims@sg.gaig.com>  
**Subject:** [External] FBK5932 O/D claim - request for survey

Dear Sir/Mdm

Pls be informed that FBK5932 owner ( Certis Cisco ) had appointed us to do an O/D claim for them.

Pls find enclosed accident report and our repair estimate.

Kindly arrange your appointed surveyor to conduct damage survey at our workshop.

Pls be informed that we are located at Blk 1006, Bukit Merah Lane 2, #01-08 S(159762) Tel : 62737469.

Thanks

c s teo  
Leong Seng Motor PL  
62737469

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

## Shiau Chan (LKKAuto)

---

**From:** leongseng <leongsen@singnet.com.sg>  
**Sent:** Saturday, 13 October 2018 9:27 AM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** Re: FBK5932X marked estimate

Dear Mdm

Thanks for your update, will submit our final bill based on your recommendation.

Regards

c s teo

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, October 12, 2018 2:29 PM  
**To:** leongseng ; SUR  
**Subject:** RE: FBK5932X marked estimate

Dear Teo,

WITHOUT PREJUDICE

Offer Lump Sum \$5,250.00 before excess \$750.00 and 5 repair days.

Kindly confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** leongseng <leongsen@singnet.com.sg>  
**Sent:** Wednesday, 3 October 2018 1:27 PM  
**To:** SUR <sur@lkkauto.com>  
**Subject:** Fw: FBK5932X marked estimate

Dear Sir/Mdm

Pls refer to our email on 13/9/18,

Kindly help to check and let us have your recommended COR.

Thanks

c s teo

**From:** leongseng  
**Sent:** Thursday, September 13, 2018 3:18 PM

## Denise Tay (LKKAUTO)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Tuesday, 11 September 2018 3:31 PM  
**To:** Denise Tay (LKKAUTO); Shiau Chan (LKKAUTO); assignments  
**Cc:** SUR  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Dense

Thank you.

Please proceed on Lump Sum basis if damage is consistent, excess \$750/-

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

---

**From:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>  
**Sent:** Tuesday, September 11, 2018 2:39 PM  
**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** [External] RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Rachel,

I've check with repairer, towing fee will be absorbed by the workshop.

Repair will be done on lump sum

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Monday, 10 September 2018 5:35 PM  
**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Rachel,

Due to Shiau chan absence, I will check and let you know.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 11 September 2018 2:39 PM  
**To:** Tan, Rachel; Shiau Chan (LKKAuto); assignments  
**Cc:** SUR  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Rachel,

I've check with repairer, towing fee will be absorbed by the workshop.

Repair will be done on lump sum

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 10 September 2018 5:35 PM  
**To:** Tan, Rachel <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>; Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Rachel,

Due to Shiau chan absence, I will check and let you know.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>  
**Sent:** Monday, 10 September 2018 5:25 PM  
**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Shiau Chan

Towing should be absorbed by the workshop for OD repairs.

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Monday, 10 September 2018 5:35 PM  
**To:** Tan, Rachel; Shiao Chan (LKKAUTO); assignments  
**Cc:** SUR  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Rachel,

Due to Shiao Chan absence, I will check and let you know.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>  
**Sent:** Monday, 10 September 2018 5:25 PM  
**To:** Shiao Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Shiao Chan

Towing should be absorbed by the workshop for OD repairs.  
Can the workshop do a Lump Sum repair instead? Thank you.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

---

**From:** Shiao Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Friday, September 7, 2018 1:39 PM  
**To:** Tan, Rachel <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** [External] RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Rachel,

Enclosed herewith preliminary advice of FBK 5932X.  
We have not authorise repair.

Kindly advise on authorisation and excess.

Best Regards,

**Shiao Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**



## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 7 September 2018 1:39 PM  
**To:** 'Tan, Rachel'; assignments  
**Cc:** SUR  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey  
**Attachments:** CSGAI18016298T1qd3.pdf, FBK5932 EST.pdf

Dear Rachel,

Enclosed herewith preliminary advice of FBK 5932X.  
We have not authorise repair.

Kindly advise on authorisation and excess.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, 6 September 2018 2:39 PM  
**To:** 'Tan, Rachel' <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]  
**Sent:** Thursday, 6 September 2018 2:00 PM  
**To:** [leongsen@singnet.com.sg](mailto:leongsen@singnet.com.sg)  
**Cc:** LKK Assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** FW: CLMOMVM000000368] FBK5932X O/D claim - request for survey

Dear Mr Teo

Noted on your OD survey request, we will arrange for LKK to conduct OD survey.

Dear LKK

Please assist. Attached estimates and GIA report at NAC.

Regards  
Rachel Tan



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Policy No. : CLMOMVM000000368

Date: 07<sup>th</sup> September 2018

Our Ref: CS/GAI18016298/T1qd3

The Motor Claims Department  
Great American Insurance Company

Attn: Rachel

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. FBK 5932X .**


We thank you for the instruction on 06/09/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/09/2018 the premises of M/s LEONG SENG MOTOR. and have the following to report:-

Workshop Estimate Amount	: S\$	<u>7,563.70</u>	.
Revised Estimate Amount	: S\$	<u>4,623.20</u>	.
"Check" Items Amount	: S\$	<u>2,305.00</u>	.
Market Value	: S\$	<u>17,000.00</u>	.
Salvage Value	: S\$	<u>4,408.00</u>	.
Nett Value	: S\$	<u>12,592.00</u>	.

Description of Damage:

The vehicle sustained damages at the front portion & o/s body.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Recommend days of repair: 5 days.

We have NOT authorise repair.

Yours faithfully

Taufikh  
Automotive Assessor

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0882K
Vehicle Details	
Vehicle No.:	FBK5932X
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400X
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	NC47E5000303
Chassis No.:	JH2NC4797EK000332
Maximum Power Output:	-
Open Market Value:	\$6,659.00
Original Registration Date:	05 Nov 2015
First Registration Date:	05 Nov 2015
Transfer Count:	1
Actual ARF Paid:	\$999.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Nov 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,158.00
COE Rebate Amount:	\$4,408.00
<b>Total Rebate Amount:</b>	<b>\$4,408.00</b>

The information contained herein is correct as at 07 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/09/2018 19:31
Date Of Accident	26/08/2018 06:30
Exact Location Of Accident	ALONG MARINA EAST DRIVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK5932X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Co Reg No	200900882K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86614647
Alternative Phone No	OFFICE-86614647

### Vehicle Particulars

Manufacturer	HONDA
Model	CB400X-399CC
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	MOTORCYCLE
------------------	------------

### Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	MT20171758

### Driver

Name of Driver	MUHAMAD SHAMEER BIN ABDULLAH
NRIC No	S9215643E
Date Of Birth	02/05/1992
Occupation	OUTDOOR
Date Of Driving Pass	13/03/2013
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86614647
Fax Number	
Contact Number	OTHERS-86614647
EMail Address	NOEMAIL



# SINGAPORE POLICE FORCE



J/20180904/2018

1 of 2

## POLICE REPORT (NP299)

Report No. J/20180904/2018

Police Station Of Origin  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Date/Time Report Made 04/09/2018 03:01	Vide Report No.	Station Diary No. 14		
Name Of Informant MUHAMAD SHAMEER BIN ABDULLAH	Address APT BLK 63 YUNG KUANG ROAD #06-73 SINGAPORE 610063			
ID Type / ID No. NRIC NO / S9215643E	Contact No. Home/Office	Mobile 86614647		
Nationality SINGAPORE CITIZEN	Email Address			
Occupation CISCO OFFICER	Sex Male	Age 26	Date of Birth 02/05/1992	Race Malay
Institution/School Name	Language			
Date/Time Of Incident 26/08/2018 06:30	Location Of Incident along Marina East Drive			

### Brief details.

On 26.08.2018 at about 0630hrs, I was deployed and performing roving duties at an AD-HOC event located at Marina East Drive. I was engaged to ride vehicle; FBK5932X to perform my duties. During the event, I met with an accident when I self-skidded at the said location. When the incident occurred, I was slowing down my vehicle when approaching a hump. However the lighting was dark and upon going over the hump, the said hump was sandy thus my vehicle skidded and I fell to my right.

I sustained abrasions on my right forearm and my vehicle sustained minimal damages and I was able to

Signature Of Officer Recording The Report:

J / Staff Sgt MOHAMMED AMIRULHAFIZ BIN RAMLAN

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:  
J / Jurong Police Divisional Investigation Branch /  
Sgt 2 PATRICIA TAN SHILING  
Contact No.: 67910000

Signature Of Informant:

Date/Time:  
04/09/2018 03:01

Classification Of Case:

Authentication Stamp

SN 126



Signature :

Singapore Police Force

# Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBK5932X

Model : CB400X

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Front fender <i>cna</i>		\$ 225.00		
2	Front wheel rim <i>? bt ✓</i>		\$ 870.00		
3	Front wheel bearing <i>? wac ✓</i>		\$ 50.00		
4	Front wheel axle <i>? bt ✓</i>		\$ 95.00		
5	Front fork assy <i>? bt ✓</i>		\$ 950.00		
6	Fork under bracket <i>? bt ✓</i>		\$ 285.00		
7	Front nose <i>cna</i>		\$ 185.00		
8	Top cowling <i>de</i>		\$ 385.00		
9	Wind shield <i>cna</i>		\$ 268.00		
10	Front side cowling <i>de</i>		\$ 365.00		
11	Handle bar <i>bt</i>		\$ 235.00		
12	Handle balancer <i>cut</i>		\$ 45.00		
13	Brake lever <i>cut</i>		\$ 50.00		
14	Mirror <i>RY</i>		\$ 95.00		
15	Front footrest <i>cut</i>		\$ 85.00		
16	Brake pedal <i>dd</i>		\$ 150.00		
17	Rear footrest bracket <i>bw</i>		\$ 275.00		
18	Exhaust protector <i>dd</i>		\$ 220.00		
19	Exhaust muffler <i>dd</i>		\$ 760.00		
20	Front no plate <i>bl</i>			\$ 15.00	
21	Front blinker lamp <i>cna</i>			\$ 155.00	
22	Front top crash bar <i>bl</i>		250	\$ 350.00	
23	Rear crash bar <i>bl</i>		200	\$ 280.00	
24	Side box <i>cna</i>			\$ 250.00	
25	Side box reflective sticker <i>at</i>		100	\$ 200.00	
26	Co logo sticker <i>ur</i>		150	\$ 180.00	
27	Respray		250	\$ 350.00	
28	Towing 2 way		80Xm	\$ 120.00	Xnn
29	Repair alignment <i>pluto</i>		150Xm	\$ 280.00	
30	Labour		250	\$ 350.00	
31	<p><i>Tan Jiah 97495744</i></p> <p><i>Not Authorise</i></p> <p><i>Ex: to be advise</i></p> <p><i>5 days</i></p> <p><i>Lumpsum</i></p> <p><i>Respray after repair</i></p> <p><i>Surp / handover</i></p> <p><i>7/11/18</i></p>				
32					
33					
34					
35					
36					
37					
38					
39					

\$ 5,593.00 \$ 2,530.00

Less 10%

\$ 559.30

\$ 5,033.70

756370

# Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBK5932X

Model : CB400X

S/No	Parts Description	QTY	List Price	Nett Price	Remark
1	Front fender <i>cut</i>		\$ 225.00		
2	Front wheel rim <i>hl</i>		\$ 870.00		
3	Front wheel bearing <i>hl</i>		\$ 50.00		
4	Front wheel axle <i>hl</i>		\$ 95.00		
5	Front fork assy <i>hl</i>		\$ 950.00		
6	Fork under bracket <i>hl</i>		\$ 285.00		
7	Front nose <i>cut</i>		\$ 185.00		
8	Top cowling <i>de</i>		\$ 385.00		
9	Wind shield <i>cut</i>		\$ 268.00		
10	Front side cowling <i>de</i>		\$ 365.00		
11	Handle bar <i>hl</i>		\$ 235.00		
12	Handle balancer <i>cut</i>		\$ 45.00		
13	Brake lever <i>cut</i>		\$ 50.00		
14	Mirror <i>ky</i>		\$ 95.00		
15	Front footrest <i>cut</i>		\$ 85.00		
16	Brake pedal <i>dd</i>		\$ 150.00		
17	Rear footrest bracket <i>hl</i>		\$ 275.00		
18	Exhaust protector <i>dd</i>		\$ 220.00		
19	Exhaust muffler <i>dd</i>		\$ 760.00		
20	Front no plate <i>hl</i>			\$ 15.00	
21	Front blinker lamp <i>cut</i>			\$ 155.00	
22	Front top crash bar <i>hl</i>		250	\$ 350.00	
23	Rear crash bar <i>hl</i>		200	\$ 280.00	
24	Side box <i>cut</i>			\$ 250.00	
25	Side box reflective sticker <i>cut</i>		100	\$ 200.00	
26	Co logo sticker <i>cut</i>		150	\$ 180.00	
27	Respray		250	\$ 350.00	
28	Towing 2 way		80	\$ 120.00	
29	Repair alignment	<i>plnt.</i>	150?	\$ 280.00	
30	Labour		250	\$ 350.00	
31	<i>Tougher 9749544</i> <i>Not Authorise</i> <i>Ex: to be advise.</i> <i>5 days</i> <i>Lumpsum</i> <i>Repairing after repair.</i> <i>Surp / handover.</i>				
32					
33					
34					
35					
36					
37					
38					
39					

\$ 5,593.00 \$ 2,530.00

Less 10%

\$ 559.30

\$ 5,033.70

*Resum*  
*13/9/18*






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18016298/T1qd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 16-10-2018		
		Code : GAI		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected	FBK 5932X	
Policy No.	MT20171758	Coverage (\$)	0.00	
Claim No.	CLMOMVM000000368	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	06/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CB400	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JH2NC4797EK000332	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	PIRELLI	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	PIRELLI	5 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/08/2018	Inspection Date	06/09/2018	
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.			
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$17,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 5932X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER	CRACKED	225.00	225.00
1	FRONT WHEEL RIM	BENT	870.00	870.00
1	FRONT WHEEL BEARING	NECESSARY	50.00	50.00
1	FRONT WHEEL AXLE	BENT	95.00	95.00
1	FRONT FORK ASSY	BENT	950.00	950.00
1	FORK UNDER BRACKET	BENT	285.00	285.00
1	FRONT NOSE	CRACKED	185.00	185.00
1	TOP COWLING	DEFORMED	385.00	385.00
1	WIND SHIELD	CRACKED	268.00	268.00
1	FRONT SIDE COWLING	DEFORMED	365.00	365.00
1	HANDLE BAR	BENT	235.00	235.00
1	HANDLE BALANCER	CUT	45.00	45.00
1	BRAKE LEVER	CUT	50.00	50.00
1	MIRROR	TO REPAIR SEE LABOUR	95.00	-
1	FRONT FOOTREST	CUT	85.00	85.00
1	BRAKE PEDAL	DENTED	150.00	150.00
1	REAR FOOTREST BRACKET	BROKEN	275.00	275.00
1	EXHAUST PROTECTOR	DENTED	220.00	220.00
1	EXHAUST MUFFLER	DENTED	760.00	760.00
	LESS 10% DISCOUNT		-559.30	-549.80
			5,033.70	4,948.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NO PLATE (SN)	BENT	15.00	15.00
1	FRONT BLINKER LAMP (SN)	CRACKED	155.00	155.00
1	FRONT TOP CRASH BAR (SN)	BENT	350.00	250.00
1	REAR CRASH BAR (SN)	BENT	280.00	200.00
1	SIDE BOX (SN)	CRACKED	250.00	250.00
1	SIDE BOX REFLECTIVE STICKER (SN)	CUT	200.00	100.00

Report Ref No. CS/GAI18016298/T1qd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CO LOGO STICKER (SN)	NECESSARY	180.00	150.00
			1,430.00	1,120.00
	<b>LABOUR</b>			
	RESPRAY.		350.00	250.00
	TOWING 2 WAY.	NOT NECESSARY	120.00	-
	REPAIR ALIGNMENT.	NOT NECESSARY	280.00	-
	LABOUR. INCLUSIVE OF THE REPAIR OF MIRROR.		350.00	250.00
			1,100.00	500.00
<b>GRAND TOTAL</b>			<b>7,563.70</b>	<b>6,568.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,250.00</b>

Report Ref No. CS/GAI18016298/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.