

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Saturday, 2 November 2019 1:54 PM  
**To:** eqjprs@eqinsurance.com.sg  
**Cc:** Admin A  
**Subject:** <SEEL MANDATE> EQ ref : DM18HO02187 \*LKK ref : CC4/EQ18016308/R1pa3s2 [ACCIDENT INVOLVING SLJ4408L(EQ-OI) EP2468C(TP)/ OTHERS ON 21/08/2018]  
**Attachments:** LKK Survey Report & Photos.pdf; TP LOD & Docs.pdf

EQ ref : **DM18HO02187**  
LKK ref : CC4/EQ18016308/R1pa3s2

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SLJ4408L(EQ-OI) EP2468C(TP)/ OTHERS ON 21/08/2018**

We refer to the above matter.

The said chain collision involved 4 vehicles whereby our insured was the 3rd vehicle.  
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We seek your approval to offer Third Party repairer "**TAN CHONG MOTOR SALES PTE LTD**" at **\$12,103.20(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 13,741.50	\$ 11,239.75
2. Loss of Rental (8days x \$110.00)(w/GST)	\$ 941.60	\$ 856.00 (8days x \$100.00)(w/GST)
3. LTA/GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 14,690.55	<b><u>\$ 12,103.20</u></b>

Surveyor recommended 8 days for repair.

Enclosed here with all the relevant documents for your perusal.

**Kindly let us have your approval/instruction.**

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)