

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

06 SEP 2018

ESTIMATE

Estimate No. : b1 48342
Date Estimated : 06/09/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Antonio Del Pilar Cailao
28 Duchess Road
#02-11, The Tresor

Singapore 269030

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFS5968D	EE63363	29/01/2018	X1 sDrive18i	0

DESCRIPTION

To replace frt & rear right door assembly & all attachment
cause by accident.

VALUE

1700 3,400.00

Painting on frt & rear right door assembly

1764 2,076.00

To check electrical wiring systems for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel) Front Door

100 118.00

To carry out body cavity preservation.
(Per panel) Rear Door

100 118.00

Sundries.

? 150.00

Total Labour 1: **6,039.00**

DESCRIPTION

QTY PRIC

VALUE

FRT RH DOOR	1	1,168.60	bt 1,168.60
RR RH DOOR	1	1,168.60	bt 1,168.60
RH UPPER FRONT DOOR HINGE	1	54.65	R 54.65
RH LOWER FRT DOOR HINGE	1	54.65	R 54.65
RH LOWER REAR DOOR HINGE	1	57.15	? 57.15
RH UPPER REAR DOOR HINGE	1	57.15	? 57.15
FRT RH MOULDING ROCKER PANEL	1	74.60	? 74.60
REAR RH MOULDING ROCKER PANEL	1	60.25	? 60.25
Channel seal right	1	66.10	? 66.10
FRT RH DOOR COLUMN B COVER	1	74.05	ne 74.05
FRT RH DOOR EXTERIOR CHANNEL COVER	1	126.30	? 126.30
FRT RH DOOR WINDOW FRAME COVER (ALU)	1	74.90	? 74.90
REAR RH DOOR COLUMN B COVER	1	38.00	ne 38.00
REAR RH DOOR JOINT SEAL	1	34.75	? 34.75
RR RH DOOR WINDOW FRAME COVER (ALU)	1	59.75	? 59.75
RR RH DOOR OUTER CHANNEL COVER (ALU)	1	126.30	? 126.30
FRT DOOR EGDE PROTECTION	1	173.30	? 173.30
REAR DOOR EDGE PROTECTION	1	173.30	? 173.30



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 48342**
Date Estimated : **06/09/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFS5968D	EE63363	29/01/2018	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
FRT RH DOOR JOINT SEAL	1	59.00	59.00
REAR DOOR SEALING TAPE ENTRANCE	1	34.75	34.75
FRT RH DOOR JOINT SEALING ENTRANCE	1	34.75	34.75
Total Parts :			3,770.90

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 24/9/18 Excess \$ _____

Surveyor's Name Tan Jui Sign [Signature]

Surveyor's Tel 97445164 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PART PML BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail tanjui@lkkauto.com

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,039.00
Parts	:	3,770.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	686.69
Grand Total	:	10,496.59

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **