



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 05/09/2018

Attn: The Motor Claims Department

Your Insured veh no : SGH 384 S

AXA Insurance S'pore Pte Ltd

8 Shenton way

27-01 AXA Tower

Singapore 068811

Tel : 6880 4711 claim dep

Fax : 6880 4838 claim dep

Dear Sir / Madam

Estimate Cost repair Bill To Mit Canter NO YP 4256 Y & SGH 384 S on 04/08/2018

To Supply :-

2pcs	Rear aluminium door	Dented	\$1,450.00
1pc	Rear cross member	Cracked	
1pc	Rear number plate	But	
1pc	Rear number plate lamp	New	

list: 350 SN: 2875
 less 25%: 262.50
 \$2,900.00 2400 (SN)
 \$ 350.00 ✓
 \$ 40.00 25 (SN)
 \$ 89.00 *
 \$3,379.00
 \$ 675.80
 \$2,703.20

Advertisement Stickers.
 1pc 60km/h New

450 less
 550 ✓

20%
 25%

\$ 15.00 s/nett ✓ SN: 15

To dismantle & replace damage parts, panel beat where necessary.

\$1,200.00 600.

To putty, apply primer & body paint work on the affected portion.

\$ 550.00 x. 600

To check wiring functions.

\$ 80.00 x.
 \$4,548.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
 L/s 22/10/18
 04 days

total: 3752.50
 1/5: 3K.

3K