

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josey Loh

Date: 10 Sep 2018

## **Preliminary Advice**

Insured Vehicle No	: SLM4453P	Accident Date	: 05/09/2018
TP Vehicle No	: SGG466U	Assignment Date	: 07/09/2018
Make	: VOLKSWAGEN JETTA	Est. Duration of Repair	: 5 days
Date of Inspection	: 07/09/2018		
Inspection At	: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48 Autobay Singapore 417883		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,178.27
Revised Amount	:S\$	6,641.17
Check Items (Estimated)	:S\$	1,912.50
Total	:S\$	8,553.67

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.