



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

NO. : 32975

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120

DATE : 06/09/2018  
CLAIM NO. : 11184  
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FQ1933R  
MAKE/MODEL : BMW /

(Page 1 of 2)

| S/N | Description                                                               | Action         | Qty  | Unit Price | Amount   |
|-----|---------------------------------------------------------------------------|----------------|------|------------|----------|
| 1   | BOX REAR(HEPCO&BECKER) GOBI TC42 SILVER                                   | REPLACE        | 1.00 | \$546.00   | 546.00   |
| 2   | BRACKET FAIRING                                                           | REPLACE        | 1.00 | \$508.00   | 508.00 ? |
| 3   | COVER CYLINDER HEAD                                                       | REPLACE        | 1.00 | \$441.00   | 441.00 X |
| 4   | EMBLEM                                                                    | REPLACE        | 2.00 | \$45.00    | 90.00 ?  |
| 5   | FOOTREST FRONT(PIVOT PEGZ) SET                                            | REPLACE        | 1.00 | \$360.00   | 360.00 X |
| 6   | GASKET CYLINDER HEAD<br>P/N: 42940                                        | REPLACE        | 2.00 | \$85.00    | 170.00 X |
| 7   | GASKET INNER CYLINDER HEAD                                                | REPLACE        | 2.00 | \$19.00    | 38.00 X  |
| 8   | GUARD HANDLE RH                                                           | REPLACE        | 1.00 | \$126.00   | 126.00   |
| 9   | HANDLE GUARD (BARBUSTERS) SET                                             | REPLACE        | 1.00 | \$336.00   | 336.00   |
| 10  | LABOUR<br>P/N: 06766<br>- FOR DISMANTLING AND ASSEMBLING PARTS<br>QUOTED. | Supply/Install | 1.00 | \$385.00   | 385.00   |
| 11  | PEDAL BRAKE                                                               | REPLACE        | 1.00 | \$328.00   | 328.00 X |
| 12  | POWDER COAT BRACKET (MISC)<br>P/N: 48368                                  | REPLACE        | 1.00 | \$95.00    | 95.00    |
| 13  | RUBBER MOUNT<br>P/N: 42941                                                | REPLACE        | 4.00 | \$12.00    | 48.00 ?  |



| S/N         | Description                                                                                     | Action  | Qty  | Unit Price | Amount               |
|-------------|-------------------------------------------------------------------------------------------------|---------|------|------------|----------------------|
| 14          | STICKER FUEL TANK                                                                               | REPLACE | 2.00 | \$120.00   | 240.00 <i>rec</i> ✓  |
| 15          | STICKER NUMBER PLATE FRONT (BLACK)<br>STRAIGHT<br>P/N: 32921                                    | REPLACE | 1.00 | \$12.00    | 12.00 <i>scrnk</i> ✓ |
| 16          | TRANSPORT CHARGES (MOTORCYCLE)<br>OVERSIZED<br>P/N: 45837<br>- FOR COLLECTION OF ACCIDENT BIKE. |         | 1.00 | \$70.00    | 70.00 <i>45</i>      |
| SUB TOTAL   |                                                                                                 |         |      |            | \$3,793.00           |
| GST @ 7 %   |                                                                                                 |         |      |            | \$265.51             |
| GRAND TOTAL |                                                                                                 |         |      |            | <b>\$4,058.51</b>    |

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

