

SERVICE ESTIMATE

4155 - C00001 SL: SERVICE SALES - PC

Mr Chng Chng Ah Seng Patrick
4A Jalan Rimau

Singapore 418736

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Chng Ah Seng Patr

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 07/09/2018

WIP No. . : 26096

Veh.In/Out:

*Tel.No. . : Mobile: 91466662

Reg.No. . : SLE497G

Reg.date . : 28/08/2012

Mileage . : 0

Chassis No: SAJAC37G9CMY38520

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT LH WING MIRROR,	0	3600.00	0		3,600.00	S
	REPAIR FRT LH DOOR, REAR LH DOOR, ETC						
800	TO PUTTY SPRAYPAINT ON	0	3300.00	0		3,300.00	S
	LH WING MIRROR COVER,						
	FRT LH DOOR, REAR LH DOOR						
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	JC2D18458/DOOR MIRRO	1.0 EA	1071.50			1,071.50	S
	MIRROR COVER LH XF R	1.0 EA	166.90			166.90	S
	MIRROR GLASS LH XJL	1.0 EA	633.70			633.70	S
	MIRROR MOTOR LH XJ	1.0 EA	252.50			252.50	S
	MIRROR FINISHER COVE	1.0 EA	175.90			175.90	S
	DOOR MIRROR LAMP LH	1.0 EA	86.10			86.10	S
	DOOR MIRROR LAMP LH	1.0 EA	40.30			40.30	S

Gross Total. 9,812.90

Labour Total 7,386.00
Parts Total 2,426.90
Package Total 0.00

Net..... 9,812.90
GST @ 7.0% 686.90
Total..... 10,499.80
Paid..... 0.00
Please Pay.. 10,499.80

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated