

## PDI TUAS

PDI TUAS

MAHIDI  
89 BUKIT DRIVE  
#01-22 THE RAINTREE  
Singapore, 587846  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV036945  
Quote No. SER/QUO/1801487  
QuoteDate 10/09/18  
Salesperson  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make               | Model Description              | Mileage              | Service Advisor |
|--------------------|--------------------------------|----------------------|-----------------|
| Volkswagen Passeng | JETTA 1.4 TSI 7 SPEED DSG 90KW | 84,052               | Cheong Pearlyn  |
| License No.        | VIN                            | Initial Registration | Sales Advisor   |
| SJW3515Y           | WVWZZZ1KZAM075517              | 18/03/10             |                 |
| Engine Code        | Labor Type                     | Engine No.           | Model Code      |
|                    | M2                             | CAX 408475           | 1K23G5          |

| No.                | Description                                            | Qty. | UoM     | Unit Price | Amount           |
|--------------------|--------------------------------------------------------|------|---------|------------|------------------|
| P B&P ALEX LABOUR  | LABOUR                                                 | 4    | UNIT    |            | 1680 3,360.00    |
| P B&P ALEX PAINT   | SPRAY PAINT                                            | 4    | UNIT    |            | 1600 3,200.00    |
| P B&P NUMBER PLATE | B&P NUMBER PLATE -NETT                                 | 1    | pcs     |            | 80.00            |
| P B&P DIAG         | PROGRAMMING & CALIBRATION<br>COMPULSORY TO DO AFTER AC | 1    | Time Un |            | 480.00           |
| P B&P MECH         | CHECK WIRE HARNESS, ECU, S<br>Nett                     | 1    | Time Un |            | 280.00           |
|                    | <b>Sum Labor</b>                                       |      |         |            | <b>7,400.00</b>  |
| P 1K5807251A       | FOAM                                                   | 1    | Pieces  |            | 74.91            |
| P 1K5807305A       | REAR CROSS MEMBER                                      | 1    | Pieces  |            | 492.62           |
| P 1K5807393        | REAR BUMPER BRACKET LH                                 | 1    | Pieces  |            | 48.93            |
| P 1K5807394        | REAR BUMPER BRACKET RH                                 | 1    | Pieces  |            | 48.93            |
| P 1K5807417H GRU   | REAR BUMPER<br>Use Predecessor 1K5807417E GR           | 1    | Pieces  |            | 1,022.36         |
| P 1K5807521A 9B9   | REAR LOWER SPOILER                                     | 1    | Pieces  |            | 451.44           |
| P 1K5807863B       | REAR CENTER GUIDE<br>Use Predecessor 1K5807863A        | 1    | Pieces  |            | 71.43            |
| P 1K5827025AN      | REAR BOOT LID                                          | 1    | Pieces  |            | 1,197.50         |
| P 1K5853630 ULM    | REAR VW EMBLEM                                         | 1    | Pieces  |            | 72.45            |
| P 1K5853687 739    | JETTA EMBLEM                                           | 1    | Pieces  |            | 53.07            |
|                    | <b>Sum carried forward</b>                             |      |         |            | <b>10,933.64</b> |

## PDI TUAS

PDI TUAS

MAHIDI  
89 BUKIT DRIVE  
#01-22 THE RAINTREE  
Singapore, 587846  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV036945  
Quote No. SER/QUO/1801487  
QuoteDate 10/09/18  
Salesperson  
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make               | Model Description              | Mileage              | Service Advisor |
|--------------------|--------------------------------|----------------------|-----------------|
| Volkswagen Passeng | JETTA 1.4 TSI 7 SPEED DSG 90KW | 84,052               | Cheong Pearlyn  |
| License No.        | VIN                            | Initial Registration | Sales Advisor   |
| SJW3515Y           | WVWZZZ1KZAM075517              | 18/03/10             |                 |
| Engine Code        | Labor Type                     | Engine No.           | Model Code      |
|                    | M2                             | CAX 408475           | 1K23G5          |

Continued 10,933.64

Sum Item

3,533.64

Sum Labor 7,400.00  
Sum Item 3,533.64

Total SGD 10,933.64  
7% GST 10,933.64 765.35  
Total SGD Incl. GST 11,698.99

## Explanations

P = Proportionately Charged

## Payment Terms

No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Passu*  
*HP 90010068*  
*5 days*  
*14/09/18 @ 1220*

Payments to:

- BBN: - Acc.-No.: