

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000336

Date : 10/09/2018

Vehicle Num. : SLH 1891D (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 07/09/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID	1,350.00	X R
2.	1	REAR WINDSCREEN GLASS MOULDING	250.00	X R
3.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE)	89.00	X R
4.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE)	89.00	X R
5.	1	REAR BOOT REFLECTOR LAMP RH	580.00	X R
6.	1	REAR BUMPER	1,150.00	X R
7.	1	REAR BUMPER RETAINER RH	89.00	X R
8.	1	REAR BUMPER TOW COVER	100.00	X R
9.	1	REAR END PANEL	950.00	X R
10.	1	REAR END PANEL TOP GARNISH	260.00	X R
11.	1	REAR BUMPER INNER FOAM - RH	180.00	X R
12.	1	REAR BUMPER REFLECTOR GARNISH RH	170.00	X R
13.	1	REAR BUMPER REFLECTOR LENS RH	180.00	X R
14.	1	REAR TAIL LAMP - RH	850.00	X R

List Total S\$:

6,287.00

20.00% Discount S\$:

1,257.40

5,029.60

SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT	100.00	X R
2.	1	REAR BUMPER CLIP	40.00	X R
3.	1	REVERSE SENSOR	280.00	X R
4.	1	REAR END PANEL TOP GARNISH CLIPS	40.00	X R
5.	1	REAR TAIL LAMP CLIPS	40.00	X R

Special Nett Total S\$:

500.00

LABOUR :

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

180.00 X R

CONTINUE / ...

WORLD AUTO PTE LTD

47-Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000336

Date : 10/09/2018
 Vehicle Num. : SLH 1891D (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 07/09/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

.		REMOVE & REFIT REAR WINDSCREEN GLASS		180.00 <i>x 11</i>
.		TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00 <i>x 50</i>
.		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING CUT/WELD, PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS		1,000.00 <i>600</i>
.		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER&OUTER)		900.00 <i>600</i>
.		TO CHECK WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS		180.00 <i>30</i>
.		TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.		380.00 <i>200</i>
.		TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.		380.00 <i>200</i>
		Labour Total S\$:		3,380.00

E. & O.E.

Total S\$: 8,909.60

for WORLD AUTO PTE LTD

NAZ LKK
 10/9/18 1615
 P/P
 5 Days

BEFORE PAINT PHOTO.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: