

INS. CASE OWNER:

CC # / III180

LKK:

IDAC:

ASSIGNMENT

Driver:

Date:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner? (YES ☒ NO)

If NO, Driver Name / Age:

Driver Tel No.:

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 8-2-19

Confirm with 4106

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: 651

SS

7,89.23

Loss of Rental (LOR):

SS

600

(6 days) 100

Loss of Use (LOU):

SS

-

(5 x days)

Loss of Income (LOI):

SS

-

(5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

36.45

(29 + 7.45)

Medical

SS

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

-

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

-

3) Survey fee:

Total:

SS

8,325.68

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee I:

SS

8,325.68

Name I:

SME MOTOR PTE LTD

Payee II:

SS

-

Name II:

X

REF:

III

ASSIGNMENT

From:
Estimated Cost:

Date:

11/09/18

Veh No:

SLT612L

Vt Regs:

10/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OO: TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLT612L

at Workshop n/s

SME Motor

of 1 Kaki Bkt Ave 6 #02-15

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value:

ID No. Accident Report

Consistent? : Yes or No

CA / PR Seen

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. 1-24 HRS up

Vehicle: IN / OUT

Date

Person Contacted:

Truck / Trailer or

Make

Honda Vezel Hybrid 1496

Colour

Black

A/C

Insured / Std / NI / NA

Sp. Reading

16838

T/Radio

Insured / Std / NI / NA

Eng/No

C/No

RU31247306

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

7

mm

R/Bal

3

mm

L/Bal

7

mm

L/Bal

3

mm

D.O.A.

6/9/18

D.O.I

11/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

New O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A48311

1B1 \$ 7,184.20

R1 \$ 4,823.28 / 407.)

Date/Time: File Return to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Weekend \$

Survey Fee

Computation:

1) \$ = RS. 14

2) Photos

3) Other

TOTAL

Report Format :

Lump Sum / L.B.L: (\$

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

TP INSURER: India International Insurance Pte Ltd (HQ)

MARK PAUL HENSEL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

\$7186.20

not Advised
Late more
Take photo before
painting
6 days
11/9/18

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	18/III/TP-183 (09)
Policy No:		Date of Loss:	06/09/2018
Vehicle Reg. No.:	SLT612L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	WONG CHUI TEING	Driver (Insured):	WONG CHUI TEING

Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	16/10/2017
Vehicle Colour:	BLACK		
Engine No:	LEB5947323	Chassis No:	RU31247306
Odometer:	0 KM		

Paint Type:
List Item Discount: 20.00 %
Total Loss? NO
Est. Duration of Repair 7 (day)

Description of Accident/Loss ON 06/09/2018 AT 6.30PM, I WAS DRIVING MY CAR (SLT612L) TURNING LEFT FROM KALLANG AIRPORT WAY. I STOPPED TO ALLOW ON-COMING VEHICLE GOING STRAIGHT. SUDDENLY, I FELT A HUGE IMPACT ON MY REAR. WHEN I WAS ALIGHTING, A TAXI (VEH B SHA5845X) THAT COLLIDED ONTO MY REAR THEN DROVE FORWARD AND AGAIN COLLIDED ONTO MY RIGHT DOOR. LUCKILY I AVOIDED IT OR VEHICLE B WOULD HAVE COLLIDED ONTO ME PHYSICALLY. AFTER VEHICLE B REVERSE, I WAS THEN ABLE TO ALIGHT AND I REALISED THERE WAS A THIRD CAR (VEHICLE C SLF1588R) INVOLVED. VEHICLE C'S DRIVER TOLD ME THAT VEHICLE B COLLIDED ONTO ME AND REVERSED TO COLLIDE ONTO HIM AND DROVE FORWARD TO COLLIDE ONTO MY RIGHT DOOR AGAIN.

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS	Amount
Parts	7,364.48
Miscellaneous Items	320.00
Labour	4,325.00

(1)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2018)
 Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SME Motor Pte Ltd/SLT612L/10/09/2018 11:54
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR GATE <i>body</i>	20.00	0.00	*955.00 FL ✓
2	4		*REAR WINDSCREEN MOULDING <i>neu</i>	20.00	0.00	*180.00 FL ✓
3	1		*REAR GATE VEZEL EMBLEM <i>neu</i>	20.00	0.00	*49.00 FL ✓
4	1		*REAR GATE HYBRID EMBLEM <i>neu</i>	20.00	0.00	*48.00 FL ✓
5	1		*REAR BUMPER (CENTER) <i>Dis</i>	20.00	0.00	*645.00 FL ✓
6	2		*REAR BUMPER RETAINER <i>0/5 Ref</i>	20.00	0.00	<i>28</i> *56.00 FL <i>1pc</i>
7	10		*REAR BUMPER CLIP <i>neu</i>	20.00	0.00	*55.00 FL ✓
8	1		*REAR RH CORNER <i>neu</i>	20.00	0.00	*149.00 FL ✓
9	1		*REAR RH TAIL LAMP	20.00	0.00	*448.00 FL ?
10	1		*REAR RH FENDER <i>Body/2nd</i>	20.00	0.00	*603.00 FL ✓
11	1		*REAR RH FENDER PROTECTOR <i>To.1</i>	20.00	0.00	*202.00 FL ✓
12	1		*REAR RH FENDER AIR DUCT <i>Yuri</i>	20.00	0.00	*35.00 FL ?
13	1		*REAR RH FENDER INNER COWLING <i>To.1</i>	20.00	0.00	*95.00 FL ✓
14	10		*INNER COWLING CLIP <i>neu</i>	20.00	0.00	*55.00 FL ✓
15	1		*REAR END PANEL	20.00	0.00	*445.00 FL ?
16	1		*REAR BUMPER REFLECTOR RH <i>neu</i>	20.00	0.00	*151.00 FL ✓
17	1		*REAR END PANEL TOP GARNISH <i>AA</i>	20.00	0.00	*69.00 FL X
18	1		*REAR END PANEL TOP GARNISH CLIP <i>AA</i>	20.00	0.00	*31.00 FL X
19	1		*REAR EXHAUST BOX <i>R</i>	20.00	0.00	*558.00 FL X
20	1		*REAR EXHAUST BOX CHROME FINISHER <i>CU7</i>	20.00	0.00	*145.00 FL ✓
21	2		*REAR EXHAUST BOX RUBBER HOLDER <i>AA</i>	20.00	0.00	*70.00 FL X
22	1		*FRT RH DOOR <i>Body/2nd</i>	20.00	0.00	*845.00 FL ✓
23	3		*FRT RH DOOR INNER RUBBER <i>neu</i>	20.00	0.00	*114.00 FL ✓
24	1		*FRT RH DOOR TOP STICKER <i>neu</i>	20.00	0.00	*35.00 FL ✓
25	1		*FRT RH DOOR LOCK <i>AA</i>	20.00	0.00	*225.00 FL X
26	1		*FRT RH DOOR HINGE (TOP)	20.00	0.00	*45.00 FL ?
27	1		*FRT RH DOOR HINGE (LOWER)	20.00	0.00	*45.00 FL ?
28	1		*REAR RH SHOCK ABSORBER <i>AA</i>	20.00	0.00	*240.00 FL X
29	1		*REAR RH WHEEL HUB	20.00	0.00	*314.00 FL ?
30	1		*REAR AXLE <i>AA</i>	20.00	0.00	*1,513.00 FL ✓
31	1		*REAR RH SPORTS RIM <i>CU7</i>	20.00	0.00	*815.00 FL <i>450</i>

F=Franchise part, L=ListItemDisc

Sub Total (\$\$) *4389* ✓ 9,205.60
 - List Item Discount on L Items (\$\$) *3511.20* 1,841.12
 Total Parts (\$\$) 7,364.48

SME Motor Pte Ltd/SLT612L/10/09/2018 11:54. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
<u>Miscellaneous Items</u>				
1	1	REAR WINDSCREEN GUM	new	60.00 40
2	1	REVERSE SENSOR	cm	250.00 200
3	1	OD/TP Case (Insurer)	new	10.00
Sub Total (S\$)				320.00 250 450 700

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00 ✓
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00 ✓
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00 60
4	CAVITY PROTECTION ON ALL AFFECTED AREA	New	150.00 100
5	REMOVE & REFIX REAR UNDERCARRIAGE (WITH AXLE)	New	350.00 ?
6	4 WHEEL ALIGNMENT	New	65.00 ✓
7	REMOVE & REFIX EXHAUST BOX	New	120.00 60
8	REMOVE & REFIX CUSHION AND SEATS	New	150.00 80
9	TRANSFER DOOR COMPONENTS FROM OLD TO NEW	New	120.00 60
10	LABOUR CHARGE	New	1,600.00 1200
11	SPRAY PAINTING	New	1,500.00 1200
Gross Labour Cost (S\$)			2975 4,325.00

SME Motor Pte Ltd/SLT612L/10/09/2018 11:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

List 3511-20 ✓
SN 700
LC 2975

7186-20

OK.
7/11/18

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 10 Sep 2018)

Parts: M1-SUV

HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLT612L/10/09/2018 11:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR GATE <i>30/600</i>			
2	4		*REAR WINDSCREEN MOULDING <i>ren</i>	20.00	0.00	*955.00 FL
3	1		*REAR GATE VEZEL EMBLEM <i>ren</i>	20.00	0.00	*180.00 FL
4	1		*REAR GATE HYBRID EMBLEM <i>ren</i>	20.00	0.00	*49.00 FL
5	1		*REAR BUMPER (CENTER) <i>7.5</i>	20.00	0.00	*48.00 FL
6	2		*REAR BUMPER RETAINER <i>0/500 28</i>	20.00	0.00	*645.00 FL
7	10		*REAR BUMPER CLIP <i>ren</i>	20.00	0.00	*56.00 FL <i>12c</i>
8	1		*REAR RH CORNER <i>one</i>	20.00	0.00	*55.00 FL
9	1		*REAR RH TAIL LAMP <i>A1</i>	20.00	0.00	*149.00 FL
10	1		*REAR RH FENDER <i>3.0/500/300</i>	20.00	0.00	*448.00 FL
11	1		*REAR RH FENDER PROTECTOR <i>To.1</i>	20.00	0.00	*603.00 FL
12	1		*REAR RH FENDER AIR DUCT <i>Yuni</i>	20.00	0.00	*202.00 FL
13	1		*REAR RH FENDER INNER COWLING <i>To.1</i>	20.00	0.00	*35.00 FL
14	10		*INNER COWLING CLIP <i>ren</i>	20.00	0.00	*95.00 FL
15	1		*REAR END PANEL <i>R</i>	20.00	0.00	*55.00 FL
16	1		*REAR BUMPER REFLECTOR RH <i>one</i>	20.00	0.00	*445.00 FL
17	1		*REAR END PANEL TOP GARNISH <i>A1</i>	20.00	0.00	*151.00 FL
18	4		*REAR END PANEL TOP GARNISH CLIP <i>A1</i>	20.00	0.00	*69.00 FL
19	1		*REAR EXHAUST BOX <i>R</i>	20.00	0.00	*31.60 FL
20	1		*REAR EXHAUST BOX CHROME FINISHER <i>(47)</i>	20.00	0.00	*558.00 FL
21	2		*REAR EXHAUST BOX RUBBER HOLDER <i>A1</i>	20.00	0.00	*145.00 FL
22	1		*FRT RH DOOR <i>0/500</i>	20.00	0.00	*70.00 FL
23	3		*FRT RH DOOR INNER RUBBER <i>ren</i>	20.00	0.00	*845.00 FL
24	1		*FRT RH DOOR TOP STICKER <i>ren</i>	20.00	0.00	*114.00 FL
25	1		*FRT RH DOOR LOCK <i>A1</i>	20.00	0.00	*35.00 FL
26	1		*FRT RH DOOR HINGE (TOP) <i>A1</i>	20.00	0.00	*225.00 FL
27	1		*FRT RH DOOR HINGE (LOWER) <i>A1</i>	20.00	0.00	*45.00 FL
28	1		*REAR RH SHOCK ABSORBER <i>A1</i>	20.00	0.00	*45.00 FL
29	1		*REAR RH WHEEL HUB <i>A1</i>	20.00	0.00	*210.00 FL
30	1		*REAR AXLE <i>A1</i>	20.00	0.00	*314.00 FL
31	1		*REAR RH SPORTS RIM <i>(47)</i>	20.00	0.00	*1,513.00 FL

F=Franchise part. L=List Item Disc.

Sub Total (S\$)

9,205.60

- List Item Discount on L Items (S\$)

1,841.12

Total Parts (S\$)

7,364.48

SME Motor Pte Ltd/SLT612L/10/09/2018 11:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

P-4389

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR WINDSCREEN GUM	60.00
2	1	REVERSE SENSOR	250.00
3	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			320.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00
4	CAVITY PROTECTION ON ALL AFFECTED AREA	New	150.00
5	REMOVE & REFIX REAR UNDERCARRIAGE (WITH AXLE)	New	350.00
6	4 WHEEL ALIGNMENT	New	65.00
7	REMOVE & REFIX EXHAUST BOX	New	120.00
8	REMOVE & REFIX CUSHION AND SEATS	New	150.00
9	TRANSFER DOOR COMPONENTS FROM OLD TO NEW	New	120.00
10	LABOUR CHARGE	New	1,600.00
11	SPRAY PAINTING	New	1,500.00
Gross Labour Cost (S\$)			4,325.00

SME Motor Pte Ltd/SLT612L/10/09/2018 11:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Post FREE Ad to Sell Your Used Items!
Have preloved items cluttering around your house?
Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an AdAdvertiser LoginWays of Selling

05/2017 Mazda 3 @ \$66K 100% Zero Downpayment



Sept 2018 Offer \$0
Downpayment \$0 Insurance. Fr
2.98% Fr \$800/Month. Ending
Soon
Privilege Group Pte StarAd

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

View Our Cars

Browse by Category

Back (1 2 3) Next >

Sort by Date Posted20 results/page

47 vehicles

Honda Vezel

Advanced SearchSubmit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Vezel		Any	Any	2017	Any	Any	Any	Available



Honda Vezel Hybrid 1.5A X \$87,800 \$9,590 /yr 04-Aug-2017 1,496 cc 9,000 km SUV Available

Fuel Type: Petrol-Electric
Facelift Model, Low Fuel Consumption, Almost New Honda Hybrid With Honda Sensing. 10% Down Payment, 10 Years Repayment, In House Loan Or Balloon Scheme Available! Lowest Interest Rate In Town! Lowest ...

Trust Motoring
Posted: 11-Sep-2018 Tags: 2017 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



Honda Vezel Hybrid 1.5A X \$89,800 \$9,830 /yr 28-Jul-2017 1,496 cc 9,000 km SUV Available

Fuel Type: Petrol-Electric
Almost New Honda Vezel Hybrid With Honda Sensing, Lane Departure, Pre-Collision Sensing, Paddle Shifter, New Facelift Morpho Blue, 10% Down Payment 10 Years Repayment, In House Loan Or Balloon Scheme ...

Trust Motoring
Posted: 11-Sep-2018 Tags: 2017 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



Honda Vezel Hybrid 1.5A X \$87,800 \$9,710 /yr 22-Jun-2017 1,496 cc 5,000 km SUV Available

Fuel Type: Petrol-Electric
Almost New Honda Vezel Hybrid With Honda Sensing Lane Departure, Pre-Collision Sensing, Paddle Shifter, New Facelift Russett Black, 10% Down Payment 10 Years Repayment, In House Loan Or Balloon Scheme ...

Trust Motoring
Posted: 11-Sep-2018 Tags: 2017 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



Honda Vezel Hybrid 1.5A X \$87,800 \$9,760 /yr 06-Jun-2017 1,496 cc 9,000 km SUV Available

Fuel Type: Petrol-Electric
Facelift Model, Low Fuel Consumption, Almost New Honda Hybrid With Honda Sensing. 10% Down Payment, 10 Years Repayment, In House Loan Or Balloon Scheme Available! Lowest Interest Rate In Town! Lowest ...

Trust Motoring
Posted: 11-Sep-2018 Tags: 2017 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda

Car BuyingCar SellingCar OwnershipBuying a pre-owned car, but Unsure of its Condition?Get, STA Car Evaluation

Car AftermarketOn The MoveLifestyle



Honda Vezel 1.5A X \$76,800 \$8,100 /yr 15-Jun-2017 1,496 cc 8,143 km SUV Available

Not A Private Hire Unit! 1 Owner Only! Under Utilize With Extremely Low Mileage Of 8000 Plus KM Only. Brand New Condition, As Good As New Unit. Very Well Maintain, In Original Condition And With Warra...

Car (S) Pte Ltd
Posted: 10-Sep-2018 Tags: 2017 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



Honda Vezel 1.5A X Honda Sensing \$75,800 \$8,250 /yr 02-Feb-2017 1,496 cc SUV Available

\$2300 Drive Away, Insurance Can Pay By GIRO For 12 Months. No Hidden Cost No Gimmicks! Call Us Now For More Details.

Alimotoring.sg

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Foreign Identification Number
Owner ID:	4440U

Vehicle Details

Vehicle No.:	SLT612L
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5947323
Chassis No.:	RU31247306
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,661.00
Original Registration Date:	16 Oct 2017
First Registration Date:	16 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Oct 2027
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	15 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$44,561.00
Total Rebate Amount:	\$48,311.00

The information contained herein is correct as at 11 Sep 2018

OK

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

TP INSURER: India International Insurance Pte Ltd (HQ)
 MARK PAUL HENSEL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

*not Advised
 Let more
 Take photo before
 painting
 7 day
 11/9/18*

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	18/III/TP-183 (09)
Policy No:		Date of Loss:	06/09/2018
Vehicle Reg. No.:	SLT612L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	WONG CHUI TEING	Driver (Insured):	WONG CHUI TEING

Make/Model: HONDA VEZEL, 1.5 (A)
 Vehicle Colour: BLACK
 Engine No: LEB5947323
 Odometer: 0 KM

Vehicle Reg. Date: 16/10/2017

LRK Auto Consultants hence notify
 the Repairer of the following:
 Chassis No: RU31247306

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Paint Type:
 List Item Discount: 20.00 %
 Total Loss? NO
 Est. Duration of Repair 7 (day)

Acknowledged by Repairer
 Signature:
 Date:

Description of Accident/Loss
 ON 06/09/2018 AT 6.30PM, I WAS DRIVING MY CAR (SLT612L) TURNING LEFT FROM KALLANG AIRPORT WAY. I STOPPED TO ALLOW ON-COMING VEHICLE GOING STRAIGHT. SUDDENLY, I FELT A HUGE IMPACT ON MY REAR. WHEN I WAS ALIGHTING, A TAXI (VEH B SHA5845X) THAT COLLIDED ONTO MY REAR THEN DROVE FORWARD AND AGAIN COLLIDED ONTO MY RIGHT DOOR. LUCKILY I AVOIDED IT OR VEHICLE B WOULD HAVE COLLIDED ONTO ME PHYSICALLY. AFTER VEHICLE B REVERSE, I WAS THEN ABLE TO ALIGHT AND I REALISED THERE WAS A THIRD CAR (VEHICLE C SLF1588R) INVOLVED. VEHICLE C'S DRIVER TOLD ME THAT VEHICLE B COLLIDED ONTO ME AND REVERSED TO COLLIDE ONTO HIM AND DROVE FORWARD TO COLLIDE ONTO MY RIGHT DOOR AGAIN.

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	7,364.48
Miscellaneous Items	320.00
Labour	4,325.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2018)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLT612L/10/09/2018 11:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR GATE <i>300/500</i>	20.00	0.00	*955.00 FL
2	4		*REAR WINDSCREEN MOULDING <i>rec</i>	20.00	0.00	*180.00 FL
3	1		*REAR GATE VEZEL EMBLEM <i>rec</i>	20.00	0.00	*49.00 FL
4	1		*REAR GATE HYBRID EMBLEM <i>rec</i>	20.00	0.00	*48.00 FL
5	1		*REAR BUMPER (CENTER) <i>Di</i>	20.00	0.00	*645.00 FL
6	2		*REAR BUMPER RETAINER <i>0/5 rec</i>	20.00	0.00	*56.00 FL <i>12c</i>
7	10		*REAR BUMPER CLIP <i>rec</i>	20.00	0.00	*55.00 FL
8	1	<i>buy</i>	*REAR RH CORNER LAMP <i>rec</i>	20.00	0.00	*149.00 FL
9	1		*REAR RH TAIL LAMP	20.00	0.00	*448.00 FL
10	1		*REAR RH FENDER <i>300/500/300</i>	20.00	0.00	*603.00 FL
11	1		*REAR RH FENDER PROTECTOR <i>To.1</i>	20.00	0.00	*202.00 FL
12	1		*REAR RH FENDER AIR DUCT <i>Yuni</i>	20.00	0.00	*35.00 FL
13	1		*REAR RH FENDER INNER COWLING <i>To.1</i>	20.00	0.00	*95.00 FL
14	10		*INNER COWLING CLIP <i>rec</i>	20.00	0.00	*55.00 FL
15	1		*REAR END PANEL	20.00	0.00	*445.00 FL
16	1		*REAR BUMPER REFLECTOR RH <i>rec</i>	20.00	0.00	*151.00 FL
17	1		*REAR END PANEL TOP GARNISH <i>11</i>	20.00	0.00	*69.00 FL
18	4		*REAR END PANEL TOP GARNISH CLIP <i>11</i>	20.00	0.00	*31.60 FL
19	1		*REAR EXHAUST BOX <i>R</i>	20.00	0.00	*558.00 FL
20	1		*REAR EXHAUST BOX CHROME FINISHER <i>647</i>	20.00	0.00	*145.00 FL
21	2		*REAR EXHAUST BOX RUBBER HOLDER <i>11</i>	20.00	0.00	*70.00 FL
22	1		*FRT RH DOOR <i>300/500</i>	20.00	0.00	*845.00 FL
23	3		*FRT RH DOOR INNER RUBBER <i>rec</i>	20.00	0.00	*114.00 FL
24	1		*FRT RH DOOR TOP STICKER <i>rec</i>	20.00	0.00	*35.00 FL
25	1		*FRT RH DOOR LOCK <i>11</i>	20.00	0.00	*225.00 FL
26	1		*FRT RH DOOR HINGE (TOP)	20.00	0.00	*45.00 FL
27	1		*FRT RH DOOR HINGE (LOWER)	20.00	0.00	*45.00 FL
28	1		*REAR RH SHOCK ABSORBER <i>11</i>	20.00	0.00	*210.00 FL
29	1		*REAR RH WHEEL HUB	20.00	0.00	*314.00 FL
30	1		*REAR AXLE <i>11</i>	20.00	0.00	*1,513.00 FL
31	1		*REAR RH SPORTS RIM <i>647</i>	20.00	0.00	*815.00 FL

F=Franchise part. L=ListItemDisc

Sub Total (\$\$) 9,205.60

- List Item Discount on L Items (\$\$) 1,841.12

Total Parts (\$\$) 7,364.48

SME Motor Pte Ltd/SLT612L/10/09/2018 11:54. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR WINDSCREEN GUM	60.00
2	1	REVERSE SENSOR	250.00
3	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			320.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00
4	CAVITY PROTECTION ON ALL AFFECTED AREA	New	150.00
5	REMOVE & REFIX REAR UNDERCARRIAGE (WITH AXLE)	New	350.00
6	4 WHEEL ALIGNMENT	New	65.00
7	REMOVE & REFIX EXHAUST BOX	New	120.00
8	REMOVE & REFIX CUSHION AND SEATS	New	150.00
9	TRANSFER DOOR COMPONENTS FROM OLD TO NEW	New	120.00
10	LABOUR CHARGE	New	1,600.00
11	SPRAY PAINTING	New	1,500.00
Gross Labour Cost (S\$)			4,325.00

SME Motor Pte Ltd/SLT612L/10/09/2018 11:54. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Print Received Message

This mail is associated with :

SLT612L (MCT18090152)
[SHA5845X]
TP
MARK PAUL HENSEL
Sep 6 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
SME Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 01/02/2019 16:59 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8325.68) - SLT612L - Claim Handler: Priya

Approved:8325.68.

LETTER OF AUTHORITY

To: M/s India International Insurance Pte Ltd
Singapore

Accident involving my/our vehicle no. SLT612L and SHA 5845X on 06/09/18

along Kallang Airport Way

I/We, Mark Paul Hensel NRIC No. G30944401

of — Singapore —

the registered owner of vehicle no. SLT612L at the material time of accident, do

hereby authorise Messrs SME MOTOR PTE LTD as my/our agent and representative

to correspond in, negotiate and settle, on my/our behalf, my/our claim against you as

owner/operator/insurer of vehicle no. SHA 5845X.

I/We also authorise them to accept settlement cheque on my/our behalf. Kindly issue

your cheque in favour of "M/s. SME MOTOR PTE LTD".

Dated this 18 day of 09 2018



Signature of Owner or his/her/their
Duly Authorised Representative

Company's Stamp (For Firm)

INDIA International Insurance Pte Ltd
64 Cecil Street # 04-05
IOB Building
Singapore 049711

Your Insured Veh No. : **SHA5848X**
Your Ref :
Our Ref : **SLT612L**

Date : 20/11/2018

WITHOUT PREJUDICE

Dear Sir/Madam

**Accident involving SHA5848X and SLT612L
on 06/09/2018 at KALLANG AIRPORT WAY.**

Please refer only to the boxes marked (x).

☒ We refer to ☒ the above accident
☐ our/your letter dated

☒ We have been authorised by the owner of vehicle number **SLT612L** which was damaged by your insured's motor vehicle number **SHA5848X** in the aforesaid accident.

☒ We are instructed that the accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

Cost of Repair / Insurance Excess	7,689.23
Survey report fees/ TP report fee	29.00
Loss of Use(days @ \$0.00 per day)	-
Car Rental Fees	600.00
GIA/LTA search fees	7.45
Total S\$	8,325.68

☒ We forward herewith the following relevant supporting documents:-

☐ Survey Reports & photographs (To be returned within 7 days on demand)

☒ Final repair bill(Tax Invoice)

☒ Copy of NRIC/Driving licence

☒ Bill/Receipt for the excess / TP report search Fee

☒ Copy of LTA/GIA vehicle search

☒ Rental Agreement

☒ Non-injury motor report form

☒ Copy of the Insurance Certificate

☒ Letter of Authority

☒ Cheque to be made payable to **Messrs SME MOTOR PTE LTD.**

☐ Any request for a re-survey of our client's vehicle must be arranged within the 14 days upon receipt of this letter. The re-survey must be conducted at our premises, in the presence of our client.

☒ Please note that you should send to us an acknowledgment of receipt of this letter within 07 days of your receipt of this letter.

Yours faithfully,

WE HEREBY ACKNOWLEDGE RECEIPT

SME MOTOR PTE LTD

encl:

Date: _____
PLEASE CHOP AND SIGN

LKK

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

Without Prejudice
to any claim for
personal injury

India Ref: MCT18090152
Claimant Ref: SLT 612L

We/I, SME MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 7,689.23 (repair cost), S\$ 600.00 (loss of ~~rental~~/rental), S\$ 36.45 (search fee), vehicle no. SLT 612L that was damaged pursuant to the accident which occurred on 06.09.2018 (date) at KALLANG AIRPORT WAY (location) involving vehicle no. SHA 5845X (insured vehicle). This is pursuant to the inspection conducted on 11.09.2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner MARK PAUL HENSEL ("the third party claimant") of vehicle no. SLT 612L to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLT 612L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 8,325.68 to SME MOTOR PTE LTD

Dated this 11 day of 09 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

SME Motor Pte. Ltd.
1 Kaki Bukit Ave 6, #02-15
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67476106 (6 lines)
Fax: 67442368

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:



OKS

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street #04/05,
IOB Building
Singapore 049711
TEL: 63476100 **FAX:** 62244174
ATTN: Motor Claim Department
Your Ref No: 18/III/TP-183(09)
Claim Type: Third Party
Accident Date: 06/09/2018
TP Veh Reg No: SHA5845X

Claim No: EST0004550
Final No: INV0003769
Date: 19 Dec 2018
Policy No: GA279564
Veh Reg No: SLT612L
Make/Model: HONDA VEZEL
Chasis No: 0
Engine No:
Reg. Date:

Tax Invoice to Vehicle No :SLT612L

Description	Quantity	List Price S\$	Amount S\$
Others			
1 COST OF REPAIR	1 PC	7,186.20	7,186.20
		7,186.20	7,186.20
		Total	S\$ 7,186.20
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 7,186.20
		Add GST @ 7%	503.03
		Total Amount Payable	S\$ 7,689.23

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED EIGHTY NINE AND CENTS TWENTY THREE ONLY

For SME Motor Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE

CHIN HUI CAR RENTAL

BLK 7, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-76,
SINGAPORE 575642. TEL: 6453 4680
REGN. NO.: 53090791K

VEHICLE RENTAL AGREEMENT

NO: 8228

HIRER'S PARTICULAR		Vehicle No: 8D7147A		Mileage Out: 199115													
Hirer: Hensei Mark Paul		Make & Model: TOYOTA ALTIS		Auto / Manual Group: ☒ Auto													
NRIC / Passport No: 93094440U		OUT : Date: 12/9/18		OUT : Time: 9.35													
Address: 90 BLK 736 BEDOK RESERVOIR RD #11-21 S (479264)		Replace Veh No:		Mileage Out:													
Driving Licence No: 63094440U		OUT : Date:		OUT : Time:													
Pass Date: 24/11/2015																	
Contact Number: 96138710																	
DRIVERS PARTICULARS (If different from Hirer)		CHARGES															
Appointed Driver: WONG CHUI TEING		Daily 6 @ \$100/- per day 600.00															
NRIC / Passport No: S8087012A		Weekly @ \$ per week															
Date of Birth: 10/06/1980		Monthly @ \$ per month															
Address: BLK 736 BEDOK RESERVOIR RD #11-21 S (479264)		Hours @ \$ per hour															
Driving Licence No: S8087012A		Others @ \$															
Pass Date: 06/07/2017																	
Contact Number: 91260012																	
		SUB-TOTAL \$ 600.00															
New Insurance Policy Terms & Conditions as at 08-12-2010 1. NOT PERMITTED TO DRIVE - Not Covered Driver Age 22 years old and below Driver above Age 70 years old Driver less than 2 years Driving Experience 2. ADDITIONAL EXCESS - S\$3000.00 Driver Age 23 to 25 years old with 2 years driving experience Driver Age 65 to 70 years old with 2 years driving experience		PETROL LEVEL															
		<table border="1"> <tr> <td>Out</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> </tr> <tr> <td>In</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> </tr> </table>				Out	E	1/4	1/2	3/4	F	In	E	1/4	1/2	3/4	F
		Out	E	1/4	1/2	3/4	F										
		In	E	1/4	1/2	3/4	F										
TOTAL CHARGES \$ 600.00																	
REMARKS		IMPORTANT! FOR SINGAPORE USE ONLY															
		Excess Liability: S\$2500.00															
		Malaysia Excess (With Prior Consent): Not Allowed.															
		Hirer's Signature:  Addition Driver's Signature: 															

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CHIN HUI CAR RENTAL in connection with this agreement is true.

* IMPORTANT

- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AND ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY CHIN HUI CAR RENTAL.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY, IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CHIN HUI CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	SIGNATURE OF HIRER / DRIVER
18/9/2018	1615 hrs.	199477		

SME (SLT612L)

CHIN HUI CAR RENTAL

REGN. NO.: 53090791K

BLK 7, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-76, SINGAPORE 575642. TEL: 6453 4680

OFFICIAL RECEIPT

M/s HENSEL MARK PAUL

No: 272992

C/O BLK 736 BEDOK RESERVOIR RD

#11-21, SINGAPORE 479264.

Date: 18.09.2018

S/No.	Description	Amount
1	RENTAL FEES FOR SJD 7147A VRA NO. 8228	<u>\$ 600.00</u>

SINGAPORE DOLLARS SIX HUNDRED ONLY

PAYMENT MODE:

CASH -

CHEQUE -


Chin Hui Car Rental

SEARCH RESULTS

Our Ref No: GR-18-139876
Date of Request: 07/09/2018

Your Ref No: Online Purchase

SME Motor Pte Ltd
1 Kaki Bukit Ave 6 #02-15
AutoBay @ Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 06/09/2018
Place of Accident: KALLANG AIRPORT WAY
Client Vehicle No: SLT612L

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHA5845X	KALLANG AIRPORT WAY TWDS KPE	06/09/2018 18:30

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

[> Back to OneMotoring](#)

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. M4-0006529-2

Print Date/Time : 07 Sep 2018 / 10:34:12

Receipt Date/Time : 07 Sep 2018 / 10:34:12

Tax Invoice/Receipt

Receipt No. ITNET-00000-180907-000592

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
	Result of Insurance Enquiry - SHA5845X As at 06 Sep 2018/18:30:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SHA5845X Enquiry Fee 20180907103308099907	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx6735 Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2018 Sendback Est	10 Sep 2018 11:54 \$512,009.48	11 Sep 2018 08:50 Edit Adj Rpt	\$57,186.20 Edit Estimates	\$57,186.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R, Tel: +6596138710								
Main Claimant:	MARK PAUL HENSEL , ID: G3094440U								
Vehicle Reg. No.:	SLT612L	Date of Loss:	06/09/2018 18:00 - :59 [10 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18090152	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA5845X	Policy No. (Claimant):	GA279564						
		Excess:							
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/09/2018]								
Driver/Custodian (Insured):	WONG CHUI TEING (36 / Female) , NRIC: S8287012A, Tel: +6591260012 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (01/02/2019): Alert - Adj Mandate Approved (\$58325.68) - SLT612L - Claim Handler: Priya - III_SG (19/09/2018): Alert - Adj Mandate Maintained - SLT612L - Claim Handler: Priya									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLT612L (MCT18090152)
[SHA5845X]
TP
MARK PAUL HENSEL
Sep 6 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
SME Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		☒	
No	Finalized On	India International Insurance Pte Ltd (HQ)						Thumbnail	Print	
1	19/09/18 15:18	Video - Accident						Load MP4		
Assessment Reports							1 per page		☒	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)						Thumbnail	Print	
1	10/09/18 11:54	Repairer Estimates						Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	01/02/19 16:03	General View						Load JPG	☒	
2	01/02/19 16:03	General View						Load JPG	☒	
3	01/02/19 16:03	General View						Load JPG	☒	
4	01/02/19 16:03	General View						Load JPG	☒	
5	01/02/19 16:03	General View						Load JPG	☒	
6	01/02/19 16:03	General View						Load JPG	☒	
7	01/02/19 16:03	General View						Load JPG	☒	
8	01/02/19 16:03	General View						Load JPG	☒	
9	01/02/19 16:03	General View						Load JPG	☒	
10	01/02/19 16:03	General View						Load JPG	☒	
11	01/02/19 16:03	General View						Load JPG	☒	
12	01/02/19 16:03	General View						Load JPG	☒	
13	01/02/19 16:03	General View						Load JPG	☒	
14	01/02/19 16:03	General View						Load JPG	☒	
15	01/02/19 16:03	General View						Load JPG	☒	
16	01/02/19 16:03	General View						Load JPG	☒	
17	01/02/19 16:03	General View						Load JPG	☒	
18	01/02/19 16:03	General View						Load JPG	☒	
19	01/02/19 16:03	General View						Load JPG	☒	
20	01/02/19 16:03	General View						Load JPG	☒	
21	01/02/19 16:03	General View						Load JPG	☒	
22	01/02/19 16:03	General View						Load JPG	☒	
23	01/02/19 16:03	General View						Load JPG	☒	
24	01/02/19 16:03	General View						Load JPG	☒	
25	01/02/19 16:03	General View						Load JPG	☒	
26	01/02/19 16:03	General View						Load JPG	☒	
27	01/02/19 16:03	General View						Load JPG	☒	
28	01/02/19 16:03	General View						Load JPG	☒	
29	01/02/19 16:03	General View						Load JPG	☒	
30	01/02/19 16:03	General View						Load JPG	☒	

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
31	01/02/19 16:03	General View	 Load JPG	☒
32	01/02/19 16:03	General View	 Load JPG	☒
33	01/02/19 16:03	General View	 Load JPG	☒
34	01/02/19 16:03	General View	 Load JPG	☒
35	01/02/19 16:03	General View	 Load JPG	☒
36	01/02/19 16:03	General View	 Load JPG	☒
37	01/02/19 16:03	General View	 Load JPG	☒
38	01/02/19 16:03	General View	 Load JPG	☒
39	01/02/19 16:03	General View	 Load JPG	☒
40	01/02/19 16:03	General View	 Load JPG	☒
41	01/02/19 16:03	General View	 Load JPG	☒
42	01/02/19 16:03	General View	 Load JPG	☒
43	01/02/19 16:03	General View	 Load JPG	☒
44	01/02/19 16:03	General View	 Load JPG	☒
45	01/02/19 16:03	General View	 Load JPG	☒
46	01/02/19 16:03	General View	 Load JPG	☒
47	01/02/19 16:03	General View	 Load JPG	☒
48	01/02/19 16:03	General View	 Load JPG	☒
49	01/02/19 16:03	General View	 Load JPG	☒
50	01/02/19 16:03	General View	 Load JPG	☒
51	01/02/19 16:03	General View	 Load JPG	☒
52	01/02/19 16:03	General View	 Load JPG	☒
53	01/02/19 16:03	General View	 Load JPG	☒
54	01/02/19 16:03	General View	 Load JPG	☒
55	01/02/19 16:03	General View	 Load JPG	☒
56	01/02/19 16:03	General View	 Load JPG	☒
57	01/02/19 16:03	General View	 Load JPG	☒
58	01/02/19 16:03	General View	 Load JPG	☒
59	01/02/19 16:03	General View	 Load JPG	☒
60	01/02/19 16:03	General View	 Load JPG	☒
61	01/02/19 16:03	General View	 Load JPG	☒
62	01/02/19 16:03	General View	 Load JPG	☒
63	01/02/19 16:03	General View	 Load JPG	☒
64	01/02/19 16:03	General View	 Load JPG	☒
65	01/02/19 16:03	General View	 Load JPG	☒
66	01/02/19 16:03	General View	 Load JPG	☒
67	01/02/19 16:03	General View	 Load JPG	☒
68	01/02/19 16:03	General View	 Load JPG	☒
69	01/02/19 16:03	General View	 Load JPG	☒
70	01/02/19 16:03	General View	 Load JPG	☒
71	01/02/19 16:03	General View	 Load JPG	☒
72	01/02/19 16:03	General View	 Load JPG	☒
73	01/02/19 16:03	General View	 Load JPG	☒
74	01/02/19 16:03	General View	 Load JPG	☒
75	01/02/19 16:03	General View	 Load JPG	☒
76	01/02/19 16:03	General View	 Load JPG	☒
77	01/02/19 16:03	General View	 Load JPG	☒
78	01/02/19 16:03	General View	 Load JPG	☒
79	01/02/19 16:03	General View	 Load JPG	☒
80	01/02/19 16:03	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
81	01/02/19 16:03	General View		☒
82	01/02/19 16:03	General View		☒
83	01/02/19 16:03	General View		☒
84	01/02/19 16:03	General View		☒
85	01/02/19 16:03	General View		☒
86	01/02/19 16:03	General View		☒
87	01/02/19 16:03	General View		☒
88	01/02/19 16:03	General View		☒
89	01/02/19 16:03	General View		☒
90	01/02/19 16:03	General View		☒
91	01/02/19 16:03	General View		☒
92	01/02/19 16:03	General View		☒
93	01/02/19 16:03	General View		☒
94	01/02/19 16:05	Reinspection Photo		☒
95	01/02/19 16:05	Reinspection Photo		☒
96	01/02/19 16:05	Reinspection Photo		☒
97	01/02/19 16:05	Reinspection Photo		☒
98	01/02/19 16:05	Reinspection Photo		☒
99	01/02/19 16:05	Reinspection Photo		☒
100	01/02/19 16:05	Reinspection Photo		☒
101	01/02/19 16:05	Reinspection Photo		☒
102	01/02/19 16:05	Reinspection Photo		☒
103	01/02/19 16:05	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	10/09/18 11:56	E-filed GIA report		
2	10/09/18 11:57	LTA SEARCH		
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 08:48	Singapore Accident Statement		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 19:48	TP ESTIMATE - MARKED		
2	29/01/19 12:53	RENTAL RECEIPT		
3	29/01/19 12:53	LTA SEARCH		
4	29/01/19 12:53	GIA SEARCH		
5	08/03/19 10:42	WORKSHOP INVOICE		
6	08/03/19 10:42	AUTHORISATION TO ACT FORM		
7	08/03/19 10:42	DISCHARGE VOUCHER		
8	08/03/19 10:42	LOD		

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	07/09/18 13:27	Accident Statement		
Photos/Images			3 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	07/09/18 13:26	Driving License		☒
2	07/09/18 13:26	INSURANCE		☒
3	07/09/18 13:26	Accident Photo		☒
4	07/09/18 13:26	Accident Photo		☒
5	07/09/18 13:26	Accident Photo		

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
				☒
6	07/09/18 13:26	Accident Photo	Load JPG	☒
7	07/09/18 13:26	Accident Photo	Load JPG	☒
8	07/09/18 13:26	Accident Photo	Load JPG	☒
9	07/09/18 13:27	Accident Photo	Load JPG	☒
10	07/09/18 13:27	Accident Photo	Load JPG	☒
11	07/09/18 13:27	Accident Photo	Load JPG	☒
12	07/09/18 13:27	Accident Photo	Load JPG	☒
13	07/09/18 13:27	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	07/09/18 13:26	Sketch Plan	Load TIF	
2	07/09/18 13:26	Sketch Plan #2	Load TIF	
3	07/09/18 13:26	Sketch Plan #3	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18016552/UJA3Q2

Date: 08/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SLT612L

Insured Vehicle No: SHA5845X

Date of Loss: 06/09/2018

Nature of Claim: TP

Claim No: MCT18090152

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT612L

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: LEB5947323

Reg. Date: 16/10/2017 (Man. Year: 2017)

Chassis No: RU31247306

Colour: Black

Odometer: 16838 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,364.48	3,961.20	3,403.28	46.21
Miscellaneous Items	320.00	250.00	70.00	21.88
Labour	4,325.00	2,975.00	1,350.00	31.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,009.48	7,186.20	4,823.28	40.16
+ GST 7.00/7.00% (S\$)	840.66	503.03	337.63	40.16
Nett Amount (S\$)	12,850.14	7,689.23	5,160.91	40.16
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,325.68		

INSPECTION

Date of Assignment: 11/09/2018 Present Location:

Date Inspected: 11/09/2018 Inspected At:

SME Motor Pte Ltd (Kaki Bukit)

SME Motor Pte Ltd (Kaki Bukit)

1 Kaki Bukit Ave 6 #02-15, AutoBay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT612L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE	Badly Dented	955.00 FL	*955.00 FL
2	4		*REAR WINDSCREEN MOULDING	Necessary	180.00 FL	*180.00 FL
3	1		*REAR GATE VEZEL EMBLEM	Necessary	49.00 FL	*49.00 FL
4	1		*REAR GATE HYBRID EMBLEM	Necessary	48.00 FL	*48.00 FL
5	1		*REAR BUMPER (CENTER)	Distorted	645.00 FL	*645.00 FL
6	1		*REAR BUMPER RETAINER	O/S Bent	58.00 FL	*28.00 FL
7	10		*REAR BUMPER CLIP	Necessary	55.00 FL	*55.00 FL
8	1		*REAR RH CORNER LAMP	Cracked	149.00 FL	*149.00 FL
9	1		*REAR RH TAIL LAMP	Not Necessary	448.00 FL	*- FL
10	1		*REAR RH FENDER	Badly Dented / Buckled	603.00 FL	*603.00 FL
11	1		*REAR RH FENDER PROTECTOR	Torn	202.00 FL	*202.00 FL
12	1		*REAR RH FENDER AIR DUCT	Twisted	35.00 FL	*35.00 FL
13	1		*REAR RH FENDER INNER COWLING	Torn	95.00 FL	*95.00 FL
14	10		*INNER COWLING CLIP	Necessary	55.00 FL	*55.00 FL
15	1		*REAR END PANEL	Repair	445.00 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Cracked	151.00 FL	*151.00 FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	69.00 FL	*- FL
18	4		*REAR END PANEL TOP GARNISH CLIP	Not Necessary	31.60 FL	*- FL
19	1		*REAR EXHAUST BOX	Repair	558.00 FL	*- FL
20	1		*REAR EXHAUST BOX CHROME FINISHER	Cut	145.00 FL	*145.00 FL
21	2		*REAR EXHAUST BOX RUBBER HOLDER	Not Necessary	70.00 FL	*- FL
22	1		*FRT RH DOOR	Dented / Buckled	845.00 FL	*845.00 FL
23	3		*FRT RH DOOR INNER RUBBER	Necessary	114.00 FL	*114.00 FL
24	1		*FRT RH DOOR TOP STICKER	Necessary	35.00 FL	*35.00 FL
25	1		*FRT RH DOOR LOCK	Not Necessary	225.00 FL	*- FL
26	1		*FRT RH DOOR HINGE (TOP)	Not Necessary	45.00 FL	*- FL
27	1		*FRT RH DOOR HINGE (LOWER)	Not Necessary	45.00 FL	*- FL
28	1		*REAR RH SHOCK ABSORBER	Not Necessary	210.00 FL	*- FL
29	1		*REAR RH WHEEL HUB	Not Necessary	314.00 FL	*- FL
30	1		*REAR AXLE	Not Necessary	1,513.00 FL	*- FL
31	1		*REAR RH SPORTS RIM	Cut	815.00 FL	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	9,205.60	4,839.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,841.12	877.80
Total Parts (\$\$)	7,364.48	3,961.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR WINDSCREEN GUM (NECESSARY)	60.00	40.00
2	1	REVERSE SENSOR (CRACKED)	250.00	200.00
3	1	OD/TP Case (Insurer) (NECESSARY)	10.00	10.00
Sub Total (S\$)			320.00	250.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	30.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60.00
4	CAVITY PROTECTION ON ALL AFFECTED AREA	New	150.00	100.00
5	REMOVE & REFIX REAR UNDERCARRIAGE (WITH AXLE)	New	350.00	0.00
6	4 WHEEL ALIGNMENT	New	65.00	65.00
7	REMOVE & REFIX EXHAUST BOX	New	120.00	60.00
8	REMOVE & REFIX CUSHION AND SEATS	New	150.00	80.00
9	TRANSFER DOOR COMPONENTS FROM OLD TO NEW	New	120.00	60.00
10	LABOUR CHARGE	New	1,600.00	1,200.00
11	SPRAY PAINTING	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			4,325.00	2,975.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >