

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO : AIG DATE : 101/09/2018
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SLF9265U
MODEL : HYUNDAI ELANTRA AD 1.6 GLS AT
CHASSIS NO

ACCIDENT DETAILS DATE : 9-Sep-18
TIME : 17:00HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS (REAR)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH <i>Dented</i>	1	\$ 1,355.60	\$ 1,355.60 ✓
2	REAR DOOR STICKER RH <i>new</i>	1	\$ 90.30	\$ 90.30 ✓
3	REAR DOOR LOCK RH <i>Not new</i>	1	\$ 276.50	\$ 276.50 +
4	REAR DOOR WEATHER STRIP RH <i>new</i>	1	\$ 174.30	\$ 174.30 ✓
5	REAR BUMPER <i>Rebuilt</i>	1	\$ 699.20	\$ 699.20 ✓
6	REAR BUMPER SIDE RETAINER RH <i>new</i>	1	\$ 62.00	\$ 62.00 ✓
7	REAR FENDER RH <i>Repair</i>	1	\$ 1,950.90	\$ 1,950.90 x.
8	REAR FENDER INNER COWLING RH	1	\$ 130.00	\$ 130.00 x
9	REAR FENDER AIR VENT RH <i>new</i>	1	\$ 64.30	\$ 64.30 x
10	REAR WINDSCREEN MOULDING	1	\$ 80.00	\$ 80.00 x
11	REAR ALEX <i>Not new</i>	1	\$ 1,455.90	\$ 1,455.90 x
12	REAR BEARING WITH HUB RH <i>2 new</i>	1	\$ 356.80	\$ 356.80 x
13	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 355.60	\$ 355.60 +

TOTAL PRICE \$ 7,051.40

LESS 20% \$ 1,410.28

SUB TOTAL PRICE \$ 5,641.12

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
2	REAR FENDER SEALANT RH <i>new</i>	1	\$ 100.00	\$ 100.00	X.
3	REAR FENDER INNER COWLING RH CLIPS(SET) <i>new</i>	1	\$ 22.00	\$ 22.00	✓
4	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00	✓
5	REAR WHEEL SPORT RIM <i>lit</i>	1	\$ 850.00	\$ 850.00	700.
6	REAR WHEEL TYRE RH <i>new</i>	1	\$ 350.00	\$ 350.00	X

TOTAL \$ 1,442.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL & REPLACING PANEL	\$ 1,400.00	500.	
2	TO SPRAY PAINT AFFECTED AREAS	\$ 1,000.00	600.	
3	TO APPLY RUST PROOFING & TUFF COAT	\$ 120.00	X.	
4	WIRING CHECK	\$ 60.00	30.	
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	X.	
6	FOUR WHEEL ALIGNMENT	\$ 120.00	80	
7	REMOVE & REFIX WINDSCREEN	\$ 180.00	X.	
8	REMOVE & REFIX UNDER CARRIAGE	\$ 350.00	X	
9	TO TRANSFER FRONT AND REAR DOOR MECHANISM	\$ 200.00	80.	
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50	

TOTAL \$3,730.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,083.12
TOTAL LABOUR COST : \$ 3,730.00
TOTAL REPAIR COST : \$ 10,813.12

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

Adrian Ling
L/S 10/09/18.
04 days.