

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

143 Cecil Street #01-01 GB Building

069542

Attention : Motor Claim Department

Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000334

Date : 10/09/2018

Vehicle Num. : SLM 2849U

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 03/09/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BUMPER	900.00	xR
2.	1	REAR EXTENSION FILLER LH	230.00	xR
3.	1	REAR FENDER	950.00	DD
4.	1	REAR FENDER UNDERDUST COVER LH	250.00	xSVC
5.	1	REAR DOOR - LH	1,450.00	DD
6.	1	SIDE SKIRT LH	550.00	xR
7.	1	REAR BUMPER TAIL LAMP LH	750.00	xSVC
8.	1	REAR TAIL LAMP - LH	900.00	xSVC

List TotalS\$:

5,980.00

25.00% Discount S\$:

1,495.00

4,485.00

SPECIAL NETT ITEMS :				
1.	1	REAR BUMPER CLIP	40.00	xnn
2.	1	REAR FENDER UNDERDUST COVER CLIPS	40.00	xnn
3.	1	SIDE SKIRT CLIPS	40.00	?
4.	1	REAR TAILLAMP CLIPS	40.00	xnn

Special Nett Total S\$:

160.00

LABOUR :

TRANSFER DOOR MECHANISM

180.00 50

TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.

180.00 50

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO

1,200.00 800

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000334

Date : 10/09/2018
 Vehicle Num. : SLM 2849U
 Make/Model : TOYOTA PRIUS HYBRID 1.8S
 Chassis/Eng# :
 Accident Date : 03/09/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
 PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS
 AND REFIT BACK SAME

280.00 *280.00*

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

1,000.00 *700*

TO REMOVE, REARRANGE ALL ELECTRICAL WIRING, CHECK
 LIGHTINGS & RESET LAMP FOCUSING

180.00 *50*

Labour Total S\$:

3,020.00

*NAZLIK
 10/9/18 1645
 PIR
 5 DAYS
 BEFORE PAINT PHOTO*

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

Total S\$: 7,665.00

=====

for WORLD AUTO PTE LTD