



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 10th September 2018
Motor claims Department
Axa Insurance Singapore Pte Ltd
8 Shenton Way #27-01
Axa Tower
Singapore 068811

Dear Sirs,

Re: Cost of repair to Kawasaki KRR2000 - FU 6033

1 pc of Side box
" Tank cover
" Rear footrest bracket LH
" Lower cowling LH
" Mirror
" Clutch lever
" Seat lock
" Handle bar LH
" Front signal LH

S\$ 2600 at ✓
400 at ✓
600 X
115.00 X
45.00 X
100 X
4500 ✓
750 X
200 X

702.00 353
70.20 102
631.80 317.70

Less 10%

Nett

spray painting
Alignment fork
Labour

2000 100 } 170
65.00 X
1500 70

S\$ 1046.80
317.70
170.00
487.70

202
390.16
41-400

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR

Rasul
4p 90010068

2 days

4/5

11/09/18 @ 1130

Reg after repair

Tel : 6880 4888

Email : motor_survey @ axa.com.sg