



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

24 September 2018

HHTPClaims18-99

AXA Insurance Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

ACCIDENT INVOLVING SLZ 5561 K, SCU 2221 U, SDB 8817 A & SKT 2778 R ON 08/09/2018 ALONG CTE TOWARDS CITY AT ABOUT 1105 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SLZ 5561 K
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No : ZYX102113430
Policy No : 5087272209-01
Date of Accident : 08/09/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 950.00
2	10	Rear Bumper Clip	\$ 3.00	\$ 30.00
3	1	Rear Bumper (Lower)		\$ 650.00
4	1	Rear Bumper Tow Cover		\$ 55.00
5	1	Rear Reinforcement		\$ 520.00
				\$ 2,205.00
Less 20%				\$ (441.00)
				\$ 1,764.00

6 1 Reverse Sensor NETT \$ 200.00

To dismantle & change rear bumper, rear reinforcement, rear lower bumper, knocking & pull straight rear end panel and all area affected by accident. \$ 600.00

To perform wire checking. \$ 20.00

To dismantle & refit rear bumper sensor. \$ 60.00

To spray rear bumper, rear reinforcement and rear panel. \$ 600.00

\$ 3,244.00
\$ 227.08
\$ 3,471.08

Ayys



Authorised by Claims Dept
Mrs Tan @ 9639 9195

LKK Auto Consultants hence notify the F... of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No... is allowed
- Any... item(s) must be resurveyed and is subject to final approval from Insurance Company

As acknowledged by Repairer

Signature:
Date:

huahong.com.sg

GST Reg. No. 200900309M

Co. Reg. No. 200900309M

% GST
Total

NA2 LKK
7/5/19 1730
PIP
3 Days
CHECK ITEM PHOTOS
BEFORE PAINT PHOTOS