

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHD 3339M

DATE 11/9/2018 11:41

AVA

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (LH) <i>x repair</i>			\$ 1,294.70
	Rear Door Protector(LH) <i>x repair</i>			\$ 54.50
	Front Door (LH) <i>-</i>			\$ 1,344.50
	Front Door Outer Handle (LH) <i>x repair</i>			\$ 37.00
	Rear Wheel Hup-Cap (LH) <i>-</i>			\$ 145.00
	<i>Rear Fender (LH) x repair</i>			
	<i>Front Fender (LH) x repair</i>			
	SUB TOTAL			\$ 2,875.70
	LESS 20%			\$ 575.14
	DISCOUNTED TOTAL			\$ 2,300.56
	Rear Fender Advertisement Logo (LH) <i>-</i>			\$ 100.00 Nett
	Rear Door Advertisement Logo (LH) <i>-</i>			\$ 100.00 Nett
	Rear Door Tel No. Sticker (LH) <i>-</i>			\$ 10.00 Nett
	Front Door Coloured Comfort Logo (LH) <i>-</i>			\$ 75.00 Nett
	Front Door Advertisement Logo (LH) <i>-</i>			\$ 100.00 Nett
	Front Fender Advertisement Logo(LH) <i>-</i>			\$ 100.00 Nett
				\$ 485.00
	Labour Charge			
	Panel Beating			\$ 350.00 ²⁰⁰
	Spray Painting Charge-2 Fender & 2 Door			\$ 1,000.00 ⁸⁰⁰
	Tuff Kote			\$ 50.00 ²⁰
	Rear Wheel Alignment			\$ 120.00 ^X
	Transfer of Door			\$ 240.00 ⁵⁰
				\$ 1,760.00
	TOTAL LABOUR			
	ESTIMATE TOTAL			\$ 4,545.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal methods/careless is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kalinilley
11/9/18 1525h.
3 hrs
45
At the Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.