

**COMFORTDELGRO ENGINEERING PTE LTD**

VEHICLE NO : SHD 3339M

DATE 11/9/2018 11:41

*Ava*

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (LH) <i>Part</i>			\$ 1,294.70
	Rear Door Protector(LH) <i>x repair</i>			\$ 54.50
	Front Door (LH) <i>Part</i>			\$ 1,344.50
	Front Door Outer Handle (LH) <i>x repair</i>			\$ 37.00
	Rear Wheel Hup-Cap (LH) <i>Part</i>			\$ 145.00
	<i>Rear Fender (LH) x repair</i>			
	<i>Front Fender (LH) x repair</i>			
	<b>SUB TOTAL</b>			\$ 2,875.70
	<b>LESS 20%</b>			\$ 575.14
	<b>DISCOUNTED TOTAL</b>			\$ 2,300.56

Rear Fender Advertisement Logo (LH) <i>Part</i>	\$ 100.00	Nett
Rear Door Advertisement Logo (LH) <i>Part</i>	\$ 100.00	Nett
Rear Door Tel No. Sticker (LH) <i>Part</i>	\$ 10.00	Nett
Front Door Coloured Comfort Logo (LH) <i>Part</i>	\$ 75.00	Nett
Front Door Advertisement Logo (LH) <i>Part</i>	\$ 100.00	Nett
Front Fender Advertisement Logo(LH) <i>Part</i>	\$ 100.00	Nett
	<b>\$ 485.00</b>	

**Labour Charge**

- Panel Beating
- Spray Painting Charge-2 Fender & 2 Door
- Tuff Kote
- Rear Wheel Alignment
- Transfer of Door

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before spray painting  
 • To display damaged part at during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification is allowed  
 • Supplementary work must be resurveyed and is subject to final approval from Insurance Company

	\$ 200
	\$ 350.00
	\$ 1,000.00 <i>800</i>
	\$ 50.00 <i>20</i>
	\$ 120.00 <i>x 10</i>
	\$ 240.00 <i>50</i>

**TOTAL LABOUR** *Acknowledged by Repairer* **\$ 1,760.00**

**ESTIMATE TOTAL** **\$ 4,545.56**

*Kalvin 11/9/18*  
*11/9/18 1525h.*  
*3 P.*  
*US*  
*After Repair photo*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.