

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 7659D

DATE 10/9/2018 14:42

MAKE :

MODEL : HYUNDAI i40

4/Sum  
AXA

| Qty                                                                                                                                                                                                            | Parts Description/ Labour              | Type | Unit Price | Amount             |      |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|------|------------|--------------------|------|
|                                                                                                                                                                                                                | Front Bumper Cover ✓                   |      |            | \$ 544.50          |      |
|                                                                                                                                                                                                                | Front Bumper Grille (LH) ?             |      |            | \$ 41.60           |      |
|                                                                                                                                                                                                                | Front Bumper Bracket Top (LH) ?        |      |            | \$ 22.40           |      |
|                                                                                                                                                                                                                | Front Bumper Bracket (LH) ?            |      |            | \$ 24.60           |      |
|                                                                                                                                                                                                                | Headlamp (LH) ✕                        |      |            | \$ 1,388.00        |      |
|                                                                                                                                                                                                                | Front Fender (LH) ✓                    |      |            | \$ 566.30          |      |
|                                                                                                                                                                                                                | Front Fender Shield (LH) ?             |      |            | \$ 175.90          |      |
|                                                                                                                                                                                                                | Front Fender Retainer ✕                |      |            | \$ 24.60           |      |
|                                                                                                                                                                                                                | Front Wheel Rim (LH) ?                 |      |            | \$ 325.30          |      |
|                                                                                                                                                                                                                | Front Wheel Hub Cap (LH) ✓             |      |            | \$ 107.10          |      |
|                                                                                                                                                                                                                | Front Wheel Bearing ?                  |      |            | \$ 150.90          |      |
|                                                                                                                                                                                                                | Front Shock Absorber (Assy) (LH) ?     |      |            | \$ 342.20          |      |
|                                                                                                                                                                                                                | Front Shock Absorber Mounting (LH) ?   |      |            | \$ 108.80          |      |
|                                                                                                                                                                                                                | Front Drive Shaft (LH) ?               |      |            | \$ 1,030.80        |      |
|                                                                                                                                                                                                                | Stabilizer Bar ?                       |      |            | \$ 252.30          |      |
|                                                                                                                                                                                                                | Stabilizer Bar Bush (LH) ?             |      |            | \$ 16.40           |      |
|                                                                                                                                                                                                                | Stabilizer Bar Link ?                  |      |            | \$ 61.10           |      |
|                                                                                                                                                                                                                | Stabilizer Bracket ?                   |      |            | \$ 24.00           |      |
|                                                                                                                                                                                                                | Front Suspension Lower Arm (H) ?       |      |            | \$ 529.30          |      |
|                                                                                                                                                                                                                | Knuckle Arm (LH) ?                     |      |            | \$ 552.00          |      |
|                                                                                                                                                                                                                | <i>Front Bumper &amp; repair</i>       |      |            |                    |      |
|                                                                                                                                                                                                                | <b>SUB TOTAL</b>                       |      |            | <b>\$ 6,288.10</b> |      |
|                                                                                                                                                                                                                | <b>LESS 20%</b>                        |      |            | <b>\$ 1,257.62</b> |      |
|                                                                                                                                                                                                                | <b>DISCOUNTED TOTAL</b>                |      |            | <b>\$ 5,030.48</b> |      |
|                                                                                                                                                                                                                | Front Fender Advertisement Logo (LH) ✓ |      |            | \$ 100.00          | Nett |
|                                                                                                                                                                                                                | Frt Tyre (LH) ✓                        |      |            | \$ 216.00          | Nett |
|                                                                                                                                                                                                                | <b>Labour Charge</b>                   |      |            |                    |      |
|                                                                                                                                                                                                                | Panel Beating                          |      |            | \$ 316.00          |      |
|                                                                                                                                                                                                                | Spray Painting Charge                  |      |            | \$ 400.00          |      |
|                                                                                                                                                                                                                | Tuff Kote                              |      |            | \$ 250.00          | 600  |
|                                                                                                                                                                                                                | Wiring                                 |      |            | \$ 50.00           | 20   |
|                                                                                                                                                                                                                | Towing Fee                             |      |            | \$ 60.00           | ✕    |
|                                                                                                                                                                                                                | Remove/Refix Undercarriage (FRT)       |      |            | \$ 200.00          | 100? |
|                                                                                                                                                                                                                | FRT Wheel Alignment                    |      |            | \$ 120.00          | 60   |
|                                                                                                                                                                                                                | <b>TOTAL LABOUR</b>                    |      |            | <b>\$ 2,080.00</b> |      |
|                                                                                                                                                                                                                | <b>ESTIMATE TOTAL</b>                  |      |            | <b>\$ 7,426.48</b> |      |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |                                        |      |            |                    |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts requiring resurvey
- Parts prices are subject to confirmation
- Third party survey must be on a "no prejudice" basis
- No illegal modification to be carried out
- Supplementary survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: *[Signature]*  
Date: *11/9/18*