

Submitting

DOI:

ASSIGNMENT

13/9/2018

Date / Time:

11/9/2018

Registered in Merimon:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 802 C

Name of Insured:

Lim Teck

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

21/9/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Wong boon Teng Louis
86539094 (VL: YES / NO)

Driver Tel No.:

Claim No.:

17/18/18/18/02089

Policy No.:

217405016189

Make / Model:

V-7011

Place of Accident:

AYE C (WAS)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SFx 8830 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Motor
Edgevantage

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/9
11/18SFx 8830 X - on VAL 109 8326 / K9 : not 21/8/18
SLK 802 C - X

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

31/5/2019

Confirm with:

Mandy.

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or P 28, Ass. Lia: 0%

Repair Cost:

S\$ 10900.20

O&D involved in 3 p.c

Loss of Rental (LOR):

S\$

-

(

days)

O&D is the involved

Loss of Use (LOU):

S\$ 500.00

(3100 x 5

days)

Wkshop forward

Loss of Income (LOI):

S\$

-

(\$

x

days)

Original to Lpc

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

S\$

-

(e.g. Tow/Independent)

2) Report Format:

Legal Cost

S\$

-

3) Survey fee:

Total:

S\$ 11400.20

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payer 1:

S\$ 11400.20

Name 1:

Motor Edgevantage Pte Ltd

Payer 2: (Strike if N/A)

S\$

Name 2:

Payer 3: (Strike if N/A)

S\$

Name 3:

18/11/19

Revised

Val

REF: Lpc

7686C

ASSIGNMENT

From: Date: 13/09/18

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFX 8830X

at Workshop w/s: Motor Vantage

of 160 Bin Ming Drive # 03-01/02

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record) 11am @ owner waiting

Make of Veh: Mandy @ 87783280

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$115K

IDAC Accident Report: Consistent? Yes or No

GIA / FR Seen: Consistent? Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 2.8-2% 3 Val: Yes or No

CA / REV / REP. 1-24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Vin No: SFX 8830X Yr Regn: 12 Sep 2013

Type: ☒ M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: Rover Evoque

Make: Land Rover Range

Colour: white

Sp. Reading: 74141

Eng No:

C/No: SALVADA 80H798094

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: F: 235/55 R19

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: R/Bal: 6 mm

Rear: R/Bal: 6 mm

L/Bal: 6 mm

D.O.A. D.O.I. 13-09-18

Survey held at: w/s 11Am

Des. of Damages: Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
16/7/19	Confirm 2.8-2% \$10187.10 with 5 working day.

Date/Time, File Path(s):

1) ☐ : Prel. Report

2) ☐ : Final Report

Date/Time, File Return(s):

3)

Report Format:

Lump Sum / L.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey For:

Transportation

☐ S + R + M

☐ Other

☐ Other

TOTAL

cell - \$6003.91

37.1



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05/020897
Our ref: CC4/LPC18016588/Gwa3

Date: 17.09.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SFX 8830X

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.09.2018 at the premises of M/s MOTOR EDGEVANTAGE PTE LTD have the following to report:-

Workshop Estimate Amount	: S\$	15,440.00
Revised Estimate Amount	: S\$	11,438.00
"Check" Items Amount	: S\$	305.00
Total (Including Check Items)	: S\$	11,743.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7686C
Vehicle Details	
Vehicle No.:	SFX8830X
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	LAND ROVER
Vehicle Model:	RANGE ROVER EVOQUE 2.0 AT ABS 4WD HID SR
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	170413063123204PT
Chassis No.:	SALVA2AG8DH798094
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$56,106.00
Original Registration Date:	12 Sep 2013
First Registration Date:	12 Sep 2013
Transfer Count:	1
Actual ARF Paid:	\$72,991.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2023
PARF Rebate Amount:	\$51,093.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$77,100.00
COE Rebate Amount:	\$38,495.00
Total Rebate Amount:	\$89,588.00

The information contained herein is correct as at 14 Sep 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a man.

Licence Number: **S7927686C**
 Name: **TAN HWEE HOCK (CHEN WEIFU)**
 Birth Date: **20 Sep 1979**
 Issue Date: **22 Feb 2003**

Barcode: 000245776H

REPUBLIC OF SINGAPORE

IDENTITY CARD NO **S7927686C**


Portrait photo of a man.

Name: **TAN HWEE HOCK (CHEN WEIFU)**
 陈 韦 福
 Race: **CHINESE**
 Date of birth: **20-09-1979** Sex: **M**
 Country of birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Valid Until
Class 2B	Motorcycles not exceeding 200 cc	11 Jul 2001
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 3000 kilograms	20 Feb 2003

NP 429A

Barcode: Licence No: S7927686C

4659602

Barcode

NRIC No: **S7927686C**
 Date of issue: **17-12-2010**
 Address: **APT BLK 988A JURONG WEST STREET 93 #10-023 SINGAPORE 641988**

MOTOR EDGEVANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 & GST 201534758N
+65 6453 7683 client services@edgevantage.com www.edgevantage.com

To:

Mr Wilson Tan H H

SFX8830X, LAND ROVER, RANGE ROVER EVOQUE 2.0 AT ABS 4WD
HID SR

LONPAC INSURANCE BHD
300, Beach Road #17-04/07
The Concourse
Singapore 199555

Attn: Wilson Tan H H (96882479)

Work Order

Job No. : WJ1809093

Date : 13/09/2018

Time in : 13/09/2018 11:00

Time out :

T	Job Description	Operation	Quantity	UOM	Unit Price	Amt
Ad hoc						
P	LR tailgate Evoque / LFA	N/A	1.00	PCS	3,021.00	3,021.00 ✓
P	LR rear windscreen Evoque / MC	N/A	1.00	PCS	991.00	991.00 ✓
P	LR rear bumper Evoque pure / CC	N/A	1.00	PCS	2,463.00	2,463.00 1680. ✓
P	LR rear bumper reinforcement Evoque	N/A X NN	1.00	PCS	1,137.00	1,137.00 X
P	LR rear bumper heat shield Evoque / BT	N/A	1.00	PCS	115.00	115.00 /
P	LR parking aid Evoque / DM	N/A	1.00	PCS	190.00	190.00 /
S	LR rear bumper bracket LH X NN	N/A	1.00	PCS	62.00	62.00 X
S	LR rear bumper bracket RH X NN	N/A	1.00	PCS	62.00	62.00 X
P	LR exhaust muffler Evoque / BT	N/A	1.00	PCS	2,301.00	2,301.00 2100. ✓
P	LR rear wheel arch moulding LH / BT	N/A	1.00	PCS	181.00	181.00 185 ✓
P	LR rear fog lamp LH X CFA	N/A	1.00	PCS	251.00	251.00
P	LR "Land Rover" nameplate tailgate Evoque	N/A	1.00		34.00	34.00
P	LR "Evoque S14" name plate tailgate Evoque	N/A	1.00	PCS	158.00	158.00 /
P	LR "RANGE" name plate tailgate Evoque	N/A	1.00	PCS	147.00	147.00 /
P	LR "ROVER" name plate tailgate Evoque	N/A	1.00	PCS	147.00	147.00 /
S	To replace rear bumper, rear bumper reinforcement, rear parking sensor rh center, rear tailgate, lower moulding, Lh side outer wheel arch moulding	N/A	1.00		1,200.00	1,200.00 500 ✓
S	To putty respray rear bumper, rear tailgate	N/A	1.00		1,200.00	1,200.00 600 ✓

Continue on next page...

Approved by Repairs

Signature

Date

Approved by Repairs

Signature

Date

Approved by Repairs

Signature

Date

Rear Bumper cover LH & RH / LFA

MOTOR EDGEVANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 & GST 201534758N
+65 6453 7683 clientservices@edgevantage.com www.edgevantage.com

To:

Mr Wilson Tan H H

SFX8830X, LAND ROVER, RANGE ROVER EVOQUE 2.0 AT ABS 4WD
HID SR

LONPAC INSURANCE BHD
300, Beach Road #17-04/07
The Concourse
Singapore 199555

Attn: Wilson Tan H H (96882479)

Work Order

Job No. : WJ1810244

Date : 21/10/2018

Time In : 21/10/2018 09:07

Time out :

T	Job Description	Operation	Quantity	UOM	Unit Price	Amt
	Ad hoc					
S	Supplementary parts	N/A	1.00		0.00	0.00
S	LR Rear bumper moulding RH Evoque	N/A	1.00		285.00	285.00
S	LR Rear bumper moulding LH Evoque	N/A	1.00		285.00	285.00
S	LR rear wheel arch outer moulding LH Evoque	N/A	1.00		181.00	181.00

9519
10%: 8567.1
1620
10187.1

This is a computer generated Work Order . No Signature is required.

Subtotal	751.00
GST 7.0%	52.57
Total	803.57

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 11 September 2018 10:20 AM
To: assignments
Subject: FW: SFX8830X claiming against SLK802C

10:30 am @ 11/09/2018
person @ Mandy
vehicle not in

Best Regards,
Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 11 September 2018 9:33 AM
To: mandy.neo@edgevantage.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: SFX8830X claiming against SLK802C

WITHOUT PREJUDICE

Our Ref : 17/18/18/VP05/020897

Dear Mandy,

We shall appoint LKK Auto Consultants Pte Ltd to survey the vehicle and revert to you on Direct Settlement.

Aside to LKK- Attn:Catherine/Nivitha
Kindly proceed accordingly.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: mandy.neo@edgevantage.com [mailto:mandy.neo@edgevantage.com]
Sent: Monday, 10 September, 2018 10:29 AM
To: GERALD POH WEE BIN
Subject: SFX8830X claiming against SLK802C

Hi,

Attached for TP claim

please advise if direct settlement is possible.

160 sin ming # 03-01/02

sin ming autocity Singapore 575722

contact 87783280

Mandy Neo

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 19 September, 2018 11:30 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Vivian Lau (LKKAUTO)
Subject: RE: SFX8830X claiming against SLK802C

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

Kindly verify with the surveyor if the items marked ? are included in the revised estimate as the amount appear to be more than \$305.00

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 19 September, 2018 11:18 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; ONG LI LI; ericwoo; Vivian Lau (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: RE: SFX8830X claiming against SLK802C

WITHOUT PREJUDICE

LPC ref: 17/18/18/VP05/020897
LKK REF: CC4/LPC18016588/Gwa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SFX 8830X

We have not authorized repairs.

Enclosed for your perusal is:

- . TP estimated cost of repair
- . TP GIA report
- . Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

-----Original Message-----

From: mandy.neo@edgevantage.com [mailto:mandy.neo@edgevantage.com]

Sent: Monday, 10 September, 2018 10:29 AM

To: GERALD POH WEE BIN

Subject: SFX8830X claiming against SLK802C

Hi,

Attached for TP claim

please advise if direct settlement is possible.

160 sin ming # 03-01/02

sin ming autocity Singapore 575722

contact 87783280

Mandy Neo

This email has been checked for viruses by AVG.

<https://www.avg.com>

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 19 September, 2018 11:26 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: SFX8830X claiming against SLK802C
Attachments: 19092018112328.pdf

Categories: HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 19 September, 2018 11:18 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; ONG LI LI; ericwoo; Vivian Lau (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: RE: SFX8830X claiming against SLK802C

WITHOUT PREJUDICE

LPC ref: 17/18/18/VP05/020897
LKK REF: CC4/LPC18016588/Gwa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SFX 8830X

We have not authorized repairs.

Enclosed for your perusal is:
· TP estimated cost of repair
· TP GIA report
· Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler, you may contact the undersigned.

To: GERALD POH WEE BIN

Subject: SFX8830X claiming against SLK802C

Hi,

Attached for TP claim
please advise if direct settlement is possible.

160 sin ming # 03-01/02

sin ming autocity Singapore 575722

contact 87783280

Mandy Neo

This email has been checked for viruses by AVG.
<https://www.avg.com>

(PAYMENT BREAKDOWN)

Vehicle No	:	SFX 8830X (Insd veh)	Model	:	Land Rover Evoque 2.0
	:	SLK 802C (TP veh)			
Date of Accident	:	07.09.2018			

Global Sum Settlement	:	☐ YES	☐ NO
Liability	:	100 %	(Agreed/Assessed)

Repair Estimate	:	\$ 16,520.80	
Final Repair Cost	:	\$ 10,900.20	
Loss of Use	:	\$ 750	5 days at \$ 150 per day
Rental (if any)	:	\$	days at \$ (Incls of GST) per day
Others	:	\$	
	:	\$	
	:	\$	
	:	\$	
Final Settlement Sum	:	\$	

Remarks: _____

Payment Instruction: Payee's Breakdown			
1)	Repair bill	:	\$ 10,900.20
2)	loss of use	:	\$ 750.00
3)	LTA Search fee	:	\$ 7.45
4)		:	\$

[Mail](#)[Contacts](#)[Settings](#)[Back](#)[Compose](#)[Reply](#)[Reply all](#)[Forward](#)[Delete](#)[Move](#)[Print](#)[Mark](#)[More](#)**Inbox****1**

Drafts

Sent

Junk

Trash

spam

RE: SFX8830X clai...

Message 1 of 42

From **Vivian Lau (LKKAUTO)**
To **mandy.neo@edgevantage.com**
Cc **Thin Thin (LKKAUTO)** , **Admin A**
Date **Thu 15:00**

WITHOUT PREJUDICE

Dear Sir/Madam,

**ACCIDENT INVOLVING SFX 8830X & SLK 802C ON
07/09/2018**

We refer to the above matter

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at her DID 6841 8625.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

AUTHORIZATION TO ACT

I, Tan Hwee Hock ("the third party Claimant")

of Blk 988A Jurong West St 93 #10-623 (address),

owner of SFX8830X (vehicle no.)

hereby authorize Motor Edgevantage Pte Ltd ("The workshop")

to act for me with respect to my claim for repair costs and / or rental and / or loss of use

("claim") for my Vehicle No. SFX8830X that was damaged

pursuant to the accident which occurred on 07/09/2018 (date) along


Along AYE towards Tuas near Alexandra (location)

involving Vehicle No/s SLK802C ("The accident").

I further authorize the workshop to sign the discharge voucher on my behalf to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle/s is concerned.

Date this _____ day of _____ (month) 20 _____ (year)



Signed by "the third party claimant"



Signed by "the workshop"

MOTOR EDGEVANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 ☎ & GST 201534758N

+65 6453 7683 ✉ clientservices@edgevantage.com 🌐 www.edgevantage.com

Mr Wilson Tan H H

SFX8830X

LAND ROVER RANGE ROVER EVOQUE 2.0 AT ABS 4WD HID SR

LONPAC INSURANCE BHD

300, Beach Road #17-04/07

The Concourse

Singapore 199555

Tel: 96882479

Attn: Wilson Tan H H (96882479)

Invoice

Inv No. : INV19010065
Invoice Date : 08 Jan 2019
Ref : WJ1809093
Terms : COD
Mechanic : Yap Kim Thien
Mileage In : 76506 KM

#	Description	Qty	UOM	U/P	Amt
1	LR tailgate Evoque	1.00	PCS	2,718.90	2,718.90
2	LR rear windscreen Evoque	1.00	PCS	891.90	891.90
3	LR rear bumper Evoque pure	1.00	PCS	1,512.00	1,512.00
4	LR rear bumper heat shield Evoque	1.00	PCS	103.50	103.50
5	LR parking aid Evoque	1.00	PCS	171.00	171.00
6	LR exhaust muffler Evoque	1.00	PCS	1,890.00	1,890.00
7	LR rear fog lamp LH	1.00	PCS	166.50	166.50
8	LR "Land Rover" nameplate tailgate Evoque	1.00		30.60	30.60
9	LR "Evoque Si4" name plate tailgate Evoque	1.00	PCS	142.20	142.20
10	LR "RANGE" name plate tailgate Evoque	1.00	PCS	132.30	132.30
11	LR "ROVER" name plate tailgate Evoque	1.00	PCS	132.30	132.30
12	To replace rear bumper, rear bumper reinforcement , rear parking sensor rh center, rear tailgate, lower moulding, Lh side outer wheel arch moulding	1.00		500.00	500.00
13	To putty respray rear bumper , rear tailgate	1.00		600.00	600.00
14	To transfer tailgate components parts	1.00		60.00	60.00
15	To remove rear windscreen	1.00		100.00	100.00
16	To install rear windscreen UV film	1.00		180.00	180.00
17	To replace rear exhaust muffler Lh side	1.00		120.00	120.00
18	To check wiring including electrical module	1.00		60.00	60.00
19	Supplementary parts	1.00		0.00	0.00
20	LR Rear bumper moulding RH Evoque	1.00		256.50	256.50
21	LR Rear bumper moulding LH Evoque	1.00		256.50	256.50
22	LR Rear wheel arch outer moulding LH Evoque	1.00		162.90	162.90

This is a computer generated Invoice. No Signature is required.

Subtotal : S\$ 10,187.10
GST 7.0% : S\$ 713.10
Total : S\$ 10,900.20

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

W518 29093
R3m18090010

Print Date/Time : 08 Sep 2018 / 15:37:48

Receipt Date/Time : 08 Sep 2018 / 15:37:48

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180908-000672

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SLK802C

As at 07 Sep 2018/00:19:40

Insurance Co: LONPAC INSURANCE BHD

1 Insurance Enquiry - SLK802C
Enquiry Fee
20180908153445960577

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

xxxxxxxxxxxx0415 Credit Card:
Visa/MasterCard

Total			7.45
Cash Change			0.00
Tendered Amount			7.45
Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

WJ1809093
R2m1809010

Print Date/Time : 08 Sep 2018 / 15:37:48

Receipt Date/Time : 08 Sep 2018 / 15:37:48

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180908-000672

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SLK802C

As at 07 Sep 2018/00:19:40

Insurance Co: LONPAC INSURANCE BHD

1 Insurance Enquiry - SLK802C

Enquiry Fee

20180908153445980577

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

xxxxxxxxxxxx0415

Credit Card:

Visa/MasterCard

Total			7.45
Cash Change			0.00
Tendered Amount			7.45
Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18016588/Gwa3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 17-07-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 802C	Veh. Inspected	SFX 8830X	
Policy No.	Z17VP05016189	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020897	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	11/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	LAND ROVER RANGE	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	SALVA2AG8DH798094	Colour	WHITE	
Odometer	74141	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	MICHELIN	6 mm	
L/H Front Tyre	235/55 R19	MICHELIN	6 mm	
R/H Rear Tyre	235/55 R19	MICHELIN	6 mm	
L/H Rear Tyre	235/55 R19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/09/2018	Inspection Date	13/09/2018	
Survey held at	MOTOR EDGEVANTAGE PTE LTD 160 SIN MING DRIVE #03-02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFX 8830X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LR TAILGATE EVOQUE	CRACKED	3,021.00	3,021.00
1	LR REAR WINDSCREEN EVOQUE	NECESSARY	991.00	991.00
1	LR REAR BUMPER EVOQUE PURE	DEFORMED	2,463.00	1,680.00
1	LR REAR BUMPER REINFORCEMENT EVOQUE	NOT NECESSARY	1,137.00	-
1	LR REAR BUMPER HEAT SHIELD EVOQUE	BENT	115.00	115.00
1	LR PARKING AID EVOQUE	DAMAGED	190.00	190.00
1	LR REAR BUMPER BRACKET LH	NOT NECESSARY	62.00	-
1	LR REAR BUMPER BRACKET RH	NOT NECESSARY	62.00	-
1	LR EXHAUST MUFFLER EVOQUE	BENT	2,301.00	2,100.00
1	LR REAR WHEEL ARCH MOULDING LH EVOQUE	NOT NECESSARY	181.00	-
1	LR REAR FOG LAMP LH	CRACKED	251.00	185.00
1	LR 'LAND ROVER' NAMEPLATE TAILGATE EVOQUE	NECESSARY	34.00	34.00
1	LR 'EVOQUE SI4' NAME PLATE TAILGATE EVOQUE	NECESSARY	158.00	158.00
1	LR 'RANGE' NAME PLATE TAILGATE EVOQUE	NECESSARY	147.00	147.00
1	LR 'ROVER' NAME PLATE TAILGATE EVOQUE	NECESSARY	147.00	147.00
1	LR REAR BUMPER MOULDING RH EVOQUE (ADDITIONAL)	MISSING	285.00	285.00
1	LR REAR BUMPER MOULDING LH EVOQUE (ADDITIONAL)	MISSING	285.00	285.00
1	LR REAR WHEEL ARCH OUTER MOULDING LH EVOQUE (ADDITIONAL)	DEFORMED	181.00	181.00
	LESS 10% DISCOUNT		-	-951.90
			12,011.00	8,567.10
LABOUR				
	TO REPLACE REAR BUMPER ,REAR BUMPER REINFORCEMENT,REAR PARKING SENSOR RH CENTER ,REAR TAILGATE ,LOWER MOULDING ,LH SIDE OUTER WHEEL ARCH MOULDING .		1,200.00	500.00
	TO PUTTY RESPRAY REAR BUMPER ,REAR TAILGATE.		1,200.00	600.00
	TO TRANSFER TAILGATE COMPONENTS PARTS.		300.00	60.00
	TO REMOVE REAR WINDSCREEN.		400.00	100.00
	TO INSTALL REAR WINDSCREEN UV FILM.		280.00	180.00

Report Ref No. CC4/LPC18016588/Gwa3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE REAR EXHAUST MUFFLER LH SIDE.		400.00	120.00
	TO CHECK WIRING INCLUDING ELECTRICAL MODULE.		400.00	60.00
			4,180.00	1,620.00
GRAND TOTAL			16,191.00	10,187.10
RECOMMENDED COST OF REPAIRS				10,187.10

Report Ref No. CC4/LPC18016588/Gwa3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.