



MOTOR EDGEVANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 & GST 201534758N

+65 6453 7683 clientservices@edgevantage.com www.edgevantage.com

To:

Mr Wilson Tan H H

SFX8830X, LAND ROVER, RANGE ROVER EVOQUE 2.0 AT ABS 4WD
HID SR

LONPAC INSURANCE BHD
300, Beach Road #17-04/07
The Concourse
Singapore 199555

Attn: Wilson Tan H H (96882479)

Work Order

Job No. : WJ1809093

Date : 08/09/2018

Time in : 08/09/2018 15:17

Time out :

T	Job Description	Operation	Quantity	UOM	Unit Price	Amt
Ad hoc						
P	LR tailgate Evoque	N/A	1.00	PCS	3,021.00	3,021.00
P	LR rear windscreen Evoque	N/A	1.00	PCS	991.00	991.00
P	LR rear bumper Evoque pure	N/A	1.00	PCS	2,463.00	2,463.00
P	LR rear bumper reinforcement Evoque	N/A	1.00	PCS	1,137.00	1,137.00
P	LR rear bumper heat shield Evoque	N/A	1.00	PCS	115.00	115.00
P	LR parking aid Evoque	N/A	1.00	PCS	190.00	190.00
S	LR rear bumper bracket LH	N/A	1.00	PCS	62.00	62.00
S	LR rear bumper bracket RH	N/A	1.00	PCS	62.00	62.00
P	LR exhaust muffler Evoque	N/A	1.00	PCS	2,301.00	2,301.00
P	LR rear wheel arch moulding LH Evoque	N/A	1.00	PCS	181.00	181.00
P	LR rear fog lamp LH	N/A	1.00	PCS	251.00	251.00
P	LR "Land Rover" nameplate tailgate Evoque	N/A	1.00		34.00	34.00
P	LR "Evoque SI4" name plate tailgate Evoque	N/A	1.00	PCS	158.00	158.00
P	LR "RANGE" name plate tailgate Evoque	N/A	1.00	PCS	147.00	147.00
P	LR "ROVER" name plate tailgate Evoque	N/A	1.00	PCS	147.00	147.00
S	To replace rear bumper, rear bumper reinforcement , rear parking sensor rh center, rear tailgate, lower moulding, Lh side outer wheel arch moulding	N/A	1.00		1,200.00	1,200.00

Continue on next page...



MOTOR EDGEVANTAGE PTE LTD

🏠 160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 📠 & GST 201534758N

☎ +65 6453 7683 ✉ clientservices@edgevantage.com 🌐 www.edgevantage.com

To:

Mr Wilson Tan H H

SFX8830X, LAND ROVER, RANGE ROVER EVOQUE 2.0 AT ABS 4WD
HID SR

LONPAC INSURANCE BHD
300, Beach Road #17-04/07
The Concourse
Singapore 199555

Attn: Wilson Tan H H (96882479)

Work Order

Job No. : WJ1809093

Date : 08/09/2018

Time in : 08/09/2018 15:17

Time out :

T	Job Description	Operation	Quantity	UOM	Unit Price	Amt
S	To putty respray rear bumper , rear tailgate	N/A	1.00		1,200.00	1,200.00
S	To transfer tailgate components parts	N/A	1.00		300.00	300.00
S	To remove rear windscreen	N/A	1.00		400.00	400.00
S	To install rear windscreen UV film	N/A	1.00		280.00	280.00
S	To replace rear exhaust muffler Lh side	N/A	1.00		400.00	400.00
S	To check wiring including electrical module	N/A	1.00		400.00	400.00

Remarks:

3rd party claim

Notice (8): Undefined variable: EXCLUSIVE_TAX [**APP/View/Elements/pdf/footer2/motoredgevantage/wor**

Notice (8): Undefined variable: DEEMED_SUPPLY [**APP/View/Elements/pdf/footer2/motoredgevantage/wc**

Notice (8): Undefined variable: INCLUSIVE_TAX [**APP/View/Elements/pdf/footer2/motoredgevantage/wor**

This is a computer generated Work Order. No Signature is required.

Total

16,520.80