

22/03/2002

ASS. REC. BY:

REF:

CS/CTI18016616/Ncd302

Special Instruction:

Surveyor
Maimen

Haz

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

12/09/2018 10:32am

Estimated Cost:

Bill to:

OD / TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 1884J

Insured:

XE 2161U

at Workshop m/s

Jas Auto

Tel:

9672 9559

of

6D Mundai Estate #03-02

Policy No:

DmCVSN1659601802

Claim No:

SNM18D04338C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

12/09/2018 11:26am

Person Contacted:

Gibson

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 1884J - x

XE 2161U - x

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Sep 2018		12 Sep 2018 10:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TOPZONE E&C PTE LTD, Co. Reg. No.: 1997005622		
Main Claimant:	PAULINE ANG SIEW NGOH, ID: S1430617Z		
Vehicle Reg. No.:	SLK1884J	Date of Loss:	05/09/2018 17:00 - :59
Claim Type:	TP / SNM18D04338C02	Policy/Cover Note No.:	DMCVSN1659601802 (Comprehensive)
Vehicle Reg. No. (Insured):	XE2161U	Policy No. (Claimant):	5097162854
		Excess:	S\$0.00
Repairer:	Jas Auto Services (HQ) 6D Mandai Estate, #03-02 M-Space, 729938 Mandai - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/09/2018]		
Driver/Custodian (Insured):	MARIAPPAN SURESH (40 / Male), NRIC: G7464553X, Tel: +6590069772		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0617Z
Vehicle Details	
Vehicle No.:	SLK1884J
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2NR8713097
Chassis No.:	NSP1707070322
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,798.00
Original Registration Date:	09 Jan 2017
First Registration Date:	09 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$8,798.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2027
PARF Rebate Amount:	\$6,598.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$38,704.00
Total Rebate Amount:	\$45,302.00

The information contained herein is correct as at 28 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/09/2018 12:51
Date Of Accident	05/09/2018 17:15
Exact Location Of Accident	18 SUNGEI KADUT AVE SINGAPORE 729489
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLK1884J
Insured/Policyholder	
Name Of Registered Owner	PAULINE ANG SIEW NGOH
NRIC No	S1430617Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92431217
Alternative Phone No	OTHERS-92431217
Vehicle Particulars	
Manufacturer	TOYOTA
Model	SIENTA-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097162854
Cover Note Number	
Driver	
Name of Driver	PAULINE ANG SIEW NGOH
NRIC No	S1430617Z
Date Of Birth	07/09/1960
Occupation	OUTDOOR
Date Of Driving Pass	06/12/1978
Driving Experience	39 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92431217
Fax Number	
Contact Number	OTHERS-92431217
EMail Address	NOEMAIL

Address	BLK. 775 WOODLANDS CRESCENT #10-10
Postcode	730775
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 05.09.18, AT AROUND 5.15PM, MY VEHICLE SLK1884J WAS PARKED WITHIN THE PREMISES OF 18 SUNGEI KADUT AVE SINGAPORE 729489. UPON HEARING A LOUD BANG, I WALK TOWARDS THE CARPARK AND REALISED VEHICLE XE2161U REVERSED AND HIT ONTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	DEVICE FAULTY
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE2161U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MARIAPPAN SURESH
NRIC/Passport Number	G7464553X
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



進友汽車服務有限公司
CYS Automobile Services Pte Ltd
38 Woodlands Industrial Park East 1
Reporting Centre
Name: Singapore 757700
Tel: 6219 2098 (lines) Fax: 6219 2096
NIC/FIN No: 88703072

Sketch Plan #2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 5/9/18, AT AROUND 5.15PM, MY VEHICLE SLK 1884J WAS PARKED WITHIN THE PREMISES OF 18 SUNGEI KADUT AVE S(729489). UPON HEARING A LOUD BANG, I WALK TOWARDS THE CARPARK AND REALISED VEHICLE XE 2161U REVERSED AND HIT ONTO THE REAR PORTION OF MY VEHICLE.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

©AIBMC SketchPlanForm_V3


 進友或汽車服務私人有限公司
 CYS Automobile Services Pte Ltd
 38 Woodlands Industrial Park East 1
 Reporting Centre
 Singapore 757706
 Name: [Redacted]
 Tel: 6219 2098 (Direct) / Fax: 6219 2096
 NRIC/FIN No.: 88063079

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



JAS Auto Services

6D Mandai Estate #03-02 M-Space, Singapore 729938
 Tel: 6453 1967 (5 lines). Fax: 6457 3091
 53255447K

M/s China Taiping(Singapore) Insurance Pte Ltd
 3 Anson Rd #16-00 Springleaf Tower
 Singapore 079909

Date : 13-Sep-18

Fax: 6222 1033



Attn: Motor Claim Dept

Re: Accident on 05/09/2017. Between SLK1884J. AND XE2161U. (Your Insured)

Dear Sir;

We are pleased to submit herewith the estimate for repairs to the above mentioned accident damaged vehicle **Third Party Claim.**

<u>Parts</u>	<u>Price</u>
1pc Bootlid	\$1,879.70 / DD
1pc Bootlid lock	\$51.50 X SVC
1pc Bootlid logo	\$70.70 / nec
1pc Bootlid plastic garnish(below logo)	\$217.31 X SVC
1pc Bootlid windscreen	\$1,530.20 / CRA
1pc Bootlid windscreen sealant	\$160.00 / NEC
1pc Bootlid windscreen seal	\$80.00 / nec
1pc Bootlid absorber(\$110 each)	\$220.00 ? X SVC
1pc Rear inner door trim RH	\$253.10 ? / DEF
1pc Rear inner door trim LH	\$253.10 ? X N/N
1pc Rear bumper	\$497.60 ? X SVC
1pc Rear bumper retainer LH/RH(\$48 each)	\$96.00 ? X SVC
1pc Rear bumper garnish	\$275.00 ? X SVC
1pc Rear bumper garnish LH/RH(\$150 each)	\$300.00 ? X SVC
1pc Taillamp LH/RH(\$340 each)	\$680.00 ? X SVC
1pc Taillamp Panel LH/RH(\$250 each)	\$500.00 ? X SVC
1pc Rear end panel	\$580.00 ? X SVC
1pc Rear end panel garnish	\$205.66 ? X SVC
1pc Spare tyre panel	\$927.00 ? X SVC
1pc Spare tyre board	\$357.20 ? X SVC
1pc Rear wiper with cover	\$129.85 ? X SVC
1pc Rear wiper motor	\$325.80 ? X SVC
1pc Rear right Fender <i>upper garnish</i>	\$653.20 ? X SVC
1pc Rear "in car" camera	\$345.20 ? X SVC
	Total: \$10,588.12
	Less: 25% \$2,117.62
	\$7,941.09

\$4,367

Labour

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts.

To putty & respray paint on the relevant repaired areas.

To rust proof affected areas where necessary.

\$1,200.00 400
\$1,200.00 400
\$90.00 40

Parts & Labour Total: \$10,431.09


Your Faithfully,



JAS Auto Services

Handwritten signature and date: 8/1/18

NAZ LKK
13/9/18
PIP
5 DAYS
BEFORE PAINT PHOTO



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PARTS \$ 4,367
LESS 25% \$ 3,275.25
LABOUR \$ 840.00
TOTAL \$ 4,115.25 / 4 REPAIR DAYS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Sep 2018		12 Sep 2018 10:32 Edit Adj Rpt	S\$4,115.25 Edit Estimates	S\$4,115.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TOPZONE E&C PTE LTD, Co. Reg. No.: 199700562Z								
Main Claimant:	PAULINE ANG SIEW NGOH, ID: S1430617Z								
Vehicle Reg. No.:	SLK1884J	Date of Loss: 05/09/2018 17:00 - :59 [19 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM18D04338C02	Policy/Cover Note No.: DMCVSN1659601802 (Comprehensive)							
Vehicle Reg. No. (Insured):	XE2161U	Policy No. (Claimant): 5097162854							
		Excess: S\$0.00							
Repairer:	Jas Auto Services (HQ) 6D Mandai Estate, #03-02 M-Space, 729938 Mandai - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 21/09/2018]								
Driver/Custodian (Insured):	MARIAPPAN SURESH (40 / Male), NRIC: G7464553X, Tel: +6590069772 Email: NOEMAIL								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK1884J (SNM18D04338C02)
[XE2161U]
TP
PAULINE ANG SIEW NGOH
Sep 5 2018 5:00PM
[TOPZONE E&C PTE LTD]
Jas Auto Services

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports								1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)				Thumbnail	Print		
1	06/09/18 12:59	Accident Statement					Load HTM		
Photos/Images								3 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)				Thumbnail	Print		
1	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
2	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
3	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
4	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
5	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
6	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
7	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
8	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
9	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
10	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
11	06/09/18 12:59	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print		
1	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
2	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
3	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
4	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
5	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
6	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
7	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
8	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
9	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
10	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
11	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
12	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
13	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
14	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
15	13/09/18 08:49	General View					Load JPG	<input checked="" type="checkbox"/>	
16	28/12/18 12:05	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>	
17	28/12/18 12:05	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>	
18	28/12/18 12:05	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
19	28/12/18 12:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
20	28/12/18 12:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
21	28/12/18 12:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
22	28/12/18 12:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
23	28/12/18 12:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
24	28/12/18 12:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
25	28/12/18 12:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
26	20/03/19 18:23	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
27	20/03/19 18:23	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
28	20/03/19 18:23	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
29	20/03/19 18:23	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/09/18 10:31	PRS	Load PDF	
2	12/09/18 10:31	TP GIA	Load PDF	
3	12/09/18 10:32	OI GIA	Load PDF	

No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	06/09/18 12:57	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	06/09/18 12:57	Sketch Plan #2 <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	06/09/18 12:59	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	06/09/18 12:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	06/09/18 12:57	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	06/09/18 12:57	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118016616/NCD3E2
Date: 29/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1659601802
Claimant Vehicle No :	SLK1884J	Insured Vehicle No :	XE2161U
Date of Loss:	05/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04338C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK1884J	Engine No:	2NR8713097
Make & Model:	TOYOTA SIENTA, 1.5 X CVT (A)	Chassis No:	NSP1707070322
Reg. Date:	09/01/2017 (Man. Year: 2016)	Odometer:	40064 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,941.09	3,275.25	4,665.84	58.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	840.00	1,650.00	66.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,431.09	4,115.25	6,315.84	60.55

INSPECTION

Date of Assignment:	12/09/2018		
Date Inspected:	12/09/2018	Inspected At:	Jas Auto Services (HQ) 6D Mandai Estate, #03-02 M-Space Singapore 729938
Estimated Period of Repair:	4.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2019)	
Parts: M1-MPV	TOYOTA SIENNA 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLK1884J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,879.70 FL	*1,600.00 FL
2	1		*BOOTLID LOCK	Serviceable	51.50 FL	*- FL
3	1		*BOOTLID LOGO	Necessary	70.70 FL	*70.70 FL
4	1		*BOOTLID PLASTIC GARNISH (BELOW LOGO)	Serviceable	217.31 FL	*- FL
5	1		*BOOTLID WINDSCREEN	Cracked	1,530.20 FL	*1,300.00 FL
6	1		*BOOTLID WINDSCREEN SEALANT	Necessary	160.00 FL	*70.00 FL
7	1		*BOOTLID WINDSCREEN SEAL	Necessary	80.00 FL	*80.00 FL
8	2		*BOOTLID ABSORBER	Serviceable	220.00 FL	*- FL
9	1		*REAR INNER DOOR TRIM RH	Deformed	253.10 FL	*253.10 FL
10	1		*REAR INNER DOOR TRIM LH	Not Necessary	253.10 FL	*- FL
11	1		*REAR BUMPER	Serviceable	497.60 FL	*- FL
12	2		*REAR BUMPER RETAINER LH/RH	Serviceable	96.00 FL	*- FL
13	1		*REAR BUMPER GARNISH	Serviceable	275.00 FL	*- FL
14	2		*REAR BUMPER GARNISH LH/RH	Serviceable	300.00 FL	*- FL
15	1		*TAILLAMP LH/RH	O/S Cracked/ N/S Serviceable	680.00 FL	*340.00 FL
16	2		*TAILLAMP PANEL LH/RH	Serviceable	500.00 FL	*- FL
17	1		*REAR END PANEL	Serviceable	580.00 FL	*- FL
18	1		*REAR END PANEL GARNISH	Serviceable	205.66 FL	*- FL
19	1		*SPARE TYRE PANEL	Serviceable	927.00 FL	*- FL
20	1		*SPARE TYRE BOARD	Serviceable	357.20 FL	*- FL
21	1		*REAR WIPER WITH COVER	Serviceable	129.85 FL	*- FL
22	1		*REAR WIPER MOTOR	Serviceable	325.80 FL	*- FL
23	1		*REAR RIGHT FENDER UPPER GARNISH	Cracked	653.20 FL	*653.20 FL
24	1		*REAR IN CAR CAMERA	Serviceable	345.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **10,588.12** **4,367.00**
 - List Item Discount on L Items 25.00/25.00% (S\$) 2,647.03 1,091.75

Total Parts (S\$) 7,941.09 3,275.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS, ALL RELEVANT ATTACHMENTS, FITTINGS TO COMMENCE REPAIRS, REPLACE THE DAMAGED PARTS, REINSTALL & REALIGN ALL NECESSARY PARTS	New	1,200.00	400.00
2	TO PUTTY & RESPRAY PAINT ON THE RELEVANT REPAIRED AREAS	New	1,200.00	400.00
3	TO RUST PROOF AFFECTED AREAS WHERE NECESSARY	New	90.00	40.00
Gross Labour Cost (S\$)			2,490.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >