

INSURANCE

Sukha

CC 4AIG160

21222 Mins

LCK
EAC

Surveyor

M

DCH

ASSIGNMENT

21/11/16

Date/Time

8/11/16

Registered in Mauritius

10/11/16

Pre-assign / CCL / FTE

SLA 44307

Claim No.

4835770939567

Policy No.

210045468

Make / Model

Kia Forte K3-1.6 1M

Place of Accident

Chip Road From Exon way

OH/GIA REPORT

YES / NO

TP/GIA REPORT

YES / NO

Insured Liability

%

Final ?

Yes / No

Insured Vehicle No.

Hong cat Park

Name of Insured

Insured Tel No.

HP

96628032

Excess Sec II : \$5

Is driver the owner?

YES / NO

Nature of Accident

If NO, Driver Name / Age

Driver Tel No.

(V/L: YES / NO)

86V8P76M

INSRS

WSP

Tel

Liability

RMKS

EM-1

INSRS

WSP

Tel

Liability

RMKS

INSRS

WSP

Tel

Liability

RMKS

INSRS

WSP

Tel

Liability

RMKS

Date/Time

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

11/11/16

RECEIVED 03 OCT 2018

STAGE

DATE / PIC

Non-Reporting in (1st)

Non-Reporting in (2nd)

Non-Reporting in (Final)

Notification in (if non-pickup)

Call Off

After call in to OH

Documentation Check List

Handler

Typed

Notification in (if non-pickup)

After call in to OH

Authorization To Act

Reimburse Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

FIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

PRELIMINARY ADVICE

Date/Time

Sent By

FINALIZATION

Date/Time

Confirm with

Confirm by

Repair Cost

\$5

days

Reduction

%

Email

Call

FINAL SETTLEMENT

Date/Time

Confirm with

Email

Call

Final Liability

%

100

Agreed / Assessed

BOLA SN No

27

If NO at B 28, Att 1a

Repair Cost

\$5

5885.00

Days of Rental (LOR)

\$5

406.60

4 days

X 95.00 + GST

Days of Use (LOU)

\$5

5

1 day

days

Days of Income (LOI)

\$5

5

1 day

days

LOI only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

Tick only one

GIA/LTA Search

\$5

5.25

Medical

\$5

Disbursement

\$5

Legal Cost

\$5

e.g. Tow/Independent

Total

\$5

6296.95

Global Sum \$5

FINAL PAYMENT

Date/Time

Confirm with

Email

Call

Payee 1

\$5

6296.95

Name 1

EM-1 Auto Pte Ltd

Payee 2 (Strike if N/A)

\$5

Name 2

Payee 3 (Strike if N/A)

\$5

Name 3

COPY SENT

11/11/16

1) Claim status: Normal/Reject/Private Settle

2) Report Format

3) Survey Fee



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL 6256 3561 FAX 6256 4315

Reg No 199607198R GST Reg No 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref CC4/AIG16021222/M1wg3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date 08-11-2016		
		Code AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 4430T	Veh. Inspected	SGV 8876M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	08/11/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/11/2016	Inspection Date	08/11/2016	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

796.20	58.20	1,000.00
596.50	66.40	1,200.00
586.20	30.00	30.00
	123.60	60.00
	60.20	60.00
	123.80	80.00
		60.00
	156.00	60.00
	40.00	80.00
	69.20	
	544.20	
	40.00	
	119.20	
	30.00	
	495.00	
	92.60	
	272.40	
	30.00	
	92.40	
	20.00	

Total List Price	\$	1,978.90
Discount		30%
List Price	\$	1,385.23
Total Nett Price	\$	3,078.40
Discount		10%
Nett Price	\$	2,770.56
Total Special Nett	\$	980.00
Total Labour	\$	2,550.00
Grand Total	\$	7,685.79
Discount 20%		20%
Lump Sum	\$	6,148.63

Columns	List Price
A	Nett Price
C	Special Nett
D	Labour
E	

File NO
4809

Vehicle No.
SGV 8876M

Model
NISSAN LATIO

Rental 7 days

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SGV 8876M
Vehicle Model : NISSAN LATIO
Accident Date : 07.11.2016
Original Reg Date : 28.06.2007

Date : 07.11.2016
Chassis : JN1BAAC11Z0005616
TP Ins. AIG

ESTIMATE

LIST ITEM

1	1 pc	Boot Lid	✓	✓	796.20	L
2	1 pc	Rear Bumper	✓	✓	596.50	L
3	1 pc	End Panel	✓	✓	586.20	L
4	1 pc	Rear Fender RH	X	X	1,052.70	L 1.978 90
					3,031.60	
					Less 30%	909.48
					2,122.12	

1	1 pc	Boot Lid Badge	✓	✓	58.20	N
2	1 pc	Boot Lid Emblem 'Latio'	✓	✓	66.40	N
3	1 set	Boot Lid Insulator Clips	✓	✓	30.00	N
4	1 pc	Boot Lid Inner Lock	✓	✓	123.60	N
5	1 pc	Boot Lid Lock Catch	✓	✓	60.20	N
6	1 pc	Boot Lid Weatherstrip	✓	✓	123.80	N
7	2 pcs	Boot Lid Hinges	RX	X	69.70	N
8	2 pcs	Rear Bumper Side Retainers	✓ Dig	✓	78.00	N
9	1 set	Rear Bumper Clips	✓ UH	✓	50.00	N 40
10	1 pc	Rear Bumper Sponge	✓	✓	69.20	N
11	2 pcs	Rear Bumper Dampers	✓ RX	✓	76.20	N
12	2 pcs	Taillamps	✓ CRA	✓	272.10	N CRA
13	2 pcs	Taillamps Inner Sealer	X	X	30.00	N NN
14	2 set	Taillamp Clips	✓ UH	✓	25.00	N 40
15	2 pcs	Taillamp Bottom Retainers	X	X	42.00	N NN
16	1 pc	End Panel Top Trim	✓	✓	119.20	N
17	1 set	End Panel Top Trim Clips	✓	✓	30.00	N
18	1 pc	Spare Tyre Panel Top Board	✓	✓	495.00	N
19	1 pc	Rear Key Antenna Sensor	✓	✓	92.60	N
20	2 pcs	Rear Fender Inner Trims	✓ RH-TN, LH-TN	✓	272.40	N
					C/F	5,171.12

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SGV 8876M

B/F

5,171.12

Nett Item

1	2 set	Rear Fender Inner Trims Clips	✓	30.00	60.00	N 30
2	2 pcs	Rear Fender Inner Shields	✓	46.20	92.40	N
3	2 set	Rear Fender Inner Shields Clips	✓	20.00	40.00	N 20
4	1 pc	Rear Windscreen Moulding	X		156.20	N
5	1 pc	Rear Windscreen Inner Seal	X		50.00	N
6	1 pc	Rear Exhaust Silencer	✓		569.20	N DD
7	2 pcs	Rear Exhaust Moutings	X	38.00	76.00	N NN
8	1 pc	Rear Exhaust Gasket	✓		46.00	N

4,138.80

Less 10% 413.88

3,724.92

Special Nett

1	1 pc	Rear Number Plate with Holder	X	20	20.00	SN
2	1 pc	Reverse Sensor	✓	220	250.00	SN
3	1 pc	Body Panel Joint Sealant	✓	40	120.00	SN
4	1 pc	Rear Windscreen Sealant	X		60.00	SN NN
5	1 pc	Rear Bumper Spoiler	✓	219	750.00	SN
6	1 pc	Breakdown Sign	✓	219	150.00	SN

Labour charge

Panel Beating	1000	1,800.00
Spray painting	1200	1,500.00
Check Wiring	30	60.00
Anti rust	60	100.00
Towing fees.	60	70.00
Remove and install rear windscreen.	—	140.00
Remove and install carpet and seat.	60	120.00
Remove and install reverse sensor	60	90.00
Remove and install rear exhaust.	207	120.00

\$ 11,237.04

Not Authorize
 4/5 Repair after part price
 7 days
 8/10/2018 @ 10:00 AM

7 days



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 6080H

Vehicle Details

Vehicle No.: SGV8876M
Vehicle to be Exported: Yes
Intended De-registration Date: 08 Nov 2016
Vehicle Make: NISSAN
Vehicle Model: LATIO 1.5L A
Primary Colour: Grey
Manufacturing Year: 2007
Engine No.: HR15172998A
Chassis No.: JN1BAAC11Z0005616
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$13,304.00
Original Registration Date: 28 Jun 2007 ✓
First Registration Date: 28 Jun 2007
Transfer Count: 0
Actual ARF Paid: \$14,635.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Jun 2017
PARF Rebate Amount: \$7,317.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2017 ✓
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$15,591.00
COE Rebate Amount: \$991.00
Total Rebate Amount: \$8,308.00 ✓

The information contained herein is correct as at 07 Nov 2016

OK

settle your car **LOANS, INSURANCE & LEGAL PAPERS**

sgCarMart can help you FOR FREE

Contact Us Now!

sgCARMART
CONNECT

Username / Email Add

password

Login

f

Connect

 • Sign Up New Account
 • Forgot Password

Nissan Latio

Price Range

2007

Transmission

Vehicle Type

x

Search

 Advanced
 Search

Home » Used Cars » Direct Owners » Nissan Latio 1.5A

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Nissan Latio 1.5A

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Contact Seller

Add to Compare

Add to Shortlist

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$14,000**

Reg Date 27-Jun-2007 ✓

Mileage -

Transmission Auto

Engine Cap 1,498 cc

Road Tax \$684 /yr

 Power 80.0 kW (107 bhp)
 View specs of the Nissan Latio Sedan (2005-2011)

 Features 1.5L DOHC Engine, 4 Speed Auto Transmission, ABS,
 Dual SRS Airbags, Keyless Start/Stop/Entry,
 Immobilizer, Auto Headlights, Climatic Aircon Controls.

 Accessories Sports Rims, Leather Seats, Keyless Entry, Knockdown
 Rear Seats, Reverse Sensors, Armrest.

 Description Well Maintained Interior, Good Condition! Excellent
 Engine And Smooth Transmission. Low Fuel
 Consumption, Large Cabin And Spacious Car Boot. Feel
 Free To Call Owner For Viewing.

COE \$16,181

OMV \$13,283

 Depreciation N.A.
 Use the Depreciation Calculator to get estimated figure

No. of Owners -

Type of Veh Mid-Sized Sedan

Category PARF Car, Direct Owner Sale

Availability Available

DIRECT OWNER

Like (824)

Posted on: 19-Oct-2016 | Last Updated on: 26-Oct-2016

Tags: Nissan Latio, 2007 Nissan Latio, Nissan, Latio, Used Nissan

Upfront Payment

» more Financial Info

Transfer Fee \$11

Down Payment \$4,200 (change) Maximum 70% Loan

1st Instalment \$1,424

Total Upfront Payment \$5,635 (excluding insurance)

Estimates based on 70% loan at 2.99% interest rate. Check with seller for exact figure.

Items for Nissan Latio

» View All


 Keyless Transponder
 \$50

 Vehicle Servicing
 Package
 From \$88


Preferred Viewing Area

Seller Information

Contact Person(s) James Loo

Contact No. 98482797

Enquiry Contact Seller

USEFUL FORMS

• Indemnity form • Sales agreement

• Receipt • Hand-over form

• M01

 Instructions on how to complete a seller to end-
 consumer deal

 Once buyer & seller confirms the deal,
 sgCarMart Connect will provide **100% FREE**
 settlement on **Loans, Insurance &**
Paperwork for both parties. Call 6744 3540.


Useful Services


 Make sure of this car condition
 with STA Evaluation.

Vehicle Evaluation


 Find out the market value for your car.
 Get a free Car Valuation.

Free Valuation

Compare

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG NO : 201316380R

Vehicle Number : SGV 8876M
Vehicle Model : NISSAN LATIO
Accident Date : 07.11.2016
Original Reg Date : 28.06.2007

Date : 07.11.2016
Chassis : JN1BAAC11Z0005616
TP Ins. : AIG

ESTIMATE

LIST ITEM

1	1 pc	Boot Lid	44	✓	796.20	L
2	1 pc	Rear Bumper	44	✓	596.50	L
3	1 pc	End Panel	44	✓	586.20	L
4	1 pc	Rear Fender RH	R	✓	1,052.70	L
					3,031.60	
					Less 30%	909.48
					2,122.12	
1	1 pc	Boot Lid Badge	44	✓	58.20	N
2	1 pc	Boot Lid Emblem "Latio"	44	✓	66.40	N
3	1 set	Boot Lid Insulator Clips	44	✓	30.00	N
4	1 pc	Boot Lid Inner Lock	44	✓	123.60	N
5	1 pc	Boot Lid Lock Catch	44	✓	60.20	N
6	1 pc	Boot Lid Weatherstrip	44	✓	123.80	N
7	2 pcs	Boot Lid Hinges	R	✓	139.40	N
8	2 pcs	Rear Bumper Side Retainers	44	✓	156.00	N
9	1 set	Rear Bumper Clips	44	✓	50.00	N 40
10	1 pc	Rear Bumper Sponge	44	✓	69.20	N
11	2 pcs	Rear Bumper Dampers	R	✓	152.40	N
12	2 pcs	Taillamps	272.10	?	544.20	N
13	2 pcs	Taillamps Inner Sealer	30.00	?	60.00	N
14	2 set	Taillamp Clips	44	✓	50.00	N 40
15	2 pcs	Taillamp Bottom Retainers	42.00	✓	84.00	N
16	1 pc	End Panel Top Trim	44	✓	119.20	N
17	1 set	End Panel Top Trim Clips	44	✓	30.00	N
18	1 pc	Spare Tyre Panel Top Board	44	✓	495.00	N
19	1 pc	Rear Key Antenna Sensor	44	✓	92.60	N
20	2 pcs	Rear Fender Inner Trims	272.40	✓	544.80	N
					C/F	5,171.12

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG NO : 201316380R

Vehicle No : SGV 8876M

B/F

5,171.12

Nett Item

1	2 set	Rear Fender Inner Trims Clips	30.00	✓ 60.00	N 36
2	2 pcs	Rear Fender Inner Shields	46.20	✓ 92.40	N
3	2 set	Rear Fender Inner Shields Clips	20.00	✓ 40.00	N 70
4	1 pc	Rear Windscreen Moulding		✓ 156.20	N
5	1 pc	Rear Windscreen Inner Seal		✓ 50.00	N
6	1 pc	Rear Exhaust Silencer		✓ 569.20	N
7	2 pcs	Rear Exhaust Moutings	38.00	✓ 76.00	N
8	1 pc	Rear Exhaust Gasket		✓ 46.00	N

4,138.80

Less 10% 413.88

3,724.92

Special Nett

1	1 pc	Rear Number Plate with Holder	20	✓ 20.00	SN
2	1 pc	Reverse Sensor	220	250.00	SN
3	1 pc	Body Panel Joint Sealant	20	120.00	SN
4	1 pc	Rear Windscreen Sealant		✓ 60.00	SN
5	1 pc	Rear Bumper Spoiler	215	600 750.00	SN
6	1 pc	Breakdown Sign	215	20 150.00	SN

Labour charge

Panel Beating	1000	1,800.00
Spray painting	1200	1,500.00
Check Wiring	30	60.00
Anti rust	60	100.00
Towing fees	60	70.00
Remove and install rear windscreen.		✓ 140.00
Remove and install carpet and seat	60	120.00
Remove and install reverse sensor	60	90.00
Remove and install rear exhaust	207	120.00

S 11,237.04

4/6/24 Authorize
 4/5 Repair after part place
 7w days
 3/4/24 @ 4/4/24 (MIA)



LKK
Consultants
Pte Ltd

20000101-25 PAVILION INDUSTRIAL PARK, SINGAPORE 480055 TEL : (65) 62560001 FAX : (65) 62564437

Our Ref: CC4/AIG16021222/M1wg3

16 November 2016

Heng Kok Peak
Blk 152 Gangsa Road
#17-311
Singapore 670152

Dear Sir/Madam,

ACCIDENT INVOLVING SLA 4430T AND SGV 8876M ON 07/11/2016

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Goh Huey Chyi ("the third party claimant")
of _____ (address),
owner of SGV 8876 M (vehicle no.) hereby authorize
EM-1 Auto Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SGV 8876 M that was
damaged pursuant to the accident which occurred on 7/11/16 (date) along
Boon Lay Way Slip Rd to Yuan Ching Rd (location)
involving vehicle no/s SLA 4430 T ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 7 day of Nov (month) 20 16 (year)



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, EM-1 Auto PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 5885.00 (repair costs), S\$ 406.60 (loss of use/rental) S\$ 5-35 (search fees) for vehicle no. SGV8876M that was damaged pursuant to the accident which occurred on 7/11/16 (date) along Boon Lay Way Slip Rd to Yuan Ching Rd (location) involving vehicle no/s SLA4430T.

This is pursuant to the inspection conducted on 8/11/16 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Goh Huey Chyi ("third party claimant") of vehicle no. SGV8876M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGV8876M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 3 day of Oct (month) 20 16 (year)



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

TAX INVOICE

M/S GOH HUEY CHYI

Invoice No : 18/00243/4809TP

Date : 02-Oct-2018

AIG Asia Pacific Insurance Pte. Ltd.

Motor Claim Department

AIG Building

78 Shenton Way

#07-16 Singapore 079120

Date of Accident : 07-Nov-2016
Our Client's Vehicle Number : SGV 8876M
Vehicle Make / Model : NISSAN LATIO
Your Insurer : SLA 4430T

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (Recommended by LKK Mr Ma)	5,500.00	385.00	5,885.00 SR

SGD (Five Thousand Eight Hundred Eighty-Five only)

GRAND TOTAL

5,885.00

Subject to 7% GST

385.00



Authorised Signature and Company Stamp



友立旅遊服務私人有限公司
UNIQUE TOURIST SERVICE (PTE) LTD

1, Rochor Centre, # 02-574,
Singapore 0718.
Tel: 2927656
Fax: (65) 2939720
STPB LIC TA076

GST Reg. No.: M2-0019671-6

Mr Soh Meng Wai
Blk 257 Jurong East Street 24
05-399
Singapore 600257

20, Sin Ming Lane,
#08-51, Midview City
Singapore 573968
Tel: 6292 7656

TAX INVOICE

NO. WP21091

Singapore, 12 11.2016 19

DATE	PARTICULARS		\$	cts
	Rental of one unit Toyota Corolla Altis 1.6 Auto Registration no. SGX 6848 Y self driven as from 07.11.2016 to 11.11.2016.			
	4 days at \$95.00 per day	\$	380.00	
	Add GST at 7%	\$	380.00	
	Amount Due	\$	26.60	
		\$	406.60	
	(SIN DOLLARS: FOUR HUNDRED SIX AND SIXTY CENTS ONLY)			
	Standard Rated Supplies:\$	380.00		
	Total Amount of GST:\$	26.60		

AUTHORISED SIGNATURE



UNIQUE TOURIST SERVICE (PTE) LTD.

APT. BLK 1, ROCHOR ROAD, #02-574, ROCHOR CENTRE, SINGAPORE 180001

TEL: 6292 7656 FAX: 6293 9720 EMAIL: unigtour@singnet.com.sg

COMPANY REG NO: 197401067R

GST REG NO: M2-0019671-6

THIS IS NOT A TAX INVOICE

20, Sin Ming Lane,
#08-51, Midview **RENTAL AGREEMENT**
Singapore 573968
Tel: 6292 7656 RA No. 20721

VEHICLE NO

SGX 6848Y

MAKE/MODEL

TOYOTA COROLLA ALTIS

NAME OF HIRER

MIR. SOH MENG WAI

ADDRESS

BLK 257 JURONG EAST ST 24

05-399

SINGAPORE

600257

OFFICE TEL

RES TEL

HP

97934366

NAMED DRIVER

MIR. SOH MENG WAI

OCCUPATION

NATIONALITY

SPORLEB

PASSPORT / NRIC

S6844181A

DATE OF BIRTH

11/11/68

DRIVING LIC NO

S6844181A

PLACE OF ISSUE

SPORLE

DATE PASS/EXPIRY

02/04/94

ADDITIONAL NAMED DRIVER

ADDRESS

SINGAPORE

OFFICE TEL

RES TEL

HP

OCCUPATION

NATIONALITY

PASSPORT / NRIC

DATE OF BIRTH

DRIVING LIC NO

PLACE OF ISSUE

DATE PASS/EXPIRY

BY INITIATING MARK "X" HIRER AGREE TO PAY THE FOLLOWINGS

A. COLLISION DAMAGE WAIVER (CDW) AT \$ PER DAY / WEEK / MONTH "X"

B. SURCHARGE OF \$ FOR USE IN MALAYSIA FROM

TO "X"

• THE HIRER IS RESPONSIBLE FOR ANY DAMAGES UP TO THE EXTENT OF TOTAL LOSS OF CAR, LOSS OF INCOME AND COST OF RECOVERY OF VEHICLE IF THE CAR IS DRIVEN INTO MALAYSIA WITHOUT PRIOR CONSENT FROM THE COMPANY.

COMPULSORY EXCESS, DOLLAR

\$ 1200/-

NOTE:

HIRER IS LIABLE FOR ALL PARKING & TRAFFIC VIOLATIONS.

YOUR ATTENTION IS DRAWN TO TERMS & CONDITIONS

PRINTED OVERLEAF.

FOR SINGAPORE DRIVE ONLY

DATE:

SIGNATURE OF HIRER

DATE OUT

07/11/16

TIME OUT

11:50 AM

PETROL OUT

E

1/4

1/2

3/4

(1)

DATE IN

11/11/16

TIME IN

13:45

PETROL IN

E

1/4

1/2

3/4

F

RENTAL RATES:

MONTHLY @ \$

WEEKLY @ \$

DAILY 4 @ \$

C.D.W. FEE

PETROL CONSUMPTION

DELIVERY CHARGE

COLLECTION CHARGE

SUB-TOTAL

GST @ 7%

RENTAL DEPOSIT

TOTAL:

DEPOSIT REFUND

PAYMENT BY: BILL / CO / CREDIT CARD / CASH

ATTENDED BY:

OF UNIQUE TOURIST SERVICE (PTE) LTD.

DECLARATION

I HEREBY DECLARE THAT NO MOTOR ACCIDENT HAD OCCURED DURING MY HIRE OF YOUR MOTOR VEHICLE AS STATED IN THE ABOVE MENTIONED SCHEDULE * OR TO ANY SUBSTITUTED VEHICLE AS STATED IN THE MEMORANDUM DATED.

REPLACEMENT VEHICLE NO:

1. ON TIME

2. ON TIME

3. ON TIME

DATE:

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Ms. Karen

Fax: 6457 5776

SJV 887611

Print Date/Time : 07 Nov 2016 / 14:59:00

Receipt Date/Time : 07 Nov 2016 / 11:04:13

Tax Invoice/Receipt

Receipt No. : ITNET-00000-161107-000516

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLA4430T As at 07 Nov 2016/07:50:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLA4430T Enquiry Fee 20161107110221599323	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Total Before Rounding		5.00	0.35	5.35
Rounding Difference				0.00
Total Amount Payable				5.35
Paid By				
	20161107110236622	Direct Debit: eNETS Debit (Internet Banking)		5.35
Total				5.35
Cash Change				0.00
Tendered Amount				5.35
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2016 Edit Reg		08 Nov 2016 00:00 Edit Adj Rpt	\$45,500.00 Edit Estimates	\$45,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HENG KOK PEAK , ID: S1744477H								
Main Claimant:	GOH HUEY CHYI , ID: S6916080H								
Vehicle Reg. No.:	SGV8876M	Date of Loss:	07/11/2016 07:00 - :59 [112 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4835770939SG	Policy/Cover Note No.:	2100454685 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLA4430T	Policy No. (Claimant):	2100213386-06000						
		Excess:							
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 01/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (27/09/2018): Report Send Back Alerts - SGV8876M (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGV8876M (4835770939SG)
[SLA4430T]
TP
GOH HUEY CHYI
Nov 7 2016 7:55AM
[HENG KOK PEAK]
Em-1 Auto Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
------------------	---------------	--------------------	--------------	--------------	--

Letters/Correspondences					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit		
2	05/04/18 08:50	Insurer Offer Letter/DV [Offer superseded on 2018/09/27]	1	Load HTM		

Assessment Reports					1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	11/11/16 10:06	Accident Statement From: SC - Reg. No: SLA4430T, Claimant: HENG KOK PEAK	1	Load HTM		

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	10/11/16 17:03	Odometer Reading	1	Load JPG	☒	
2	10/11/16 17:03	Chassis Number	1	Load JPG	☒	
3	10/11/16 17:03	General View	1	Load JPG	☒	
4	10/11/16 17:03	General View	1	Load JPG	☒	
5	10/11/16 17:03	General View	1	Load JPG	☒	
6	10/11/16 17:03	General View	1	Load JPG	☒	
7	10/11/16 17:03	General View	1	Load JPG	☒	
8	10/11/16 17:03	General View	1	Load JPG	☒	
9	10/11/16 17:03	General View	1	Load JPG	☒	
10	10/11/16 17:03	General View	1	Load JPG	☒	
11	10/11/16 17:03	General View	1	Load JPG	☒	
12	10/11/16 17:03	General View	1	Load JPG	☒	
13	10/11/16 17:03	General View	1	Load JPG	☒	
14	10/11/16 17:03	General View	1	Load JPG	☒	
15	10/11/16 17:03	General View	1	Load JPG	☒	
16	10/11/16 17:03	General View	1	Load JPG	☒	
17	10/11/16 17:03	General View	1	Load JPG	☒	
18	10/11/16 17:03	General View	1	Load JPG	☒	
19	10/11/16 17:03	General View	1	Load JPG	☒	
20	10/11/16 17:03	General View	1	Load JPG	☒	
21	10/11/16 17:03	General View	1	Load JPG	☒	
22	10/11/16 17:03	General View	1	Load JPG	☒	
23	10/11/16 17:03	General View	1	Load JPG	☒	
24	10/11/16 17:03	General View	1	Load JPG	☒	
25	10/11/16 17:03	General View	1	Load JPG	☒	
26	10/11/16 17:03	General View	1	Load JPG	☒	
27	10/11/16 17:03	General View	1	Load JPG	☒	

Documentation				
---------------	--	--	--	--

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/11/16 17:02	TP ESTIMATE - MARKED	 Load PDF	
2	10/11/16 17:02	TP GIA REPORT	 Load PDF	
3	10/11/16 17:02	EMAIL FROM AIG DD 08112016	 Load PDF	
4	10/11/16 17:02	NOTIFICATION FROM WORKSHOP	 Load PDF	
5	02/04/18 10:09	Email to AIG to temporary close filr SGV 8876M 2.4.18	 Load PDF	
6	03/04/18 10:27	LETTER TO OI	 Load PDF	
7	17/10/18 15:01	WORKSHOP INVOICE	 Load PDF	
8	17/10/18 15:01	AUTHORISATION TO ACT FORM	 Load PDF	
9	17/10/18 15:01	Release Voucher	 Load PDF	
10	17/10/18 15:01	RENTAL RECEIPT	 Load PDF	
11	17/10/18 15:01	LTA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLA4430T (Insd veh)	Model:	NISSAN LATIO 1.5 L (A)
	SGV8876M (TP veh)		
Date of Accident:	07/11/2016		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	12,023.63
Final Repair Cost	:	\$	5,885.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	406.60 4 days
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,296.95

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Em-1 Auto Pte Ltd	:	\$ 6,296.95
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

17 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG16021222/M1WB3Q2

Date: 17/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100454685
Claimant Vehicle No : SGV8876M **Insured Vehicle No :** SLA4430T
 Date of Loss: 07/11/2016 Nature of Claim: TP Claim No: 4835770939SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV8876M**
 Make & Model: NISSAN LATIO, 1.5 L (A) Engine No: HR1517299SA
 Reg. Date: 28/06/2007 (Man. Year: 2007) Chassis No: JN1BAAC11Z0005616
 Colour: Dark Brown Odometer: 117654 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Toyo 8 mm Rear Left Side: Toyo 8 mm
 Front Right Side: Toyo 8 mm Rear Right Side: Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,247.04	5,094.21	2,152.83	29.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	2,550.00	1,440.00	36.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,237.04	7,644.21	3,592.83	31.97
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	11,237.04	5,500.00	5,737.04	51.05
+ GST 7.00/7.00% (S\$)	786.59	385.00	401.59	51.05
Nett Amount (S\$)	12,023.63	5,885.00	6,138.63	51.05
+ Car Rental (4.0 x S\$95.00/day + 7.00% GST) (S\$)		406.60		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		6,296.95		

INSPECTION

Date of Assignment: 08/11/2016
 Date Inspected: 08/11/2016 Inspected At:

Em-1 Auto Pte Ltd (HQ)
 Blk 8 Sin Ming Industrial Estate Sector C,

#01-68
Singapore 575643

Estimated Period of Repair: 7.0 days

Adjuster: MA CHIN FOOK

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	796.20 FL	*796.20 FL
2	1		*REAR BUMPER	Deformed	596.50 FL	*596.50 FL
3	1		*END PANEL	Dented	586.20 FL	*586.20 FL
4	1		*REAR FENDER RH	Repair	1,052.70 FL	*- FL
5	1		*BOOT LID BADGE	Necessary	58.20 FN	*58.20 FN
6	1		*BOOT LID EMBLEM LATIO	Necessary	66.40 FN	*66.40 FN
7	1		*SET BOOT LID INSULATOR CLIPS	Necessary	30.00 FN	*30.00 FN
8	1		*BOOT LID INNER LOCK	Bent	123.60 FN	*123.60 FN
9	1		*BOOT LID LOCK CATCH	Bent	60.20 FN	*60.20 FN
10	1		*BOOT LID WEATHERSTRIP	Distorted	123.80 FN	*123.80 FN
11	2		*BOOT LID HINGES	Repair	139.40 FN	*- FN
12	2		*REAR BUMPER SIDE RETAINERS	Distorted	156.00 FN	*156.00 FN
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FN	*40.00 FN
14	1		*REAR BUMPER SPONGE	Torn	69.20 FN	*69.20 FN
15	2		*REAR BUMPER DAMPERS	Repair	152.40 FN	*- FN
16	2		*TAILLAMPS	Cracked	544.20 FN	*544.20 FN
17	2		*TAILLAMPS INNER SEALER	Not Necessary	60.00 FN	*- FN
18	2		*SET TAILLAMP CLIPS	Necessary	50.00 FN	*40.00 FN
19	2		*TAILLAMP BOTTOM RETAINERS	Not Necessary	84.00 FN	*- FN
20	1		*END PANEL TOP TRIM	Torn	119.20 FN	*119.20 FN
21	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FN	*30.00 FN
22	1		*SPARE TYRE PANEL TOP BOARD	Distorted	495.00 FN	*495.00 FN
23	1		*REAR KEY ANTENNA SENSOR	Shorted	92.60 FN	*92.60 FN
24	1		*REAR FENDER INNER TRIMS	O/S Torn / N/S Not Necessary	544.80 FN	*272.40 FN
25	2		*SET REAR FENDER INNER TRIMS CLIPS	Necessary	60.00 FN	*30.00 FN
26	1		*REAR FENDER INNER SHIELDS	N/S Cracked / O/S Not Necessary	92.40 FN	*46.20 FN
27	2		*SET REAR FENDER INNER SHIELDS CLIPS	Necessary	40.00 FN	*20.00 FN
28	1		*REAR WINDSCREEN MOULDING	Not Necessary	156.20 FN	*- FN
29	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FN	*- FN
30	1		*REAR EXHAUST SILENCER	Dented	569.20 FN	*569.20 FN
31	2		*REAR EXHAUST MOUNTINGS	Not Necessary	76.00 FN	*- FN
32	1		*REAR EXHAUST GASKET	Necessary	46.00 FN	*46.00 FN
33	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	70.00 FS	*- FS
34	1		*REVERSE SENSOR	Shorted	250.00 FS	*220.00 FS
35	1		*BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS
36	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
37	1		*REAR BUMPER SPOILER	Distorted	750.00 FS	*600.00 FS
38	1		*BREAKDOWN SIGN	Distorted	150.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,570.40	5,991.10
- List Item Discount on L Items 30.00/30.00% (\$\$)	909.48	593.67
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	413.88	303.22
Total Parts (\$\$)	7,247.04	5,094.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,000.00
2	SPRAY PAINTING	New	1,500.00	1,200.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	100.00	60.00
5	TOWING FEES	New	70.00	60.00
6	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	0.00
7	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
8	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	60.00
9	REMOVE AND INSTALL REAR EXHAUST	New	120.00	80.00
Gross Labour Cost (S\$)			3,990.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLA4430T (Insd veh)	Model:	NISSAN LATIO 1.5 L (A)
	SGV8876M (TP veh)		
Date of Accident:	07/11/2016		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	12,023.63
Final Repair Cost	:	\$	5,885.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	406.60 4 days
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,296.95

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Em-1 Auto Pte Ltd	:	\$ 6,296.95
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

17 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))