

22/02/2003

ASS. REC. BY:

REF:

CS/CTL18016806/Gthb

Special Instruction:

Surveyor:

Mehmet

ASSIGNMENT (Office)

Date/Time:

14/09/2018 954am

From (Person):

Catharine Thia

of

CTL

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured:

SFU 7102L

To Inspect Vehicle No:

SJE 41L

Tel:

8128 9800

at Workshop m/s

Trans Bunkers

of

Subi Close

Policy No:

DMHCSN1745931700

Claim No:

SNM18D0439500.

Sum Insured:

Excess:

D.O.A.

09/09/2018

Make of Veh:
(Client's Record)

18/09/2018 @ 430pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'up'

Jess

Vehicle IN / OUT

Date/Time:

14/09/2018 1027am

Person Contacted:

Date/Time

Action/Instruction (✓) Estimate

SJE 41L - X

SFU 7102L - X

Vehicle not sent in for repair

Submit preli report

Reference

XRL

REF:

CTI

5353D

ASSIGNMENT

From:

Date:

18092018

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJE 411

at Workshop m/s

Trans Eumkars

of

5 ubi close

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

4:30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJE 411

Yr Regn:

23 Mar 2018

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 2

C.C.

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

16490

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MM 6DL 2S AATW 361533

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

185 / 65 R15

R:

11

BS / ☒ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

18-09-18

Survey held at

w/s

4:30pm

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 25 JAN 2019

Date/Time. File Pass to?



☒ Preli. Report



☐ Final Report

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) -

Days Of Repair: 6

Resurvey No. of Trip: -

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Sep 2018		14 Sep 2018 09:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S LIHENG ONG, Co. Reg. No.: 53365692C		
Main Claimant:	VANESSE LIM YU RUI, ID: 58305353D		
Vehicle Reg. No.:	SJE41L	Date of Loss:	09/09/2018 15:00 - :59
Claim Type:	TP / SNM18D04395C02	Policy/Cover Note No.:	DMHCSN1745931700 (Comprehensive)
Vehicle Reg. No. (Insured):	SFU7102L	Policy No. (Claimant):	3100027483
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]		
Driver/Custodian (Insured):	NG SIEW GEK (54 / Female), NRIC: S1596958Z, Tel: +6597973853		
Adj Asg. Remarks:	EST \$15,032.16, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: jess.francis@eurokars.com.sg
Sent: Thursday, 24 January 2019 10:17 PM
To: Denise Tay (LKKAuto)
Cc: ronald.yap@eurokars.com.sg
Subject: RE: CHINA TAIPING - SFU7102L / TEPL - SJE41L / DOA SEP 9, 2018 / REQ FOR SURVEY - SNM18D04395C02/2

Dear Denise,

The liability for this case is not clear. We normally do not practice repairing cars if the liability is not clear.

Sincerely,

Jess Francis Carlos
Insurance Claims Executive
Trans Eurokars Pte Ltd
5 Ubi Close
Singapore 408605
Email: jess.francis@eurokars.com.sg
HP no.: 8128 9802

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: 04 January 2019 3:42 PM
To: Jess Francis Amurao Carlos <jess.francis@eurokars.com.sg>
Subject: RE: CHINA TAIPING - SFU7102L / TEPL - SJE41L / DOA SEP 9, 2018 / REQ FOR SURVEY - SNM18D04395C02/2

Dear Jess,

Can check for me this case, vehicle has sent in for repair? If yes please forward finalization

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jess.francis@eurokars.com.sg <jess.francis@eurokars.com.sg>
Sent: Friday, 14 September 2018 10:27 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: lucas.lee@sg.cntaiping.com
Subject: RE: CHINA TAIPING - SFU7102L / TEPL - SJE41L / DOA SEP 9, 2018 / REQ FOR SURVEY - SNM18D04395C02/2

Hi LKK Team,

Kindly arrange the survey to our client's car on Sep 18, 2018 at 4:30 pm.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 15:52
Date Of Accident	09/09/2018 15:00
Exact Location Of Accident	CHOA CHU KANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE41L
Insured/Policyholder	
Name Of Registered Owner	VANESSE LIM YU RUI
NRIC No	S8305353D
Email Address	VANESSE_LIM@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98424641
Alternative Phone No	OTHERS-98424641

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	3100027483

Driver

Name of Driver	VANESSE LIM YU RUI
NRIC No	S8305353D
Date Of Birth	09/02/1983
Occupation	INDOOR
Date Of Driving Pass	18/03/2003
Driving Experience	15 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98424641
Fax Number	
Contact Number	OTHERS-98424641
Email Address	VANESSE_LIM@YAHOO.COM.SG

Address	BLK 403 BUKIT BATOK WEST AVENUE 7 #14-20
Postcode	650403
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


REFER SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFU7102L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG SIEW GEK
NRIC/Passport Number	S1596958Z
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and discuss and transfer such personal information to all insurer(s) who have insured vehicle(s) involving in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sit outside of Singapore, for one or more of the above Purposes.

10/9/2018 2.45pm

10-9-2018

Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policy holder) / Date & Time Witnessed by Reporting Centre Personnel

SKETCH PLAN



Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am at the Junction of Chua Chu Kang Road & Chua Chu Kang Way.
The traffic light at the Junction turns green, the first vehicle at the traffic light
is going very slow so I decided to change lane. After I am on the right
lane, I suddenly ^{felt} ~~heard~~ another car no. SFU 7102L, bang / hit me on the
left side of my car.

Declaration

I/We declare the foregoing particulars are true in every respect.

Signature 10/9/2018 2.45pm

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policy holder) / Date & Time Witness's Signature (if any) / Date & Time

10-9-2018
Signature

➤ Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	5353D

Vehicle Details

Vehicle No.:	SJE41L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5 AT STANDARD PLUS EU6
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	P520445452
Chassis No.:	MM6DL2SAAJW361533
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$14,656.00
Original Registration Date:	23 Mar 2018
First Registration Date:	23 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2028
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	22 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$36,130.00
Total Rebate Amount:	\$39,880.00

The information contained herein is correct as at 19 Sep 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8305353D



Name
VANESSE LIM YU RUI

林于芮

Race
CHINESE

Date of Birth
09-02-1988

Sex
F

Country of Birth
SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE



Vanessa Lim Yu Rui

09 FEB 1988

18 MAR 2003



4853922



NR ID No. S8305353D



Date of Issue
26-03-2013

Address
APT BLK 403 BUKIT BATOK WEST AVENUE 7
#14-20
SINGAPORE 650408

YOU ARE PERMITTED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 1 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2400 Kilograms

18 Mar 2003

Vanessa Lim Yu Rui

NR 428A



ORIGINAL

Co. Reg. No. 201009404M

Hotline: (65) 6419-3000 Fax: (65) 6415-3723

If you do not receive your Certificate of Insurance and policy documents **within 30 days** from the inception date stated on this cover note, please contact AIG immediately.



Cover Note: 3100027483

The following risk described in the Schedule below is hereby covered subject to the applicable terms and conditions of AIG's policy issued to the Policyholder. The Policy to which this Cover Note relates to is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Schedule (please circle where applicable)

Policyholder/Insured	VANEISE LIM YU RUI	
Age Condition	1	All Age
	2	30 Years Old and Above
	3	35 Years Old and Above
	4	40 Years Old and Above
	5	Named Driver Basis
Policy Type		Comprehensive
		Third Party Fire and Theft
		Third Party only
Policy Period	23/03/2018 to 23/03/2020 23:59	
Registration Number		
Make/Model	MAZDA 2 STANDARD SEDAN PLUS	
CC/Tonnage	1496	
Engine Number	P520445452	
Chassis Number	MM6DL2PAJW361533	
Year of Registration	2018	
Hire Purchase Company	HONG LEONG FINANCE	
Excess	SS	600 (Section VII Both)
	SS	100 (Windscreen excess)

Please note that acceptance of the risk is subject to our final acceptance and the terms and conditions applicable to the policy. For important notes and applicable laws and regulations, please refer to the reverse page.

Issued in Singapore

20/03/2018

Date of issuance

Authorised Representative

Agent Code

Manik Bucha, Personal Insurance

This insurance is underwritten by AIG Asia Pacific Insurance Pte. Ltd.

503599-190



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-139469
Date of Request: 10/09/2018

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
12 Sungei Kadut Ave
Singapore 729648

Dear Sir/Madam,

Enquiry Date: 10/09/2018
Enquiry By: Chan Yuan Huey
TP Vehicle No: SFU7102L
Accident Date: 09/09/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SFU7102L	China Taiping Insurance (Singapore) Pte. Ltd.	30/06/2018-12/05/2019	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-139469
Date of Request: 10/09/2018

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
12 Sungei Kadut Ave
Singapore 729648

Dear Sir/Madam,

Enquiry Date 10/09/2018
Enquiry By Chan Yuan Huey
TP Vehicle No. SFU7102L
Accident Date 09/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Survey - 18, 2018 @ 4:30 PM -

DOA 09-09-18
SJE4102L



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



(UB)

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Vanesse Lim Yu Rui ADDRESS : 403 Bukit Batok West Avenue 7 #14-20 Singapore 650403 TEL : 98424641		WIP : 28099 EXCESS : DATE : 10-Sep-18	
VEH NO :	SJE41L	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	MM6DL2SAAJW361533	MILEAGE :	116,490	TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.:	23-Mar-18	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	FRONT DOOR LHS X repair	1	MDAY0-59-02XF		\$ 1,109.30
2	FASTENER, FRONT DOOR X	1	MGHP9-58-762A		\$ 3.00
3	GROMMET, FRONT DOOR X	10	MGJ6A-58-975		\$ 28.00
4	FASTENER, FRONT DOOR X	1	MGD7A-50-EA1		\$ 3.00
5	CLIP, FRONT DOOR X	1	MGS1D-58-315A		\$ 2.20
6	GROMMET, FRONT DOOR X	1	M9991-00-503		\$ 3.60
7	REAR DOOR LHS / DO	1	MDAY0-73-02XE		\$ 825.40
8	FASTENER, REAR DOOR /	4	MGS1M-58-762		\$ 48.80
9	FASTENER, REAR DOOR /	1	MGHP9-58-762A		\$ 3.00
10	FASTENER, REAR DOOR /	1	MD09L-73-762		\$ 12.60
11	FASTENER, REAR DOOR /	1	MGD7A-50-EA1		\$ 3.00
12	GROMMET, REAR DOOR /	7	MGJ6A-58-975		\$ 19.60
13	CLIP, REAR DOOR /	1	MGS1D-58-315A		\$ 2.20
14	GROMMET, REAR DOOR /	1	M9991-00-503		\$ 3.60
15	STRIPE SIDE LHS, FRONT DOOR /	1	MDB2M-50-8W1		\$ 23.70
16	STRIPE SIDE LHS, REAR DOOR /	1	MDB2M-50-8W2		\$ 21.60
17	CLIP, DOOR GARNISH /	3	MKD53-50-M38		\$ 35.10
18	REAR FENDER LHS X Repair	1	MDBYA-71-41X		\$ 944.30
19	GUARD STONE LHS /	1	MDB1L-50-4R2		\$ 14.00
20	RETAINER LHS, REAR BUMPER X	1	MDB7A-50-2J1		\$ 21.70
21	FASTENER, REAR BUMPER X	7	MB45A-56-146A		\$ 19.60
22	GROMMET, REAR BUMPER X	4	MBHN1-50-021A		\$ 10.00
23	GASKET LHS, TAILLAMP /	1	MDB7A-51-163		\$ 31.90
24	GASKET RHS, TAILLAMP /	1	MDB7A-51-153		\$ 31.90
25	REAR WINDSCREEN MOULDING X	1	MDB7M-50-611A		\$ 48.90
26	SPACER, REAR WINDSCREEN X	3	MDB7G-50-897		\$ 32.40
			TOTAL PARTS		\$ 3,302.40
			LESS 10%		\$ 330.24
			TOTAL PARTS COST		\$ 2,972.16

1076.4

968.76

Labour Description				
1		TO REPLACE FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH. TO REPAIR REAR BUMPER AND ALL AREAS AFFECTED BY THE ACCIDENT.	1920	\$ 4,620.00
2		TO RESPRAY FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH. AND REAR BUMPER.	2520	\$ 3,150.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT	\$ 120.00
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	330	2PCS \$ 1,320.00
6	MZ-BR-TRIMS2	TO REMOVE & REFIT SEAT ASSY, CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	X	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00

6 Days.

before paint photos.

Guo Q: anp.

18/9/18.

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 12,060.00
TOTAL PARTS	\$ -	\$ 2,972.16
TOTAL	\$ -	\$ 15,032.16
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

6238.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price is subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Sep 2018		14 Sep 2018 09:54 Edit Adj Rpt	\$56,238.76 Edit Estimates	\$56,238.76 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S LIHENG ONG, Co. Reg. No.: 53365692C		
Main Claimant:	VANESSE LIM YU RUI, ID: S8305353D		
Vehicle Reg. No.:	SJE41L	Date of Loss:	09/09/2018 15:00 - :59 [5 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04395C02	Policy/Cover Note No.:	DMHCSN1745931700 (Comprehensive)
Vehicle Reg. No. (Insured):	SFU7102L	Policy No. (Claimant):	3100027483
		Excess:	\$0.00
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/09/2018]		
Driver/Custodian (Insured):	NG SIEW GEK (54 / Female), NRIC: S1596958Z, Tel: +6597973853		
Adj Asg. Remarks:	EST \$15,032.16, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJE41L (SNM18D04395C02)**
[SFU7102L]

TP
VANESSE LIM YU RUI
Sep 9 2018 3:00PM
[M/S LIHENG ONG]
Trans Eurokars Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/09/18 16:01	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/09/18 16:02	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/09/18 15:58	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	10/09/18 15:58	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	10/09/18 15:58	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	10/09/18 15:58	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	10/09/18 15:58	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 10:45	General View	Load JPG	☒
2	25/01/19 10:45	General View	Load JPG	☒
3	25/01/19 10:45	General View	Load JPG	☒
4	25/01/19 10:45	General View	Load JPG	☒
5	25/01/19 10:45	General View	Load JPG	☒
6	25/01/19 10:45	General View	Load JPG	☒
7	25/01/19 10:45	General View	Load JPG	☒
8	25/01/19 10:45	General View	Load JPG	☒
9	25/01/19 10:45	General View	Load JPG	☒
10	25/01/19 10:45	General View	Load JPG	☒
11	25/01/19 10:45	General View	Load JPG	☒
12	25/01/19 10:45	General View	Load JPG	☒
13	25/01/19 10:45	General View	Load JPG	☒
14	25/01/19 10:45	General View	Load JPG	☒
15	25/01/19 10:45	General View	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/09/18 09:54	EMAIL FM TRANS	Load PDF	
2	14/09/18 09:54	REPAIR EST WITH TP GIA	Load PDF	
3	14/09/18 09:55	OI GIA	Load PDF	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print

Video			1 per page ▼	✓
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/09/18 15:56	Sketch Plan [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Video			View	View in Browser ▼
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	1 per page ▼	✓
			Thumbnail	Print
1	10/09/18 16:01	Video - Accident	Load MP4	
Assessment Reports			1 per page ▼	✓
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/09/18 16:02	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/09/18 15:58	Accident Photo	Load JPG	✓
2	10/09/18 15:58	Accident Photo	Load JPG	✓
3	10/09/18 15:58	Accident Photo	Load JPG	✓
4	10/09/18 15:58	Accident Photo	Load JPG	✓
5	10/09/18 15:58	Accident Photo	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/09/18 15:56	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18016806/GTBS2
Date: 25/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN1745931700
 Claimant Vehicle No: SJE41L Insured Vehicle No: SFU7102L
 Date of Loss: 09/09/2018 Nature of Claim: TP Claim No: SNM18D04395C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE41L**
 Make & Model: MAZDA 2, 1.5 V (A) Engine No: P520445452
 Reg. Date: 23/03/2018 (Man. Year: 2018) Chassis No: MM6DL2SAAJW361533
 Colour: Blue Odometer: 16490 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,072.16	988.76	2,083.40	67.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,960.00	5,250.00	6,710.00	56.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,032.16	6,238.76	8,793.40	58.50
+ GST 7.00/7.00% (S\$)	1,052.25	436.71	615.54	58.50
Nett Amount (S\$)	16,084.41	6,675.47	9,408.94	58.50

INSPECTION

Date of Assignment: 14/09/2018
 Date Inspected: 18/09/2018 Inspected At: Trans Eurokars Pte Ltd
 NO 5 UBI CLOSE
 SINGAPORE 408605
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2019)
Parts:	144	MAZDA 2 1.5 V (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE41L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LHS	Repair	1,109.30 FL	*- FL
2	1		*FASTENER, FRONT DOOR	Not Necessary	3.00 FL	*- FL
3	10		*GROMMET, FRONT DOOR	Not Necessary	28.00 FL	*- FL
4	1		*FASTENER, FRONT DOOR	Not Necessary	3.00 FL	*- FL
5	1		*CLIP, FRONT DOOR	Not Necessary	2.20 FL	*- FL
6	1		*GROMMET, FRONT DOOR	Not Necessary	3.60 FL	*- FL
7	1		*REAR DOOR LHS	Dented	825.40 FL	*825.40 FL
8	4		*FASTENER, REAR DOOR	Necessary	48.80 FL	*48.80 FL
9	1		*FASTENER, REAR DOOR	Necessary	3.00 FL	*3.00 FL
10	1		*FASTENER, REAR DOOR	Necessary	12.60 FL	*12.60 FL
11	1		*FASTENER, REAR DOOR	Necessary	3.00 FL	*3.00 FL
12	7		*GROMMET, REAR DOOR	Necessary	19.60 FL	*19.60 FL
13	1		*CLIP, REAR DOOR	Necessary	2.20 FL	*2.20 FL
14	1		*GROMMET, REAR DOOR	Necessary	3.60 FL	*3.60 FL
15	1		*STRIPE SIDE LHS, FRONT DOOR	Necessary	23.70 FL	*23.70 FL
16	1		*STRIPE SIDE LHS, REAR DOOR	Necessary	21.60 FL	*21.60 FL
17	3		*CLIP, DOOR GARNISH	Necessary	35.10 FL	*35.10 FL
18	1		*REAR FENDER LHS	Repair	944.30 FL	*- FL
19	1		*GUARD STONE LHS	Necessary	14.00 FL	*14.00 FL
20	1		*RETAINER LHS, REAR BUMPER	Not Necessary	21.70 FL	*- FL
21	7		*FASTENER, REAR BUMPER	Not Necessary	19.60 FL	*- FL
22	4		*GROMMET, REAR BUMPER	Not Necessary	10.00 FL	*- FL
23	1		*GASKET LHS, TAILLAMP	Necessary	31.90 FL	*31.90 FL
24	1		*GASKET RHS, TAILLAMP	Necessary	31.90 FL	*31.90 FL
25	1		*REAR WINDSCREEN MOULDING	Not Necessary	48.90 FL	*- FL
26	3		*SPACER, REAR WINDSCREEN	Not Necessary	32.40 FL	*- FL
27	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,402.40	1,096.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	330.24	107.64
Total Parts (\$\$)	3,072.16	988.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH. TO REPAIR REAR BUMPER AND ALL AREAS AFFECTED BY THE ACCIDENT.	New	4,620.00	1,920.00
2	TO RESPRAY FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH, AND REAR BUMPER.	New	3,150.00	2,520.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	560.00	0.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	New	120.00	0.00
5	TO TRANSFER THE DOOR MECHANISM.	New	1,320.00	330.00
6	TO REMOVE & REFIT SEAT ASSY, CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	New	990.00	0.00
7	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	New	350.00	0.00
8	TO CARRY-OUT BODY CAVITY PERSERVATION.	New	250.00	150.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	250.00	150.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	350.00	180.00
Gross Labour Cost (S\$)			11,960.00	5,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >