22/03/2002 ASS, REC, BY:	REF: CS/FOI	8016809 / Kel	Special Instruct	tion:
Surveyor Kanneth	ASSIGNI		-	
From (Person): (WS J	banne Yong of		Date/Tim	e: 1409 2018 920am
Estimated Cost:	J	Bill to:		
To Inspect Vehicle No:	OD RES/EVA/INV/MV SCW 93131		Insured:S	HC 8477U
at Workshop m/s	Lai Huut (Mung	KW	Tel: (
of	160 Sin ming Draw	# 64-01		
Policy No:			D181014	8 MTSH
Sum Insured:		Excess:		
Make of Veh: (Client's Record)			D.O.A.	12042018
CA / REV / REP. / RI Date/Time: NW 2018	EV 24 HRS 'DS' 1006UM Person Contacted	d: Jonny	H.O.D. F	indorsement:
Date/Time Action/Inst	ruction (🗸) Estinu	ite		
S(N 93)	31 - X		-	
SHC 843	AU - CC3/AXA 1301281	16/Mbushiz		DUA 150713
1-//	15 p.m. revised			via enal.
7/11 61G	, Pleasel. Can	hus y e	enal	

ASSIGNMENT

From: Date: 14092018	Veh No: Scw 93	8632 Yr Regn: 0	6 06
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Var	/ Lorry / Taxi / Prime Mo	ver /
OD / P WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	a mpr	/
To Inspect Vehicle No: S(W 9313L	Make: Toy Pi	cni2 0.0	1998
at Workshop m/s Lai Muat (Mung Kee)	Colour M. Silve	A/C: Insured /	Std / NI / NA
of 160 SIN MING DINE #04-01	Sp.Reading 21499		Std / NI / NA
Insured:	Eng/No:	ā	
Policy No.	C/No: TTEGH	23870002	21911
Claims No.	Gen. Cond: Cood Fair / Poor / B		
Sum Insured: Excess:	Steering: Inorder Jammed / Lea	ked / Burnt or	
(Client's Record)	Brake: In order / Jammed / Lea	ked / Burnt or	
Make of Veh:	Modi: Nil / S/Rim / STO A/Ri	n or	
	Tyre Size: F:	215/601	211
(Policy Condition)	R:		
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / L	IZA / MIC / OHTSU / PIR /	SUMI/
repair at the time of inspection.	TOYO / YOKO br		
Bal. or Market Value: 8 221c	Front	Rear	
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 9 mm	R/Bal.	7 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5° mm	L/Bal.	mm
Est. Repairs: 12 days Res.: Yes or No	D.O.A. 1219118	D.O.I. /-	418/18
Lum Sum; % 3 Val.: Yes or No	Survey held at		
6'21	Des. of Damages : Frt / Rear /	O/S / N/S / U/C / Rooft	op or
CA / REV / REP. / 24 HRS Vehicle: IN / OU	T & 1897		
Date: Person Contacted:	The U/C / Chassis frame /	Body Structure affected of	tue to collision.
Date / Time Action / Instruction 19 15/16 1981 to Corkerine 07/11/18 Confirmed 45 \$ 8,000/- (\$ 1,301.10 ped - 14%)		Kenneth.	march
MV - 22K RECEI	VED 0 8 NOV 2018	7	11/2018.
LTA-\$ 12,426.00			, 0
Me# - \$ 9, 74/-			
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 12		
1) Typ.2+ : Final Report	Resurvey No. of Trip: 2	Survey Fee: Transportation:	170
2) Add Fe	ee: Site Insp (\$)S+RSSI	50450
	: Interview (\$) Photos	32
Report Format :	Tech, Invs (\$) Others	
Lump Sum / I.B.I: (\$ 2,000/- 45)	Weekend (\$)	
.,		TOTAL	352



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

13-09-2018

Our Ref No. D18006798MFSH

Accident Date

12-09-2018

Claim Type. Third Party

Insured Vehicle

SHC8477U

Third Party Vehicle. SCW9363L

Survey Location

160 SIN MING DRIVE #04-01/#04-02/#07-03SIN MING AUTOCITY

Contact Person.

JENNY LIM

Contact No.

64538110/0

Fax No. 64596267

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

LAI HUAT (MENG KEE)

MOTOR PTE LTD

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

JOANNEY

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	1082C
Vehicle No.:	SCW9363L
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1AZ5410019
Chassis No.:	JTEGH23B700021911
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$26,212.00
Original Registration Date:	23 Jun 2006
First Registration Date:	23 Jun 2006
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$28,834.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	•
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	22 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$24,240.00
COE Rebate Amount:	\$12,726.00
Total Rebate Amount: Message	\$12,726.00
	be further renewed. The vehicle must be de-registered upon COE expiry or when the

vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Nov 2018

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

09/2016 Honda Vezel @\$68k \$0 Down From 1.98%



Year-end Clearance Sale190

Privilege Group Pte



Browse by Category

Post an Ad

Advertiser Login

Ways of Selling

Sort by Date Posted

▼ 20 results/page

18 vehicles

Toyota Picnic

Model

Price

Depreciation

Reg Date Eng Cap Mileage

Veh Type

Status

Search Selection

> 10 year(s) old

Anv

Any

Advanced Search

Any

Available

Toyota Picnic

\$7,040 /vr

16-Oct-2008

1.998 cc

Available

Toyota Picnic 2.0A (COE till 10/2023) 2.88% Per Annum By GV Cars Financing At \$2000 Down Payment From \$688 Lowest Monthly With 100% Loan Approval, 2 Years Warranty By GV In House Workshop. New \$2k Metallic Paint/6 Months Road Tax. Extra A...

\$34,800

MPV

PREMIUMAN

2.88%P.A Lowest Interest@Gv Cars Financing \$2000 Downpayment Monthly From \$688 GV Credit Pte Ltd

Posted: 07-Nov-2018 Tags: 2008 Toyota Picnic, 2008 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, Dicnic, Used

Toyota Picnic 2.0A (COE till 02/2027)

\$52,500

\$6,350 /yr

14-Feb-2007

1,998 cc

MPV

Available

1 Owner! Accident Free! Service Regularly Without Fail, Major Wear And Tears Parts Have Fully Replaced. Stylish Looks, Spacious And Comforts Yet Powerful To Move Around, Dream Of Owning It? Grab It No...

Posted: 05-Nov-2018 Tags: 2007 Toyota Picnic, 2007 toyota picnic, Toyota Picnic, Toyota Picnic, Toyota Picnic, Used Toyota

Toyota Picnic 2.0A (COE till

03/2022)

\$26,388

\$7,960 /yr

02-Mar-2007

1,998 cc

168,000 km

Available

AA Trust Certified Pre Owned Quality Vehicle! Well Maintained By Previous Owner! Original Black With Beige Interior! Popular And Spacious MPV From Toyotal Perfect For Your Getaway Across The Causeway!...

AA Trust Automotive

Posted: 04-Nov-2018 Tags: 2007 Toyota Picnic, 2007 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota

Toyota Picnic 2.0A (COE till 05/2022)

\$27,800

\$7,850 /yr

24-May-2007

1,998 cc

MPV

Available

Super Price! Worth It! Come And Get This Mpv Family Vehicle Today! Visit Classic Credit P/L Now! Only \$2,980 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And H.,

Posted: 01-Nov-2018

Tags: 2007 Toyota Picnic, 2007 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable, We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today,



Toyota Picnic 2.0A (New 5-yr COE)

\$38,800

\$7,760 /yr

24-Oct-2008

1,998 cc

MPV

Available

Very Well Kept Both Interior And Exterior, Fuel Efficient And Affordable Maintenance, High Trade In Available, Flexible Bank And In House Loan Available, Kindly Call Our Friendly Consultant For Viewin...

Posted: 01-Nov-2018 Tags: 2008 Toyota Picnic, 2008 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota



Toyota Picnic 2.0A (COE till 10/2021)

\$23,800

\$8,030 /vr

25-Oct-2006

1.998 cc

Available

2 Owner Till Date, Low Mileage Done, Depreciation At Only \$7.3k Per Year, High Paper Value At \$18k, Well Maintained Exterior And Interior, Loan/Trade-In Available, Call To Scrutinize.

osted: 01-Nov-2018 Tags: 2006 Toyota Picnic, 2006 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, Used Toyota

https://www.sgcarmart.com/used_cars/listing.php?MOD=Toyota+Picnic&PRC=0&DEP=0&RGD=10&VEH=0&AVL=2



Toyota Picnic 2.0A (COE till 08/2027)

\$54,500

\$6,180 /yr

12-Sep-2007

1,998 cc

139,000 km

MPV

Available

Showroom Condition, Definitely A Must View Unit, Low Mileage, Low Depreciation, Low Down Payment And Low Monthly, Drive Away This Best Selling MPV, Call Us Now For A No Obligation Test Drive, Quality ... Posted: 17-Sep-2018 Tags: 2007 Toyota Picnic, 2007 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota

1,998 cc

MPV

Toyota Picnic 2.0A (COE till 08/2021)

\$19,000

\$6,810 /yr

23-Aug-2006

Available

New Paintwork, High Loan And Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only. Boeki Auto & Marine

Posted: 13-Sep-2016 Tags: 2006 Toyota Picnic, 2006 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota

Save this search criteria, to get email alerts whenever a match is found

Depreciation

Reg Date: Eng Cap

Mileage

Veh Type

20 ▼ results/page

For old advertisements, view Expired ads

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Tuesday, 18 September 2018 3:15 PM

To:

JOANNEYONG@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'

Cc:

'Catherine Chong (LKK Auto)'; 'SUR'; ASSIGNMENTS@LKKAUTO.COM

Subject:

RE: SURVEY ASSESSMENT - D18006798MFSH/1

Attachments:

SCW 9363L - Preli Advise.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SCW 9363L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Friday, 14 September 2018 10:08 AM

To: 'Claim Workflow System' < cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM

Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18006798MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Friday, 14 September, 2018 9:20 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18006798MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the workshop, we saw this vehicle sustained front and rear n/s portion damage.

The damages seen during our survey were front n/s fender assy, front n/s tyre, front n/s tront n/s under carriage, front n/s door, rear n/s door, rear n/s fender, rear bumper, rear n/s under carriage and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Thism Soon Motor Services estimated a repair cost of \$\$12,032.99. We adjusted it to \$\$8,765.32 on a part-by-part basis.

As this vehicle was more than 5 years old during the accident, we assess repairs on a lumpsum basis is appropriate. By applying the market discount of 20% from the part-by-part repairs, the re-adjusted repair cost on lumpsum basis is \$\$7,012.26, round upto \$\$7,010.00.

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at \$\$7,000.00.

The repairs would require a period of 12 working days.

Tommie Lim



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18006798MFSH

Date: 18 September 2018

Our Ref: CS/FCI18016809/Ksb

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SCW 9363L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/09/2018 at the premises of M/s Lai Huat (Meng Kee) Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$</u>	7,979.34	- 1
Revised Estimate Amount	: <u>S</u> \$	7,491.77	
"Check" Items Amount	: <u>S\$</u>	297.57	
Market Value	: <u>S</u> \$		34
LTA Reimbursement Value	: <u>S\$</u>		
Nett Value	: <u>S\$</u>		

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages Consistent. Repair days: 12 Days

Yours faithfully, Kenneth Kong Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

•	~	~	П				т Λ		M = 1	
	u	v.	u	_	хι	0	ΙА	TEN	n = 0	ч.

Date Of Report 12/09/2018 16:08

Date Of Accident 12/09/2018 10:50

Exact Location Of Accident ALONG ECP TOWARDS CHANGI AIRPORT

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCW9363L

Insured/Policyholder

Name Of Registered Owner GUNAWAN HADI

NRIC No S2221082C

Email Address GUNHADI@GMAIL.COM

Mobile Phone No (LOCAL) +65-98304731

Alternative Phone No OTHERS-91173676

Vehicle Particulars

Manufacturer TOYOTA

Model PICNIC

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

200

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number D18MTPV01009585

Cover Note Number

Driver

Name of Driver JOHANNES HADI

 NRIC No
 S9070036G

 Date Of Birth
 01/06/1990

 Occupation
 INDOOR

 Date Of Driving Pass
 26/01/2010

Driving Experience 8 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91173676

Fax Number

Contact Number

EMail Address JOHANNESHADI@GMAIL.COM

Address

27 BALMORAL PARK

#08-29

Postcode

259855

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

NO 3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

: LANNY SANTOSO

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC8477U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLM901P

Vehicle Make/Model/Colour

GRAB TAXI

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

JAY SOON

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, (d) investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

12 SEP 2018 CHAMINE ((CANINA) Driver Signature

(If drive is not the policyholder)

F2 SEP 2018

608 hrs.

Reporting Centre Personnel's Signature

Name:

NRIC/FIN Roh Kwee Choo S6840583A

SKETCH PLAN	Eq. 7	EWARDS CHANGI AIRBRT.
[SHC 8427/W] [IMPA	SCH 9363C) STM901P	
		Organismon Comps
DESCRIBE CIRCUMSTANCES OF THE AC		100/10
AT OR ABOUT 10:50 P	IM THIS MANNER ()	2 (09/18), [WAS DRIVING
VEHICLE DW9363L AU	ONLY EAST COAST PARKEN	AY (FCP) TOWARDS CHANGS
AHRORT- MY VEHICLE	WAS IN LANE 2 (M	IDDLE) - I SAW THAT THERE
MAS PRIAMPHE TREE PR	WING WORKS IN U	ANE I NEAR COURSE
DIVIDER AND THAT	CARS WERE PILTERIN	of INTO CANE 2. THE
TRAPAC IN LANE 2 J	LOWED SUGHTLY AS	BLOT OUR I MA PINESS A
DOWN ACCORDINALY. 1	THEN JAW VEHICLE	SLM 901P IN FRONT OF
ME BRAKE AND STOP	R 1 AUGO BRAKED	- 4 WAS FIFN STORMLY
IMPACTED FROM THE &	FAR WIH QUITE	A GREAT FREE. THIS
CANGED MY VEHICLE TO	6 MOVE POLIMARD AN	D MPACI SUMPOIP. THE
2001 B. 1 (1900 B. 1900 B. 190	WAS CMFORT TAXL ue in every respect. CMILAINTS en signature liver is not the policyholder)	SHC 8477 M. I SAW THAT AS INVIRED AND THERE WARE IN FIRE SAME. Reporting Centre Personnel's Signature Name: Poh Kwan Chan
A STATE OF THE STA	1607 WS -	Name: Poh Kwee Choo NRIC/FIN No.: S6840583A

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$9070036G



JOHANNES HADI



Race CHINESE Date of birth 01-06-1990 M Country of birth INDONESIA

990700389



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$22210820



GUNAWAN HADI

CHINESE 20-02-1955

INDONESIA

4691996

Done of leave

27 BALMORAL PARK #08-29 SINGAPORE 259855

10-03-2011

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive 26 Jan 2010 of the driver; and other motor vehicles =< 2500kg

NP 428A

Licence No: S9070036G



S2221082C

Bluog Group Date of leader

A+ 24-09-1998

27 BALMORAL PARK #08-29 SINGAPORE 259855 NRIC No: \$22210820

Date: 03/07/2010

No: 6449704

3046040



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg Co. Reg. No.: 198905490E | GST Reg. No.: M200903198

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No.

: D18MTPV01009585

Insured

: GUNAWAN HADI

Motor Car (Registration No.) : SCW9363L

: Comprehensive - ExcelDrive GoldPlus

Policy Commencement Date : 23 JUNE 2018 00:00

Policy Expiry Date

: 22 JUNE 2019 23:59

Maximum Liability (Section I): Market value at time of loss

Excess*

: \$600 - Section I

(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim

per policy year)

Voluntary Excess*

Windscreen Excess*

: S\$100.00 - Waived if Repair at ExcelDrive Workshop

Loss of Use

: Per Policy Schedule

Persons or Classes of Persons entitled to drive*

- The Insured.
- 2. Any other person who is driving on the Insured's order or with his permission.
- 3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b, any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref ASMTP.3

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue: 23 MAY 2018 08:52

IMPORTANT NOTICE

Keep the Certificate in your Motor Car, Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;

On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);

This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

^{*} Subject to GST wherever applicable

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1082C

Vehicle Details

Vehicle No.: SCW9363L

Vehicle to be Exported: Yes

Intended Deregistration Date: 13 Sep 2018
Vehicle Make: TOYOTA

Vehicle Model: PICNIC AUTO

Primary Colour: Silver
Manufacturing Year: 2006

Engine No.: 1AZ5410019

Chassis No.: JTEGH23B700021911 Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$26,212.00
Original Registration Date: 23 Jun 2006
First Registration Date: 23 Jun 2006

Transfer Count: 0

Actual ARF Paid: \$28.834.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Jun 2021

COE Category: E - Open Category

COE Period(Years): 5

PQP Paid: \$24,240.00
COE Rebate Amount: \$13,453.00
Total Rebate Amount: \$13,453.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Sep 2018

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

SHC8477U 12 Sep 2018 / 10:50:00 Successful F03 MS FIRST CAPITAL INSURANCE LIMITED

Previous OK



Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 12 Sep 2018, 16:19:38.

To return to ONE.MOTORING, please click here

For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/No.LL Asset Type

1 Vehicle

Asset ID

Log Date/Time 12 Sep 2018 / 16:20:04

SHC8477U

Asset Owner ID

Transaction Type

18.32 Insurance Enquiry (GIRO Payment)

Transaction Amount(S\$)

7.49

来發(明记)障哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267 RCB No: 199407592C

ESTIMATE

EST. No EST0020223

. TP-SHC 8477U MS Fir

Job No. 69813

Payment

Date 13/9/2018

Attn

Vehicle No ... SCW 9363L Vehicle Model : Toyota Picnic

Accident on 12/9/2018

Not Nothorial Ulling 8? Permy Athe Paint 12days

Quantity Unit	Description	Unit price	Disc. pct.	Amount
	Supply of Parts		TIME	
1.00 Pc	Rear tailgate	1,306.90	25,00	By 980.18 -
1.00 Pc	Rear Toyota logo emblem '	70.91	25.00	m 53.18 -
1.00 Pc	Rear Toyota emblem	41.44	25.00	ha 31 08 -
1.00 Pc	Rear Picnic emblem	48.44	25.00	ma 36.33 -
1.00 Pc	Rear bumper	511.20	25.00	383.40 W
1.00 Pc	Rear bumper tow cover LH	18.20	25.00	n17 13.85 -
1.00 Pc	Rear bumper side holder LH	38.71		m 29.03 _
1.00 Pc	Rear windscreen moulding	120.55		Ma 90.41 -
1.00 Pc	Rear end panel	418.60	25.00	By 312.45 -
1.00 Pc	Rear luggage panel	756.50		4 567 38 -
1.00 Pc	Rear luggage bracket	65.70	25 00	49 28 7
1.00 Pc	Rear luggage reinforcement	83,50	25.00	62.63 7 .
1.00 Pc	Rear bumper reflector LH	56,90		M 42.68
4.00 Pcs	Rear bumper clips	3.50	25.00	m 10.50 -
1.00 Pc	Rear tailgate weatherstrip	247.55	25.00	185.66 7
1.00 Pc	Front bumper c/w centre grille	Bu 521.80	25 00 4	14 391.35 -
1.00 Pc	Front radiator grille c/w logo emblem	458.00		m 343.50 -
1.00 Pc	Front brace panel	79.87	25.00	R 59.90 -

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- » Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and

is subject to final approval from insurance Company 可提供给多种数式的车身及给于快速 有准确的测量方式和大铁修理。

Acknowledged by Repairer

"Our services include the latest and reliable CAROL MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

本公司拥有最先进的 CAROLINER MARK IV 机械 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

来發(明记)障哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267 RCB No: 199407592C

ESTIMATE

TP-SHC 8477U MS Fin Your ref.

Job No Our ref 18.09.19

Payment

13/9/2018

Attn

Vehicle No SCW 9363L

Vehicle Model : Toyota Picnic Accident on . : 12/9/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
1.00	Po	Front headlamp LA 4	30.50 530.50	25.00	397.88	_
1.00		Front headlamp RH	30.50	25.00	397 88	_
1.00		Front bumper sponge 1	84.63	25.00	cns 63.47	_
1.00	Pc	Front bumper reinforcement	322.90	25.00	Ben 242.18	_
		Nett item:	11/1/			
1.00	Pc	Deluxe emblem // Special nett item.	/ / / 22,60	10.00	M 20,34	_
4 00	Do	Transfer must be relate	25.00		Br 35.00	-
1.00		Front number plate Rear reversing sensor with installation (3 pcs)	35.00 280.00	•	m 280.00	~
		Labour & Misc:			,	201
1.00		To remove and refix rear windscreen	140.00		140.00	
1.00		To supply sealant	40.00		40.00	~

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 障哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267 RCB No: 199407592C

ESTIMATE

EST_No EST0020223

Your ref.

TP-SHC 8477U MS Fin Job No. ..

Payment

Date 13/9/2018

Attn

Vehicle Model : Toyota Picnic Accident on ... 12/9/2018

Quantity Unit	Description	Unit price Disc pct	Amount
1.00	To dismantle and refix rear side trim carpet, etc	120.00	120.00
1.00	To straighten rear body including cutting and welding, to renew of parts (rear portion)	1,200.00	1,200.00
1.00	To spray paint (rear portion)	900.00	900 00 83
1.00	To knock dents on front support panel and renew of parts	250.00	250.00 -
1.00	To spray paint (front portion)	250.00	250.00 -

7,979.34 Sub-Total GST 7.00% Total 8.537.89

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發(明记)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267 RCB No: 199407592C

ESTIMATE

EST. No EST0020223

Gunawan Hadi

Page1

Your ref. TP-SHC 8477U MS Fir

Job No 69813 Our ref 18.09.19

Payment

Attn

Vehicle No SCW 9363L Vehicle Model: Toyota Picnic Accident on ... 12/9/2018

Not Nothone LISmy 8: -10%. Resurry After Paray 12days 3

Quantity	Unit	Description		'nit price	Disc pct	Amount
		Supply of Parts.				-
1 00	Fc	Rear tailgate	pr s	1,306 90	25.00	By 980.18
1.00	Po	Rear Toyota logo emblem		70.91	25.00	· 12 53 18 _
1 00	Pc	Rear Toyota emblem		41 44	25 00	14 31.08 -
1.00	Fc	Rear Pionic emblem		48.44	25 00	12 36.33 -
1.00	Pc	Rear bumper		511.20	25.00	马 383.40 _
1.00	Pc	Rear bumper tow cover LH		18.20	25.00	MIN 1365
1.00	Pc	Rear bumper side holder LH		38 71	25.00	cm 2903
1.00	Pc	Rear windscreen moulding		120.55	25.00	Ma 90.41 -
1.00	Po	Rear end panel		416.60	25.00	图 312.45 —
1.00	Pc	Rear luggage panel		756.50	25.00	B 567.38 -
1.00	Pc	Rear luggage bracket		65.70	25.00	Dr1 49.28 EX
1.00	Pc	Rear luggage reinforcement		83.50	25.00	R 62.63
1.00	Pc	Rear bumper reflector LH		56.90	25.00	cm 42.68
4.00	Pcs	Rear bumper clips	Sin	3.50	25.00	Ma 10.50 -
4.00	Pc	Rear-tailgate weatherstrip-		247.55	25 00	185 90 🗙
1.00	Pc	Front bumper c/w centre grille	Bu	521.80	25.00	C44 391.35°
1.00	Pc	Front radiator grille c/w logo emblem		458.00	25.00	em 343.50 -
1.00	Pc	Front brace panel		79 87	25.00	星 59 90
1.00	Pc	Front brace panel		7987	25.00	图 59 90 _

3461.93

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种数式的车身及给于快速与准确的测量方式和大快修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發(明记)障哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267 RCB No: 199407592C

ESTIMATE

EST. No EST0020223

Gunawan Hadi

Page 2 of 3

Your ref. TP-SHC 8477IJ MS Fir

Job No : 69813 Our ref : : : 18.09.19

Payment:

Date 13/9/2018

Attn

Vehicle No SCW 9363L Vehicle Model : Toyota Picnic Accident on .: 12/9/2018

Quantity	Unit	Description		Unit price	Disc pct	Amount
1.00	Pc	Front headlamp LH	whilm	530.50	25.00	397.88
1.00	Pc	Front headlamp RH	milm	530.50	25.00	397 88
1 00	Pc	Front bumper sponge		84 63	25 00	CRA 63 47 -
1.00	Pc	Front bumper reinforcement		322.90	25.00	Bear 242.18
		Nett item.				
1.00	Pc	Deluxe emblem		22.60	10.00	Ma 20.34
		Special nett item				1121.75
1.00	Pc	Front number plate		35.00		By 35.00 -
1 00	Set	Rear reversing sensor with installation (3 pcs)		280.00	i	(315)
		Labour & Misc.				12
1.00		To remove and refix rear windscreen		140.00		140.00
1.00		To supply sealant		40.00		40.00

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种数式的车身及给于快速与准确的测量方式和大铁修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發(明记)障哆有限公司 LAI HÚAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267 RCB No: 199407592C

ESTIMATE

EST. No EST0020223

Gunawan Hadi

Page 3 of 3

Your ref TP-SHC 8477U MS Fir

Date 13/9/2018

Attn

Vehicle No ... SCW 9363L Vehicle Model . Toyota Picnic Accident on ... 12/9/2018

Description	Unit price	Disc. pct.	Amount
To dismantle and refix rear side trim carpet, in the	120.00		120.00
To straighten rear body including cutting and welding, to renew of parts (rear portion)	1,200.00		1,200.00
To spray paint (rear portion)	900.00		900.00
To knock dents on front support panel and renew of parts	250.00		250.00
To spray paint (front portion)	250.00		17/2 250.00
			2710.
	To dismantle and refix rear side trim carpet, etc To straighten rear body including cutting and welding, to renew of parts (rear portion) To spray paint (rear portion) To knock dents on front support panel and renew of parts	To dismantle and refix rear side trim carpet, 120.00 etc To straighten rear body including cutting and welding, to renew of parts (rear portion) To spray paint (rear portion) To knock dents on front support panel and renew of parts 250.00	To dismantle and refix rear side trim carpet, To straighten rear body including cutting and welding, to renew of parts (rear portion) To spray paint (rear portion) To knock dents on front support panel and renew of parts 250.00

Sub-Total 7,979.34 GST 7.00% 558.55 Total S\$ 8,537.89

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Ks

来發(明记)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267 RCB No: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No EST0020223

Gunawan Hadi

Page 1 of 1

Your ref TP-SHC 8477U MS Fir

Payment

Attn

Vehicle No SCW 9363L Vehicle Model . Toyota Picnic Accident on ...: 12/9/2018

Description	Unit price	Disc. pct.	Amount
Supply of Parts:			
SUPPLEMENTARY ITEM:			2
Air con condenser	1,405.30	25:00	Pa 1,053.98 —
Front bumper side retainer LH	85.19	25.00	
Front bumper side retainer RH	85 19	25 00	011 63 89
Labour & Misc:			(181.76)
To remove and renew air con condenser and refill air con gas	140.00		140.00 /00
	Supply of Parts: SUPPLEMENTARY ITEM: Air con condenser Front bumper side retainer LH Front bumper side retainer RH Labour & Misc: To remove and renew air con condenser and	Supply of Parts: SUPPLEMENTARY ITEM: Air con condenser 1,405.30 Front bumper side retainer LH 85.19 Front bumper side retainer RH 85 19 Labour & Misc: To remove and renew air con condenser and 140.00	Supply of Parts: SUPPLEMENTARY ITEM: Air con condenser Front bumper side retainer LH Front bumper side retainer RH Labour & Misc: To remove and renew air con condenser and 1,405.30 25.00 85.19 25.00 140.00

 Sub-Total
 1,321.76

 GST 7.00%
 92.52

 Total
 S\$ 1,414.28

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种数式的车身及给于快速与准确的测量方式和大铁修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En Automob	lle	
MS	FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI18016809/	Ksbe2	
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 29-11-2018 Code: FCI2		
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SHC 8477U	Veh. Inspected	SCW 9363L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D18006798MFSH	Excess (\$)	0.00	
	Assign From	JOANNE YONG	Assign Date	14/09/2018	
2.		Vehicle Parti	culars & Condition		
	Make & Model	TOYOTA PICNIC (A)	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	JTEGH23B700021911	Colour	METALLIC SILVER	
	Odometer	214943	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.		Condit	ions of Tyres		
Size Make Balance					
	R/H Front Tyre	215/60 R16	YOKOHAMA	9 mm	
	L/H Front Tyre	215/60 R16	YOKOHAMA	9 mm	
	R/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm	
	L/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm	
4.			on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE FR	ONT AND REAR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		Genera	Il Information		
	Accident Date	12/09/2018	Inspection Date	14/09/2018	
	Survey held at	LAI HUAT (MENG KEE) MOTO	R PTE LTD		
		160 SIN MING DRIVE #04-01/0 SIN MING AUTOCITY SINGAPORE 575722	2		
5a.		R	lemarks		
	B)THE INSPECTION	ISISTENT TO ACCIDENT REPOI ON WAS CONDUCTED ON A"WI" CE TO YOUR INSTRUCTIONS, V	THOUT PREJUDICE" BASIS.		
5b.	Tierda The	Estimate	Days of Repair		
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCW 9363L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	BENT	1,306.90	1,306.90
1	REAR TOYOTA LOGO EMBLEM	NECESSARY	70.91	70.91
1	REAR TOYOTA EMBLEM	NECESSARY	41.44	41.44
1	REAR PICNIC EMBLEM	NECESSARY	48.44	48.44
1	REAR BUMPER	BENT	511.20	511.20
1	REAR BUMPER TOW COVER LH	MISSING	18.20	18.20
1	REAR BUMPER SIDE HOLDER LH	CRACKED	38.71	38.71
1	REAR WINDSCREEN MOULDING	NECESSARY	120.55	120.55
1	REAR END PANEL	BENT	416.60	416.60
1	REAR LUGGAGE PANEL	BENT	756.50	756.50
1	REAR LUGGAGE BRACKET	DISTORTED	65.70	65.70
1	REAR LUGGAGE REINFORCEMENT	BENT	83.50	83.50
1	REAR BUMPER REFLECTOR LH	CRACKED	56.90	56.90
4	REAR BUMPER CLIPS	NECESSARY	14.00	14.00
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	247.55	-
1	FRONT BUMPER C/W CENTRE GRILLE	BUCKLED	521.80	521.80
1	FRONT RADIATOR GRILLE C/W LOGO EMBLEM	CRACKED	458.00	458.00
1	FRONT BRACE PANEL	BENT	79.87	79.87
1	FRONT HEADLAMP LH	MTG CRACKED	530.50	530.50
1	FRONT HEADLAMP RH	MTG CRACKED	530.50	530.50
1	FRONT BUMPER SPONGE	CRACKED	84.63	84.63
1	FRONT BUMPER REINFORCEMENT	BENT	322.90	322.90
1	AIR CON CONDENSER (ADDITIONAL)	PUNCTURE	1,405.30	1,405.30
1	FRONT BUMPER SIDE RETAINER LH (ADDITIONAL)	DISTORTED	85.19	85.19
1	FRONT BUMPER SIDE RETAINER RH (ADDITIONAL)	DISTORTED	85.19	85.19
	LESS 25% DISCOUNT		-1,975.25	-1,913.36
			5,925.73	5,740.07
	NETT ITEMS			
1	DELUXE EMBLEM (N)	NECESSARY	22.60	22.60

Report Ref No. CS/FCI18016809/Ksbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LESS 10% DISCOUNT		-2.26	-2.26
			20.34	20.34
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
1	SET REAR REVERSING SENSOR WITH INSTALLATION (3 PCS) (SN)	CRACKED	280.00	280.00
	The state of the s		315.00	315.00
	LABOUR			
	TO REMOVE AND REFIX REAR WINDSCREEN.		140.00	120.00
	TO SUPPLY SEALANT.		40.00	40.00
	TO DISMANTLE AND REFIX REAR SIDE TRIM CARPET, ETC.		120.00	100.00
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING, TO RENEW OF PARTS (REAR PORTION)		1,200.00	1,100.00
	TO SPRAY PAINT (REAR PORTION)		900.00	850.00
	TO KNOCK DENTS ON FRONT SUPPORT PANEL AND RENEW OF PARTS.		250.00	250.00
	TO SPRAY PAINT (FRONT PORTION)		250.00	250.00
	TO REMOVE AND RENEW AIR CON CONDENSER AND REFILL AIR CON GAS. (ADDITIONAL)		140.00	100.00
	, page 152		3,040.00	2,810.00
	GRAND TOTAL		9,301.07	8,885.41

RECOMMENDED COST OF LUMP SUM REPAIRS	THE PERSON NAMED IN	8,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI18016809/Ksbe2

MARKET VALUE: \$22,000.00(EST)-LTA REIMBURSEMENT VALUE: \$12,726.00=NETT VALUE: \$9,274.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.