

REF:

CC3/17618016906/Arbcr

ASSIGNMENT

Form

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 1800052485

Claims No. 860451317656

Sum Insured:

Excess:

\$0.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

20K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04/8/8

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMA427S

Yr Regn:

2018 / June

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A5

CC 1984

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

5108

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU222F54JA099662

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 265/40R18

R: 265/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

16

Rear

R/Bal:

mm

R/Bal:

06

mm

L/Bal:

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

17/09/18

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD A/C

7/11/18

Confirm with Mr Bo. \$3664.08, 4 days

Red: \$10,447.02, 74%

RECEIVED 12 NOV 2018

Date/Time, File Pass to?



Prel. Report

1) typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee

200

Transportation

\$ + RS \$

Photos

Others

10

TOTAL

210

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

00

Lump Sum / I.B.I. (\$

3664.08

Survey Department Check List (Case Handler)

Reference No.: 113 / A1618016906 / A/b
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.				
C	Customer Code				
N	Assign From				
C	Assign Date				
C	Veh No (Inspected)				
C	Veh No (Insured)				
C	D.O.A				
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type				
C	Weekend Charges				
N	Survey held at/Repairer				
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No				
C	Regn Month/Year				
N	Vehicle Type				
N	Make & Model				
C	Engine Capacity. (C.C)				
N	Colour				
C	Odometer. (Sp.Reading)				
C	Chassis No				
N	General Condition				
N	Steering				
N	Brake				
N	Modification (Modi)				
C	Tyre Size				
N	Tyre Make				
C	Tyre Balance				
C	Date of Inspection				
N	Survey held				
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:
Case Handler Date

*C: Critical *N: Non-Critical

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/09/2018 12:29
Date Of Accident	04/09/2018 07:20
Exact Location Of Accident	COLLEGE OF MEDICINE BLDG WILSON OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA4427S
Insured/Policyholder	
Name Of Registered Owner	LIM THOU YEE
NRIC No	S7824271Z
Email Address	THOUYEE@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96636121
Alternative Phone No	HOME-98787325

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SB 2.0 TFS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800052485
Cover Note Number	

Driver

Name of Driver	CHONG HOU MENG
NRIC No	S8016166B
Date Of Birth	01/06/1980
Occupation	INDOOR
Date Of Driving Pass	24/02/1999
Driving Experience	19 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98787325
Fax Number	
Contact Number	
Email Address	TAOMIN80@GMAIL.COM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/09/2018 12:29
Date Of Accident	04/09/2018 07:20
Exact Location Of Accident	COLLEGE OF MEDICINE BLDG WILSON OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA4427S
Insured/Policyholder	
Name Of Registered Owner	LIM THOU YEE
NRIC No	S7824271Z
Email Address	THOUYEE@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96636121
Alternative Phone No	HOME-98787325

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SB 2.0 TFS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800052485
Cover Note Number	

Driver

Name of Driver	CHONG HOU MENG
NRIC No	S8016166B
Date Of Birth	01/06/1980
Occupation	INDOOR
Date Of Driving Pass	24/02/1999
Driving Experience	19 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98787325
Fax Number	
Contact Number	
Email Address	TAOMIN80@GMAIL.COM

Address	10 FLORA DRIVE #04-08
Postcode	506942
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SMA4427S WAS PARKED AND STATIONARY IN CARPARK LOT. WHILE SLF7542H, REVERSED AND TRYING TO PARK IN THE NEXT ADJACENT LOT. DRIVER CHONG HOU MENG WAS STILL IN VEHICLE, WHILE ACCIDENT HAPPENED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF7542H
Vehicle Make/Model/Colour	TOYOTA / AXIO / DARK BROWN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NEO WEN YANG
NRIC/Passport Number	S8507057F
Contact Number	92741579
Address	
Postcode	
Insurance Company Name	ETIQA INSURANCE PTE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

04/09/18 12:00pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

04/09/18 12:00pm

Reporting Centre Personnel's Signature

Name:

WONG HONG SEW, G004

NRIC/FIN No: 62167143x

SKETCH PLAN

8-5LF 75424)

SMA 4427S WAS PARKED AND STATIONARY IN CARPARK LOT. WHILE SLF7542H REVERSED AND TRYING TO PARK IN THE NEXT ADJACENT LOT, IT'S REAR IMPACTED THE FRONT OF SMA4427S

DRIVER CHONG HOU MENG WAS STILL IN VEHICLE WHILE ACCIDENT HAPPENED

I/We declare the foregoing particulars are true in every respect.

04/09/18, 12:00 PM

04/09/18 1200 PM

NRIC/TIN No. C-2337143

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0000 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 – 17:00
UEN: S865526200 / GST Reg. No.: MNR0017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No: SUA 4407S
Name (as shown in NRIC) : Lwin Thon Yee NRIC/FIN/Passport No : _____
[*Vehicle Driver / Vehicle Owner] [*] Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : _____ Time of Accident : _____
Place of Accident : _____
Insurance Company : AIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To convert to claiming my own Policy

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: TUTENG S.
NRIC/FIN No.: _____
Date:

Accident Photo



Accident Photo





COVER NOTE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder: LIM THOU YEE (LIN DAOYI)
 Period of Insurance: 01/01/2018 to 06/30/2019
 Engine No: CVK061652
 Chassis No: WAUZZZF54JA099662

Vehicle No: SMA442TS
 Cover Note No: 1800052485
 Endorsement No:
 Issued Date: 09 May 2018

ABOUT THE COVER

Make/Model: AUDI A5 Sportback 2.0TFSI S Tronic (Design)
 Engine Capacity/Tonnage: 1,984.00 CC
 Driver Restriction: NA
 Sum Insured: Market Value
 Off Peak Car: No
 First Year of Registration: 2018
 Insuring with COE/PAF: Yes

Person or Classes of Persons Entitled to Drive*:
 a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$1,000 as "Young and/or inexperienced Driver Excess" ("YICR") if You are or Your Authorised Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition: All Age Condition

Limitation as to use*:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)
 LIM THOU YEE (LIN DAOYI) - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/Audited Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MALAYAN BANKING BERHAD

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact us immediately.
 We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of Insurance.

0504125203

PREMIUM LEASING - KT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

Cheng Guan Yee

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licensee's Name: **S8016166B**

CHONG HOU MENG (ZHANG TAOMIN)

Date of Birth: **01 Jun 1980**
 Issue Date: **27 Jan 2003**

80161666

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8016166B

CHONG HOU MENG (ZHANG TAOMIN)
张 菊 珉

Race: **CHINESE**
 Date of birth: **01-06-1980**
 Country of birth: **SINGAPORE**

Sex: **F**

80161666

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7824271Z

LIM THOU YEE (LIN DAOYI)
林 道 毅

Race: **CHINESE**
 Date of birth: **27-08-1978**
 Country of birth: **SINGAPORE**

Sex: **M**

7824271Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

Class 5 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Valid Date: **24 Feb 1999**

License No: **S8016166B**

NP 425A

8894030

S8016166B

10 FLORA DRIVE #04-08 SINGAPORE 506942

Date of issue: **04-06-2010**

4211918

S7824271Z

10 FLORA DRIVE #04-08 SINGAPORE 506942

NRIC No: **S7824271Z** Date: **04/03/2010** No: **8438887**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1035/2018/PH
Date	:	6-Sep-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : SLF 7542 H

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Lim Thou Yee
Address	:	10 Flora Drive #04-08 Singapore 506942
Telephone	:	(HP) +65 91181904
Type of Claim	:	Own Damage Claims
Policy No.	:	1800052485
Vehicle No	:	SMA 4427 S
Model Code	:	AUDI A5 SB 2.0 TFSI
Model / Year	:	Jun-18
Engine No	:	CVK 061652
Chassis No	:	WAUZZZF54JA099662
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	4-Sep-18
Place of Accident	:	COLLEGE OF MEDICINE BLDG WILSON OPEN

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMA 4427 S.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and parking aid.	S/N \$ 480.00	✓ /
2	To dismantle front bumper, rhs front fender and rhs headlight. Renew rhs front fender. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,450.00	100% /
3	To respray front bumper and rhs front fender	\$ 1,700.00	100% /
4	To carry out diagnostic check.	S/N \$ 192.00	✓ /
TOTAL LABOUR CHARGES		: <u>4,822.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 4427 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER RH <i>Dented</i>	\$ 921.00	✓ 735.60
2	FRONT FENDER ATTACHMENTS RH <i>Not Nec.</i>	\$ 49.00	✗
3	FRONT FENDER CLOSING RH	\$ 65.00	✗
4	FRONT FENDER BRACKET RH	\$ 64.00	✗
5	FRONT FENDER BRACE RH	\$ 103.00	✗
6	FRONT FENDER BRACKET RH	\$ 43.00	✗
7	WHEEL HOUSING LINER RH	\$ 246.00	✗
8	WHEEL HOUSING LINER ATTACHMENT RH	\$ 78.00	✗
9	WHEEL HOUSING SPOILER RH	\$ 31.00	✗
10	WHEEL HOUSING STONE CHIP GUARD RH	\$ 44.00	?
11	WHEEL HOUSING LINER TRIM RH <i>Not Nec.</i>	\$ 138.00	✓ 110.90
12	LED HEADLIGHT RH	\$ 7,019.00	✗
13	GUIDE SECTION RH	\$ 31.00	✗
14	PARKING AID SENSOR SEAL <i>Not Nec.</i>	\$ 14.00	✗
15	SUNDRIES <i>New.</i>	\$ 400.00	7 11.60
TOTAL SPARE PARTS CHARGES		\$ 9,246.00	
TOTAL LABOUR CHARGES		\$ 4,822.00	
GRAND TOTAL		\$ 14,068.00	14,111.10

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

10/10/08

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Ling*
Surveyed Date : *17/09/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorized Repairs, 04 Pys*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1035/2018/PH 18-Sep-18 GLORY 1 OF 1 SMA 4427 S A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	RHS WING TRIM <i>Repaired.</i>	\$ 138.00	138.00
2	RHS COVER (SHORT) <i>3 New</i>	\$ 13.10	✓ 10.48
3	RHS COVER (LONG)	\$ 30.00	✓ 24.00
		\$ 181.10	
<u>LABORS</u>			
	TOTAL	\$ 181.10	

Adrian Ling
SLG

For Premium Automobiles Pte Ltd

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PAOD/1035/2018/PH
Date : 06-Sep-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : SLF 7542 H

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
4 days - ok - jb - 18 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lim Thou Yee
Address : 10 Flora Drive
#04-08
Singapore 506942
Telephone : (HP) +65 91181904
Type of Claim : Own Damage Claims
Policy No. : 1800052485
Vehicle No : **SMA 4427 S**
Model Code : AUDI A5 SB 2.0 TFSI
Model / Year : Jun-18
Engine No : CVK 061652
Chassis No : WAUZZZF54JA099662
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 04-Sep-18
Place of Accident : COLLEGE OF MEDICINE BLDG WILSON OPEN

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMA 4427 S.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and parking aid.	S/N	\$ 480.00	\$ 480.00
2	To dismantle front bumper, rhs front fender and rhs headlight. Renew rhs front fender. Re-organize front crash management components. Reinstall all parts removed.		\$ 2,450.00	\$ 1,000.00
3	To respray front bumper and rhs front fender		\$ 1,700.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>4,822.00</u>	<u>2,772.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 4427 S.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remarks</u>
1	FRONT FENDER RH	\$ 921.00	\$ 735.60
2	FRONT FENDER ATTACHMENTS RH	\$ 49.00	
3	FRONT FENDER CLOSING RH	\$ 65.00	
4	FRONT FENDER BRACKET RH	\$ 64.00	
5	FRONT FENDER BRACE RH	\$ 103.00	
6	FRONT FENDER BRACKET RH	\$ 43.00	
7	WHEEL HOUSING LINER RH	\$ 246.00	
8	WHEEL HOUSING LINER ATTACHMENT RH	\$ 78.00	
9	WHEEL HOUSING SPOILER RH	\$ 31.00	
10	WHEEL HOUSING STONE CHIP GUARD RH	\$ 44.00	
11	WHEEL HOUSING LINER TRIM RH	\$ 138.00	
12	LED HEADLIGHT RH	\$ 7,019.00	
13	GUIDE SECTION RH	\$ 31.00	
14	PARKING AID SENSOR SEAL	\$ 14.00	
15	SUPPLEMENTARY	\$ 181.10	\$ 144.88
16	SUNDRIES	\$ 400.00	\$ 11.60
TOTAL SPARE PARTS CHARGES :		\$ 9,427.10	\$ 892.08
TOTAL LABOUR CHARGES :		\$ 4,822.00	\$ 2,772.00
GRAND TOTAL :		\$ 14,249.10	\$ 3,664.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Janice Lee (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, October 18, 2018 5:42 PM
To: Adrian Ling (LKKAuto); SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SMA4427S - OD AIG - SURVEYED 17 SEP 18
Attachments: PA10352018 - SMA 4427 S - AUDI A5 SPORTSBACK 2.0 TFSI - Rear (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$3664.08 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1035/2018/PH

Date

18-Sep-18

Service Advisor

GLORY

Pages

1 OF 1

Regn No

SMA 4427 S

Model No

A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	RHS WING TRIM	\$ 138.00	110.40
2	RHS COVER (SHORT)	\$ 13.10	10.48
3	RHS COVER (LONG)	\$ 30.00	24.00
		\$ 181.10	144.88
LABORS			
TOTAL		\$ 181.10	

For Premium Automobiles Pte Ltd

Authorised Signature

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, November 07, 2018 10:05 AM
To: 'Boo seng yak'; Adrian Ling (LKKAUTO); SUR; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SMA4427S - OD AIG - SURVEYED 17 SEP 18

Dear Mr. Boo,

Confirm \$3,664.08 @ 4 days

*Kindly send us the dv and invoice for our early closure

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Thursday, October 18, 2018 5:42 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SMA4427S - OD AIG - SURVEYED 17 SEP 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$3664.08 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMA 4427 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1035/2018/MAS

10 Nov 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SMA 4427 S, Audi A5 SB 2.0 TFSIS-Tro

With reference to the above-mentioned vehicle, no **SMA 4427 S**, claimant,
Mr. Lim Thou Yee, please find the related document per attached.

1. A copy of the Original invoice no. 85013116 – S\$3,920.57
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SMA 4427 S

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6386 2223
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408653
Telephone: 6386 1031
Telefax: 6386 1031

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6346 2323
6428 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 16:01

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013116 Date : 09/11/2018 Order : SMA44275 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SMA44275 (V 38256) Regn Date: 07/06/2018 Mileage: 5108 WIP No.: 23611
Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF54JA099662 Engine: CVK 061652 Dept: U
USB No.:
You have been assisted by :- UB-Jiayee (50)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND PARKING AID	488.00	1.00	488.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW RHS FRONT FENDER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ABW6821106B	FENDER Less 820%	1.00	919.50	735.60
X	ABW6823746	COVER Less 820%	1.00	13.10	10.40
X	ABW6853602A PUZ	TRIM Less 820%	1.00	138.00	110.40
X	ABW6820562B	COVER Less 820%	1.00	30.00	24.00
X	AN 0161857	POP-RIVET Less 820%	5.00	2.90	11.60

Parts 892.00
Labour 0.00
Sublet 2,772.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,664.00
7% GST 256.49
Grand Total 3,920.57



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMA 4427 S

Norah Khai
6768 9828
6841 1183

Body Repair
PA/OD/1035/2018/PH
21 September 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SB 2.0 TFSI
Vehicle Chassis No. : WAUZZZF54JA0099662
Vehicle Regn No. : **SMA 4427 S**
Vehicle Mileage : 5108 KM
Vehicle Owner : Mr. Lim Thou Yee
Certificate No : 1800052485
Policy Excess : S\$ NIL (Inclusive GST)
Accident Date : 04/09/2018
Place : College of medicine BLDG Wilson Open
Repair Cost : \$ 3,920.57
WIP No. : 23611
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 

Time :

Date : 21/09/2018

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of a woman.

Licence Number: **S8016166B**

Name: **CHONG HOU MENG (ZHANG TAOMIN)**

Date of Birth: **01 Jun 1980**

Issue Date: **27 Jan 2003**

Barcode: **000152666E**

REPUBLIC OF SINGAPORE

Identity Card No. **S8016166B**

Portrait of a woman.

Name: **CHONG HOU MENG (ZHANG TAOMIN)**

张 菊 珉

Race: **CHINESE**

Date of Birth: **01-06-1980**

Sex: **F**

Country of Birth: **SINGAPORE**

4884030

REPUBLIC OF SINGAPORE

Identity Card No. **S7824271Z**

Portrait of a man.

Name: **LIM THOU YEE (LIN DAOYI)**

林 道 毅

Race: **CHINESE**

Date of Birth: **27-08-1978**

Sex: **M**

Country of Birth: **SINGAPORE**

57824271Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Valid Date: **24 Feb 1999**

Licence No: **S8016166B**

NP 428A

Barcode: **4884030**

NRIC No: **S8016166B**

Portrait of a fingerprint.

Date of Issue: **04-06-2010**

Address: **10 FLORA DRIVE #04-08 SINGAPORE 506942**

Barcode: **4271816**

NRIC No: **S7824271Z**

Portrait of a fingerprint.

Date of Issue: **01-09-2008**

Address: **10 FLORA DRIVE #04-08 SINGAPORE 506942**

NRIC No: **S7824271Z**

Date: **04/03/2010**

No: **6436687**



COVER NOTE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder: LIM THOU YEE (LIN DAOYI)
 Period of Insurance: 01 Jan 2018 to 06 Jun 2019
 Engine No.: CVK061652
 Chassis No.: WAUZZZF54JA099662

Vehicle No.: SMA4427S
 Cover Note No.: 1800052485
 Endorsement No.:
 Issued Date: 09 May 2018

ABOUT THE COVER

Make/Model: AUDI A5 Sportback 2.0TFSI S Tronic (Design)
 Engine Capacity/Tonnage: 1,984.00 CC
 Driver Restriction: NA
 Person or Classes of Persons Entitled to Drive*:
 a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)
LIM THOU YEE (LIN DAOYI) - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MALAYAN BANKING BERHAD

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of Insurance.

0504125203

PREMIUM LEASING - KT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

Cheng Qian Yee

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2018		17 Sep 2018 15:58 Edit Adj Rpt	S\$3,664.08 Edit Estimates	S\$3,664.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM THOU YEE , ID: 57624271Z								
Vehicle Reg. No.:	SMA4427S	Date of Loss:	04/09/2018 07:00 - :59 [2 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 8604513176SG	Policy/Cover Note No.:	1800052485 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Daily Amri, Mimi Zarina] MimiZarina.DailyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/09/2018]								
Driver/Custodian:	CHONG HOU MENG (38 / Female), NRIC: S8016166B, Tel: +6598787325								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (21/09/2018): SMA4427S / OD / 04/09/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMA4427S (8604513176SG)**
OD
Sep 4 2018 7:20AM
[LIM THOU YEE]
Premium Automobiles Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#) |
 [Upload Video](#) |
 [Upload Audio](#)

View View in Browser

Video 1 per page ☐

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/18 17:18	Video - Accident [Linked Accident Report Documents]	Load MP4	

Photos/Images 3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/09/18 09:46	General View	Load JPG	☒
2	20/09/18 09:46	General View	Load JPG	☒
3	20/09/18 09:46	General View	Load JPG	☒
4	20/09/18 09:46	General View	Load JPG	☒
5	20/09/18 09:46	General View	Load JPG	☒
6	20/09/18 09:46	General View	Load JPG	☒
7	20/09/18 09:46	General View	Load JPG	☒
8	20/09/18 09:46	General View	Load JPG	☒
9	20/09/18 09:46	General View	Load JPG	☒
10	20/09/18 09:46	General View	Load JPG	☒
11	20/09/18 09:46	General View	Load JPG	☒
12	20/09/18 09:46	General View	Load JPG	☒
13	20/09/18 09:46	General View	Load JPG	☒
14	05/11/18 13:04	Reinspection Photo	Load JPG	☒
15	05/11/18 13:04	Reinspection Photo	Load JPG	☒
16	05/11/18 13:04	Reinspection Photo	Load JPG	☒

Documentation 1 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/09/18 09:42	SMA 4427S EST	Load PDF	
2	20/09/18 09:42	Singapore Accident Statement	Load PDF	
3	21/09/18 10:18	SMA 4427S NRIC & DL	Load PDF	
4	21/09/18 10:18	Certificate of Insurance	Load PDF	
5	13/11/18 10:00	Workshop Invoice	Load PDF	
6	13/11/18 10:00	Discharge Voucher	Load PDF	
7	13/11/18 10:00	Supplementary	Load PDF	

Linked Accident Report Documents

View View in Browser

Video 1 per page ☐

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/18 17:18	Video - Accident	Load MP4	

Assessment Reports 1 per page ☐

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/18 17:33	Accident Statement	Load HTM	

Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
2	15/09/18 13:02	Addendum Sheet	 Load JPG	☒	
3	15/09/18 13:03	Accident Statement Addm. #1	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	04/09/18 17:32	Accident Photo	 Load JPG	☒	
2	04/09/18 17:32	Accident Photo	 Load JPG	☒	
3	04/09/18 17:32	Accident Photo	 Load JPG	☒	
4	04/09/18 17:32	Accident Photo	 Load JPG	☒	
5	04/09/18 17:32	Accident Photo	 Load JPG	☒	
6	04/09/18 17:32	Accident Photo	 Load JPG	☒	
7	04/09/18 17:32	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	04/09/18 12:47	Sketch Plan	 Load JPG	☒	
2	04/09/18 12:47	Sketch Plan #2	 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18016906/ARBE2

Date: 13/11/2018

REFERENCE

Insured/Claimant: LIM THOU YEE Policy No: 1800052485
Date of Loss: 04/09/2018 Nature of Claim: OD Claim No: 8604513176SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA4427S**
Make & Model: AUDI A5, 1.8 SPORTBACK (A) Engine No: CVK061652
Reg. Date: 07/06/2018 (Man. Year: 2018) Chassis No: WAUZZZF54JA099662
Colour: Blue Odometer: 5108 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$210,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/40 R18 Rear Tyre Size: 265/40 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,418.48	892.08	8,526.40	90.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,822.00	2,772.00	2,050.00	42.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,240.48	3,664.08	10,576.40	74.27
+ GST 7.00/7.00% (S\$)	996.83	256.49	740.34	74.27
Nett Amount (S\$)	15,237.31	3,920.57	11,316.74	74.27

INSPECTION

Date of Assignment: 17/09/2018
Date Inspected: 17/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Damaged	921.00 FS	*735.60 FS
2	1		*FRONT FENDER ATTACHMENTS RH	Not Necessary	49.00 FS	*- FS
3	1		*FRONT FENDER CLOSING RH	Not Necessary	65.00 FS	*- FS
4	1		*FRONT FENDER BRACKET RH	Not Necessary	64.00 FS	*- FS
5	1		*FRONT FENDER BRACE RH	Not Necessary	103.00 FS	*- FS
6	1		*FRONT FENDER BRACKET RH	Not Necessary	43.00 FS	*- FS
7	1		*WHEEL HOUSING LINER RH	Not Necessary	246.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ATTACHMENT RH	Not Necessary	78.00 FS	*- FS
9	1		*WHEEL HOUSING SPOILER RH	Not Necessary	31.00 FS	*- FS
10	1		*WHEEL HOUSING STONE CHIP GUARD RH	Not Necessary	44.00 FS	*- FS
11	1		*WHEEL HOUSING LINER TRIM RH	Necessary	138.00 FS	*110.40 FS
12	1		*LED HEADLIGHT RH	Not Necessary	7,019.00 FS	*- FS
13	1		*GUIDE SECTION RH	Not Necessary	31.00 FS	*- FS
14	1		*PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
15	1		*SUNDRIES	Necessary	400.00 FS	*11.60 FS
16	1		*RHS WING TRIM	Repeated	138.00 FS	*- FS
17	1		*RHS COVER (SHORT)	Necessary	10.48 FS	*10.48 FS
18	1		*RHS COVER (LONG)	Necessary	24.00 FS	*24.00 FS
Total Parts (S\$)					9,418.48	892.08

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND PARKING AID	New	480.00	480.00
2	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW RHS FRONT FENDER. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,700.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,822.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >