

ASS. REC. BY:

REF:

CS/FCL18016908 / Gvbn2

Special Instruction:

Surveyor

GA

ASSIGNMENT (Office)

From (Person): CWS Karen Tan

of

FCL

Date/Time: 17092018 3:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 699J

Insured:

SHB 4166Z

at Workshop m/s

Kang Auto

Tel:

6556 0103

of

160 Sin Ming Dr #02-16

Policy No:

Claim No:

D18006785MTSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

17092018 3:41pm

Person Contacted:

May

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJY 699J - CS / ALH 140146FT / RYJ392

DCA: 290714

SHB 4166Z - NBN / INC 18014037 / Y

DCA: 300718

3/10 @ 2:11pm LS \$1150 confirmed with may (Red 1307.60, 53%)

3/10/18

Email preli revised to FCI

Surveyor

XPL.

REF:

Fei

4527A

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP/WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Kang Auto

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$75k

IDAC Accident Rpt.:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

2

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJY 699J

Yr Regn:

30 Nov 2012

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 320i

C/C

1997

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

143002

T/Radio:

Insured / Std / NI / NA

Eng/No:

WBA 3B 160 40 N P 47394

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In Order / Jammed / Leaked / Burnt or

Brake: ☒ In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F: 245/40 R18

R:

11

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

01-10-18

Survey held at

W/S

4:30pm

Des. of Damages: ☒ Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 04 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

3/10 - typist

Report Format :

CWS

Lump Sum / I.B.I: (\$

1150 /

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

110

50

23

183



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006785MFSH
Our ref: CS/FCI18016908/Gvb

Date: 3/10/2018

The Motor Claims Department
M/s First Capital Insurance Limited

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJY 699J


We thank you for your instruction on 17/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/10/2018 at the premises of M/s KANG AUTO ENGINEERING PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$2,457.60
Revised Estimate Amount	:S\$1,150.00 (LUMP SUM)
"Check" Items Amount	:S\$
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)
M.MATAI, AMSAE-A
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-09-2018	Our Ref No. D18006785MFSH
Accident Date	10-09-2018	Claim Type. Third Party
Insured Vehicle	SHB4166Z	Third Party Vehicle. SJY699J
Survey Location	BLK 1 KAKI BUKIT AVE 6 #01-13 AUTOBAY @ KAKI BUKIT	
Contact Person.	MAY ANG	
Contact No.	65560103/ 0	Fax No. 65561015
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KANG AUTO ENGINEERING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 October 2018 2:26 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006785MFSH/1, SJY 699J
Attachments: SJY 699J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJY 699J
Date of survey: 1/10/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 17 September 2018 3:46 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006785MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 17 September, 2018 3:27 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006785MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4527A
Vehicle Details	
Vehicle No.:	SJY699J
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320i AT D/AB 4DR ABS HID NAV M SPORT
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	A9170254N20B20B
Chassis No.:	WBA3B16040NP47394
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$39,338.00
Original Registration Date:	30 Nov 2012
First Registration Date:	30 Nov 2012
Transfer Count:	0
Actual ARF Paid:	\$39,338.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2022
PARF Rebate Amount:	\$27,536.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$92,400.00
COE Rebate Amount:	\$38,423.00
Total Rebate Amount:	\$65,959.00

The information contained herein is correct as at 02 Oct 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4527A

Vehicle Details

Vehicle No.: SJY699J

Vehicle to be Exported: Yes

Intended Deregistration Date: 26 Sep 2018

Vehicle Make: B.M.W.

Vehicle Model: 320I AT D/AB 4DR ABS HID NAV M
SPORT

Primary Colour: White

Manufacturing Year: 2012

Engine No.: A9170254N20B20B

Chassis No.: WBA3B16040NP47394

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$39,338.00

Original Registration Date: 30 Nov 2012

First Registration Date: 30 Nov 2012

Transfer Count: 0

Actual ARF Paid: \$39,338.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Nov 2022

PARF Rebate Amount: \$27,536.00

Intended COE Rebate Details

COE Expiry Date: 29 Nov 2022

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$92,400.00

COE Rebate Amount: \$38,577.00

Total Rebate Amount: \$66,113.00

The information contained herein is correct as at 12 Sep 2018

[> Back to OneMotoring](#)

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SHB4166Z	10 Sep 2018 / 20:00:00	MS FIRST CAPITAL INSURANCE LIMITED

[Print](#)

[OK](#)

[Save as PDF](#)



redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

Certificate of Insurance

account number
11066

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 -Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	PAM SEW CHAW	Certificate number	GA139037 / 1
Cover	Comprehensive	Chassis number	WBA3B16040NP47394
Plan name	Flexi+	Engine number	A9170254N20B208
NCD applicable	50%		
Vehicle registration number	SJY699J		
Period of Insurance	from 30/11/2017 to 29/11/2018 (both dates inclusive)		
Finance loan company	BMW FINANCIAL SERVICES SINGAPORE PTE. LTD.		

Persons or classes of persons entitled to drive*

- (a) The Policyholder.
(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S8816344C**
 Name: **JASON ONG KOON YEW (WANG KUNYAO)**
 Birth Date: **11 May 1988**
 Issue Date: **22 Sep 2006**

001447078G

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8816344C


 Name: **JASON ONG KOON YEW**
王坤耀
 Race: **CHINESE**
 Date of birth: **11-05-1988** Sex: **M**
 Country of birth: **SINGAPORE**

S8816344C

(91776990)

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

PASS DATE: **22 Sep 2006**

NP 428A

Licence No: S8816344C

4854143


 NRIC No: **S8816344C**


 Date of issue: **27-03-2013**

Address:
22 CANBERRA DRIVE
#06-08
SINGAPORE 768426

KANG

AUTO ENGINEERING PTE LTD



Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S PAM SEW CHAW
22 CANBERRA DRIVE
#08-08
SINGAPORE 768426

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/09/1119
VEHICLE NO : SJY699J
MAKE/MODEL : BMW 320I
DATE OF ACCIDENT : 10.09.2018

1	PC	FRONT BUMPER	cut	S\$	1,265.00	1012
1	SET	FRONT BUMPER CLIPS	mbc		56.00	
1	PC	FRONT BUMPER SIDE RETAINER (R/H)	X		115.00	
1	PC	FRONT BUMPER TOWING COVER	X		128.00	
				S\$	1,564.00	1068
				LESS 10%	156.40	
					1,407.60	961.2

TO PUTTY AND SPRAY PAINT
LABOUR CHARGES

S\$ 600.00 250.
450.00 250.
1461.2
20%: 1150
S\$ 2,457.60

SGD TWO THOUSAND FOUR HUNDRED FIFTY-SEVEN AND CENTS SIXTY ONLY.

YOURS FAITHFULLY,

KANG AUTO ENGINEERING PTE LTD

lump sum repair.
After repair photos.
Gus Giam - 82880282
01/10/18.
3 Days.

3/10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016908/Gvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4166Z	Veh. Inspected	SJY 699J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006785MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	17/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 320i	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBA3B16040NP47394	Colour	WHITE	
Odometer	143002	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	245/40 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	245/40 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	245/40 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/09/2018	Inspection Date	01/10/2018	
Survey held at	KANG AUTO ENGINEERING PTE LTD 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 699J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT	1,265.00	1,012.00
1	SET FRONT BUMPER CLIPS	NECESSARY	56.00	56.00
1	FRONT BUMPER SIDE RETAINER (R/H)	NOT NECESSARY	115.00	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	128.00	-
	LESS 10% DISCOUNT		-156.40	-106.80
			1,407.60	961.20
LABOUR				
	TO PUTTY AND SPRAY PAINT.		600.00	250.00
	LABOUR CHARGES.		450.00	250.00
			1,050.00	500.00
GRAND TOTAL			2,457.60	1,461.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,150.00

Report Ref No. CS/FCI18016908/Gvbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.