

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM18017054/T1ga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHEN XINYOU		Date: 28-08-2020 Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJJ 3607J	Veh. Inspected	SLR 171C	
	Policy No.	GA138454	Coverage (\$)	0.00	
	Claim No.	S8M00W0W	Excess (\$)	0.00	
	Assign From		Assign Date	24/09/2018	
2. Vehicle Particulars & Condition					
	Make & Model	SUBARU IMPREZA	c.c	1600	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JF1GT3KC5HG006383	Colour	SILVER	
	Odometer	18837	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/50 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	205/50 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	205/50 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	205/50 R17	BRIDGESTONE	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	12/09/2018	Inspection Date	24/09/2018	
	Survey held at MOTOR IMAGE ENTERPRISES PTE LTD				
		19 TOA PAYOH LORONG 8 . SINGAPORE 319255			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				