

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	69844
Policy No:	DMPCSN3086821702	Date of Loss:	15/09/2018
Vehicle Reg. No.:	SJZ6296T	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	NG SIK SUAN		
Driver:	VALERIE NG ZHI-YAN		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	15/12/2010
Vehicle Colour:	BROWN		
Engine No:	27186030157361	Chassis No:	WDD2120472A347221
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN		

COST OF CLAIMS

	Amount
Parts	351.00
Miscellaneous Items	370.00
Labour	500.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,221.00
+ GST 7.00% (S\$)	85.47
Nett Amount (S\$)	1,306.47
+ Previous Estimates (S\$)	13,872.64
Claim Total (S\$)	15,179.11

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Oct 2018)

Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/12/10/2018 10:31

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WHEEL SPEED SENSOR LH	0.00 ✓	0.00	dis ✓ *185.00 F ✓
2	1		*L/F BALL JOINT	0.00 ✓	0.00	bt ✓ *73.00 F ✓
3	1		*FRONT ABSORBER BEARING LH	0.00 ✓	0.00	bt ✓ *32.00 F ✓
4	1		*FRONT ABSORBER STOPPER LH	0.00 ✓	0.00	bt ✓ *35.00 F ✓
5	1		*FRONT ABSORBER STOPPER BOOT LH	0.00 ✓	0.00	dis ✓ *26.00 F ✓

F=Franchise part.

Total Parts (S\$)

351.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/12/10/2018 10:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	L/F TYRE	220.00
2	1	REAR WINDSCREEN MOULDING	150.00
Sub Total (S\$)			370.00

195 90% out ✓
 ✓ rec ✓ 150.00 ✓

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REPAIR STEERING LOCK	New ✓ rec ✓	250.00
2	REPROGRAMME STEERING LOCK	New ✓ rec ✓	250.00
Gross Labour Cost (S\$)			500.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/12/10/2018 10:31. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	69844
Policy No:	DMPCSN3086821702	Date of Loss:	15/09/2018
Vehicle Reg. No.:	SJZ6296T	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	NG SIK SUAN		
Driver:	VALERIE NG ZHI-YAN		

Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	15/12/2010
Vehicle Colour:	BROWN		
Engine No:	27186030157361	Chassis No:	WDD2120472A347221
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN

COST OF CLAIMS

	Amount
Parts	88.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	88.00
+ GST 7.00% (S\$)	6.16
Nett Amount (S\$)	94.16
+ Previous Estimates (S\$)	15,179.11
Claim Total (S\$)	15,273.27

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Oct 2018)

Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/18/10/2018 11:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/F W-HOUSE CVR REAR	0.00	0.00	*88.00 F (A)
Total Parts (S\$)						88.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/18/10/2018 11:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/18/10/2018 11:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	69844
Policy No:	DMPCSN3086821702	Date of Loss:	15/09/2018
Vehicle Reg. No.:	SJZ6296T	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	NG SIK SUAN		
Driver:	VALERIE NG ZHI-YAN		

Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	15/12/2010
Vehicle Colour:	BROWN		
Engine No:	27186030157361	Chassis No:	WDD2120472A347221
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN

COST OF CLAIMS	Amount
Parts	182.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	182.00
+ GST 7.00% (S\$)	12.74
Nett Amount (S\$)	194.74
+ Previous Estimates (S\$)	15,273.27
Claim Total (S\$)	15,468.01

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2019)**Parts:** 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/11/04/2019 17:39**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RIGHT OUTER TIE ROD BALL	0.00	0.00	*88.00 F <i>ms</i>
2	1		*RIGHT TIE ROD	0.00	0.00	*94.00 F <i>ms</i>
Total Parts (S\$)						182.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/11/04/2019 17:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ6296T/11/04/2019 17:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >