

ASS. REC. BY:

REP:

CS/FCI18017093/ Urd3 n2

Special Instruction:

Survivor:

Marius

ASSIGNMENT (Office)

CWS

From (Person):

Karen Tan

of

FCI

Date/Time: 19/9/18 @ 5:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 3737C

Insured:

SH 7706J

at Workshop m/s

Kah Motor

Tel:

68 465671

of

15 Ubi Rd 4

Policy No:

Claim No:

D18006913MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 09/09/2018

20/9/18 @ 4:30pm.

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

5:20pm @ 19/9/18

Person Contacted:

Mr. Lim

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKT 3737C - X

SH 7706J - CC3 / III 16017319 / M/wb 3q2

D.O.A. 11/9/16

Revert thru email.

REF: FCI

## ASSIGNMENT

Front Date 20/9/18

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT 3737C

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

CA / PR Seen:


Est. Repairs:

Lum Sum:

CA / REV / REP. 1-24 HRS 'up

Date:

Person Contacted:

Kah Motor  
15 Ubi Rd 44-30pm owner waiting  
Mr. Lim

Veh No: SKT 3737C Yr Regn: 6, 15

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or ☒ CA /

Make: Honda Jate cc 1498

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 27642 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHM6K5850 FX20 3/13

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55 R16  
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. mm  
L/Bal. mm  
D.O.A. 9/9/18

Rear R/Bal. mm  
L/Bal. mm  
D.O.I. 20/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Grs. 9-11/18 &amp; 20

9/11/18 confirmed final R/L of \$1497.54 with Mr. Lim.  
(Red: \$319.40, 18%)

RECEIVED 09 NOV 2018

Signature  
9/11/2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.L. (\$) 1497.54

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee:

☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

) S + RS (\$)

) Photos

) Others

TOTAL

100

50

50 + 50

45

295



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017093/Urd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-09-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7706J	Veh. Inspected	SKT 3737C
Policy No.		Coverage (\$)	0.00
Claim No.	D18006913MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	19/09/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	09/09/2018	Inspection Date	20/09/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006913MFSH

Date: 9 November 2018

Our Ref: CS/FCI18006913/Urd3

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SKT 3737C .**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/09/2018 at the premises of M/s Kah Motor Co. Sdn Bhd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,816.94</u> .
Revised Estimate Amount	: S\$ <u>1,497.54</u> .
"Check" Items Amount	: S\$ <u>                    </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:  
The vehicle sustained damages  
at the n/s front portion.



Yours faithfully

MARCUS  
Automotive Assessor

### MOTOR SURVEY ASSIGNMENT

Date	19-09-2018	Our Ref No. D18006913MFSH
Accident Date	09-09-2018	Claim Type. Third Party
Insured Vehicle	SH7706J	Third Party Vehicle. SKT3737C
Survey Location	15 UBI ROAD 4	
Contact Person.	LIM CHOU SIONG	
Contact No.	68465671/ 81006303	Fax No. 67480770
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244335)



PRI Documents



Close



## PRI Header Details

Claim No	D18006913MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & KAH MOTOR
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : LIM CHOU SIONG)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 81006303 , Phone: 68465671 , Fax: 67480770 EmailId: CSLIM@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7706J	TP Vehicle No	SKT3737C
PRI Recieved Date	19-09-2018 04:53:32 PM	Surveyor Appointed Date	19-09-2018 05:15:49 PM	Surveyor Accept Date	19-09-2018 0

## Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-09-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

## Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

## Janice Lee (LKKAUTO)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Friday, November 09, 2018 10:27 AM  
**To:** 'Claim Workflow System'  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG  
**Subject:** RE: SURVEY ASSESSMENT - D18006913MFSH/1  
**Attachments:** SKT 3737C.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SKT 3737C

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, September 19, 2018 5:22 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18006913MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Wednesday, 19 September 2018 5:16 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18006913MFSH/1

Dear Sir/Mdm,

We refer to the above reference.  
Please find attached the necessary documents for survey.  
Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number:** 5079815085-02

**Cover :** drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SKT3737C**  
 Chassis Number : JHMGK5850FX203113
2. Name of Policyholder : **NG HWEE YIAN (HUANG HUIYAN)**
3. Effective Date of Insurance : **10 Jun 2018**
4. Expiry Date of Insurance : **09 Jun 2019**
5. Persons or Classes of Persons entitled to drive#  
 (a) The Policyholder.  
 (b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#  
 (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

**This Policy does not cover**

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: NG HWEE YIAN (HUANG HUIYAN)
NAMED DRIVER (1)	: CHUNG CHEE WAH (ZHANG ZHIHUA)
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: OCBC BANK LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TELESales-DIRECT MARKETING (00000601661)  
 Date of Issue : 21 May 2018 20:54 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

\_\_\_\_\_  
 Authorised Officer



\_\_\_\_\_  
 Chief Executive

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7618279E



Name  
NG HWEE YIAN  
(HUANG HUIYAN)

黄慧燕

Race

CHINESE

Date of Birth

22-06-1976

Sex

F

Country of Birth

SINGAPORE

S7618279E

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S7618279E

Name

NG HWEE YIAN  
(HUANG HUIYAN)

Birth Date: 22 Jun 1976

Issue Date: 25 Mar 2013



002163882K

3009076



NRIC No. S7618279E



Blood Group Date of issue

O+

17-02-1998

BLK 42 DAKOTA CRESCENT #07-20  
SINGAPORE 399940

NRIC No: S7618279E

Date: 02/02/2011 (R)


No: 6676202

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 16 May 2001

~



Licence No: S7618279E

NP 428A

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article



**Inchcape**  
Pre-Owned

**WIDE RANGE OF PRE-OWNED  
TOYOTA AND OTHER MAKES  
AVAILABLE**

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRES

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

10 Or 5 Years COE Extension. High OMV \$30222.


 Accident Free Panoramic Roof  
Black Interior Multi Function  
Steering AFS Lights.  
Direct Owner StarAd


Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by

11 vehicles

honda jazz

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
<b>Search Selection</b>	<b>honda jazz</b>		Any	Any	<b>2015</b>	Any	
	<b>Honda Jazz 1.5A RS</b>		<b>\$61,800</b>	<b>\$9,020 /yr</b>	<b>13-Apr-2015</b>	<b>1,498 cc</b>	<b>74</b>
High Loan Available! 1 Owner, Kah Motor Unit, Serviced And Maintained By Kah Motor, 5 Years Warranty! Hua Yang Group Certified, Bank Loan, In House Loan, Balloon Scheme, 100% ...							
Hua Yang Credit Pte Ltd							
Posted: 19-Sep-2018 Tags: 2015 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda							
	<b>Honda Jazz 1.5A RS</b>		<b>\$63,800</b>	<b>\$8,500 /yr</b>	<b>27-Aug-2015</b>	<b>1,498 cc</b>	<b>48</b>
High Loan Available! 1 Owner, Kah Motor Unit, Serviced And Maintained By Kah Motor, 5 Years Warranty From First Regi Km Mileage Free Servicing, Definitely Worth Buying This ...							
Creative Auto							
Posted: 15-Sep-2018 Tags: 2015 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda							
	<b>Honda Jazz 1.5A RS</b>		<b>\$55,800</b>	<b>\$8,420 /yr</b>	<b>19-Jan-2015</b>	<b>1,498 cc</b>	
1 Owner, Maintained, And Servicing By Agent 5 Year Warranty By Kah Motor, Excellent Condition Inside Out, Regularly Se To Believe, Call Or Sms Our Friendly Staff For Viewin...							
Posted: 14-Sep-2018 Tags: 2015 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda							
	<b>Honda Jazz 1.5A</b>		<b>\$59,366</b>	<b>\$8,460 /yr</b>	<b>19-May-2015</b>	<b>1,498 cc</b>	<b>55</b>
High Loan Available! 1 Owner, Kah Motor Unit, Serviced And Maintained By Kah Motor, 5 Years Warranty From First Regi Km Mileage Free Servicing, Definitely Worth Buying This ...							
Creative Auto							
Posted: 10-Sep-2018 Tags: 2015 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda							

Car Buying

Car Selling

Car Ownership

Compare

On The Move

Lifestyle

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8279E
<b>Vehicle Details</b>	
Vehicle No.:	SKT3737C
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15B31000518
Chassis No.:	JHMGK5850FX203113
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$15,189.00
Original Registration Date:	10 Jun 2015
First Registration Date:	10 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$5,189.00 2594
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2025
PARF Rebate Amount:	\$3,891.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,749.00
COE Rebate Amount:	\$45,517.00
<b>Total Rebate Amount:</b>	<b>\$49,408.00</b>

The information contained herein is correct as at 21 Sep 2018

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

*Cindly Help to arrange  
Surveyor to survey this  
Vehicle thanks***QUOTATION**GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Page 1

Customer : MS FIRST CAPITAL INSURANCE  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

Registration No : SKT3737C  
Chassis No : JHMGK5850FX203113  
Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)  
Owner's Name : NG HWEE YIAN  
Ins Policy No. :  
Date of Accident : 9/9/2018

Document No. : SQT18003888  
Date : 15. Sep 2018  
Customer No. : WZF002  
Svc Advisor : LIM CHOU SIONG  
Engine No : L15B31000518  
Date | Time : 15. Sep 2018 8:17:53 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NG HWEE YIAN OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD ACC DATE: 9/9/2018 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SH7706J						
76251-T5A-J31ZG	CAPL SKULL <i>mirror cover</i>	<i>one</i> 1	50.90	25	38.17	2.67	40.84
76258-T5A-J32	MIRROR ASSY. L.	<i>one</i> 1	496.60	25	372.45	26.07	398.52
67364-T5A-003	TAPE SET L. FR. DOOR	<i>one</i> 1	32.90	25	24.67	1.73	26.40
72450-TD4-003	MOLDING ASSYL. FR. DOOR	<i>two</i> 1	42.20	25	31.65	2.22	33.87
			<i>43.00</i>		<b>Sum Item</b> 466.94	<b>32.69</b>	<b>499.63</b>
BOSUN	SUNDRIES	<i>one</i> 1	50.00	20	50.00	3.50	53.50
BKDR11K	REPLACE FR L WING MIRROR ASSY., KNOCK & REPAIR	1	700.00	<i>560</i>	700.00	49.00	749.00
BP01R	FR L DOOR	1	600.00	<i>450</i>	600.00	42.00	642.00
	SPRAY PAINTING ON FR L DOOR				<b>Sum Labor</b> 1350.00	<b>94.50</b>	<b>1,444.50</b>

Survey By Marcus Loke *C Slim* 1817.54

Date & Time 20/9/18 Total Amount 1,816.94 127.19 1,944.13

Excess --- Total (Inclusive of GST) 1,944.13

Status No Authorised

Signature Who photo After repair *2 ch*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 15/9/2018 8:28:39 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480

08/11/2018 Page 1/1

© **SERVICE PRE-INVOICE**

Attn: Marcus (L.K.K.)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

2 days

**Customer:** WZF002 / MS FIRST CAPITAL  
**Chassis No:** JHMGK5850FX203113  
**License No:** SKT3737C  
**Mileage:** 28988  
**Engine No:** L15B31000518

**Document No:** SVO18065904  
**Printed By:** CSLIM  
**Order Date:** 7. November 2018  
**Order Time:** 10:01:20 AM  
**Service Advisor:** LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Includ Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 71555) OWNER: NG HWEE YIAN OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD ACC DATE: 9/9/2018 SURVEYED BY: MARCUS ( L.K.K. ) DATE: 20/09/2018 @ 16:30PM REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SH7706J						
76261-T5A-J31ZG	CAPL.SKULL	1	50.90	25	38.17	2.67	40.84
76258-T5A-J32	MIRROR ASSY,L	1	496.60	25	372.45	26.07	398.52
6736A-T5A-003	TAPE SETL.FR.DOOR	1	32.90	25	24.87	1.73	26.40
72450-TD4-003	MOLDING ASSYL.FR.DOOR	1	43.00	25	32.25	2.26	34.51
	<b>SUM PARTS:</b>				<b>467.64</b>	<b>32.73</b>	<b>500.27</b>
BOSUN	0672 SUNDRIES	1	20.00		20.00	1.40	21.40
BKDR11K	EXT-YJ REPLACE FR L WING MIRROR ASSY., KNOCK & REPAIR FR L DOOR.	1	580.00		580.00	39.20	599.20
BP01R	EXT-YBH SPRAY PAINTING ON FR L DOOR	1	450.00		450.00	31.50	481.50
	<b>SUM LABOUR:</b>				<b>1,030.00</b>	<b>72.10</b>	<b>1,102.10</b>
	<b>TOTAL SGD</b>				<b>1,497.64</b>	<b>104.83</b>	<b>1,602.37</b>

**Total Payable (SGD)****1,602.37**

GST Amount is calculated from individual line(s)






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017093/Urd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-11-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 7706J	Veh. Inspected	SKT 3737C	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18006913MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	19/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA JAZZ (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHMGK5850FX203113	Colour	GREY	
Odometer	27642	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	YOKOHAMA	8 mm	
L/H Front Tyre	185/55 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm	
L/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/09/2018	Inspection Date	20/09/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 3737C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	CAPL SKULL MIRROR COVER (SN)	CRACKED	38.17	38.17
1	MIRROR ASSY,L (SN)	CRACKED	372.45	372.45
1	TAPE SETL FR DOOR (SN)	NECESSARY	24.67	24.67
1	MOLDING ASSYL FR DOOR (SN)	TWISTED	32.25	32.25
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			517.54	487.54
<b>LABOUR</b>				
	REPLACE FR L WING MIRROR ASSY,KNOCK & REPAIR FR L DOOR.		700.00	560.00
	SPRAY PAINTING ON FR L DOOR.		600.00	450.00
			1,300.00	1,010.00
<b>GRAND TOTAL</b>			<b>1,817.54</b>	<b>1,497.54</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,497.54</b>

Report Ref No. CS/FC118017093/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.