

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

Not Adjust
2/53
Wholesale Price
Sdy
21/9/18

PC2616E Golden Dragon XML6957J14B

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>Dis</i>	\$ 2,800.00 ✓
2	2	Rear side reflector <i>0/5000</i>	\$ 282.00 <i>42</i>
3	1	Rear tailgate assy <i>2</i>	\$ 6,700.00 <i>x</i>
4	1	Rear tailgate xiamen golden dragon bus co ltd emblem <i>mer</i>	\$ 350.00 ✓
5	1	Rear tailgate XML6957J14B emblem <i>mer</i>	\$ 250.00 ✓
6	1	Rear tailgate outer handle <i>11</i>	\$ 195.00 <i>x</i>
7	1	Rear left taillamp <i>22 11</i>	\$ 750.00 <i>x</i>
8	1	Rear right taillamp <i>1 11</i>	\$ 750.00 ✓
9	1	Rear lower panel assy	\$ 4,870.00 <i>?</i>
10	1	Rear left lower side panel <i>2</i>	\$ 3,600.00 <i>x</i>
11	1	Rear right lower side panel <i>11</i>	\$ 3,600.00 ✓
12	1	Rear air con compressor <i>11</i>	\$ 2,600.00 <i>x</i>
13	1	Rear air con fan cowling <i>11</i>	\$ 450.00 <i>x</i>
14	1	Rear air con fan blade <i>11</i>	\$ 250.00 <i>x</i>
15	1	Rear air con fan pulley <i>11</i>	\$ 650.00 <i>x</i>
16	1	Rear air con fan belt <i>11</i>	\$ 240.00 <i>x</i>
17	1	Rear air con fan motor assy <i>11</i>	\$ 360.00 <i>x</i>
18	1	Rear power steering pump assy <i>11</i>	\$ 4,500.00 <i>x</i>
19	1	Rear power steering pump belt <i>11</i>	\$ 200.00 <i>x</i>
20	1set	Rear power steering pump pulley <i>11</i>	\$ 1,200.00 <i>x</i>
21	1	Rear engine crankshaft pulley belt <i>11</i>	\$ 240.00 <i>x</i>
22	1	Rear engine crankshaft pulley <i>11</i>	\$ 1,400.00 <i>x</i>
23	1	Rear engine alternator assy <i>11</i>	\$ 2,800.00 <i>x</i>
24	1	Rear engine air con compressor fan belt <i>11</i>	\$ 200.00 <i>x</i>
25	1set	Rear engine wire harness complete assy <i>11</i>	\$ 800.00 <i>x</i>
26	1set	Rear left engine mounting <i>11</i>	\$ 380.00 <i>x</i>
27	1set	Rear right engine mounting <i>11</i>	\$ 380.00 <i>x</i>
28	1set	Rear centre engine mounting <i>11</i>	\$ 380.00 <i>x</i>
29	1set	Rear gearbox mounting <i>11</i>	\$ 380.00 <i>x</i>
			\$ 41,557.00
Less 10%			\$ 4,155.70
			\$ 37,401.30

Special Nett Items

1	1	Rear 60km/h sticker	<i>mer</i> \$ 30.00 <i>10</i>
2	1set	Rear company sticker	<i>mer</i> \$ 350.00 ✓
3	1	Rear no plate	<i>31</i> \$ 80.00 <i>40</i>
			\$ 460.00

Total parts

\$ 37,861.30

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

PC2616E Golden Dragon XML6957J14B

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 3,500.00 2500
2	To putty and spray painting rear portion.	\$ 3,500.00 1500
3	To apply anti rust proofing to rear affected area.	1 1 \$ 180.00 X
4	To remove and install rear engine to facilitate the repair.	1 1 \$ 650.00 X
5	To remove and install rear alternator assy.	1 1 \$ 350.00 X
6	To remove and install rear power steering pump assy.	1 1 \$ 350.00 X
7	To remove and install rear engine pulley and belting assy.	1 1 \$ 350.00 X
8	To remove and install rear air con compressor assy.	1 1 \$ 350.00 X
9	To remove and install rear engine mounting.	1 1 \$ 400.00 X
10	To remove and install rear gearbox mounting.	1 1 \$ 400.00 X
11	Towing service.	1 1 \$ 250.00 X
Total labour :		\$ 10,280.00

Total parts : \$ 37,861.30

Total labour : \$ 10,280.00

Total repair cost : \$ 48,141.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: