

INSURANCE

INS. CASE OWNER

CC 4/18/1801

LKK
IDAC

Surveyor:

ECMETH

DOI:

ASSIGNMENT

20/1/18

Date / Time:

20/1/18

Registered in Merimen:

20/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

512 5762M

Name of Insured:

UR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

20/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO: Driver Name / Age:

Vinh PFF Ho

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

9075 26 78756

Policy No.:

99999999

Make / Model:

HONDA

Place of Accident:

WUQUEN RO TMS
THUMSON RO

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKG 9115L



INSRS:
WSP:
Tel:
Liability:
RMKS:

Cheng
Hoe



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

20/1/18
vinh
27/1/18

SKG 9115L-x 512 5762M-x

email letter, to 02

STAGE

DATE / PIC

Non-Reporting hr (1st):
Non-Reporting hr (2nd):
Non-Reporting hr (Final):
Notification hr (if non-pickup):
Call OI:
After call hr to OI: 27/1/18 email.

Documentation Check List: Handler Typist

Notification hr (if non-pickup)	☒	☐
After call hr to OI	☒	☐
Authorisation To Act	☒	☐
Release Voucher	☒	☐
Final Repair Bill	☒	☐
Car Rental Invoice	☒	☐
Towing Invoice	☒	☐
LTA / GIA	☒	☐
Medical Bill	☒	☐
PDR	☒	☐
Mandate/Reject Instruction	☒	☐
LOD	☐	☐
Payment Breakdown Form	☐	☐
Post-Repair Photos	☐	☐
Others	☐	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

31-1-19

Confirm with:

JUNE

Email

Cal

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: NIL

If NO or B 28, Ass. Lia:

Repair Cost:

GST

SS

5,136.xx

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

-

(days)

Loss of Income (LOI):

SS

900

(5

100 x 9

days)

THUMSON CM

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search

SS

8.44

Medical

SS

-

Disbursement:

SS

-

(e.g. Tow/Independent)

Legal Cost

SS

-

Total:

SS

6,044.xx

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

SS

6,044.xx

Name 1:

CHENG HOE MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

x

Name 2:

x

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee:

ASS. REC. BY:

REF:

ALG

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKG 93756

Yr Regn: 10, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

c.c. 1598

Colour:

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

110465

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053R EE 104149369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size:

Maxxis 205/55R16

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

19/9/18

D.O.I.

20/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/9 File pass to Catherine

31/1 11 By 8480d Confirmed E-Code

Tuition Co
(8+1 x 100)

R(\$1,996.78/2970)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/LCR18017127/Kwb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 20-09-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 5762U	Veh. Inspected	SKG 9325L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/09/2018	Inspection Date	20/09/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1891076/AMK

Date: 20 Sep 2018

Policy No: 5091916894

Veh Reg No: SKG9325L

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053REE104149369

Engine No: 1ZR230396

Reg. Date: 23/10/2012

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 19/09/2018

TP Veh Reg No: SLQ5762U

Not Authorized

Liberty

Resurvey After Paint

Today

Estimate Repair Cost to Vehicle No :SKG9325L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT LH DOOR	1,201.70	1PC	1,201.70	✓
2 FRONT LH DOOR INNER LOCK	411.67	1PC	411.67	✓
3 FRONT LH DOOR POWER WINDOW MOTOR	401.90	1PC	401.90	✓
4 FRONT LH DOOR POWER WINDOW REGULATOR	181.75	1PC	181.75	✓
5 FRONT LH DOOR FRAME STICKER	68.10	1SET	68.10	✓
6 FRONT LH DOOR INNER RUBBER	178.90	1PC	178.90	✓
7 FRONT LH DOOR PROTECTOR	95.20	1PC	95.20	✓
8 FRONT LH DOOR CHROME	34.20	1PC	34.20	✓
9 REAR LH DOOR	1,091.23	1PC	1,091.23	✓
10 REAR LH DOOR POWER WINDOW MOTOR	401.91	1PC	401.91	✓
11 REAR LH DOOR REGULATOR	181.75	1PC	181.75	✓
12 REAR LH DOOR CHECKER	171.03	1PC	171.03	✓
13 REAR LH DOOR PROTECTOR	89.80	1PC	89.80	✓
14 REAR LH DOOR PROTECTOR CHROME	29.80	1PC	29.80	✓
15 REAR LH DOOR FRAME STICKER	68.10	1SET	68.10	✓
16 LH CENTRE DOOR PILLAR	409.12	1PC	409.12	✓
			5,016.16	
		Less 25%	1,254.04	3,762.13
Labour				
17 REMOVE & REFIX BOTH LH DOOR & ATTACHMENTS:TO CUT,WELD & RENEW LH CENTRE DOOR PILLAR:KNOCKING & REPAIR BOTH LH FENDERS & REALIGN THE SAME	1,100.00	1LA	1,100.00	✓
18 PUTTY & RESPRAY BOTH BUMPERS, BOTH LH FENDERS,BOTH LH DOORS,LH CENTRE DOOR PILLAR & ALL AFFECTED AREAS	1,200.00	1LA	1,200.00	✓
19 REMOVE & REFIX BOTH LH DOOR WINDOW GLASSES AND RESET CENTRAL LOCKING	100.00	1LA	100.00	✓
20 REMOVE & REFIX LH SEATS,CARPET TO FACILITATE REPAIR	100.00	1LA	100.00	✓
21 RUSTPROOFING	90.00	1LA	90.00	✓
			2,590.00	2,590.00

REPAIR TO FACILITATE
The Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 19/09/2018
TP Veh Reg No: SLQ5762U

Estimate No: ES1891076/AMK
Date: 20 Sep 2018
Policy No: 5091916894
Veh Reg No: SKG9325L
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053REE104149369
Engine No: 1ZRX230396
Reg. Date: 23/10/2012

Estimate Repair Cost to Vehicle No :SKG9325L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	S\$ 6,352.13
			Add GST @ 7%	444.65
			Total Amount Payable	<u>S\$ 6,796.78</u>

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 7078J

Vehicle Details

Vehicle No.: SKG9325L
Vehicle to be Exported: No
Intended Deregistration Date: 19 Sep 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Silver
Manufacturing Year: 2012
Engine No.: 1ZRX230396
Chassis No.: MR053REE104149369
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$14,944.00
Original Registration Date: 23 Oct 2012
First Registration Date: 23 Oct 2012
Transfer Count: 2
Actual ARF Paid: \$14,944.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Oct 2022
PARF Rebate Amount: \$10,460.00

Intended COE Rebate Details

COE Expiry Date: 22 Oct 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$63,000.00
COE Rebate Amount: \$25,775.00
Total Rebate Amount: \$36,235.00

The information contained herein is correct as at 19 Sep 2018

OK

W-3 j'

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	:	SLQ5762U
Claimant Vehicle No.	:	SKG9325L
Date of Accident	:	19/09/2018
Traffic Accident involving vehicle/s No.	:	MOULMEIN ROAD

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 5,136.00	
2	Loss of Income	\$ 900.00	(\$100 x 9 days) Tuition car
3	LTA Search	\$ 8.00	
TOTAL		\$ 6,044.00	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Thursday, 27 September, 2018 2:24 PM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO)
Subject: ACCIDENT INVOLVING SKG 9325L and SLQ 5762U on 19/09/2018

Our Ref: CC4/LCR18017127/Kwb3

27 September 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SKG 9325L and SLQ 5762U on 19/09/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT
(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

I, Lau Chai Cheng (the third party claimant) of R1k 188B Rivervale Drive #15-1074 S 642188 (address), owner of SKG9325L (vehicle no.) hereby authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SKG9325L that was damaged pursuant to the accident which occurred on 19/9/2018 (date) along Moulmein Road (location) involving vehicle no/s SLQ5762U ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 19 (day) of Sept (month) 20 18 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident. This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, CHENG HOE MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$5136.00 (Repair Cost), S\$900.00 (Loss of Income), S\$8.00 (Disbursement), for vehicle no SKG9325L that was damaged pursuant to the accident which occurred 19/9/2018 (date) along Moulmein Road (location) involving vehicle no/s SLQ5762U. This is pursuant to the inspection conducted on 28/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Lau Chai Cheng ("the third party claimant") of vehicle no. SKG9325L make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage SKG9325L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23 (day) of Feb (month) 2019 (year)


LKK

Signed by appointed surveyor


Y

Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

NO: CL8190025
Date: 23 Jan 2019
Policy No: 5091916894
Veh Reg No: SKG9325L
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Job No: JC1599030

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 19/09/2018
TP Veh Reg No: SLQ5762U

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	S\$ 4,800.00	S\$ 4,800.00

Total	S\$ 4,800.00
Add GST @ 7%	336.00
Total Amount payable	S\$ 5,136.00

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358
TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD	BILL NO: B067/ 2018
YOUR REF:	
OUR REF : ACS.CH.LTA.2018 (SEPT 2018)	DATE : 11/10/18

TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusal, attendance preparation examination of documents relating thereto; correspondence, attendance perusal, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.

LTANET SEARCHES FOR THE MONTH SEPTEMBER 2018

S/NO	TP NO.	CHM	DOA
1	1/9/2018	SFG8078R	SKJ6349Y 31/8/2018
2	3/9/2018	SFB8390P	SJM9547T 3/9/2018
3	3/9/2018	YP9103Y	SKW5225J 2/9/2018
4	3/9/2018	GBF3839Y	SCN8900R 2/9/2018
5	3/9/2018	SKF3018T	SKC2888X 31/8/2018
6	4/9/2018	GBA1406C	SLN8297S 4/9/2018
7	6/9/2018	SLG6161A	SLB1606T 4/9/2018
8	8/9/2018	XE808B	SGJ3486B 7/9/2018
9	14/9/2018	GBC9612K	SJM2879G 13/9/2018
10	15/9/2018	SLA610S	EJ9989B 15/9/2018
11	17/9/2018	SLH4163C	SLD3079R 16/9/2018
12	18/9/2018	SKH4674G	SCR7268T 17/9/2018
13	19/9/2018	SFR1308R	SJL9723G 15/9/2018
14	19/9/2018	SLQ5762U	SKG9325 19/9/2018
15	19/9/2018	SJU5151K	XD5672Y 16/9/2018
16	19/9/2018	SKP6097S	SMA5560R 19/9/2018
17	20/9/2018	SJE66919G	SJT1165 19/9/2018
18	24/9/2018	SGM9692S	SJG4447M 21/9/2018
19	25/9/2018	GBG7025Y	SLZ1308C 24/9/2018
20	26/9/2018	SCU8333R	GBF5787A 16/9/2018
21	26/9/2018	XD1714L	YP6458T 4/9/2018
22	28/9/2018	SKV8930S	SJR2439S 27/9/2018

22 searches @\$8.00 per search

S 176.00

[SINGAPORE DOLLARS: ONE HUNDRED & SEVENTY-SIX ONLY.]

M/s. A.C. SYED & PARTNERS
ADVOCATES & SOLICITORS
SINGAPORE

We reserved the right to forward a subsequent bill for any
disbursements omitted herein.

E. & O.E.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2018 Edit Reg		20 Sep 2018 00:00 Edit Adj Rpt	S\$4,800.00 Edit Estimates	S\$4,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	LAU CHAI CHENG, ID: S01770783								
Vehicle Reg. No.:	SKG9325L	Date of Loss:	19/09/2018 00:00 - :59 [70 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7075288387SG	Policy/Cover Note No.:	0999994807 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLQ5762U	Policy No. (Claimant):	5091916894						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Bldg 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angle-GL] Angiegeokling.Gan@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (21/09/2018): Request To Upload TP GIA Report - AIG_SG (21/09/2018): < No subject >									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKG9325L (7075288387SG)**
[SLQ5762U]
TP
LAU CHAI CHENG
Sep 19 2018 12:00AM
[LCRF PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/03/19 11:57	LKK INSPECTION PHOTOS		Load PDF	
2	04/03/19 11:57	LKK RE-INSPECTION PHOTOS		Load PDF	
3	04/03/19 11:57	LKK RE-INSPECTION PHOTOS 2		Load PDF	

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	20/09/18 14:42	EMAIL FROM AIG DD 20092018		Load PDF	
2	21/09/18 17:16	TP ESTIMATE- MARKED		Load PDF	
3	21/09/18 17:16	TP GIA REPORT		Load PDF	
4	27/09/18 14:26	Email letter to OI ACCIDENT INVOLVING SKG 9325L and SLQ 5762U on 19.09.2018		Load PDF	
5	05/03/19 10:03	WORKSHOP INVOICE		Load PDF	
6	05/03/19 10:03	AUTHORISATION TO ACT FORM		Load PDF	
7	05/03/19 10:03	Release Voucher		Load PDF	
8	05/03/19 10:03	LTA SEARCH		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	21/09/18 14:38	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ5762U (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SKG9325L (TP veh)		1.6 (A)
Date of Accident:	19/09/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	: \$	6,796.77	
Final Repair Cost	: \$	5,136.00	
Loss of Use	: \$	900.00	9.00 days at \$100.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	8.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	6,044.00	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____100____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	: \$	6,044.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

05 Mar
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18017127/KJB3Q2

Date: 05/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994807

Claimant Vehicle No : SKG9325L

Insured Vehicle No : SLQ5762U

Date of Loss: 19/09/2018

Nature of Claim:

TP

Claim No: 7075288387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG9325L

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Reg. Date: 23/10/2012 (Man. Year: 2012)

Colour: Metallic Silver

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1ZRX230396

Chassis No: MR053REE104149369

Odometer: 110465 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Maxxis 7 mm

Rear Left Side: Goodyear 5 mm

Front Right Side: Maxxis 7 mm

Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,762.12	3,717.39	44.73	1.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	2,290.00	300.00	11.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,352.12	6,007.39	344.73	5.43
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	6,352.12	4,800.00	1,552.12	24.43
+ GST 7.00/7.00% (S\$)	444.65	336.00	108.65	24.43
Nett Amount (S\$)	6,796.77	5,136.00	1,660.77	24.43
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		6,044.00		

INSPECTION

Date of Assignment: 20/09/2018

Date Inspected: 20/09/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial

Park A
Singapore 768761

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,201.70 FL	*1,201.70 FL
2	1		*FRONT LH DOOR INNER LOCK	Dented	411.67 FL	*411.67 FL
3	1		*FRONT LH DOOR POWER WINDOW MOTOR	Jammed	401.90 FL	*401.90 FL
4	1		*FRONT LH DOOR POWER WINDOW REGULATOR	Distorted	181.75 FL	*181.75 FL
5	1		*SET FRONT LH DOOR FRAME STICKER	Necessary	68.10 FL	*68.10 FL
6	1		*FRONT LH DOOR INNER RUBBER (50%)	Cut	134.18 FS	*89.45 FS
7	1		*FRONT LH DOOR PROTECTOR	Dented	95.20 FL	*95.20 FL
8	1		*FRONT LH DOOR CHROME	Buckled	34.20 FL	*34.20 FL
9	1		*REAR LH DOOR	Bent	1,091.23 FL	*1,091.23 FL
10	1		*REAR LH DOOR POWER WINDOW MOTOR	Jammed	401.91 FL	*401.91 FL
11	1		*REAR LH DOOR POWER REGULATOR	Bent	181.75 FL	*181.75 FL
12	1		*REAR LH DOOR CHECKER	Distorted	171.03 FL	*171.03 FL
13	1		*REAR LH DOOR PROTECTOR	Dented	89.80 FL	*89.80 FL
14	1		*REAR LH DOOR PROTECTOR CHROME	Necessary	29.80 FL	*29.80 FL
15	1		*SET REAR LH DOOR FRAME STICKER	Necessary	68.10 FL	*68.10 FL
16	1		*LH CENTRE DOOR PILLAR	Buckled	409.12 FL	*409.12 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,971.44	4,926.71
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,209.32	1,209.32
Total Parts (\$\$)	3,762.12	3,717.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX BOTH LH DOOR & ATTACHMENTS ,TO CUT,WELD & RENEW LH CENTRE DOOR PILLAR ,KNOCKING & REPAIR BOTH LH FENDERS & REALIGN THE SAME	New	1,100.00	900.00
2	PUTTY & RESPRAY BOTH BUMPERS ,BOTH LH FENDERS ,BOTH LH DOORS,LH CENTRE DOOR PILLAR & ALL AFFECTED AREAS	New	1,200.00	1,100.00
3	REMOVE & REFIX BOTH LH DOOR WINDOW GLASSES AND RESET CENTRAL LOCKING	New	100.00	100.00
4	REMOVE & REFIX LH SEATS ,CARPET TO FACILITATE REPAIR	New	100.00	100.00
5	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (S\$)			2,590.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >