



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 630694
Tel: +65 6861 0007 Fax: +65 6861 3876 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No. 166003863G

Page 1 / 2

ESTIMATE

Date	: 12/09/2018	Reg No	: XE471M
To	: LONPAC INSURANCE BHD.	Model	: FP51SDR3VDEA C/C
Attn.	:	Chassis No	: FP51SDA10145
Office / Mobile	:	Engine No	: OM457295278
Email Address	:	Quotation No.	: 70826
From	: GOLDBELL ENGINEERING PTE LTD	Ref. No.	: GBE/SVC/SALES-4688/180912
Attn.	: LILEWEI	D.O.A.	: 10/09/2018
Office / Mobile	: +65 6864 0637	Policy No.	: D-17088925MFVS/6
Email / Fax No.	: LiLewei@goldbell.com.sg	Claim Type	: TP CLAIM - LONPAC
		Workshop	: 29 TANJONG PENJURU

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price	
1	MK656490	CROSSMEMBER NO.3 <i>bt</i>	1	1,042.90	-10	938.61	938.61	✓
2	MK372162	TANK,AIR ?	1	1,193.04	-10	1,073.74	1,073.74	NNX
3	MC085637	BRKT,LICENSE PLATE LAMP <i>aa</i>	1	71.62	-10	64.46	64.46	✓
4	MC085638	BRKT,LICENSE PLATE LAMP <i>aa</i>	1	71.62	-10	64.46	64.46	✓
5	MX915944	LAMP,LICENSE PLATE <i>bt</i>	2	66.98	-10	60.28	120.56	✓
6	MK631324	SPRING,REAR <i>x</i>	2	6,437.99	-10	5,794.19	11,588.38	NNX
7	MC013467	SHACKLE LINK ASSY <i>y</i>	2	371.16	-10	334.04	668.09	NNX
8	MK300383	PIN,SHACKLE <i>x</i>	4	62.49	-10	56.24	224.96	NNX
9	MF524022	NIPPLE,GREASE (10) <i>x</i>	4	4.82	-10	4.34	17.35	NNX
10	MH031237	HOSE,AIR ?	2	198.56	-10	178.70	357.41	NNX
11	MH030789	HOSE,RR AXLE BRAKE TUBE ?	2	255.48	-10	229.93	459.86	NNX
12	MK326200	BRACKET,AIR TANK,NO.2 ?	2	95.40	-10	85.86	171.72	NNX

PARTS TOTAL : 15,749.60 1320.10
10%-1188.0

SPECIAL NETT ITEMS

1	REAR NUMBER PLATE	1	<i>bt</i> 20.00	✓
2	REAR NUMBER PLATE HOLDER	2	? 240.00	NNX

PARTS TOTAL: 260.00 20

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC		<i>600</i> 18000	✓
2	TO REMOVE AND REFIX BRAKE AIR TANK, TO CHECK FUNCTION.		? 600.00	NNX
3	TO REMOVE AND REFIX BOTH SUSPENSION & LEAF SPRING ASSY		<i>x</i> 2400.00	NNX
4	TO CHECK AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK		150 180.00	✓
5	TO PUTTY, CLEAN & SPRAY PAINT		200 400.00	✓
6	SUNDRIES		50 80.00	✓

LABOUR TOTAL : 4,860.00 1600

SUB-TOTAL : 20,869.60





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 636894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No: 158903963G

ESTIMATE

Date	: 12/09/2018	Reg No	: XE471M
To	: LONPAC INSURANCE BHD.	Model	: FP51SDR3VDEA C/C
Attn.	:	Chassis No	: FP51SDA10145
Office / Mobile	:	Engine No	: OM457295278
Email Address	:	Quotation No.	: 70826
From	: GOLDBELL ENGINEERING PTE LTD	Ref. No.	: GBE/SVC/SALES-4688/180912
Attn.	: LILEWEI	D.O.A.	: 10/09/2018
Office / Mobile	: +65 6864 0637	Policy No.	: D-17088925MFVS/6
Email / Fax No.	: LiLewei@goldbell.com.sg	Claim Type	: TP CLAIM - LONPAC
		Workshop	: 29 TANJONG PENJURU

GST @ 7% for \$ 20,869.60 1,460.87
GRAND TOTAL (\$\$) : 22,330.47

PREPARED BY : LILEWEI

DATE / TIME : 26/9/18 @ 1400

SURVEYOR : Tanpin

MOBILE NO : 97493740

OFFICE FAX NO : _____

EMAIL ADDRESS : sur@lkkauto.com

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED WP

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 3 days

REMARKS : _____

P: 1188.09.

S/N: 20

L: 1600

total: 2808.09

US: 2250#

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ST R Certificate No: PAKS/10/2018 Certificate No: LKK/10/18