

SERVICE ESTIMATE

0 - C00010	SL: CHINA TAIPING INSURANCE (SINGAPORE)	
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD		GST Reg.No:M28920628X
3 ANSON ROAD	Inv.No. . : B&P	0 Page 1
#16-00, SPRINGLEAF TOWER	Inv.date. : 24/10/2018	
SINGAPORE 079909	WIP No. . : 28063	
	Veh.In/Out: 18/09/2018 23/10/2018	
	*Tel.No. . : 63896111	
	Reg.No. . : 3DY5138A	
Closed by : Richmond Ho	Reg.date . : 29/09/2014	
Svc Consultant : ACC	Mileage .. : 115,852	
Remarks : Mr Loh Yuen Pin	Chassis No: YV1FS84ABF2340007	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BONNET,FRT BUMPER,FRT GRILL,FRT BRACKET,FRT HEADLAMP,FRT TOP PANEL,FRT RADIATOR,FRT CONDENSER,ETC	0	4800.00	0		4,800.00	S
800	TO PUTTY SPRAY PAINT ON FRT BONNET,FRT BUMPER,ETC	0	2450.00	0		2,450.00	S
802	TO VACCUM & TOP UP A/C GAS	0	350.00	0		350.00	S
280	TO FOCUS HEADLAMP	0	150.00	0		150.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S
R06	TO INSTALL FRONT NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00	S
	BUMPER COVER FRT SV6	1.0 EA	1519.90	15		1,291.92	S
	BUMPER BRACKET LHF V	1.0 EA	88.70	15		75.40	S
	BUMPER BRACKET RHV V	1.0 EA	88.70	15		75.40	S
	BUMPER BRACKET LHF S	1.0 EA	88.70	15		75.40	S

SERVICE ESTIMATE

0 - C00010	SL: CHINA TAIPING INSURANCE (SINGAPORE)	
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD		GST Reg.No:M28920628X
3 ANSON ROAD	Inv.No. . : B&P	0 Page 2
#16-00, SPRINGLEAF TOWER	Inv.date. : 24/10/2018	
SINGAPORE 079909	WIP No. . : 28063	
	Veh.In/Out: 18/09/2018 23/10/2018	
	*Tel.No. . : 63896111	
	Reg.No. . : SDY5138A	
Closed by : Richmond Ho	Reg.date. : 29/09/2014	
Svc Consultant : ACC	Mileage . : 115,852	
Remarks : Mr Loh Yuen Pin	Chassis No: YV1FS84ABF2340007	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET RHF S	1.0 EA	88.70	15		75.40	S
	RADIATOR GRILLE D2 E	1.0 EA	578.70	15		491.90	S
	FRAME PANEL FRT SV60	1.0 EA	1707.10	15		1,451.04	S
	BUMPER RAIL (BEAM) F	1.0 EA	1158.80	15		984.98	S
	V009437654/*D* VOLVO	2.0 EA	40.50	15		68.85	S
	BONNET FRT S60 14~ C	1.0 EA	2642.80	15		2,246.38	S
	BONNET LOCK LH XC60	1.0 EA	235.20	15		199.92	S
	BLIND RIVET 4.0*21 P	10.0 EA	3.00	15		25.50	S
	ADHESIVE TUBE CHEMIC	4.0 EA	75.80	15		257.72	S
	V031353654/BUMPER CO	1.0 EA	105.80	15		89.93	S
	V031353655/BUMPER CO	1.0 EA	105.80	15		89.93	S
	HEADLAMP RH T2 SV60	1.0 EA	919.20	15		781.32	S
	BUMPER FOAM FRT SV60	1.0 EA	345.20	15		293.42	S
	RADIATOR RETAINER LH	1.0 EA	7.40	15		6.29	S
	RADIATOR AIR GUIDE R	1.0 EA	119.50	15		101.58	S
	RADIATOR AIR GUIDE L	1.0 EA	103.90	15		88.32	S
	RADIATOR T4 T5 D2 S6	1.0 EA	853.50	15		725.48	S

SERVICE ESTIMATE

0 - C00010	SL: CHINA TAIPING INSURANCE (SINGAPORE)	
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD		GST Reg.No:M28920628X
3 ANSON ROAD	Inv.No. . : B&P	0 Page 3
#16-00, SPRINGLEAF TOWER	Inv.date. : 24/10/2018	
SINGAPORE 079909	WIP No. . : 28063	
	Veh.In/Out: 18/09/2018 23/10/2018	
	*Tel.No. . : 63896111	
	Reg.No. . : SDY5138A	
Closed by : Richmond Ho	Reg.date. : 29/09/2014	
Svc Consultant : ACC	Mileage . : 115,852	
Remarks : Mr Loh Yuen Pin	Chassis No: YV1FS84ABF2340007	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	V031368867/FAN MOTOR	1.0 EA	957.00	15		813.45	S
	D AUTO TRANS OIL 4	1.0 EA	232.70	15		197.80	S
	BUMPER CLIP	10.0 EA	5.40	15		45.90	S
	BUMPER INSTALLING MT	1.0 EA	83.40	15		70.89	S

				Gross Total..	18,884.12
Labour Total	8,260.00			Net.....	18,884.12
Parts Total	10,624.12			GST @ 7.0%	1,321.89
Package Total	0.00			Total.....	20,206.01
				Paid.....	0.00
				Please Pay..	20,206.01

GST: S=StdRated; O=OutOfScope; Z=ZeroRated