

SERVICE ESTIMATE

87054 - C00001 SL: SERVICE SALES - PC

Ms FOO MEI YAN
210B PUNGGOL FIELD
#14-220

Singapore 822201

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Ms FOO MEI YAN

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 31/10/2018
WIP No. . : 35207
Veh.In/Out:
*Tel.No. . : Mobile: 97677686
Reg.No. . : SJQ5310P
Reg.date . : 29/09/2016
Mileage .. : 0
Chassis No: SJKDAAH15U1012255

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR LOWER BUMPER, ETC	0	2700.00	0		2,700.00	S 900
800	TO PUTTY & SPRAY PAINT ON REAR BUMPER, REAR LOWER BUMPER, ETC	0	2400.00	0		2,400.00	S 800
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0	390.00	0		390.00	S
	BUMPER SET-RR Q30 DE	1.0 EA	1440.20			1,440.20	S
	S MLDG RR BMPR BE	1.0 EA	504.00			504.00	S
	BUMPER BRACKET RR LH ?	1.0 EA	121.00			121.00	S
	BUMPER BRACKET RR LH ?	1.0 EA	121.00			121.00	S
	REINFORCEMENT-BUMPER ?	1.0 EA	1021.30			1,021.30	S
	BRKT-RR BUMPER ?	1.0 EA	12.40			12.40	S
	RETAINER LH-RR BUMPE ?	1.0 EA	50.40			50.40	S
	RETAINER RH-RR BUMPE ?	1.0 EA	50.40			50.40	S
	RETAINER-BUMPER Q30 ?	1.0 EA	231.90			231.90	S

SERVICE ESTIMATE

87054 - C00001
 Ms FOO MEI YAN
 210B PUNGGOL FIELD
 #14-220

SL: SERVICE SALES - PC

Singapore 822201

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Ms FOO MEI YAN

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2
 Inv.date. : 31/10/2018
 WIP No. . : 35207
 Veh.In/Out:
 *Tel.No. . : Mobile: 97677686
 Reg.No. . : SJQ5310P
 Reg.date. : 29/09/2016
 Mileage . : 0
 Chassis No: SJKDAAH15U1012255

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRACKET-BUMPER ?	1.0 EA	55.50			55.50	S
	REFLECTER LAMP REAR ?	1.0 EA	56.80			56.80	S
	REFLECTER LAMP REAR ?	1.0 EA	56.80			56.80	S
	BODY PANEL SEALANT X	1.0 EA	942.20			942.20	S
	ADHESIVE SEALER FL2 X	1.0 EA	549.10			549.10	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Perme
HP 90010068
3 days
01/11/18 @ 1125
Resurvey by part

Labour Total 5,490.00
 Parts Total 5,213.00
 Package Total 0.00

Gross Total. 10,703.00
 Net..... 10,703.00
 GST @ 7.0% 749.21
 Total..... 11,452.20
 Paid..... 0.00
 Please Pay.. 11,452.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated