

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

21/09/2018 12:46

JOB-NO: 50110968

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7299Z

TRANS: AUTO

CHASSIS: KMHLB41UMGU093590

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU671690

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	1000 650
2 R&R RADIATOR & CONDENSER & TURBO	1.00	180.00	0.00	180.00		Y	180 80
3 CHECK WIRING & HEAD LAMP AIM	1.00	180.00	0.00	180.00		Y	30
4 ALIGNMENT BONNET & FENDER & SUPPORT PANEL	1.00	180.00	0.00	180.00		Y	X
5 RUST PROOFING	1.00	120.00	0.00	120.00		Y	40
6 SUNDRIES	1.00	120.00	0.00	120.00		Y	X
7 RESPRAY FRONT BONNET & FENDER RHS & BUMPER	1.00	750.00	0.00	750.00		Y	550
8 TOP UP AIR-COND GAS 134A	1.00	120.00	0.00	120.00		Y	80
TOTAL:		2,650.00	0.00	2,650.00			

MATERIALS

1 FRONT BUMPER	1.00	599.68	119.94	479.74	L	Y	PRIDE
2 FRONT BUMPER RETAINER RHS	1.00	42.32	8.46	33.86	L	Y	an X
3 FRONT BUMPER RETAINER LHS	1.00	42.32	8.46	33.86	L	Y	X
4 FRONT SUPPORT PANEL	1.00	962.87	192.57	770.30	L	Y	X CR1
5 FRONT HEAD LAMP PANEL RHS	1.00	198.67	39.73	158.94	L	Y	X
6 FOG LAMP COVER RHS	1.00	178.55	35.71	142.84	L	Y	X
7 FRONT FENDER RHS	1.00	659.50	131.90	527.60	L	Y	14
8 FRONT FENDER INNER SHIELD RHS	1.00	185.12	37.02	148.10	L	Y	X
9 HEAD LAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	CR1
10 BONNET	1.00	1,812.68	362.54	1,450.14	L	Y	repair
11 BONNET HINGE RHS	1.00	41.85	8.37	33.48	L	Y	X
12 RADIATOR COOLANT	1.00	89.55	17.91	71.64	L	Y	X
TOTAL:		6,621.21	1,324.23	5,296.98			

TOTAL PARTS & LABOUR : 9,271.21 1,324.23 7,946.98

EXCESS/LOADING:\$ 0.00

No. Of Day: 6 days

RE-SURVEY BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 21 / 09 / 18

SURVEYED BY: RASue

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: