210

### Note: This document has not been finalised.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

Singapore 079120

78 Shenton Way #07-16

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Date:

24 Sep 2018

### **Preliminary Advice**

Vehicle No

: SLT9355U

Accident Date

: 19/09/2018

Make

: AUDI A4

Assignment Date

Policy No.

: 1700075439

Date of Inspection

: 24/09/2018

Excess

: S\$0.00

: 24/09/2018

Est. Duration of Repair

Inspection At

: 7 days

: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,142.00
Revised Amount	:S\$	17,948.00
Check Items (Estimated)	:S\$	1,199.00
Total	:S\$	19,147.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	128,000.00
COE / PARF Rebate	:S\$	73,360.00
Salvage Value	:S\$	
Margin for Repair	:S\$	54,640.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy covera	ge. Kindly
	let us have your authorisation.	

) Th	e vehicle is	s uneconomical	to be	repaired,	you are advised	to invite	tender fo	or the wrec	:k
------	--------------	----------------	-------	-----------	-----------------	-----------	-----------	-------------	----

Other comments:

### Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Friday, 21 December 2018 3:53 PM

To:

'Boo seng yak'

Cc:

Adrian Ling (LKKAuto); SUR; 'Carrine Leong'; jiayee.yap@premiumauto.com.sg;

'Chang Chee Sing'

Subject:

RE: FINAL REVISION - SLT9355U - OD AIG - SURVEYED 24 SEP 18

Dear Mr Boo.

Confirmed final fig \$15,843.52 @ 8 days of repairs before excess \$600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Tuesday, 18 December 2018 5:00 PM

To: Adrian Ling <adrianling@lkkauto.com>; shirleyHiew@lkkauto.com; sur@lkkauto.com; Carrine Leong

<carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing

<claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLT9355U - OD AIG - SURVEYED 24 SEP 18

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$15,843.52 @ 8 days of repairs with checked items replaced.

Your early closure is well appreciated.

Best regards - jb

### Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Tuesday, 25 September 2018 5:57 PM

To:

'Claims Dept'

Cc:

'SUR'; 'Admin A'

Subject:

RE: od CLAIM FOR SLT 9355 U

Dear All,

As instructed by our client, please proceed to repair the insured vehicle SLT 9355U (Excess \$ 600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]

Sent: Friday, 21 September 2018 4:11 PM

To: 'SUR' <sur@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>

Cc: 'Claims Dept' <claims@premiumauto.com.sg>

Subject: re: od CLAIM FOR SLT 9355 U

Good afternoon all,

Here are the estaimate & GIA report for your kind reference .

Thank you .

Best Regards,

Phua

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



### Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

### View Received Message

This mail is associated with:

### \*SLT9355U (6467767598SG)

OD Sep 19 2018 8:00PM [AMOS LEE CHEE KEONG] Premium Automobiles Pte Ltd

Reply All Mark as Unread Print Message Delete Message Forward Reply AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 25/09/2018 14:23 PM. From Alert - Adj Mandate Approved (S\$17948.00) - SLT9355U - Claim Handler: Dally Amri, Mimi Zarina Subject Approved:17948.00:Re-inspection to be done for damage check and supplementary items / labour.

### **DOCUMENTS SUMMARY**

There are no documents.

### > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	7518H
Vehicle No.:	SLT9355U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CVN045367
Chassis No.:	WAUZZZF44JA023477
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,726.00
Original Registration Date:	16 Nov 2017
First Registration Date:	16 Nov 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$27,817.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2027
PARF Rebate Amount: Intended COE Rebate Details	\$20,862.00
COE Expiry Date:	15 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$52,498.00
Total Rebate Amount:	\$73,360.00

The information contained herein is correct as at 24 Sep 2018

### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

<ol> <li>By the lodgement of this report to the insurers, you hereby consaforesaid.</li> </ol>	sent to the archiving of this report at the centre and to copies of the report being made available
TO THE SECOND PROPERTY.	ACCIDENT STATEMENT
Date Of Report	20/09/2018 13:58
Date Of Accident	19/09/2018 20:30
Exact Location Of Accident	403A FERNVALE LANE CAR PARK
Country/State of Loss	SINGAPORE
National Contract of the Contr	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLT9355U
Insured/Policyholder	
Name Of Registered Owner	AMOS LEE CHEE KEONG
NRIC No	S7527518H
Email Address	CKAMOS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91073707
Alternative Phone No	OTHERS-91073707
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy	YES

for repair to your vehicle?

If No. Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD. Name of Insurance Company

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1700075439

Cover Note Number

Driver

Name of Driver KRISTINE LEE WAI MUN

NRIC No S7318425H Date Of Birth 20/04/1973 Occupation INDOOR Date Of Driving Pass 22/07/1996

Driving Experience 22 YEARS AND 1 MONTH

Gender FEMALE

Mobile Number (LOCAL) +65-91073707

Fax Number

Contact Number OTHERS-91073707

EMail Address NOEMAIL Address

BLK 128B PUNGGOL FIELD WALK

#05-357

SIBLING

Postcode

822128

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PROPERTY

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

WHILE DRIVING UP THE CARPARK RAMP, ACCIDENTALLY HIT THE LEFT SIDE OF THE CONCRETE PILLAR.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

CONCRETE PILLAR

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### Sketch Plan

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 2076 Gart

11 15300

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature Name: | 1/4 | 1/5 | 1/16

NAUC/FIR NO. BY SCISE OF

### Sketch Plan #2

SK		CH	mi	×	h
24	5.4	чn	PL	~	n




SCRIBE CIRCUMSTANCES OF THE ACCIDENT	pork	
while driving up the	car ramp accin	de ntall
bit the left side of	f the concrete	ollar!
/	,	
	1	
LARATION declare the foregoing particulars are true in every respect.	Wi C	
	M	7

Policyholder's Signature
Date & Time: 2 \* 7 in S + 7 if 1 S (if driver is not the policyholder)

1 / 0 or Date & Time:

Reporting Control Personnel's Signature
Name: (319 185 31654)
NRIC/FIN No. (4)



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7527518H

Namo





AMOS LEE CHEE KEONG (LI ZHIQIANG)

李 志 强

CHINESE Date of birth 11-09-1975

8752761811

4406104

Country of birth SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Motor cars without clutch pedals (Auto) with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight =< 2500kg 11 Oct 2017

NP 428A





S7527518H



Date of Issue 22-05-2009

APT BLK 403A FERNVALE LANE #12-179 SINGAPORE 791403



TOU AND LICEN'S TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Gare 3 Motor Cap and Motor Teachers do majed at

N 24 1000

Lines by Wyneson

307 428A

## REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7318425H





KRISTINE LEE WAI MUN

敏

CHINESE

Date of birth

20-04-1973 F Country of birth

SINGAPORE



3399735



18-09-2003

APT BLK 1288 PUNGGOL FIELD WALK #05-357 SINGAPORE 822128



# CERTIFICATE OF INSURANCE

### AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: AMOS LEE CHEE KEONG (LI ZHIQIANG)

Period of Insurance

: 16 Nov 2017 To 15 Nov 2018 : CVN045367

Engine No. Chassis No.

: WAUZZZF44JA023477

Vehicle No.

: SLT9355U

Policy No.

: 1700075439

Endorsement No.

Issued Date

: 17 Nov 2017

### ABOUT THE COVER

Make/Model

: AUDI A4 1.4 TFSI S tronic

Engine Capacity/Tonnage : 1,395.00 CC

Sum Insured : Market Value

First Year of Registration

Driver Restriction

Off Peak Car : No

· NA

Insuring with COE/PARF

### Person or Classes of Persons Entitled to Drive\*:

a) The Policyholder b) Any other person who is driving on the Policyholder's order or with histher permission This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition

: 30 years old and above

### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving fution, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

### Loss of Use

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be

### EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Property Demage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

(LI ZHIQIANG) AMOS LEE CHEE KEONG

# APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE Chieng Qian Yee Accident Photo






YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

PASS DATE

Gate 2

Motor Cars and Biotor Tractors the weight of which unladen does not specied 2500 kilograms

22 July 1996



NP 428A

# DENTITY CARD NO. S7318425H



KRISTINE LEE WAI MUN





CHINESE Date of bore

Sex

20-04-1973 F

SINGAPORE


57318425H

Date of timus

18-09-2003

**Fiddress** 

APT BLK 128B PUNGGOL FIELD WALK #05-357 SINGAPORE 822128



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7527518H





Name

AMOS LEE CHEE KEONG (LI ZHIQIANG)

强

CHINESE Date of birth

875276 1811

4406104

11-09-1975 Country of birth SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Motor cars without clutch pedsis (Auto) with unladen 11 Oct 2017 weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight =< 2500kg

NP 428A





RIC No. S7527518H

22-05-2009

APT BLK 403A FERNVALE LANE #12-179 SINGAPORE 791403



# CERTIFICATE OF INSURANCE

### AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: AMOS LEE CHEE KEONG (LI ZHIQIANG)

Period of Insurance

: 16 Nov 2017 To 15 Nov 2018

Engine No. Chassis No. : CVN045367 : WAUZZZF44JA023477 Vehicle No. Policy No.

: SLT9355U : 1700075439

Endorsement No.

Issued Date

17 Nov 2017

### ABOUT THE COVER

Make/Model

Driver Restriction

AUDI A4 1.4 TFSI S tronic

Engine Capacity/Tonnage : 1,395.00 CC

Sum Insured : Market Value

First Year of Registration : 2017

Off Peak Car No

Insuring with COE/PARF : Yes

### Person or Classes of Persons Entitled to Drive\*:

a) The Policyholder

: NA

b). Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience

Age Condition

: 30 years old and above

#### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

#### Loss of Use

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 85 of the Road Transport Act. 1987 (Malaysia), are not to be included under these headings.

### EXCESS

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

(LI ZHIQIANG) AMOS LEE CHEE KEONG

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add. 55 Util Road 1 Singapore 408699 63662323

For other: Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

If We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap., 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

### Telefax

Estimate : Accident Repairs

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/1092/2018/PH

Date : 21-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Amos Lee Chee Keong

Address : Blk 128B Punggol Field Walk

#05-357

Singapore 822128

Telephone : HP +65 91073707

Type of Claim : Own Damage Claims

Policy No. : 1700075439

Vehicle No : SLT 9355 U

Model Code : Audi A4 Sedan 1.4 TFSI S-tronic

 Model / Year
 : Nov-17

 Engine No
 : CVN 045367

Chassis No : WAUZZZF44JA023477

Mileage :
Date In :
Liability :

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 19-Sep-18

Place of Accident : 403A Fernvalve Lane carpark

# Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

### Telefax

## Estimated Labour Charges for Accident Vehicle SLT 9355 U.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and trransfer front wire harness for headlights, horns, outside temperature and headlight washer assy.	S/N	\$ 360.00	/
2	To remove and renew lhs air conditioning pipes. To carry out vacuum and regas.	S/N	\$ 480.00	
3	To dismantle and renew front bumper, bonnet, lhs front fender, lhs headlight and lhs front door. Inspect lhs fender inner support for damages. Re-organise front crash management components. Reinstall all parts removed.		\$ 3,900,00	1750.200/
4	To respray front bumper,bonnet,lhs fender and lhs front door,hinges		\$ 3,500.00	2750
5	To carry out wheel alignment	S/N	\$ 240.00	×
6	To carry out diagnostic check	S/N	\$ 192.00	/
	TOTAL LABOUR CHARGES		\$8,672.00	

# Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

### Telefax

## Material List for Accident Vehicle Regn No. SLT 9355 U.

S/N	Parts Description	Damaged Pa	rts & Prices Remark
3/14	Parts Description	57.1161.	Kellidik
1	FRONT BUMPER Distorted	\$ 1,849.00	1479.20
2	FRONT BUMPER FIXING PARTS ME	\$ 245.00	
3	SECURING STRIP ~~~ 2	\$ 60.00	
4	GRILLE SATIN BLACK - CENTRE 24	\$ 171.00 <sup>*</sup>	
5	CLOSING ELEMENT - CENTRE LOWER Not NEL -	\$ 180.00	X
6	AIR GUIDE - LH Et	\$ 73.00	7 57.94
7	AIR GUIDE GRILLE - LH 🏲 d ·	\$ 118.00	94.00
8	GUIDE SECTION - LH 2- d	\$ 31.00	- 24.56
9	FRONT FENDER - LH Pistonted	\$ 665.00 _	532.00
10	ATTACHMENT PARTS FOR FENDER	\$ 45.00	35.84
11	CLOSING ELEMENT - LH 2 2	\$ 44.00 -	34.56
12	BRACKET FOR FENDER - LH 7-	\$ 31.00	- 24.16
13	BRACKET FOR DEFORMATION - LH	\$ 43.00 ك	- 34.16
14	BRACKET FOR FENDER But	\$ 27.00	21.60
15	BRACKET The Dangel	\$ 15.00	9 ? 11.76
16	FRONT FENDER BRACE - LH But	\$ 103.00	82.40
17	WHEEL HOUSING LINER - LH Delad	\$ 215.00	171.60
18	ATTACHMENT PARTS FOR WHEEL LINER WE NEW	\$ 78.00	7 🗶
19	WHEEL SPOILER - LH Delad	\$ 63.00	50.16
20	SPOILER-LH could	\$ 30.00	? 23.92
	SUB TOTAL FOR PARTS :	\$ 4,086.00	

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved Legend: Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Material List for Accident Vehicle Regn No. SLT 9355 U.

S/N	Parts Description		Damaged Parts & Prices S/Nett Remark
21	BONNET Dented	\$	2,163.00 1730.40
22	ATTACHMENT PARTS FOR BONNET HE ME	\$	105.00 7 X
23	STONE CHIP GUARD MA	\$	44.00 - 34.56
24	LID HINGE - LH/RH wen 2	\$	532.00 +
25	BONNET IMPACT PROTECTOR - CENTRE 2	\$	24.00 - 18-88
26	BONNET IMPACT PROTECTOR - LH/RH	\$	48.00 ACJ 37.76
27	COVER-LH Not new.	\$	53.00 7 X
28	COVER - LH	\$	27.00 7 2/04
29	COVER - LH	\$	20.00 ? 15.36
30	STRIKER - LH/RH 144 2	\$	88.00
31	LID LOCK ALL	\$	188.00
32	BOWDEN CABLE - CENTRE MC 2	\$	100.00
33	LED HEADLIGHT - LH cut	\$	6,973.00 / 5578.40
34	POWER MODULE FOR MAIN LIGHT	\$	695.00 +
35	CONTROL UNIT FOR LIGHT CONTROL SYSTEM	5	657.00 🖟
36	LIFT CYLINER - LH Not me	\$	184.00 *
37	REFRIGERANT LINE BUT	\$	145.00 / 115.60
38	REFRIGERANT PIPE BUT	\$	453.00 362.40
39	FRONT DOOR - LH Per	\$	2,048.00 🗶
40	OUTER DOOR SEAL - LH MM N	\$	176.00 *
	SUB TOTAL FOR PARTS	\$	14,723.00
		-	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Material List for Accident Vehicle Regn No. SLT 9355 U.

		<b>Damaged Parts &amp; Prices</b>		
5/N	Parts Description	_	S/Nett	Remark
41	CLEANING SOLUTION	\$	64.00	
42	ATTACHMENT PARTS FOR FRONT DOOR - LH Mem	-\$	462.00	0)
43	DOOR CATCH Z	\$	92.00 ×	
44	DOOR CATCH COVER SHE Nee	\$	13.00	<b>K</b>
45	WINDOW SLOT SEAL WITH TRIM STRIP 2	\$	265.00 ←	
46	TRIM STRIP WITH CHROME STRIP	\$	222.00 X	
47	BONDING AGENT NO NOC	\$	43.00 1	
48	SUNDRIES New.	\$	500.00 ?	19.36
	TOTAL FOR PARTS :	\$	20,470.00	
	TOTAL LABOUR CHARGES	\$	8,672.00	
	GRAND TOTAL	\$	29,142.00	
	All charges are not inclusive of GST.  Legend: Remarks (OK) = Approved, Remarks (X) = Not approved			

Legend: Remarks (OK) = Approved, Remarks (X) = Not approve

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

Name

Surveyed Date

**Authorised Date** 

**Excess Cost** 

Liability

Remarks

Please Note

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

: Not Authorised, 07 Days

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

### Telefax

Estimate

Accident Repairs

Workshop Contact No Ubi Road 1 6366 2323

Fax No

6841 1183

Reference

PA/OD/1092/2018/PH

Date

: 21-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Hi Adrian

We took 8 days of repairs - jb

18-Dec-18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Ms Amos Lee Chee Keong

Address

Blk 128B Punggol Field Walk

#05-357

Singapore 822128

Telephone

HP +65 91073707

Type of Claim

Own Damage Claims

Policy No.

1700075439

Vehicle No

**SLT 9355 U** 

Model Code

: Audi A4 Sedan 1.4 TFSI S-tronic

Model / Year

Nov-17

Engine No

CVN 045367

01 ---'- N-

0 111 0 40007

Chassis No

WAUZZZF44JA023477

Mileage

Date In

•

Liability

:

**Excess Cost** 

. .

**Estimated By** 

Johnny Boo / Allan Wu

Accident Date

19-Sep-18

Place of Accident

403A Fernvalve Lane carpark

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

## Estimated Labour Charges for Accident Vehicle SLT 9355 U.

S/n	Nature of Jobs			Estimated Charges		ırveyor's nmendation
	55 S4 94 OF 40 47 38					
1	To remove and trransfer front wire harness for headlights, horns, outside temperature and headlight washer assy.	S/N	\$	360.00	s	360.00
2	To remove and renew lhs air conditioning pipes. To carry out vacuum and regas.	S/N	\$	480.00	\$	480.00
3	To dismantle and renew front bumper,bonnet,lhs front fender,lhs headlight and lhs front door.Inspect lhs fender inner support for damages.Re-organise front crash management components.Reinstall all parts removed. (\$250.00 added for R/I left front door wing mirror assy for respray door)		\$	3,900.00	s	2,000.00
4	To respray front bumper, bonnet, lhs fender and lhs front door, hinges		\$	3,500.00	\$	2,200.00
5	To carry out wheel alignment	S/N	\$	240.00		
6	To carry out diagnostic check	S/N	\$	192.00	\$	192.00
	TOTAL LABOUR CHARGES		_	\$8,672.00	s	5,232.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

# Material List for Accident Vehicle Regn No. SLT 9355 U.

			Damaged Pa	rts & F	rices
S/N	Parts Description		S/Nett		Remark
		•	4 0 40 00		4 470 20
1	FRONT BUMPER	\$	1,849.00	\$	1,479.20
2	FRONT BUMPER FIXING PARTS	\$	245.00		
3	SECURING STRIP	2 \$	60.00		
4	GRILLE SATIN BLACK - CENTRE	\$	171.00		
5	CLOSING ELEMENT - CENTRE LOWER	\$	180.00		
6	AIR GUIDE - LH	\$	73.00	\$	57.84
7	AIR GUIDE GRILLE - LH	\$	118.00	\$	94.00
8	GUIDE SECTION - LH	\$	31.00	\$	24.56
9	FRONT FENDER - LH	\$	665.00	\$	532.00
10	ATTACHMENT PARTS FOR FENDER	\$	45.00	\$	35.84
11	CLOSING ELEMENT - LH	\$	44.00	\$	34.56
12	BRACKET FOR FENDER - LH	\$	31.00	\$	24.16
13	BRACKET FOR DEFORMATION - LH	\$	43.00	\$	34.16
14	BRACKET FOR FENDER	\$	27.00	\$	21.60
15	BRACKET	\$	15.00	\$	11.76
16	FRONT FENDER BRACE - LH	\$	103.00	\$	82.40
17	WHEEL HOUSING LINER - LH	\$	215.00	\$	171.60
18	ATTACHMENT PARTS FOR WHEEL LINER	\$	78.00		
19	WHEEL SPOILER - LH	\$	63.00	\$	50.16
20	SPOILER - LH	\$	30.00	\$	23.92
	SUB TOTAL FOR PARTS	: \$	4,086.00	\$	2,677.76

All charges are not inclusive of GST.

Legend : Remarks (C

Remarks (OK) = Approved, Remarks (X) = Not approved

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

# Material List for Accident Vehicle Regn No. SLT 9355 U.

			Damaged Pa	rts & F	rices
S/N	Parts Description		S/Nett		Remark
	c/f			\$	2,677.76
21	BONNET		\$ 2,163.00	\$	1,730.40
22	ATTACHMENT PARTS FOR BONNET		\$ 105.00		
23	STONE CHIP GUARD		\$ 44.00	\$	34.56
24	LID HINGE - LH/RH	2	\$ 532.00		
25	BONNET IMPACT PROTECTOR - CENTRE		\$ 24.00	\$	18.88
26	BONNET IMPACT PROTECTOR - LH/RH	2	\$ 48.00	\$	37.76
27	COVER - LH		\$ 53.00		
28	COVER - LH		\$ 27.00	\$	21.04
29	COVER - LH		\$ 20.00	\$	15.36
30	STRIKER - LH/RH	2	\$ 88.00		
31	LID LOCK		\$ 188.00		
32	BOWDEN CABLE - CENTRE	2	\$ 100.00		
33	LED HEADLIGHT - LH		\$ 6,973.00	\$	5,578.40
34	POWER MODULE FOR MAIN LIGHT		\$ 695.00		
35	CONTROL UNIT FOR LIGHT CONTROL SYSTEM		\$ 657.00		
36	LIFT CYLINER - LH		\$ 184.00		
37	REFRIGERANT LINE		\$ 145.00	\$	115.60
38	REFRIGERANT PIPE		\$ 453.00	\$	362.40
39	FRONT DOOR - LH		\$ 2,048.00		
40	OUTER DOOR SEAL - LH		\$ 176.00		
	SUB TOTAL FOR PARTS	306	\$ 14,723.00	\$	10,592.16
		-		-	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Material List for Accident Vehicle Regn No. SLT 9355 U.

	Damaged Pa	rts & Prices		
Parts Description		S/Nett		Remark
c/f			\$	10,592.16
CLEANING SOLUTION	\$	64.00		
ATTACHMENT PARTS FOR FRONT DOOR - LH	\$	462.00		
DOOR CATCH	\$	92.00		
DOOR CATCH COVER	\$	13.00		
WINDOW SLOT SEAL WITH TRIM STRIP	\$	265.00		
TRIM STRIP WITH CHROME STRIP	\$	222.00		
BONDING AGENT	\$	43.00		
SUNDRIES	\$	500.00	\$	19.36
TOTAL FOR PARTS :	\$	20,470.00	\$	10,611.52
TOTAL LABOUR CHARGES	\$	8,672.00	\$	5,232.00
GRAND TOTAL	\$	29,142.00	\$	15,843.52
	CLEANING SOLUTION ATTACHMENT PARTS FOR FRONT DOOR - LH DOOR CATCH DOOR CATCH COVER WINDOW SLOT SEAL WITH TRIM STRIP TRIM STRIP WITH CHROME STRIP BONDING AGENT SUNDRIES TOTAL FOR PARTS :	CLEANING SOLUTION \$ ATTACHMENT PARTS FOR FRONT DOOR - LH \$ DOOR CATCH \$ DOOR CATCH COVER \$ WINDOW SLOT SEAL WITH TRIM STRIP \$ TRIM STRIP WITH CHROME STRIP \$ BONDING AGENT \$ SUNDRIES \$ TOTAL FOR PARTS \$ \$	S/Nett           CLEANING SOLUTION         \$ 64.00           ATTACHMENT PARTS FOR FRONT DOOR - LH         \$ 462.00           DOOR CATCH         \$ 92.00           DOOR CATCH COVER         \$ 13.00           WINDOW SLOT SEAL WITH TRIM STRIP         \$ 265.00           TRIM STRIP WITH CHROME STRIP         \$ 222.00           BONDING AGENT         \$ 43.00           SUNDRIES         \$ 500.00           TOTAL FOR PARTS         : \$ 20,470.00           TOTAL LABOUR CHARGES         \$ 8,672.00	c/f       \$         CLEANING SOLUTION       \$       64.00         ATTACHMENT PARTS FOR FRONT DOOR - LH       \$       462.00         DOOR CATCH       \$       92.00         DOOR CATCH COVER       \$       13.00         WINDOW SLOT SEAL WITH TRIM STRIP       \$       265.00         TRIM STRIP WITH CHROME STRIP       \$       222.00         BONDING AGENT       \$       43.00         SUNDRIES       \$       500.00       \$         TOTAL FOR PARTS       :       \$       20,470.00       \$         TOTAL LABOUR CHARGES       \$       8,672.00       \$

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

Liability

Name :
Surveyed Date :
Authorised Date :
Excess Cost :

Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SLT 9355 U Norah Khai 6768 9911 6841 1183

Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/1092/2018/MAS

19 Jan 2019

from

Telephone +65-

+65-

Telefax EMail

Our department

Our Ref Your Ref

Date

Dear Sir.

RE: INSURANCE CLAIM FOR SLT 9355 U, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. SLT 9355 U claimant, Mr. Amos Lee Chee Keong, please find the related document per attached.

- A copy of the Original invoice no. 85013354 S\$16,310.57
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG - SLT 9355 U total pages

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitte	Adj Assigned	Adj R	ot	Adj Submitted	Ins Auth'ed	Status			
Main	25 Sep 2018		24 Sep 2018 09:31 Edit Adj Rpt	S\$15,84 Edit Estin		S\$15,843.52 View Rpt	Report				1190
	Main		Reference	) c	laim De	tails	Documents		Show All		
CLAIM S	SUBFOLDER DE	TAILS	THE RESERVE TO	GOOD TOWNSHIPS THE	No. of Street, or other Designation of the Lorentz Control of the Lo	Section 1 and 1 and 1 and 1	[Create	ed by insu	irer]		
Insured:		AMO	S LEE CHEE KEON	G, ID: S752	7518H						
Vehicle R	eg. No.:	SLT	9355U		Date of I	.oss:	[10 Mor	018 20:00 oths and 3 e (Man Yr)	Days From LTA		
Claim Tyr	ne:	OD	/ 646776759850	3	Policy/Co	over Note No.:	170007	5439 (Com	439 (Comprehensive)		
Claim Ty	P.C.				Excess:		S\$600.0	00	10		
Repairer:	1)	Prei	nium Automobiles	Pte Ltd (UI	31) 55 U	bi Road 1, 408699	Ubi - Tel: 676898	28/9827/9	911		
Handling		AIG Mim	Asia Pacific Insur Zarina.DallyAmri@a	rance Pte. Lt	d. (SG)	- Tel: 65-6419-300	00 [Handled by	Dally Am	ri, Mimi Zarin		
Adjuster			Auto Consultants 03/10/2018]	Pte Ltd (HC	) - Tel:				[Final Rpt		
Driver/Co	ustodian:	KRIS	TINE LEE WAI MUN	(45 / Female	), NR	C: S7318425H,	Tel: +6591073707	,			
ASSOCI	ATED MAIL RE	CEIVED					View All	Comp	ose Case Mail		
AIG_S     AIG_S	SG (25/09/2018): SG (24/09/2018):	Alert - Adj Ma SLT9355U / G	ndate Approved ( DD / 19/09/2018	S\$17948.00 / Coverage	) - SLT & Exces	3355U - Claim Ha s update	ndler: Dally Ami	ri			
ALL AS	SOCIATED TAS	KS			Vie	ew All Search T	asks Create	e New Task	Complete		
Due D		Type Tas	k Group Subje	ect Handle	er A	ssigned By	Completed On	Create	d On Done		

### **Claim Documents**

### \*SLT9355U (6467767598SG) OD Sep 19 2018 8:00PM [AMOS LEE CHEE KEONG] **Premium Automobiles Pte Ltd**

	Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer	*
Ass	essment Reports	and the second				1 per s	page 🕶	V
	Finalized On		tants Pte Ltd (HQ)			-	Thumbnail	Prin
1	24/09/18 14:08	Adjuster Immedi	ate Advice			0	Load HTM	_
Pho	tos/Images					3 per p	page 🔻	0
No	Relabel/Reorder	LKK Auto Consult	tants Pte Ltd (HQ)				Thumbnail	Prin
1	24/09/18 13:15	General View				0	Load JPG	V
2	24/09/18 13:15	Chassis Number				0	Load JPG	V
3	24/09/18 13:15	General View				0	Load JPG	V
4	24/09/18 13:15	General View				0	Load JPG	V
5	24/09/18 13:15	General View				0	Load JPG	V
6	24/09/18 13:15	General View				0	Load JPG	V
7	24/09/18 13:15	General View				0	Load JPG	V
8	24/09/18 13:15	General View				0	Load JPG	V
9	24/09/18 13:15	General View				0	Load JPG	V
10	24/09/18 13:15	General View				0	Load JPG	V
11	24/09/18 13:15	General View				0	Load JPG	V
12	24/09/18 13:15	General View				0	Load JPG	V
13	24/09/18 13:15	General View				0	Load JPG	10
	24/09/18 13:15	General View				0	Load JPG	V
14						0		10
15	24/09/18 13:15	General View				0	Load JPG	-
16	24/09/18 13:15	General View				_	Load JPG	[V
17	24/09/18 13:15	General View				0	Load JPG	[V
18	24/09/18 13:15	General View				0	Load JPG	7
19	24/09/18 13:15	General View				0	Load JPG	V
20	24/09/18 13:15	General View				0	Load JPG	[V
21	24/09/18 13:15	General View				0	Load JPG	1
2.2	24/09/18 13:15	General View				0	Load JPG	V
23	24/09/18 13:15	General View				0	Load JPG	V
24	24/09/18 13:15	General View				0	Load JPG	V
25	24/09/18 13:15	General View				0	Load JPG	1
26	24/09/18 13:15	General View				0	Load JPG	V
27	24/09/18 13:15	General View				0	Load JPG	1
28	24/09/18 13:15	General View				0	Load JPG	1
29	24/09/18 13:15	General View				0	Load JPG	0
30	24/09/18 13:15	General View				0	Load JPG	
31	24/09/18 13:15	General View				0	Load JPG	V
32	24/09/18 13:15	General View				0	Load JPG	V
33	24/09/18 13:15	General View				0	Load JPG	10
34	24/09/18 13:15	General View				0	Load JPG	1
35	20/12/18 17:04	Reinspection Pho	oto			0	Load JPG	V
36	20/12/18 17:04	Reinspection Pho				0	Load JPG	V
37	20/12/18 17:04	Reinspection Pho	0.00			0	Load JPG	IV.
22-2	20/12/18 17:04	Reinspection Pho				0	Load JPG	Į.
38		Reinspection Pho				0	Load JPG	10
39	20/12/18 17:04	Reinspection Pho				0	Load JPG	100

					V
41	20/12/18 17:04	Reinspection Photo	0	Load JPG	V
42	20/12/18 17:04	Reinspection Photo	0	Load JPG	V
43	20/12/18 17:04	Reinspection Photo	0	Load JPG	V
44	20/12/18 17:04	Reinspection Photo	0	Load JPG	V
	and the state of t	A service was a service of the servi	Ð	Load JPG	V
45	20/12/18 17:04	Reinspection Photo	- 0	Coad JPG	(A)
	20/12/18 17:04 cumentation	Reinspection Photo	1 per j		<b>2</b>
200	umentation	LKK Auto Consultants Pte Ltd (HQ)			V
Doc				page 🔻	V
Doc	umentation Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1 per s	page *	V
Doc No 1	Relabel / Reorder 24/09/18 13:13	LKK Auto Consultants Pte Ltd (HQ) DRIVING & INS CERT DOC.pdf	1 per s	page ▼ Thumbnail Load PDF	V
No 1 2	Relabel/Reorder 24/09/18 13:13 24/09/18 13:13	LKK Auto Consultants Pte Ltd (HQ) DRIVING & INS CERT DOC.pdf ESTIMATE.pdf	1 per 1	page Thumbnail Load PDF Load PDF	V

## **Linked Accident Report Documents**

			View	Use Viewer	-
Ass	essment Reports		1 per p	age 🔻	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	20/09/18 14:28	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per p	age 🕶	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	-
1	20/09/18 14:10	Accident Photo	0	Load JPG	V
2	20/09/18 14:10	Accident Photo	0	Load JPG	V
3	20/09/18 14:10	Accident Photo	0	Load JPG	V
4	20/09/18 14:10	Accident Photo	0	Load JPG	V
5	20/09/18 14:10	Accident Photo	0	Load JPG	7
6	20/09/18 14:10	Accident Photo	Ð	Load JPG	V
7	20/09/18 14:10	Accident Photo	0	Load JPG	V
8	20/09/18 14:10	Accident Photo	0	Load JPG	V
9	20/09/18 14:10	Accident Photo	0	Load JPG	V
10	20/09/18 14:10	Accident Photo	0	Load JPG	V
11	20/09/18 14:10	Accident Photo	0	Load JPG	V
12	20/09/18 14:10	Accident Photo	0	Load JPG	V
13	20/09/18 14:10	Accident Photo	0	Load JPG	V
14	20/09/18 14:10	Accident Photo	0	Load JPG	V
15	20/09/18 14:10	Accident Photo	0	Load JPG	[2]
16	20/09/18 14:10	Accident Photo	0	Load JPG	V
Doc	cumentation		1 per	page ▼	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Prin
1	20/09/18 14:05	Sketch Plan	0	Load JPG	100
2	20/09/18 14:05	Sketch Plan #2	0	Load JPG	V

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	*
Show Remarks To: Handling Insurer  Nota: Remarks are private unless you show it to other parties.	

### LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #08-16

Singapore 079120

Our File No:

CC3/AIG18017286/ASD3N2

Date:

30/01/2019

REFERENCE

Insured/Claimant: Date of Loss:

AMOS LEE CHEE KEONG

19/09/2018

Policy No: Nature of Claim: 1700075439

OD

Engine No:

Odometer:

Chassis No:

Claim No: 6467767598SG

CVN045367

9971 km

WAUZZZF44JA023477

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

Colour:

**SLT9355U** 

Make & Model: Reg. Date:

AUDI A4, 1.4 TFSI S TRONIC (A)

16/11/2017 (Man. Year: 2017)

Black 1395 cc

Engine Capacity: Market Value/New Car

Price: Sum Insured (S\$): S\$128,000.00 Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 205/60 R16 Continental 6 mm Continental 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 205/60 R16 Continental 6 mm Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,470.00	10,611.52	9,858.48	48.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,672.00	5,232.00	3,440.00	39.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,142.00	15,843.52	13,298.48	45.63
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	28,542.00	15,243.52	13,298.48	46.59
+ GST 7.00/7.00% (S\$)	1,997.94	1,067.05	930.89	46.59
Nett Amount (S\$)	30.539.94	16,310.57	14,229.37	46.59

INSPECTION

Date of Assignment:

24/09/2018

Date Inspected:

24/09/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

8.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

		mended Parts Part No. Particulars	Condition	Repairer's	Amount
	1	*FRONT BUMPER	Distorted	1,849.00 FS	*1,479.20FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*-FS
3	2	*SECURING STRIP	Not Necessary	60.00 FS	*-FS
	1	*GRILLE SATIN BLACK-CENTRE	Not Necessary	171.00 FS	*-FS
5	1	*CLOSING ELEMENT-CENTRE LOWER	Not Necessary	180.00 FS	*-FS
5	1	*AIR GUIDE-LH	Cut	73.00 FS	*57.84 FS
7	1	*AIR GUIDE GRILLE-LH	Damaged	118.00 FS	*94.00 FS
3	1	*GUIDE SECTION-LH	Damaged	31.00 FS	*24.56 FS
9	1	*FRONT FENDER-LH	Distorted	665.00 FS	*532.00 FS
0	1	*ATTACHMENT PARTS FOR FENDER	Necessary	45.00 FS	*35.84 FS
11	1	*CLOSING ELEMENT-LH	Damaged	44.00 FS	*34.56 FS
12	1	*BRACKET FOR FENDER-LH	Damaged	31.00 FS	*24.16 FS
13	1	*BRACKET FOR DEFORMATION-LH	Necessary	43.00 FS	*34.16 FS
14	1	*BRACKET FOR FENDER	Bent	27.00 FS	*21.60 FS
15	1	*BRACKET	Damaged	15.00 FS	*11.76 FS
16	1	*FRONT FENDER BRACE-LH	Bent	103.00 FS	*82.40 FS
17	1	*WHEEL HOUSING LINER-LH	Deformed	215.00 FS	*171.60 FS
18	1	*ATTACHMENT PARTS FOR WHEEL LINER	Not Necessary	78.00 FS	*- FS
19	1	*WHEEL SPOILER-LH	Deformed	63.00 FS	*50.16 FS
20	1	*SPOILER-LH	Cracked	30.00 FS	*23.92 FS
21	1	*BONNET	Dented	2,163.00 FS	*1,730.40 FS
22	1	*ATTACHMENT PARTS FOR BONNET	Not Necessary	105.00 FS	*- FS
23	1	*STONE CHIP GUARD	Necessary	44.00 FS	
24	2	*LID HINGE-LH/RH	Not Necessary	532.00 FS	*- FS
25	1	*BONNET IMPACT PROTECTOR-CENTRE	Necessary	24.00 FS	*18.88 FS
26	2	*BONNET IMPACT PROTECTOR-LH/RH	Necessary	48.00 FS	
27	1	*COVER-LH	Not Necessary	53.00 FS	
28	1	*COVER-LH	Necessary	27.00 FS	*21.04 FS
29	1	*COVER-LH	Necessary	20.00 FS	
30	2	*STRIKER-LH/RH	Not Necessary	88.00 FS	*-F8
31	1	*LID LOCK	Not Necessary	188.00 FS	
32	2	*BOWDEN CABLE-CENTRE	Not Necessary	100.00 FS	
33	1	*LED HEADLIGHT-LH	Cut		*5,578.40 FS
34	1	*POWER MODULE FOR MAIN LIGHT	Not Necessary	695.00 FS	
35	1	*CONTROL UNIT FOR LIGHT CONTROL SYSTEM	Not Necessary	657.00 FS	
36	1	*LIFT CYLINDER-LH	Not Necessary	184.00 FS	
37	1	*REFRIGERANT LINE	Bent	145.00 FS	
38	1	*REFRIGERANT PIPE	Bent	453.00 FS	
39	1	*FRONT DOOR-LH	Repair	2,048.00 FS	
40	1	*OUTER DOOE SEAL-LH	Not Necessary	176.00 FS	
41	1	*CLEANING SOLUTION	Not Necessary	64.00 FS	
42	1	*ATTACHMENT PARTS FOR FRONT DOOR-LH	Not Necessary	462.00 FS	
43	1	*DOOR CATCH	Not Necessary	92.00 FS	
44	1	*DOOR CATCH COVER	Not Necessary	13.00 FS	
45	1	*WINDOW SLOT SEAL WITH TRIM STRIP	Not Necessary	265.00 FS	
46	1	*TRIM STRIP WITH CHROME STRIP	Not Necessary	222.00 FS	
47	1	*BONDING AGENT	Not Necessary	43.00 FS	
48	1	*SUNDRIES	Necessary	500.00 FS	*19.36 F
F=F	anchise	part. S=SpcNett.			ronneger ger einere
			Total Parts (S\$	20,470.00	10,611.52

# Recommended Miscellaneous Items There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW LHS AIR CONDITIONING PIPES.TO CARRY OUT VACUUM AND REGAS	New	480.00	480.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,LHS FRONT FENDER,LHS HEADLIGHT AND LHS FRONT DOOR.INSPECT LHS FENDER INNER SUPPORT FOR DAMAGES.RE- ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,900.00	2,000.00
4	TO RESPRAY FRONT BUMPER, BONNET, LHS FENDER AND LHS FRONT DOOR, HINGES	New	3,500.00	2,200.00
5	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labo	ur Cost (S\$)	8,672.00	5,232.00

< END OF ESTIMATES >