

## Shu Pei (LKKAUTO)

---

**From:** Justin Wong <justin.wong@eqinsurance.com.sg>  
**Sent:** Monday, 24 September 2018 5:54 PM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** Admin A; Joy Irene (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving YM603X (OI : EQI - TBA) AND SH9011S (TP : LKK REF - CC3/EQI18017318/K1jb3) on 19.09.2018  
**Attachments:** OI GIA - YM603X.PDF

Dear Shu Pei,

Please find our insured's GIA report.

Kindly note liability is conflicting, please obtain third-party accident video footage to clear liability before direct settlement.

Thank you.

Regards,  
**Justin Wong**  
Executive | Claims



### EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Shu Pei (LKKAUTO) [mailto:shupe@lkkauto.com]  
**Sent:** Monday, September 24, 2018 5:22 PM  
**To:** Justin Wong <justin.wong@eqinsurance.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving YM603X (OI : EQI - TBA) AND SH9011S (TP : LKK REF - CC3/EQI18017318/K1jb3) on 19.09.2018

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SH 9011S at M/s ComfortDelGro Engineering Pte Ltd – Loyang.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6749 5792.

Thank you.

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeilkkauto.com](mailto:shupeilkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)