

INS. CASE OWNER: CC3 / III1801 JNM, Tj. Subh / LKK: IDAC:

Surveyor: Tuftlen. DOI: ASSIGNMENT 5/10/18 Date/Time: 20/9/18 Registered in Merimen: W/A/18

Pre-assign / CCU / FTE
 Insured Vehicle No.: SHD 34659 Claim No.: MCT15090598
 Name of Insured: LTP Policy No.: MLOM2015
 Insured Tel No.: HP: N/A/18 Make / Model: Hyundai
 Excess Sec II :SS D.O.A.: Nature of Accident: BARTLEY (SUP KO) TMS upp
 Is driver the owner? (YES/NO) TP GIA REPORT: YES/NO TP GIA REPORT: YES/NO
 If NO, Driver Name / Age: UM JIM TEE LIM KONGHUI Insured Liability: % Final ? Yes / No
 Driver Tel No.: (V/L-YES/NO)



SJN JAHH → → → → →
 INSRs: WSP: Performance Tel: Liability: RMKS: INSRs: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE/PIC
20/9/18 TJH	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	
	After call Itr to OI	NA
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act	<input checked="" type="checkbox"/>
	Release Voucher	<input checked="" type="checkbox"/>
	Final Repair Bill	<input checked="" type="checkbox"/>
	Car Rental Invoice	<input checked="" type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
28-2-19	FOR MANDATE	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Final Call
 FINAL SETTLEMENT Date/Time: 5-7-19 Confirm with: CAROLINE Email Call
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27
 Repair Cost: GST SS 5,610.97
 Loss of Rental (LOR): SS (days)
 Loss of Use (LOU): SS 600 (100 x 6 days)
 Loss of Income (LOI): SS (\$ x days)
 LOR only LOU only LOR + LOU LOR + LOU [Tick only one]
 GIA/LTA Search: SS 7.45
 Medical: SS
 Disbursement: SS (e.g. Tow/Independent)
 Legal Cost: SS
 Total: SS 6,218.42 Global Sum SS:
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee:

FINAL PAYMENT Date/Time: Confirm with: Email Call
 Payee 1: SS 6,218.42 Name 1: PERFORMANCE MOTOR LIMITED
 Payee 2: (Strike if N.A.) SS X Name 2: X
 Payee 3: (Strike if N.A.) SS X Name 3: X

COPY SENT

Executive

Taylor

REF:

III

U

J

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop no/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<i>2</i>	

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 4 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date _____ Person Contacted: Chane Vehicle IN / OUT

Veh No: SSN 7911H Yr Regn: 201 Feb
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Primo Mover /
 Truck / Trailer or
 Make: MAZDA BMW 521 cc 1995
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 196508 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: WISANT 12010(X298)7
 Gen. Cond: 3 Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size F: 225/55R16.
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 5/10/18
 Survey held at: PML
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time _____ Action / Instruction _____ White: 22557

101 \$ 5,243.90

R (\$ 7,273.25 / 58%)

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Insp (\$)
 Weekend (\$)
 TOTAL _____

Report Format: _____
 Lump Sum / I.B.I: (\$)

Due 3/10

BMW Dealer

Performance Motors Limited

A member of the BMW Group
 Co. Reg. No. 19740109W GST Reg. No. M2-0020081-X



102, Alexandra Road
 BMW Group Performance Centre
 Singapore 159941
 Tel. 61190100 (Sales & Admin)
 61190111 (AfterSales)
 Fax. 64747770

180, Kampong Arang Road
 East Coast Centre
 Singapore 420185
 Tel. 61190888 (AfterSales)
 Fax. 67449775

119, Alexandra Road
 BMW Group Business Centre
 Singapore 159944
 Tel. 61190228 (AfterSales)
 61190531/532 (Motorrad)
 Fax. 64794021 (AfterSales)
 64794024 (Motorrad)

GST REG. NO : M2 - 0020081 - X

24 SEP 2018

ESTIMATE

Estimate No. : b1 48527	Page No. : 1 of 5
Date Estimated : 22/09/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Chee Han Sing 15 Kang Coo Bin Walk Singapore 548236	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520iA	0

DESCRIPTION	VALUE
Replace rear bumper and remove attachment etc	850 1,275.00
Spray painting rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To replace rear exhaust silencer including alignment system and conduct checks for leak.	451? 531.00
Sundries. <i>N/A</i>	80? 150.00
Total Labour 1: 3,171.00	

DESCRIPTION	QTY	PRIC	VALUE
RR EXHAUST RUBBER MOUNTING	1	30.85	30.85
RUBBER RING	1	38.15	38.15
BRACKET	1	44.60	44.60
RR SILENCER BRACKET	1	39.90	39.90
EXCH CATALYST WITH FRT SILENCER	1	4,002.40	4,002.40
RR SILENCER CHROME PIPE	1	122.05	122.05
REAR SILENCER	1	1,098.80	1,098.80
RR BUMPER CARRIER	1	529.25	529.25
RR BUMPER CENTRE MOUNT	1	151.20	151.20
RR BUMPER CTR BOTTOM GUIDE	1	32.75	32.75
BUMPER PDC HOLDER	1	20.30	20.30
RR BUMPER TOW HOOK COVER	1	41.80	41.80
RR BUMPER (PDC)	1	1,335.15	1,335.15
RR BUMPER LH MOUNT	1	73.85	73.85
RR BUMPER RH MOUNT	1	105.50	105.50
RR BUMPER LH REFLECTOR	1	34.15	34.15
RR BUMPER RH REFLECTOR	1	34.15	34.15
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
PDC sensor	4	368.80	1,475.20
Total Parts :			9,230.05

Performance Motors Limited

A member of the Silver Derby Group
Co. Reg. No. 197401559W; GST Reg. No. M2-0020051-X



SUPPLEMENTARY

Estimate No. : b1 48527
Date Estimated : 22/09/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chee Han Sing
15 Kang Coo Bin Walk

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 548236

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SJN7911H	CX29877	27/02/2009	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH *	60.60	1.00		60.60 <i>ht</i>
# RUBBER MOUNTING *	43.30	1.00		43.30 <i>de</i>
# PLUG *	1.40	3.00		4.20 <i>na</i>
# PUSH BUTTON*	2.20	2.00		4.40 <i>na</i>
# PLUG-IN NUT *	1.80	2.00		3.60 <i>na</i>

Total Labour :
Total Parts : 116.10
Total Labour & Parts : 116.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 167431599W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 48527
Date Estimated : 22/09/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chee Han Sing
15 Kang Coo Bin Walk

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 548236

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	S20iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
* To replace rear exhaust silencer including alignment system and conduct checks for leak	451.00		451.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR SILENCER BRACKET	39.90	1.00		39.90
RR SILENCER CHROME PIPE	122.05	1.00		122.05
# CLAMPING BUSH *	60.60	1.00		60.60
REAR SILENCER	1,098.80	1.00		1,098.80
# RUBBER MOUNTING *	43.30	1.00		43.30
# PLUG *	1.40	3.00		4.20
RR BUMPER CTR BOTTOM GUIDE	32.75	1.00		32.75
RR BUMPER (PDC)	1,335.15	1.00		1,335.15
# PUSH BUTTON*	2.20	2.00		4.40
# PLUG-IN NUT *	1.80	2.00		3.60
RR BUMPER LH REFLECTOR	34.15	1.00		34.15

SUPPLEMENTARY ITEMS

Total Labour :	2,465.00
Total Parts :	2,778.90
Total Labour & Parts :	5,243.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,243.90
GST @7%:	367.07
Grand Total :	5,610.97

Emil 21/1/19

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197451519W GST Reg. No MQ-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438183
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)

Due 3/10

GST REG. NO : M2 - 0020081 - X

24 SEP 2018

E S T I M A T E

Estimate No. : b1 48527	Page No. : 1 of 5
Date Estimated : 22/09/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Chee Han Sing 15 Kang Coo Bin Walk Singapore 548236	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520ia	0

DESCRIPTION	VALUE
Replace rear bumper and remove attachment etc	850 1,275.00
Spray painting rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To replace rear exhaust silencer including alignment system and conduct checks for leak.	451? ^{photo} 531.00
Sundries.	? 150.00
Total Labour 1:	3,171.00

DESCRIPTION	QTY	PRIC	VALUE
RR EXHAUST RUBBER MOUNTING	1	30.65	? 30.65
RUBBER RING	1	38.15	? 38.15
BRACKET	1	44.60	? 44.60
RR SILENCER BRACKET	1	39.90	? 39.90
EXCH CATALYST WITH FRT SILENCER	1	4,002.40	? 4,002.40
RR SILENCER CHROME PIPE	1	122.05	122.05
REAR SILENCER	1	1,098.80	1,098.80
RR BUMPER CARRIER	1	529.25	? 529.25
RR BUMPER CENTRE MOUNT	1	151.20	? 151.20
RR BUMPER CTR BOTTOM GUIDE	1	32.75	? 32.75
BUMPER PDC HOLDER	1	20.30	? 20.30
RR BUMPER TOW HOOK COVER	1	41.80	x 41.80
RR BUMPER (PDC)	1	1,335.15	1,335.15
RR BUMPER LH MOUNT	1	73.85	73.85
RR BUMPER RH MOUNT	1	105.50	? 105.50
RR BUMPER LH REFLECTOR	1	34.15	? 34.15
RR BUMPER RH REFLECTOR	1	34.15	? 34.15
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	x 20.20
PDC sensor	4	368.80	? 1,475.20
Total Parts :			9,230.05

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770380, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944Tel. 63190528 (AfterSales)
63190533/530 (Motocrad)
Fax. 64796601 (AfterSales)
64796624 (Motocrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T EEstimate No. : b1 48527
Date Estimated : 22/09/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520iA	0

Service Order / 2nd Party / Uninsured Losses / Claims Settlement

Estimate No. 5/10/18 e 1050 Claim No. _____
 Excess \$ _____
 Surveyor's Name: Tanpin Sign: [Signature]
 Surveyor's Tel: 97495744 Authorized: _____
 Authorized Date: WP Date: _____
 RESURVEY PARTS PHOTO BY SURVEYOR: Tanpin @ lkkauto.com
 Surveyor's E-mail: _____
 No. of Working Days Requirement: 4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Labour 1	:	3,171.00
Parts	:	9,230.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	868.07
Grand Total	:	13,269.12

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Due 3/10

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



102, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

200, Kampong Arang Road
East Coast Centre
Singapore 430180
Tel: 63190888 (AfterSales)
Fax: 63443773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

24 SEP 2018

E S T I M A T E

Estimate No. : b1 48527	Page No. : 1 of 5
Date Estimated : 22/09/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Chee Han Sing 15 Kang Coo Bin Walk Singapore 548236	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520iA	0

DESCRIPTION	VALUE
Replace rear bumper and remove attachment etc	850 1,275.00
Spray painting rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To replace rear exhaust silencer including alignment system and conduct checks for leak. ✓	451? photo 531.00
Sundries.	? 150.00
Total Labour 1: 3,171.00	

DESCRIPTION	QTY	PRIC	VALUE
RR EXHAUST RUBBER MOUNTING	1	30.65	? 30.65
RUBBER RING	1	38.15	? 38.15
BRACKET	1	44.60	? 44.60
RR SILENCER BRACKET	1	39.90	? 39.90
EXCH CATALYST WITH FRT SILENCER	1	4,002.40	? 4,002.40
RR SILENCER CHROME PIPE	1	122.05	dk 122.05
REAR SILENCER	1	1,098.80	1,098.80
RR BUMPER CARRIER	1	529.25	? 529.25
RR BUMPER CENTRE MOUNT	1	151.20	? 151.20
RR BUMPER CTR BOTTOM GUIDE	1	32.75	? 32.75
BUMPER PDC HOLDER	1	20.30	? 20.30
RR BUMPER TOW HOOK COVER	1	41.80	x 41.80
RR BUMPER (PDC)	1	1,335.15	dk 1,335.15
RR BUMPER LH MOUNT	1	73.85	nu 73.85
RR BUMPER RH MOUNT	1	105.50	? 105.50
RR BUMPER LH REFLECTOR	1	34.15	? 34.15
RR BUMPER RH REFLECTOR	1	34.15	? 34.15
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	nu x 20.20
PDC sensor	4	368.80	? 1,475.20
Total Parts :			9,230.05

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64796770280, East Coast Road
East Coast Centre
Singapore 438180
Tel: 63190098 (AfterSales)
Fax: 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48527
Date Estimated : 22/09/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520iA	0

Vehicle ID / 3rd Party / Uninsured losses / Direct Settlement

Claim No. _____

Excess \$ _____

Surveyor's Name Tan Kah Sign [Signature]

Surveyor's Tel 97495744 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tan@khan.com

No. of Working Days Requirement 4 days

Labour 1	:	3,171.00
Parts	:	9,230.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	868.07
Grand Total	:	<u>13,269.12</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kaspong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 48527**
Date Estimated : **22/09/2018**
Prepared By : **Chua Kee Sin**Page No. : **3 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520iA	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190200 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 428168
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No.	: b1 48527
Date Estimated	: 22/09/2018
Prepared By	: Chua Kee Sin

Page No. : 4 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520iA	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - to the Vendor's business partners for the purpose of carrying out product promotions;
 - to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kangkong Arang Road
East Coast Centre
Singapore 438188
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 48527**
Date Estimated : **22/09/2018**
Prepared By : **Chua Kee Sin**Page No. : **5 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520iA	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.5(a) above
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- put his request in writing;
 - provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- put his request in writing by way of an email sent to the Vendor;
 - provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors LimitedAddress:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941Email address:
dataprotection@pmi.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC3/III18017329/ub3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 24-09-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3465G	Veh. Inspected	SJN 7911H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/09/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Print Received Message

This mail is associated with :

***SJN7911H (MCT18090598)**
[SHD3465G]
TP
CHEE HAN SING
Sep 21 2018 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 04/07/2019 11:19 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6218.42) - SJN7911H - Claim Handler: Priya

Approved:6218.42.

*** FAX TX REPORT ***

TRANSMISSION OK

JOB NO.	0007
DESTINATION ADDRESS	964794601
SUBADDRESS	
DESTINATION ID	
ST. TIME	12/02 11:40
TX/RX TIME	00' 20
PGS.	1
RESULT	OK



BMW Dealer

Performance Motors Limited

A member of the Bmw Group



India Int'l Insurance Pte Ltd
 64 Cecil Street
 #04-05 IOB Building
 Singapore 049711
 Attention: Motor Claims



"Without Prejudice"

Your Ref: _____
 Our Ref: _____
 Date: 25 January 2019
 Subject: **ACCIDENT INVOLVING VEHICLES SJN7911H & SHD3465G ON 21.09.2018**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$ 5610.97
Loss of use	: S\$ 600.00 (S\$100.00 x 6 days)
LTA search fee	: S\$ 7.45
Total	: S\$ 6218.42

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & LTA search slip
3. Copy of Certificate of Insurance
4. Copy of Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Performance Motors Limited
 1000-Call-GMW (1800-2255-200)
 www.pml.com.sg
 303 Alexandra Road
 Singapore 159041
 Tel Sales 6319 0100
 Tel AfterSales: 6319 0111

PC

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no obligation but to commence legal proceedings against you without any further notice to you or

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Name of Policyholder:

CHEE HAN SING

Date of issue:

13 Feb 2018

Registration No.:

SJN7911H

Effective Date of Commencement:

27 Feb 2018 00:00

Chassis No.:

WBANT12010CX29877

Certificate No.:

SI18V01994/ VPC / R02

Date of Expiry:

26 Feb 2019 23:59

Type of Certificate:

MX1

Persons or Classes of Persons entitled to drive*:

- A) The Policyholder.
- B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- A) Use for hire or reward.
- B) Use for racing, pace-making, reliability trials or speed-testing.
- C) Use for the carriage of goods (other than samples) in connection with any trade or business.
- D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).



For and on behalf of
LIBERTY INSURANCE PTE LTD
Approved Insurers

For Information Only:

Coverage(s):	Comprehensive, Unlimited Windscreen
Sum Insured:	MARKET VALUE AT THE TIME OF LOSS
Excess:	Section I S\$800, Section I - Unnamed Drivers S\$0, Additional Excess for Young & Inexperienced Drivers S\$2500, Windscreen Excess S\$0
Name of Finance Company:	
Name of Producer:	SD CONTEGO SERVICES (A1429-5)

PLRM/82BAAAMT/SI18V01994/15-Feb-2018/MotorCI/v1.0

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of a man

Licence Number: **S02374741**

Name: **CHEE HAN SING**

Birth Date: **17 Jan 1954**

Issue Date: **06 Jan 2003**

Barcode

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	24 Jan 1978



NP 428A

IC COLLECTION SLIP
M/RIC NO : S0237474I (PINK IC)



NAME : CHEE HAN SING FEES : \$60.00

COLLECTION COUNTER : Please visit <https://eappointment.ica.gov.sg> or our mobile app, eAPPOINTICA, to make an appointment.
COLLECTION DATE : 24/09/2018

REGISTRATION OFFICER : Zunur Huda Bin Ali DATE OF ISSUE : 23/08/2018

COLLECTION HOURS : 8.00 am - 4.30 pm (Mon-Fri)
8.00 am - 12.30 pm (Sat)
SIGNATURE/RTS OF RECIPIENT :

Ali
Zunur Huda Bin Ali

Your IC will be destroyed if you do not collect it within 2 months from the collection date and you will have to pay the fee for a new replacement IC. Do not wear Colored/Patterned contact lenses during collection. You may authorize a Singapore Citizen or Singapore Permanent Resident to collect the IC on your behalf. Please inform the proxy to produce his/her IC and the collection slip duly completed on the reverse side of the collection slip. Proxy collection is not allowed at SingPost and IC-Collect.

Original IC which was recovered

Original IC collection slip

A photocopy of your bank passbook showing your particulars, most importantly your account number to facilitate the refund of the IC replacement fee

Any request for refund of IC replacement fee due to recovery of lost IC after above *grace period will not be acceded to. If the lost IC is found after the expiry of grace period, it must be returned to our office for cancellation.

Losing an IC is a serious matter. We would like to take this opportunity to remind you to be extra careful with your IC.



08 SEP 2018

ADVICE TO IDENTITY CARD (IC) HOLDER WHO HAS REPORTED LOSS IC

You have reported the loss of your identity card (IC) to our office. If you subsequently recover your IC, you are advised to bring it back to us by 08 SEP 2018 (Mon - Fri: 8.00am to 4.30pm; Sat: 8.00am to 12.30pm) for the facility of the refund of your IC replacement fee. Please come in person to ICA with the following documents:

- Original IC which was recovered
- Original IC collection slip
- A photocopy of your bank passbook showing your particulars, most importantly your account number to facilitate the refund of the IC replacement fee

Any request for refund of IC replacement fee due to recovery of lost IC after above *grace period will not be acceded to. If the lost IC is found after the expiry of grace period, it must be returned to our office for cancellation.

Losing an IC is a serious matter. We would like to take this opportunity to remind you to be extra careful with your IC.

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref:
 Claimant Ref :

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd Mr. Juvith from LKK (name of Surveyor) with respect to the amount claimed for S\$ 510.97 (repair cost), S\$ 610 (loss of use/rental), S\$ 7.45 (search fee), vehicle no SIN7911H that was damaged pursuant to the accident which occurred on 21-9-2018 (date) at Bartley Road (location) involving vehicle no S1D3465A (insured vehicle). This is pursuant to the inspection conducted on 5-10-2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Chock Han Sing ("the third party claimant") of vehicle no. SIN7911H to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SIN7911H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ _____ to _____.

Dated this _____ day of _____, 20 _____

CLAIMANT:
 Signature: [Signature]
 Name: _____
 NRIC: _____
 Address: _____
 Nationality: _____
 Occupation: _____

PERFORMANCE MOTORS LIMITED
 303 Alexandra Road
 The Party Performance Centre
 Singapore 159941
 TEL: 63190100 (Sales)
 63190111 (Insurance)
 Signed by "the workshop" (With Chop)

WITNESS:
 Signature: _____
 Name: _____
 NRIC: _____
 Address: _____
 Nationality: _____
 Occupation: _____

Signed by appointed Surveyor



India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

**"Without Prejudice"**

Your Ref :

Our Ref :

Date : 25 January 2019

Subject : **ACCIDENT INVOLVING VEHICLES SJN7911H & SHD3465G ON 21.09.2018**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$	5610.97
Loss of use	: S\$	600.00 (S\$100.00 x 6 days)
LTA search fee	: S\$	7.45
Total	: S\$	6218.42

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & LTA search slip
3. Copy of Certificate of Insurance
4. Copy of Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1600-Carl-BMW
(1800-2255-269)
www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel After-sales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel After-sales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel After-sales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

We are in receipt of your letter which is covering your attention rights to conduct a search. Kindly note that we are preserving our necessary records. We will be using your client's details.

Our Ref: MCT/18090548

Name: Dny

Date: 3/2/2019

Info: Information@pml.com.sg

3/2/2019

LETTER OF AUTHORISATION

ACCIDENT INVOLVING SJN 7911H & S10 34656 ON 21/9/2018.

I, Chee Han Sing owner of Vehicle Registration No. SJN 7911H
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment due
to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:



SO 237474 I

Name: CHEE HAN SING (Date) 22/9/18

NRIC No.:

In the presence of:

CHUA KEE SIN
Performance Motors Limited
303 Alexandra Road
Sisco Darby Performance Centre
Singapore 159941



Name:

(Date)

22/9/2018

NRIC No.:

cc106lw



INDIA
INTERNATIONAL
INSURANCE
PTE LTD
SINGAPORE

INDIA INTERNATIONAL INSURANCE PTE LTD

Co Reg No: 190717928 (07) Reg No: M2-007-000-5
14 Cecil Street, #04-07, #05-02, 06, 07, 08, 09, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
Tel: (65) 63476100 Fax: 63476100
E-mail: info@indiaintl.com.sg Website: www.indiaintl.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18090598
Claimant Ref: SJN 7911H

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for SS 5,610.97 (repair cost), SS 600.00 (loss of use/rental), SS 7.45 (search fee) vehicle no. SJN 7911H that was damaged pursuant to the accident which occurred on 21.09.18 (date) at BARTLEY ROAD (location) involving vehicle no. S1P 346SD (insured vehicle). This is pursuant to the inspection conducted on 5.10.18 (date) at "the workshop".

We/I confirm that we/I am/are authorized by the owner CHEE HAN SING ("the third party claimant") of vehicle no. SJN 7911H make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SJN 7911H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of SS 6,218.42 to PERFORMANCE MOTORS LIMITED

Dated this 5 day of July 2019

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

GARY POH CHAI HOON
Performance Motors Limited
303 Alexandra Road
Singapore 159941
SIGNED BY THE WORKSHOP (with chop)

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607196R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-23 SINGAPORE 408933



301, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438188
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190328 (AfterSales)
63190333/330 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1304462	Page No. : 1 of 2
Date IN : 05/10/2018	Invoice Number : 2058546 / WSB
Cust. Svc. Advisor: Chua Kee Sin	Invoice Date : 24/01/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -	- INVOICE TO - 219
Mr Chee Han Sing 15 Kang Coo Bin Walk Singapore 548236	India Int'L Insurance Pte Ltd 64 Cecil Street #04-05 IOB Building Singapore 049711

REGN. NO. SJN7911H	CHASSIS NO. CX29877	REGN. DATE 27/02/2009	MODEL 520IA	MILEAGE 196613
------------------------------	-------------------------------	---------------------------------	-----------------------	--------------------------

- - - - LABOUR 1 - - - -		NETT
To replace rear bumper and attachments including to remove and install body parts in order to carry out painting job.		850.00
To respray rear bumper.		934.00
To check electrical wiring systems and lightings at the rear section for proper function.		150.00
To replace rear silencer, chrome pipe and clamping bush etc including alignment system and conduct checks for leak.		451.00
Sundries.		80.00
INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT, DATE OF ACCIDENT : 21.9.2018. 3RD PARTY CAR : SHD3465G. YOUR REF NO : NIL.		0.00
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 5.10.2018 AT 10.50 AM. AUTHORISED REPAIR BY MS THIN THIN HLAING FROM LKK AUTO CONSULTANTS PTE LTD ON 1.10.2018 VIA E-MAIL.		0.00
PROPOSE LOSS OF USE = \$100X6. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.		0.00
LTA SEARCH FEE = \$7.45.		0.00
Total Labour 1:		2,465.00
- - - - PARTS - - - -		NETT
	Qty Retail Price	
PLUG	3 1.40	4.20
RR SILENCER CHROME PIPE	1 122.05	122.05
RR BUMPER CTR BOTTOM GUIDE	1 32.75	32.75
RR BUMPER LH REFLECTOR	1 34.15	34.15
RR BUMPER (PDC)	1 1,335.15	1,335.15
PLUG-IN NUT	2 1.80	3.60
PUSH BUTTON*	2 2.20	4.40
REAR SILENCER	1 1,098.80	1,098.80
RR SILENCER BRACKET	1 39.90	39.90
CLAMPING BUSH	1 60.60	60.60
RUBBER MOUNTING	1 43.30	43.30

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190328 (AfterSales)
63190333/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1304462**Date IN : **05/10/2018**Cust. Svc. Advisor: **Chua Kee Sin**Page No. : **2 of 2**Invoice Number : **2058546 / WSB**Invoice Date : **24/01/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng**Total Parts : **2,778.90**Labour Charges : **2,385.00**
Parts Charges : **2,778.90**
Lubricant/Misc : **80.00**Total Labour & Parts Charges : **S\$ 5,243.90**
Less Insurance Excess : **S\$ 0.00**
Invoice Total Amount Exclude GST : **S\$ 5,243.90**
GST @ 7% : **S\$ 367.07**
Invoice Total Amount Include GST : **S\$ 5,610.97**

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 5,610.97**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 24 Sep 2018 / 13:25:27

Receipt Date/Time : 24 Sep 2018 / 13:25:27

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180924-001188

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SHD3465G As at 21 Sep 2018/15:10:00 Insurance Co: INDIA INTL INS PTE LTD			
1	Insurance Enquiry - SHD3485G Enquiry Fee 20180924131545111551	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx9609 Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2018 Edit Reg		05 Oct 2018 00:00 Edit Adj Rpt	S\$5,243.90 Edit Estimates	S\$5,243.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	CHEE HAN SING , ID: S02374741								
Vehicle Reg. No.:	SJN7911H	Date of Loss:	21/09/2018 15:00 - :59 [114 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18090598	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD3465G	Policy No. (Claimant):	SI18V01994/VPC/R02						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (04/07/2019): Alert - Adj Mandate Approved (S\$6218.42) - SJN7911H - Claim Handler: Priya III_SG (27/02/2019): LOD upload into merimen III_SG (28/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SJN7911H - Claim Handler: Priya 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN7911H (MCT18090598)
 [SHD3465G]
 TP
 CHEE HAN SING
 Sep 21 2018 3:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		View	View in Browser	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
2	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
3	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
4	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
5	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
6	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
7	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
8	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
9	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
10	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
11	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
12	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
13	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
14	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
15	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
16	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
17	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
18	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
19	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
20	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
21	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
22	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
23	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
24	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
25	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
26	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
27	03/07/19 18:12	General View					Load JPG <input checked="" type="checkbox"/>	
28	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
29	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
30	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
31	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
32	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
33	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
34	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
35	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
36	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	
37	03/07/19 18:13	Reinspection Photo					Load JPG <input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	03/07/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/18 16:55	TP ESTIMATE	 Load PDF	
2	24/09/18 16:55	TP GIA REPORT	 Load PDF	
3	09/10/18 11:00	TP ESTIMATE- MARKED	 Load PDF	
4	10/07/19 09:45	WORKSHOP INVOICE	 Load PDF	
5	10/07/19 09:45	AUTHORISATION TO ACT FORM	 Load PDF	
6	10/07/19 09:45	DISCHARGE VOUCHER	 Load PDF	
7	10/07/19 09:45	LTA SEARCH	 Load PDF	
8	10/07/19 09:45	LOD	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	25/09/18 09:01	Singapore Accident Statement-iv	 Load PDF	
2	21/02/19 17:25	Letter of Demand from Third Party TPD LOD FROM PERFORMANCE MOTORS LTD (5JN7911H)	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18017329/T1JB3Q2

Date: 10/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015	
Claimant Vehicle No : SJN7911H	Insured Vehicle No : SHD3465G	
Date of Loss: 21/09/2018	Nature of Claim: TP	Claim No: MCT18090598

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN7911H	Engine No: A899I352N46B20BE
Make & Model: BMW 520I, 2.0 (A)	Chassis No: WBANT12010CX29877
Reg. Date: 27/02/2009 (Man. Year: 2008)	Odometer: 196508 km
Colour: Maroon	
Engine Capacity: 1995 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 225/55 R16	Rear Tyre Size: 225/55 R16
Front Left Side: Continental 6 mm	Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm	Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,496.15	2,858.90	6,637.25	69.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,021.00	2,385.00	636.00	21.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,517.15	5,243.90	7,273.25	58.11
+ GST 7.00/7.00% (S\$)	876.20	367.07	509.13	58.11
Nett Amount (S\$)	13,393.35	5,610.97	7,782.38	58.11
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,218.42		

INSPECTION

Date of Assignment:	05/10/2018	
Date Inspected:	05/10/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2019)
Parts: 143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN7911H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*RR EXHAUST RUBBER MOUNTING	Not Necessary	30.65 FS	*- FS
3	1		*RUBBER RING	Not Necessary	38.15 FS	*- FS
4	1		*BRACKET	Not Necessary	44.60 FS	*- FS
5	1		*RR SILENCER BRACKET	Bent	39.90 FS	*39.90 FS
6	1		*EXCH CATALYST WITH FRT SILENCER	Not Necessary	4,002.40 FS	*- FS
7	1		*RR SILENCER CHROME PIPE	Dented	122.05 FS	*122.05 FS
8	1		*REAR SILENCER	Bent	1,098.80 FS	*1,098.80 FS
9	1		*RR BUMPER CARRIER	Not Necessary	529.25 FS	*- FS
10	1		*RR BUMPER CENTRE MOUNT	Not Necessary	151.20 FS	*- FS
11	1		*RR BUMPER CTR BOTTOM GUIDE	Deformed	32.75 FS	*32.75 FS
12	1		*BUMPER PDC HOLDER	Not Necessary	20.30 FS	*- FS
13	1		*RR BUMPER TOW HOOK COVER	Not Necessary	41.80 FS	*- FS
14	1		*RR BUMPER (PDC)	Deformed	1,335.15 FS	*1,335.15 FS
15	1		*RR BUMPER LH MOUNT	Not Necessary	73.85 FS	*- FS
16	1		*RR BUMPER RH MOUNT	Not Necessary	105.50 FS	*- FS
17	1		*RR BUMPER LH REFLECTOR	Cracked	34.15 FS	*34.15 FS
18	1		*RR BUMPER RH REFLECTOR	Not Necessary	34.15 FS	*- FS
19	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
20	4		*PDC SENSOR	Not Necessary	1,475.20 FS	*- FS
21	1		*CLAMPING BUSH	Bent	60.60 FS	*60.60 FS
22	1		*RUBBER MOUNTING	Deformed	43.30 FS	*43.30 FS
23	3		*PLUG	Necessary	4.20 FS	*4.20 FS
24	2		*PUSH BUTTON	Necessary	4.40 FS	*4.40 FS
25	2		*PLUG-IN NUT	Necessary	3.60 FS	*3.60 FS
Total Parts (S\$)					9,496.15	2,858.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC	New	1,275.00	850.00
2	SPRAY PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
Gross Labour Cost (S\$)			3,021.00	2,385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >