

Due 3/10

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

24 SEP 2018

ESTIMATE

Estimate No. : b1 48527	Page No. : 1 of 5
Date Estimated : 22/09/2018	
Prepared By : Chua Kee Sin	

<p>- ESTIMATE REPAIR FOR - Chee Han Sing 15 Kang Coo Bin Walk Singapore 548236</p>	<p>- ACCOUNT - 40000 Cash Sales - Service Singapore</p>
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520ia	0

DESCRIPTION	VALUE
Replace rear bumper and remove attachment etc	850 1,275.00
Spray painting rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To replace rear exhaust silencer including alignment system and conduct checks for leak.	451? photo 531.00
Sundries.	? 150.00

Total Labour 1: **3,171.00**

DESCRIPTION	QTY	PRIC	VALUE
RR EXHAUST RUBBER MOUNTING	1	30.65	? 30.65
RUBBER RING	1	38.15	? 38.15
BRACKET	1	44.60	? 44.60
RR SILENCER BRACKET	1	39.90	? 39.90
EXCH CATALYST WITH FRT SILENCER	1	4,002.40	? 4,002.40
RR SILENCER CHROME PIPE	1	122.05	dh 122.05
REAR SILENCER	1	1,098.80	1,098.80
RR BUMPER CARRIER	1	529.25	? 529.25
RR BUMPER CENTRE MOUNT	1	151.20	? 151.20
RR BUMPER CTR BOTTOM GUIDE	1	32.75	? 32.75
BUMPER PDC HOLDER	1	20.30	? 20.30
RR BUMPER TOW HOOK COVER	1	41.80	x 41.80
RR BUMPER (PDC)	1	1,335.15	de 1,335.15
RR BUMPER LH MOUNT	1	73.85	nu 73.85
RR BUMPER RH MOUNT	1	105.50	? 105.50
RR BUMPER LH REFLECTOR	1	34.15	? 34.15
RR BUMPER RH REFLECTOR	1	34.15	x 34.15
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	nu 20.20
PDC sensor	4	368.80	? 1,475.20

Total Parts : **9,230.05**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48527	Page No. : 2 of 5
Date Estimated : 22/09/2018	
Prepared By : Chua Kee Sin	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN7911H	CX29877	27/02/2009	520iA	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 5/10/18 @ 1050 Excess S\$ _____

Surveyor's Name Taufik Sign [Signature]

Surveyor's Tel 97495744 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail taufik@lkkauto.com

No. of Working Days Recommend 4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	3,171.00
Parts	:	9,230.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	868.07
Grand Total	:	13,269.12

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **