

Surveyor of Markus ASSIGNMENT (Office)

From (Person) CWS May chua of FCI Date/Time: 24/9/18 @ 2:22pm

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 2633J Insured: 8H 90002

at Workshop n/s: Progressive Automotive Tel: 6741 5336

of Blk 3022A, Ubi Rd 1 #01-45/46

Policy No: _____ Claim No: D1800 6967 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/09/18

CA / REV / REP. / REV 24 HRS (Ds) H.O.D. Endorsement: _____

Date/Time: 3:36pm @ 24/9/18 Person Contacted: Pei wen Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLP 2633J - x</u>
	<u>8H 90002 - C03 / LCR 18006708 / K1j63</u> <u>D.O.A: 6/4/18</u>
<u>25/9/18-</u>	<u>VNI yet</u>
<u>28/9/18</u>	<u>vehicle still not in. (pending owner reply)</u>
<u>03/10/18</u>	<u>@ 15:31 p.m. revised PA to May chua via email.</u>

REF: FCI

ASSIGNMENT

From: Date: 01/10/18

Veh No: SLP 2633J Yr Regn: 12 10

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer of (A/)

To Inspect Vehicle No: SLP 2633J
at Workshop m/s: Progressive
of: BLK 3022A, Ubi Rd 1 #01-45/46

Make: BMW 730Li C.C. 2996

Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: 58102 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: WBAKB22020CN 74736

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

After 12:30pm

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F:

R:

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

65k

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

3

days

Res.: Yes or No

D.O.A.

19/9/18

D.O.I.

1/10/18

Lump Sum:

1.51

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS (DS)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

not 7812

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 57188 2yrs. Insh. Dep 14
No second hand parts.

RECEIVED 12 OCT 2018

12/10/18 Confirmed fuel by #2538.21 with Ray

12/10/18 Confirmed P/P \$ 2,538.21 @ 3 days with Marcus.
(\$ 2,986.73 Red - 54%)

MV - \$65k, LTA - \$57,188.00, NCA Value - \$ 7,812.00

Date/Time, File Pass to?

12/10/18

: Preli. Report

Days Of Repair: 3

1) Typist

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$)

Transportation

Report Format :

: Interview (\$)

) Photos

Lump Sum / I.B.I: (\$ 2,538.21 P/P)

: Tech. Invs (\$)

) Others

: Weekend (\$)

TOTAL

140
50
50
38
278



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006967MFSH

Date: 03 October 2018

Our Ref: CS/FCI18017350/Usd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 2633J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/10/2018 at the premises of M/s Progressive Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>SS 5,524.94</u>
Revised Estimate Amount	: <u>SS 2,538.21</u>
"Check" Items Amount	: <u>SS 1,929.74</u>
Market Value	: <u>SS</u>
LTA Reimbursement Value	: <u>SS</u>
Nett Value	: <u>SS</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 3 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-09-2018	Our Ref No. D18006967MFSH
Accident Date	19-09-2018	Claim Type. Third Party
Insured Vehicle	SH9000Z	Third Party Vehicle. SLP2633J
Survey Location	BLK 3022A UBI ROAD 1 #01-45/46	
Contact Person.	PEI WEN NG	
Contact No.	67415336/ 0	Fax No. 67417208
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 3 October 2018 3:31 PM
To: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: ASSIGNMENTS@LKKAUTO.COM; 'SUR'; 'Nivitha (LKK Auto)'
Subject: RE: SURVEY ASSESSMENT - D18006967MFSH/1
Attachments: SLP 2633J - Preli Advise.pdf

Dear May Chua,

Enclosed herewith preliminary advice of SLP 2633J.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 24 September 2018 3:38 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006967MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 24 September 2018 2:21 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006967MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



SELL YOUR CAR BY BIDDING

HIGHEST SELLING PRICE GUARANTEED!

OR GET \$100 CASH!



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



RARE Mercedes Benz C-Class
 C180 BlueEfficiency! Grab FAST
 Before It's Gone!
 Classic Credit StarAd



Republic | **CERTIFIED PRE-OWNED MERCEDES-BENZ**

[View our cars](#)

Browse by Category

Sort by Date Posted 20 results/page

14 vehicles

bmw 730

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 730		Any	Any	2010	Any	Any	Any	Available
	BMW 7 Series	730Li Sunroof	\$57,888	\$13,330 /yr	29-Apr-2010	2,996 cc	173,000 km	Luxury	Available
	Accident Free, Lots Of Parts Replaced, Transmission Just Overhaul, Rear Suspensions Replaced, Etc. Please Call For Viewing.								
	Posted: 29-Sep-2018 Tags: 2010 BMW 730Li, 2010 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	BMW 7 Series	730Li Sunroof	-	N.A	23-Jul-2010	2,996 cc	83,000 km	Luxury	Available
	Low Mileage, Good Condition.								
	Posted: 23-Sep-2018 Tags: 2010 BMW 730Li, 2010 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	BMW 7 Series	730Li Sunroof	\$58,800	\$12,250 /yr	21-Jun-2010	2,996 cc	-	Luxury	Available
	Asking Low! Superb Well Maintained Condition. Definitely Worth Viewing It. Nicely Kept Interior/Exterior, High Paper Value At \$49K, Exporters Welcome. Unit Not To Be Missed! Director Owner Posted Over...								
	AL Autocar Pte Ltd Posted: 23-Sep-2018 Tags: 2010 BMW 730Li, 2010 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	BMW 7 Series	730Li Sunroof	\$69,800	\$15,530 /yr	30-Nov-2010	2,996 cc	101,000 km	Luxury	Available
	Appointment For Viewing, Care Full Owner, Big Luxury Saloon, Mint Condition, Well Maintained By Agent Provided All Service Record Bills, 100% Accident Free, One Of The Best Condition In The Market. We...								
	HTS Motor Posted: 23-Sep-2018 Tags: 2010 BMW 730Li, 2010 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	<p>Is your COE expiring? Let us help you renew it!</p> <p>Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.</p>								
	BMW 7 Series	730Li Sunroof	\$65,288	\$16,020 /yr	30-Aug-2010	2,996 cc	115,000 km	Luxury	Available
	Loan Up To 100% With Low Monthly Installment! Balloon Scheme Welcome. Owner Well Maintained Inside Out. Upgraded 20" Breyton Rims. Accident Free Unit. 2 Owner Vehicle 3rd Due To Name Transfer Only Wit...								
	Posted: 21-Sep-2018 Tags: 2010 BMW 730Li, 2010 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	BMW 7 Series	730Li Sunroof	\$59,500	\$12,780 /yr	19-Aug-2010	2,996 cc	-	Luxury	Available
	Well Maintained With Servicing Records With Reputable Workshop, Trade In And High Loan Assist Available. 100% Accident Free Unit, STA Evaluation Welcome, Call To Arrange For An Viewing Appointment Tod...								
	Posted: 12-Sep-2018 Tags: 2010 BMW 730Li, 2010 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
<input type="button" value="Compare"/>	BMW 7 Series	730Li Sunroof	\$71,500	\$16,290 /yr	03-Dec-2010	2,996 cc	-	Luxury	Available

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6184B
Vehicle Details	
Vehicle No.:	SLP2633J
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	11397602N52B30AF
Chassis No.:	WBAKB22020CN74736
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$72,380.00
Original Registration Date:	15 Dec 2010
First Registration Date:	15 Dec 2010
Transfer Count:	1
Actual ARF Paid:	\$72,380.00 <i>36190</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2020
PARF Rebate Amount:	\$43,428.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$62,502.00
COE Rebate Amount:	\$13,760.00
Total Rebate Amount:	\$57,188.00
Message	

The information contained herein is correct as at 01 Oct 2018

OK

SKETCH PLAN #3

Accident along BKE


19-09-2018 19:48

When I drive along BKE to home, Bukit Panjang, My car SLP2633J was tailed by a taxi SH9000Z at about 19:48 19-09-2018. A SUBARU vehicle tail the taxi at the same time. There is no people injury found.

It was raining, so that we took videos and pictures (include of driving licences picture) then left to avoid traffic jam there.



SKETCH PLAN #4



SKETCH PLAN #5



Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
 GST:201006949C RCB NO.201006949C

M/S : LIU YAOWU
 BLK 609 BUKIT PANJANG RING ROAD #07-894
 SINGAPORE 670609

Estimate No: **EST1504088**
 Date: 20 Sep 2018
 Policy No: 1800056518
 Veh Reg No: **SLP2633J**
 Make/Model: B.M.W. 730LI AT ABS
 D/AB 2WD 4DR NAV
 HID SR
 Chassis No: WBAKB22020CN74736
 Engine No: 11397602N52B30AF
 Reg. Date: 15/12/2010

ATTN: FIRST CAPITAL

Your Ref No: TP 0918-5231
 Claim Type: Third Party
 Accident Date: 19/09/2018
 TP Veh Reg No: SH 9000 Z

Estimate Repair Cost to Vehicle No :SLP2633J

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER <i>r/ee</i>	1,571.15	1 PC	1,571.15	—
2 REAR BUMPER SIDE HOLDER - LH, RH <i>11</i>	192.15	2 PCS	384.30	X
3 REAR BUMPER CLIPS <i>ru</i>	5.00	10 PC	50.00	—
4 REAR BUMPER REFLECTOR - LH, RH <i>11</i>	35.20	2 PC	70.40	X
5 REAR BUMPER REINFORCEMENT <i>n</i>	800.80	1 PC	800.80	X
6 REAR BUMPER LOWER GARNISH <i>11</i>	224.45	1 PC	224.45	X
7 REAR BUMPER FOAM <i>11</i>	58.65	1 PC	58.65	—
8 REAR BUMPER TOWING COVER - RH <i>tu</i>	50.65	1 PC	50.65	—
9 REAR BUMPER SENSOR <i>sv</i>	236.85	4 PC	947.40	X
10 REAR BUMPER SENSOR WIRE <i>11</i>	89.50	1 PC	89.50	X
			4,247.30	1671.8
		Less 5%	212.37	4,034.94
Labour				
11 TO KNOCK OUT DENTS, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	500.00	1 JOB	500.00	400
12 TO RESPRAY PAINT ON ACCIDENT PORTIONS	700.00	1 JOB	700.00	400
13 TO CHECK WIRING	20.00	1 JOB	20.00	—
14 TO TRANSFER REAR BUMPER SENSOR	100.00	1 JOB	100.00	50
15 TO REMOVE, REFIX REAR GARNISH	80.00	1 JOB	80.00	—
16 TO TUFF-KOTE	30.00	1 JOB <i>11</i>	30.00	X
17 TO RESET CHECK LIGHT <i>9/12 @ 2538.24</i>	60.00	1 JOB <i>11</i>	60.00	X
			1,490.00	1,490.00

Not Authorized
LLW

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED ELEVEN AND CENTS SIXTY NINE ONLY

try h/s.
1/10/18
3 dm

LKK Auto Consultants hence notify the Repairer of the following:	Total	SS 5,524.94
• To resurvey before/after repairs	Add GST @ 7%	386.75
• To resurvey damaged parts during repairs	Total Amount Payable	SS 5,911.69
• Parts prices are subject to confirmation		
• Third party survey is on a "Without Prejudice" basis		
• No illegal modification(s) is allowed		
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
Acknowledged by Repairer		
Signature: <i>[Signature]</i>		
	AUTHORISED SIGNATURE	

For Progressive Car Care Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017350/Usd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9000Z	Veh. Inspected	SLP 2633J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006967MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	24/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 730LI (A)	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAKB22020CN74736	Colour	BLACK	
Odometer	58102	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	PIRELLI	6 mm	
L/H Front Tyre	245/50 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/50 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/50 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/09/2018	Inspection Date	01/10/2018	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2633J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	1,571.15	1,571.15
2	REAR BUMPER SIDE HOLDER-LH,RH @\$192.15	NOT NECESSARY	384.30	-
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTOR-LH,RH @\$35.20	NOT NECESSARY	70.40	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	800.80	-
1	REAR BUMPER LOWER GARNISH	NOT NECESSARY	224.45	-
1	REAR BUMPER FOAM	NOT NECESSARY	58.65	-
1	REAR BUMPER TOWING COVER-RH	TWISTED	50.65	50.65
4	REAR BUMPER SENSOR @\$236.85	SERVICEABLE	947.40	-
1	REAR BUMPER SENSOR WIRE	NOT NECESSARY	89.50	-
	LESS 5% DISCOUNT		-212.36	-83.59
			4,034.94	1,588.21
LABOUR				
	TO KNOCK OUT DENTS,CUT/WELD,REMOVE,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		500.00	400.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		700.00	400.00
	TO CHECK WIRING.		20.00	20.00
	TO TRANSFER REAR BUMPER SENSOR.		100.00	50.00
	TO REMOVE,REFIX REAR GARNISH.		80.00	80.00
	TO TUFF-KOTE.	NOT NECESSARY	30.00	-
	TO RESET CHECK LIGHT.	NOT NECESSARY	60.00	-
			1,490.00	950.00
GRAND TOTAL			5,524.94	2,538.21
RECOMMENDED COST OF REPAIRS				2,538.21

Report Ref No. CS/FCI18017350/Usd3n2

MARKET VALUE: \$65,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$57,188.00=NETT VALUE: \$7,812.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.