



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/03/2020

### Survey Details:

Date of loss	20-Sep-18
Date of appointment	21-Sep-18
Date of survey	21-Sep-18
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SHD 539Y
Make and Model	RENAULT LATITUDE 2.0L DCI AUTO
Date of registration	29-Dec-17
Excess	
Market Value (est)	\$0.00
Parf Rebate (est)	\$0.00
Nett Loss (est)	\$0.00

### Repair details:

Initial Estimate	\$ 40,103.69
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 2,554.34
Check items (estimate)	\$ -
Labour	\$ 480.00
<b>Total</b>	<b>\$ 3,034.34</b>
<b>Lump Sum(if applicable)</b>	<b>\$ -</b>

Number of days for repair	<u>2 DAYS</u>
---------------------------	---------------



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

### **Remarks:**

*We have not authorized repairs. It was reported that the insured vehicle had rear-ended TP vehicle. A letter was also sent out and no further feedback received till date from Insured. TP LOD in.*

### **Mandate:**

<b>Liability(TP)</b>	<b>100%</b>	
Proposed Repair Cost	\$ 3,246.74	w/gst
Loss of Use	\$ -	no. of days
Loss of Rental (w/gst)	\$ 530.28	(\$132.57x 4 days)
Loss of Income	\$ 200.00	(\$50 x 4 days)
LTA Search Fees	\$ 7.49	
Others (Towing Fee)	\$ -	
<b>Proposed Total</b>	<b>\$ 3,984.51</b>	
<b>***TBC - To Be Confirmed</b>		