

PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg
Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT
EQ INSURANCE CO. LTD

Date: 21.09.2018

ESTIMATED COST OF REPAIRS TO YAMAHA YBR-125

ENGINE NO :

CHASSIS NO :

VEHICLE NO : FBD 8962B

ACCIDENT ON : 06.06.2018

INSURED : TER WEI JIE

With reference to the above, the motorcycle has sustained extensive & irreparable damage to the chassis main frame area and replacement of a new frame is required. However, frame replacement is **not allowable** under LTAs' regulations.

In view of the situation and the extensive damages, we recommend the motorcycle for a **TOTAL LOSS**. Kindly send a surveyor down for a 3rd Party claim survey against your insured vehicle **SGW 5285H**.

Thank you,
Kin Wah, Pan Euro Bikes Pte Ltd
Mobile: 9731-7133

Geo Ricq.
LKK
25/9/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: