

**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667  
Tel: (65) 6469 3319, Fax: (65) 6902 6758  
GST ID No : 201023449R

**Repair Estimate****No. : QT-000014**

INDIA INTERNATIONAL INSURANCE PTE LTD

C/O LKK AUTO CONSULTANTS PTE LTD

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 26-09-2018

TEL :

FAX :

Page : 1 of 2

Item	Tax Code	Description	Qty	UOM	U/ Price	Disc.	Total
					S\$		S\$

OS THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PC163H  
Traffic accident on 21/09/2018 involving PC 163 H and SHD 4473 B at Changi Business Park Central 1

**Parts Required:**

1.	OS	REAR BUMPER	1.00		3,400.00		3,400.00 ✓CA
2.	OS	REAR RIGHT BUMPER STRUCTURAL FRAME ASSY	1.00		1,400.00		1,400.00 ?
3.	OS	SPRAY FORM FOR BUMPER	1.00		400.00		400.00
4.	OS	REAR RIGHT LID COVER ASSY	1.00		3,200.00		3,200.00 *R
5.	OS	REAR RIGHT MARKER LAMP	1.00		80.00		80.00 ✓SCR
6.	OS	REAR RIGHT LID COVER LOCK	1.00		120.00		120.00 ✓SCR
7.	OS	REAR RIGHT TAILLAMP	1.00		960.00		960.00 ?
8.	OS	LESS: 10% TRADE DISCOUNT	1.00		-95.60		-95.60
9.	OS	LABOUR CHARGES - TO KNOCK AND REPAIR ALL NECESSARY PARTS INCLUDING CHANGING OF ALL DAMAGED PARTS	1.00		1,650.00		1,650.00 1,000
10.	OS	LABOUR CHARGES TO PUTTY AND SPRAY PAINTING FOR REAR BUMPER, REAR STRUCTURE ASSY AND REAR RIGHT LID COVER	1.00		1,950.00		1,950.00 1,300

NOTE: THIS ESTIMATE IS BASED ON VISIBLE DAMAGE ONLY. SHOULD ANY HIDDEN PARTS AND/OR LABOUR CHARGES REQUIRED DURING WORKS IN PROGRESS, IT WILL BE NOTIFIED ACCORDINGLY.

*NAZ LKK*

PRICE QUOTED IS SUBJECT TO 7% GST.



**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667  
Tel: (65) 6469 3319, Fax: (65) 6902 6758  
GST ID No : 201023449R

**Repair Estimate**

**No. : QT-000014**

INDIA INTERNATIONAL INSURANCE PTE LTD  
C/O LKK AUTO CONSULTANTS PTE LTD

Your Ref. :  
Our D/O No. :  
Terms : C.O.D.  
Date : 26-09-2018  
Page : 2 of 2

TEL : FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price	Disc.	Total
					\$		\$

NAZ LKK  
2/10/18 1530  
LIS  
3 DAYS  
67418434 / 84809158  
Naz@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

SINGAPORE DOLLAR THIRTEEN THOUSAND SIXTY FOUR AND CENTS FORTY ONLY

Sub Total (Excluding GST)	13,064.40
GST payable @ 7% on 0.00	0.00
<b>Total (Inclusive of GST)</b>	<b>13,064.40</b>

- Notes :
- All cheques should be crossed and made payable to CROWN ASIA BUS BUILDER PTE. LTD.
  - Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

GST Summary	Amount(\$)	Tax(\$)
-------------	------------	---------

Authorised Signature