

25 September 2018

REG NO. : SLL 5487 R
MAKE/MODEL : MAZDA 3

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY DESCRIPTION

AMT(\$)

LIST ITEMS

1	Front bumper
1	Front bumper fog lamp
1	Front bumper fog lamp cover with chrome
1	Front bumper reinforcement
1	Front bumper side retainer 18.70
1	Front bumper side lamp
1	Front bumper rubber seal
1	Front fender -R/H
1	Front fender inner shield
1	Front door -R/H
1	Front door checker
2	Front door hinges
1	Front door inner board
1	Front door lock
1	Front door regulator
1	Front door regulator motor
1	Front door rubber
1	Front door side mirror assy 455.10
1	Front wheel rim -R/H
1	Front wheel hub
1	Front wheel bearing
1	Front shock absorber
1	Front knuckle arm
1	Front lower arm
1	Front drive shaft -R/H

Less 20%

Deep \$	1031.70	✓
\$ 11	351.00	X
\$ 500	149.20	✓
\$ 11	568.40	X
\$ 300	42.50	✓
\$ 11	315.00	X
\$ 11	112.00	X
\$ 11	550.00	X
\$ 10.1	175.00	✓
\$ 11	1,061.50	X
\$ 100	46.80	X
\$ 11	74.00	X
\$ 11	951.60	X
\$ 11	313.00	X
\$ 11	419.10	X
\$ 11	250.00	X
\$ 11	89.00	X
\$ 100	685.00	✓
\$ 11	1,022.20	X
\$ 11	185.80	X
\$ 11	146.00	X
\$ 11	381.00	X
\$ 11	349.50	X
\$ 11	516.70	X
\$ 11	1,168.60	X
\$	10,954.60	
\$	2,190.92	
\$	8,763.68	

P- 1829.7
20%
1863.76

c/f:

\$

8,763.68

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	\$	50.00	✓
1	Front fender inner shield clip (1 set)	\$	50.00	✓
1	Front tyre	\$	350.00	X
		\$	450.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	20
2	To remove and refit front undercarriage.	\$	450.00	X
3	To conduct wheel alignment.	\$	180.00	X
4	To remove, replace door damaged parts and transfer all fittings.	\$	200.00	X
5	To apply undercoating.	\$	200.00	X
6	Panel beating.	\$	1,600.00	500
7	To re-spray painting on the affected areas.	\$	1,500.00	800
		\$	4,210.00	

2883.76

GRAND TOTAL :

\$ 13,423.68

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: