



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 3909K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	CUT	1,412.00	1,240.00
1	RH FRONT BUMPER SIDE RETAINER (CONSISTENT)	NOT NECESSARY	48.00	-
1	RH FRONT FENDER (CONSISTENT)	BUCKLED	958.00	897.00
1	RH FRONT FENDER SPLASH SHIELD (CONSISTENT)	NOT NECESSARY	160.00	-
1	RH FRONT FENDER EMBLEM (CONSISTENT)	NECESSARY	68.00	68.00
1	RH HEADLAMP (CONSISTENT)	CRACKED	3,251.00	1,283.00
1	RH FRONT SHOCK ABSORBER (CONSISTENT)	BENT	697.00	697.00
1	RH FRONT SHOCK ABSORBER MOUNTING (CONSISTENT)	NOT NECESSARY	267.00	-
1	RH FRONT SHOCK ABSORBER STOPPER (CONSISTENT)	NOT NECESSARY	81.00	-
1	RH FRONT LOWER ARM (CONSISTENT)	BENT	570.00	570.00
1	RH FRONT THRUST ARM (CONSISTENT)	NOT NECESSARY	422.00	-
1	RH FRONT KNUCKLE ARM (CONSISTENT)	BENT	854.00	773.00
1	STEERING RACK (CONSISTENT)	BENT	5,793.00	4,109.78
1	RH RACK LINK (CONSISTENT)	NOT NECESSARY	210.00	-
1	RH FRONT TIE ROD END (CONSISTENT)	NOT NECESSARY	182.00	-
1	RH FRONT WHEEL RIM (CONSISTENT)	CUT	780.00	780.00
	LESS 10% DISCOUNT		-1,575.30	-1,041.78
			14,177.70	9,376.00
<u>SPECIAL NETT ITEMS</u>				
1	RH FRONT TYRE (SN) (CONSISTENT)	TORN	480.00	240.00
			480.00	240.00
<u>LABOUR</u>				
	LABOUR TO REMOVE & REPLACE AFFECTED PARTS.		700.00	400.00
	SPRAY PAINT ON THE AFFECTED PARTS.		800.00	500.00
	LABOUR TO REMOVE/RENEW FRONT UNDERCARRIAGE.		900.00	250.00
	TO WHEEL ALIGNMENT.		120.00	60.00
	LABOUR TO CONDUCT WIRING CHECK.		60.00	30.00
			2,580.00	1,240.00
GRAND TOTAL			17,237.70	10,856.00

Report Ref No. CC4/ASM18017585/Gea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,700.00
---	--	--	-----------------

Report Ref No. CC4/ASM18017585/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.